

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

20-Feb-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8778 G

1 pc	Tailgate lower garnish ✓	\$	362.61
1 pc	Tailgate weatherstrip X	\$	276.98
1 pc	Tailgate lock X	\$	216.48
1 pc	Emblem I30 ✓	\$	27.80
1 pc	Emblem CRDI ✓	\$	29.40
1 pc	Emblem Hyundai X	\$	29.40
1 pc	Rear bumper ✓	\$	811.11
1 pc	Rear bumper sponge ?	\$	79.20
1 pc	Rear bumper reinforcement ?	\$	815.64
1 pc	Rear bumper reinforcement centre ?	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 ?	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @ \$107.50 ?	\$	215.00
		\$	3,047.22
		Less 20%	\$ 609.44
		\$	2,437.78

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	Reverse sensor ✓	\$	280.00 200
1 set	Tailgate stickers ✓	\$	100.00
1 set	Tailgate lower garnish clips ✓	\$	38.00
Sundry		\$	50.00 20
To dismantle and replace reverse sensor and test system		\$	80.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, etc		\$	300 850.00
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel X		\$	360 800.00
To apply rustproofing on the repaired and replaced panels		\$	120.00 X
Total		\$	4,983.78

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consulting

the Repairer

20/2/19, 715h

3 by,

P.P. Before Rep pld

Acknowledged by Rep

Signature:

Date: