

ASS. NO. C. BY:

REF:

CO9 AIG19003260 Add 30x

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100476156-02

Claims No. _____

Sum Insured: _____ Excess: 300/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 hrs days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLES601P Yr Regn: 2016 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 Sedan C.C. 1395

Colour: Black A/C: Insured / Std / Nil / NA

Sp. Reading: 55927 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WAU222805671090376

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A. _____		D.O.I. <u>20/01/19</u>	

Survey held at Premier

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	DDAIG.
	SLES601P-X
26/2	Revert via menimen
26/2	authorise repair by koh victor.
	mv: 80k
	PV: 52.2k
	Nett:
26/2	2:23pm inform repair authorise repair excess \$300/-

RECEIVED 20 FEB 2020

All in \$27000/- repair sum (cred: 25568.32!47%)

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:		Survey Fee:	Date:
1)	2)	IN	OUT	Basic & Add.	<u>200</u>
3)	4)			_ S + RS, _ SI	
5)	6)			Photos	<u>11</u>
Preli Report				Others	
Final Report				TOTAL	<u>211</u>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 21 Feb 2019

Preliminary Advice

Vehicle No	: SLE5601P	Accident Date	: 18/02/2019
Make	: AUDI A3	Policy No.	: 2100476156-02
Assignment Date	: 21/02/2019	Excess	: S\$0.00
Date of Inspection	: 20/02/2019	Est. Duration of Repair	: 12.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,756.00
Revised Amount	:S\$	24,139.00
Check Items (Estimated)	:S\$	9,293.00
Total	:S\$	33,432.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	52,216.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,784.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : PENDING REPAIR COST FROM REPAIRER

View Received Message

This mail is associated with :

***SLE5601P (5118973751SG)**
OD
Feb 18 2019 8:00AM
[YEO TEE KHAI]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 26/02/2019 14:07 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$24139.00) - SLE5601P - Claim Handler: Dally Amri, Mimi Zarina

Approved:24139,00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 26 February 2019 2:23 PM
To: 'Claims Dept'; SUR
Cc: 'NORA '
Subject: RE: OD CLAIM FOR SLE 5601 P

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLE 5601P (Excess \$300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Tuesday, 26 February 2019 1:26 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'NORA ' <nora.khai@premiumauto.com.sg>; 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SLE 5601 P

Dear Denise,

We're able to repair at S\$ 27,000 /Part by Part.

Thank You,

Best Regards,
George Wong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 159902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

View Received Message

This mail is associated with :

*SLE5601P (5118973751SG)

OD
Feb 18 2019 8:00AM
[YEO TEE KHAI]
Premium Automobiles Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 28/05/2019 14:20 PM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SLE5601P - Claim Handler: Dally Amri, Mimi Zarina

Maintained: Labour 5 to take out - Door repair why need to transfer lock? A/C condenser fluid reservoir damage photos? Supplementary labour 2 & 3 to take out. Intake manifold not replace. Replace air con pipe should be inclusive in remove and renew

JK

68-74.

DOCUMENTS SUMMARY

There are no documents.

Referring to photos 68-74, after the removal of the lock carrier and air-con system, it can be observed that the air con pipes are still attached to the various air con components.
Therefore Premium Automobile ^{requested for the} ~~insist that~~ additional labour ~~is necessary~~ to replace the air con pipes.

Due to the impact, the air cleaner, which is positioned above the intake manifold, was pushed out of position.

Hence, the portion of the air cleaner, which is attached to the intake manifold

Adjuster recommendation S\$31,522.56 exceeds max mandate of S\$24,139.00 given by the insurer for direct offer.
Adjuster must seek a new mandate from insurer.

Insurer's Mandate Remarks

Labour 5 to take out - Door repair why need to transfer lock? A/C condenser fluid reservoir damage photos?
Supplementary labour 2 & 3 to take out. Intake manifold not replace. Replace air con pipe should be inclusive in remove
and renew condenser radiator labour.

You cannot authorize this offer because
Adjuster recommendation S\$31,522.56 exceeds max mandate of S\$24,139.00 given by the insurer for direct offer.
Adjuster must seek a new mandate from insurer.
File to be authorized by your superior.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19003262/ATD3E2
Date: 21/08/2019

REFERENCE

Insured/Claimant: YEO TEE KHAI Policy No: 2100476156
Date of Loss: 18/02/2019 Nature of Claim: OD Claim No: 5118973751SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE5601P**
Make & Model: AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A) Engine No: CZC540646
Reg. Date: 26/07/2016 (Man. Year: 2016) Chassis No: WAUZZZBV5G1090376
Colour: Black Odometer: 55927 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$80,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,246.32	20,375.56	11,870.76	36.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,322.00	11,147.00	8,175.00	42.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	51,568.32	31,522.56	20,045.76	38.87
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	51,268.32	31,222.56	20,045.76	39.10
+ GST 7.00/7.00% (S\$)	3,588.78	2,185.58	1,403.20	39.10
Nett Amount (S\$)	54,857.10	33,408.14	21,448.96	39.10

INSPECTION

Date of Assignment: 21/02/2019
Date Inspected: 20/02/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 15.0 days

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	18 Feb 2019 18:52	Clim Veh Model Changed		[] Merimen Administrator
2	18 Feb 2019 18:52	Clim Created	Reg No: SLE5601P. Policy No: 2100476156-02. Acct Date: 2019/02/18. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA119022733	[I] Merimen Administrator
3	21 Feb 2019 12:48	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	21 Feb 2019 12:48	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	21 Feb 2019 12:48	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	21 Feb 2019 12:48	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/04	[A] CELINE FONG
7	21 Feb 2019 12:48	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CELINE FONG
8	21 Feb 2019 12:48	Clim Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	21 Feb 2019 12:48	Clim Veh Model Changed	(205996) AUDI A3 1.4 SEDAN TFSI (ATTRACTION) (A).	[A] CELINE FONG
10	21 Feb 2019 12:49	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CELINE FONG
11	21 Feb 2019 14:45	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
12	21 Feb 2019 14:45	Clim Dtl Modified	JPJ Reg. Date: -> 2016/07/26.	[A] DENISE TAY KWEE CHENG
13	21 Feb 2019 14:45	Clim Details Notified		[A] DENISE TAY KWEE CHENG
14	22 Feb 2019 09:18	Clim Registration Modified	Acct Time:08:40:00->08:00:00.	[I] AIG OneClaim Integration User
15	22 Feb 2019 09:51	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/03/04	[A] DENISE TAY KWEE CHENG
16	22 Feb 2019 11:34	Clim Registration Modified	Init.Est.->7,000 - 8,000. Excess: -> 300.00. Excess Waived: -> 300.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Dally Amri, Mimi Zarina
17	22 Feb 2019 11:34	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
18	26 Feb 2019 13:34	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/03/04	[A] DENISE TAY KWEE CHENG
19	26 Feb 2019 13:34	Adj Mandate Request	Cur.Reg:27000.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
20	26 Feb 2019 14:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/04. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
21	26 Feb 2019 14:07	Adj Mandate Set	Approved:24139.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK
22	22 May 2019 10:15	Adj Mandate Request	Cur.Reg:31522.56:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
23	28 May 2019 14:20	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/03/04. Mandate Remarks: Labour 5 to take out - Door repair why need to transfer lock? A/C condenser fluid reservoir damage photos? Supplementary labour 2 & 3 to take out. Intake manifold not replace. Replace air con	[I] Koh, Victor-CK
24	28 May 2019 14:20	Adj Mandate Set	Maintained:Labour 5 to take out - Door repair why need to transfer lock? A/C condenser fluid reservoir damage photos? Supplementary labour 2 & 3 to take out. Intake manifold not replace. Replace air con pipe should be inclusive in remove and renew	[I] Koh, Victor-CK

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2064164	21/02/2019 14:45	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLE5601P		10.70

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/02/2019 17:13
Date Of Accident	18/02/2019 08:40
Exact Location Of Accident	PIE EXIT TO ECP (CITY) CORNERING BEND
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE5601P
Insured/Policyholder	
Name Of Registered Owner	YEO TEE KHAI
NRIC No	S8115402C
Email Address	ERICYEO81@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92983853
Alternative Phone No	OTHERS-92983853

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.4 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100476156-02
Cover Note Number	

Driver

Name of Driver	YEO TEE KHAI
NRIC No	S8115402C
Date Of Birth	27/05/1981
Occupation	INDOOR
Date Of Driving Pass	28/11/2001
Driving Experience	17 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92983853
Fax Number	
Contact Number	OTHERS-92983853
EMail Address	ERICYEO81@GMAIL.COM

Address	179 JALAN LOYANG BESAR #03-07
Postcode	508926
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JANE KOH GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

A CAR SKIDDED AND MY FRONT VEHICLE STOP TO ALLOW THE SKIDDED CAR TO REVERSE. AS IT WAS AT A BEND, I COULD NOT SEE THAT THE FRONT VEHICLE HAD STOPPED. WHEN I SEE IT, I TRIED TO BRAKE BUT FLOOR IS SLIPPERY AND COULD NOT BRAKE IN TIME.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU1473J
Vehicle Make/Model/Colour	BMW /520 D
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JEREMY CHAN TZE LOON
NRIC/Passport Number	
Contact Number	94777117
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature

Date & Time: 18 Feb 2019

10:27 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A car skidded and my front vehicle stop to allow the skidded car to reverse. As it was at a bend, I could not see that the front vehicle had stopped. When I see it I tried to brake but floor is slippery and the ~~brake~~ could not brake in time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NIC/TIN No.:



Accident Photo





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : YEO TEE KHAI (YANG ZHIKAI)
Period of Insurance : 26 Jul 2018 To 25 Jul 2019
Engine No. : CZC540646
Chassis No. : WAUZZZ8V5G1090376

Vehicle No. : SLE5601P
Policy No. : 2100476156-02
Endorsement No. :
Issued Date : 22 Jul 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.4 TFSI (Attraction)
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

YEO TEE KHAI (YANG ZHIKAI) - \$500 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63652323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 5338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE
AIGSGMOBILEAPP

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident.
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours of the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours of the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours of the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5402C
Vehicle Details	
Vehicle No.:	5LE5601P
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI (ATTRACTION)
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	CZC540646
Chassis No.:	WAUZZZ8V5G1090376
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$25,096.00
Original Registration Date:	26 Jul 2016
First Registration Date:	26 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$17,135.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jul 2026
PARF Rebate Amount:	\$12,851.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,000.00
COE Rebate Amount:	\$39,365.00
Total Rebate Amount:	\$52,216.00

The information contained herein is correct as at 21 Feb 2019

OK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0217/2019/KK
Date : 19-Feb-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Yeo Tee Khai
Address : 179 Jalan Loyang Besar
#03-07
Singapore 506926
Telephone : HP +65 92893853
Type of Claim : Own Damage Claims
Policy No. : 2100476156-02
Vehicle No : **SLE 5601 P**
Model Code : Audi A3 SEDAN 1.4 TFSI
Model / Year : 26/7/2016
Engine No : CZC 540646
Chassis No : WAUZZZ8V5G1090376
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Feb-19
Place of Accident : PIE Exit To ECP (CITY) Cornering Bend

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 5601 P

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To tow and recover vehicle from scene of accident.	S/N	AIG	✓ X
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	✓ ✓ 360
3	To remove and renew aircon condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas	S/N \$	1,000.00	✓ / 1000
4	To renew front windscreen.	S/N \$	480.00	✓ / 480
5	To remove and transfer rhs front doors' multi-lock systems and power window devices. Inspect for damages and renew if necessary.	S/N \$	280.00	X ✓ 280
SUB LABOUR CHARGES			: \$ 2,120.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLE 5601 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To dismantle and renew front bumper, both front fender, bonnet, both headlight and rhs front door. Cut out and reweld rhs fender top support. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	S 8,400.00	3000 ✓
2	To respray front bumper, both front fender, bonnet, rhs front fender top support, hinges, rhs front door, rhs upper A-pillar. ✓	S 5,800.00 3275	3000 5 main pieces = 2250 2 half pieces = 550 2 hinges = 200
3	To renew rhs front rim and carry out wheel alignment.	S/N S 280.00 ✓	
4	To carry out diagnostic check.	S/N S 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 16,792.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5601 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER COVER <i>Distorted</i>	\$ 1,830.00	✓ 1464
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00	+ x
3	FRONT COVER TRIM - LH/RH <i>new</i>	\$ 296.00	+ x
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 148.00	+ x
5	PULL STRAP - LOWER <i>new part</i>	4 \$ 187.00	✓ 149.12
6	FRONT GUIDE SECTION - LH/RH <i>RH and</i>	\$ 70.00	✓ 27.52
7	FRONT AIR GUIDE GRILLE - LH/RH <i>RH missing</i>	\$ 198.00	99. 78.88
8	RADIATOR GRILLE <i>cancel</i>	\$ 637.00	✓ 509.20
9	RADIATOR GRILLE COVER <i>Damaged.</i>	\$ 89.00	? 70.88
10	SIDE REINFORCEMENT <i>Best</i>	\$ 660.00	✓ 577.60
11	FOAM FILLER PIECE <i>Best</i>	\$ 125.00	✓ 99.60
12	FRONT BUMPER REINFORCEMENT COVER <i>cancel</i>	\$ 51.00	✓ 40.40
13	SIGNAL HORN - HIGH TONE RH <i>Not new</i>	\$ 182.00	? x
14	FRONT NUMBER PLATE <i>Best</i>	\$ 25.00	✓ 25
15	FRONT BONNET <i>Distorted</i>	\$ 2,898.00	✓ 2318.40
16	FRONT BONNET ATTACHMENT PARTS <i>new</i>	\$ 149.00	✓ x
17	LID HINGE - LH/RH <i>Best</i>	\$ 112.00	✓ 88.48
18	GAS FILLED STRUT <i>new</i>	\$ 109.00	+ x
19	CATCH HOOK <i>Best</i>	\$ 81.00	✓ 64.72
20	STRIKER <i>Best</i>	2 \$ 100.00	✓ x
SUB SPARE PARTS		\$ 8,117.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5601 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	EDGE PROTECTION - FRONT <i>new</i>	S	25.00 — 19.92
22	COWL SEAL COVER - RH <i>new</i>	S	37.00 — 29.04
23	CATCH HOOK <i>set</i>	S	58.00 — 45.76
24	LID LOCK MICROSWITCH <i>2nd</i>	2 S	367.00 — 293.60
25	BOWDEN CABLE <i>2nd</i>	S	53.00 ? 41.68
26	LID LOCK CABLE <i>new</i>	S	67.00 X
27	FRONT FENDER WING - LH/RH <i>RH Dislod</i>	S	1,556.00 778 622
28	FRONT FENDER ATTACHMENT PARTS <i>2nd new</i>	2 S	130.00 ? X
29	BRACKET FENDER - RH <i>set</i>	S	25.00 — 19.76
30	BRACKET <i>set</i>	S	35.00 — 27.76
31	BRACE <i>set</i>	S	88.00 — 69.84
32	WING CLOSING ELEMENT - RH <i>2nd</i>	S	30.00 — 23.76
33	ENGINE BONNET SOUND ABS. <i>Comp damaged</i>	S	201.00 — 160.80
34	WING INSULATION - RH <i>new</i>	S	38.00 ? X
35	SEAL WHEEL HOUSING LINER - RH UPPER <i>Not Nec</i>	S	31.00 ? X
36	WHEEL HOUSING LINER - RH <i>2nd</i>	S	158.00 — 126
37	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not Nec</i>	S	81.00 ? X
38	GAS DISCHARGE LAMP HEAD LIGHT - LH/RH <i>cracked</i>	S	3,650.00 — 2920
39	GAS DISCHARGE LAMP <i>2nd</i>	S	398.00 ? 313.40
40	POWER MODULE DAY DRIVING LIGHTS <i>damaged</i>	S	522.00 ? 4760
SUB SPARE PARTS			\$ 7,550.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5601 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	GAS DISCHARGE LAMP CONTRO UNIT <i>Payd.</i>	\$ 1,051.00	? 840.80
42	LIFT CYLINDER HEADLIGHT WASHER SYSTEM - LH/RH <i>RH and</i>	\$ 362.00	? 144.80
43	HEADLIGHT WASHER HOSE PIPE <i>new</i>	\$ 170.00	X.
44	COOLANT RADIATOR LOCK CARRIER <i>crackd</i>	\$ 663.00	✓ 530.40
45	A/C CONDENSER FLUID RECERVOIR <i>Best.</i>	\$ 516.00	? 412.40
46	A/C CONDENSER REFRIGERANT LINE <i>Best.</i>	\$ 461.00	? 368.80
47	A/C REFRIGERANT LINE - CUT OFF POINT <i>Best</i>	\$ 601.00	? 480.40
48	ADDITIONAL COOLER COOLANT <i>Best</i>	\$ 837.00	? 669.60
49	READY-MIX COOLANT <i>new</i>	4 \$ 84.00	✓ 67.20
50	AIR GUIDE - LH/RH <i>2H Payd</i>	\$ 44.00	✓ 34.24
51	AIR GUIDE - UPPER CENTRE <i>Not nec</i>	\$ 88.00	? X
52	RADIATOR FAN RING <i>crackd</i>	\$ 1,483.00	? 1186.40
53	AIR GUIDE <i>Best</i>	\$ 53.00	? 41.84
54	INTAKE AIR DUCT COVER <i>Best</i>	\$ 27.00	? 21.36
55	WATER DRAINAGE HOSE <i>2H</i>	\$ 31.00	? 24.48
56	AIR FILTER <i>Best.</i>	\$ 259.00	? 207.20
57	INTAKE MANIFOLD <i>Not nec</i>	\$ 113.00	? X
58	ENGINE COMPARTMENT COVER <i>Not nec</i>	\$ 103.00	? X
59	A-PILLAR CONNECTING PLATE - RH <i>Not nec</i>	\$ 214.00	? X
60	FRONT CLOSING ELEMENT - RH <i>Not nec</i>	\$ 68.00	? X
SUB SPARE PARTS		\$ 7,228.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5601 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	DOOR <i>Repis</i>	S	2,279.00 *
62	OUTER DOOR SEAL - RH <i>new</i>	S	146.00 +
63	BONDING AGENT <i>?</i>	S	45.00 *
64	CLEANING SOLUTION <i>new</i>	S	65.00 +
65	DOOR ATTACHMENT PARTS	S	218.00 +
66	DOOR CATCH <i>new</i>	S	96.00 +
67	DOOR CATCH COVER <i>new</i>	S	13.00 +
68	CORNER TRIM - RH <i>new</i>	S	41.00 +
69	TRIM STRIP WINDOW GUIDE - RH <i>Not New</i>	S	235.00 ?
70	FRONT TRIM STRIP WINDOW SLOT SEAL - RH <i>cut</i>	S	282.00 ✓ 2560
71	WATER DEFLECTOR STRIP - RH <i>cut on</i>	S	85.00 + X
72	WINDSCREEN <i>could</i>	S	988.00 ✓ 790
73	GEL FOIL RAIN SENSOR <i>new</i>	S	128.00 ✓ 102-40
74	SPRING CLIP <i>not New</i>	S	20.00 ✓ X
75	ALUMINIUM RIM <i>cut</i>	S	651.00 ✓ 520.80
76	RUBBER VALVE <i>new</i>	4 S	13.00 X X
77	SIGN ' COUTION ' <i>new</i>	S	13.00 ✓ 9.76
78	DATA PLATE TYRE PRESSURE <i>new</i>	S	26.00 + ?
79	FRONT NO PLATE <i>Replaced</i>	S/N S	25.00 + X
80	FRONT WINDSCREEN SEALANT <i>new New</i>	S/N S	200.00 ? 200
SUB SPARE PARTS		:	\$ 5,569.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5601 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
81	ACRYLIC SEALANT	S/N \$	180.00 ✓ 180
82	CAVITY WAX	S/N \$	140.00 ✓ 140
83	STONE CHIP	S/N \$	180.00 ✓ 180
84	SUNDRIES	\$	1,000.00 ? 114.64
TOTAL SPARE PARTS		\$	29,964.00
TOTAL LABOUR CHARGES		\$	16,792.00
GRAND TOTAL		\$	46,756.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

51968-32

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 20/02/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 12 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

Quantity	Description	Unit Price	Amount			
<table border="0" style="width:100%"> <tr> <td style="width:45%"> AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315 </td> <td style="width:25%"> Estimate No. Date Service Advisor Pages Regn No Model No </td> <td style="width:25%"> PA/OD/0217/2019/KK 4-Mar-19 CHANG 1 of 1 SLE 5601 P Audi A3 SEDAN 1.4 TFSI </td> </tr> </table>				AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0217/2019/KK 4-Mar-19 CHANG 1 of 1 SLE 5601 P Audi A3 SEDAN 1.4 TFSI
AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0217/2019/KK 4-Mar-19 CHANG 1 of 1 SLE 5601 P Audi A3 SEDAN 1.4 TFSI				
Labours						
1	To repair RHS front fender support and RHS front door.	\$ 750.00	\$ 500.00			
* 2	To remove and renew intake manifold with intercooler. S/N	\$ 900.00	\$ 900.00			
* 3	To remove and renew Air cond pipes. S/N	\$ 480.00	\$ 480.00			
4	To install solar film <i>Nec</i> S/N	\$ 400.00	\$ 400.00			
		\$ 2,530.00	\$ 2,280.00			
Parts						
1	A/C PIPE (EXPANSION VALVE -> COMPRESSOR ✓ BT	\$ 461.00	\$ 368.80			
2	CHARGE AIR COOLER ✓ BT	\$ 663.00	\$ 530.40			
3	AIR COOLER BOLT SET <i>nec</i>	\$ 12.00	\$ 9.60			
4	AIR COOLER SEAL <i>nec</i> 2	\$ 29.00	\$ 22.56			
5	INTAKE MANIFOLD ✓ BT	\$ 537.00	\$ 429.20			
6	RADIATOR ✓ BT	\$ 878.00	\$ 702.40			
7	RADIATOR BRACKET <i>nec</i> 2	\$ 77.00	\$ 61.28			
8	RADIATOR BUSH - LOWER ✓ <i>nec</i> 2	\$ 18.00	\$ 14.24			
9	COVER FOR PLENUM CHAMBER ✓ <i>BK</i>	\$ 164.00	\$ 130.80			
10	OUTER TEMP. SENSOR BRACKET ✓ <i>Nec</i>	\$ 17.00	\$ 13.04			
		Materials	\$ 2,856.00			
		Labour	\$ 2,530.00			
Grand tot :		\$ 5,386.00	\$ 4,562.32			

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0423/2019/KK

2-May-19

Glory Tan

1 of 1

SKQ 8750 X

Audi A6 C7 2.0 TFSI MU 4G

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Control unit for LED headlight. <i>Damaged</i>	\$ 1,051.00	✓
		\$ 1,051.00	
TOTAL		\$ 1,051.00	

LABORS

For Premium Automobiles Pte Ltd

Adrian Ling
[Signature]

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0217/2019/KK
Date : 19-Feb-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
You recommended 10 days
We took 15 days exclude 2 Sundays
ib- 28 Mar 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Yeo Tee Khai
Address : 179 Jalan Loyang Besar
#03-07
Singapore 506926
Telephone : HP +65 92893853
Type of Claim : Own Damage Claims
Policy No. : 2100476156-02
Vehicle No : **SLE 5601 P**
Model Code : Audi A3 SEDAN 1.4 TFSI
Model / Year : 26/7/2016
Engine No : CZC 540646
Chassis No : WAUZZZ8V5G1090376
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Feb-19
Place of Accident : PIE Exit To ECP (CITY) Cornering Bend

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

Start 4/3/19

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
 Attn: Mr. Adrian Ling - Motor Claims Dep
 Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
 Date
 Service Advisor
 Pages
 Regn No
 Model No

PA/OD/0217/2019/KK
 4-Mar-19
 CHANG
 1 of 1
 SLE 5601 P
 Audi A3 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	To repair RHS front fender support and RHS front door.	\$ 750.00	500.00
2	To remove and renew intake manifold with intercooler. S/N	\$ 900.00	200.00
3	To remove and renew Air cond pipes. S/N	\$ 480.00	480.00
			<u>1880.00</u>
Parts			
1	A/C PIPE (EXPANSION VALVE -> COMPRESSOR <i>big pipe BT</i>)	\$ 461.00	
2	CHARGE AIR COOLER <i>BT</i>	\$ 663.00	
3	AIR COOLER BOLT SET <i>1PC</i>	\$ 12.00	
4	AIR COOLER SEAL <i>1PC</i>	\$ 29.00	
5	INTAKE MANIFOLD <i>BT</i>	\$ 537.00	
6	RADIATOR <i>Back frame BT</i>	\$ 878.00	
7	RADIATOR BRACKET <i>1PC LH-RH BT</i>	\$ 77.00	
8	RADIATOR BUSH - LOWER <i>1PC LH RH</i>	\$ 18.00	
9	COVER FOR PLENUM CHAMBER <i>can put cover BR</i>	\$ 164.00	
10	OUTER TEMP. SENSOR BRACKET <i>1PC</i>	\$ 17.00	
GRAND TOTAL :		\$ 4,986.00	

For Premium Automobiles Pte Ltd


 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 5601 P

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To tow and recover vehicle from scene of accident.	S/N	AIG	
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
3	To remove and renew aircon condenser, radiator and additional radiator. Check electrical fans and contro unit.Pressurise cooling system. To carry out vacuum and regas	S/N	\$ 1,000.00	\$ 1,000.00
4	To renew front windscreen.	S/N	\$ 480.00	\$ 480.00
5	To remove and reinstall door trims, renew slot shield, R/l door wing mirror assy to facilitate respray of door	S/N	\$ 280.00	\$ 280.00
SUB LABOUR CHARGES		:	<u>\$ 2,120.00</u>	<u>\$ 2,120.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLE 5601 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
			\$ 2,120.00
1	To dismantle and renew front bumper, both front fender, bonnet, both headlight and rhs front door. Cut out and reweld rhs fender top support. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 8,400.00	\$ 3,000.00
2	To respray front bumper, both front fender, bonnet, rhs front fender top support, hinges, rhs front door, rhs upper A-pillar.	\$ 5,800.00	\$ 3,275.00
3	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
4	Added labour charges - see attached	\$ 2,530.00	\$ 2,280.00
5	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 16,792.00	\$ 11,147.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLE 5601 P**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER COVER	\$ 1,830.00	\$ 1,464.00
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT COVER TRIM - LH/RH	\$ 296.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 148.00	
5	PULL STRAP - LOWER	4 \$ 187.00	\$ 149.12
6	FRONT GUIDE SECTION - LH/RH	\$ 70.00	\$ 27.52
7	FRONT AIR GUIDE GRILLE - LH/RH	\$ 198.00	\$ 78.88
8	RADIATOR GRILLE	\$ 637.00	\$ 509.20
9	RADIATOR GRILLE COVER	\$ 89.00	\$ 70.88
10	SIDE REINFORCEMENT	\$ 660.00	\$ 527.60
11	FOAM FILLER PIECE	\$ 125.00	\$ 99.60
12	FRONT BUMPER REINFORCEMENT COVER	\$ 51.00	\$ 40.40
13	SIGNAL HORN - HIGH TONE RH	\$ 182.00	
14	FRONT NUMBER PLATE	\$ 25.00	\$ 25.00
15	FRONT BONNET	\$ 2,898.00	\$ 2,318.40
16	FRONT BONNET ATTACHMENT PARTS	\$ 149.00	
17	LID HINGE - LH/RH	\$ 112.00	\$ 88.48
18	GAS FILLED STRUT	\$ 109.00	
19	CATCH HOOK	\$ 81.00	\$ 64.72
20	STRIKER	2 \$ 100.00	
	SUB SPARE PARTS	\$ 8,117.00	\$ 5,463.80

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLE 5601 P**

S/N	Parts Description	Damaged Parts & Prices		
		S/Nett	Remark	
		<i>c/f</i>	\$	5,463.80
21	EDGE PROTECTION - FRONT	\$	25.00	\$ 19.92
22	COWL SEAL COVER - RH	\$	37.00	\$ 29.44
23	CATCH HOOK	\$	58.00	\$ 45.76
24	LID LOCK MICROSWITCH	2 \$	367.00	\$ 293.60
25	BOWDEN CABLE	\$	53.00	\$ 41.68
26	LID LOCK CABLE	\$	67.00	
27	FRONT FENDER WING - LH/RH	\$	1,556.00	\$ 622.00
28	FRONT FENDER ATTACHMENT PARTS	2 \$	130.00	
29	BRACKET FENDER - RH	\$	25.00	\$ 19.76
30	BRACKET	\$	35.00	\$ 27.76
31	BRACE	\$	88.00	\$ 69.84
32	WING CLOSING ELEMENT -RH	\$	30.00	\$ 23.76
33	ENGINE BONNET SOUND ABS.	\$	201.00	\$ 160.80
34	WING INSULATION - RH	\$	38.00	
35	SEAL WHEEL HOUSING LINER - RH UPPER	\$	31.00	
36	WHEEL HOUSING LINER - RH	\$	158.00	\$ 126.00
37	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	81.00	
38	GAS DISCHARGE LAMP HEAD LIGHT - LH/RH	\$	3,650.00	\$ 2,920.00
39	GAS DISCHARGE LAMP	\$	398.00	\$ 318.40
40	POWER MODULE DAY DRIVING LIGHTS	\$	522.00	\$ 417.60
	SUB SPARE PARTS	:	\$ 7,550.00	\$ 10,600.12

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLE 5601 P**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 10,600.12
41	GAS DISCHARGE LAMP CONTRO UNIT		\$ 1,051.00	\$ 840.80
42	LIFT CYLINDER HEADLIGHT WASHER SYSTEM - LH/RH		\$ 362.00	\$ 144.80
43	HEADLIGHT WASHER HOSE PIPE		\$ 170.00	
44	COOLANT RADIATOR LOCK CARRIER		\$ 663.00	\$ 530.40
45	A/C CONDENSER FLUID RECERVOIR		\$ 516.00	\$ 412.40
46	A/C CONDENSER REFRIGERANT LINE		\$ 461.00	\$ 368.80
47	A/C REFRIGERANT LINE - CUT OFF POINT		\$ 601.00	\$ 480.40
48	ADDITIONAL COOLER COOLANT		\$ 837.00	\$ 669.60
49	READY-MIX COOLANT	4	\$ 84.00	\$ 67.20
50	AIR GUIDE - LH/RH		\$ 44.00	\$ 34.24
51	AIR GUIDE - UPPER CENTRE		\$ 88.00	
52	RADIATOR FAN RING		\$ 1,483.00	\$ 1,186.40
53	AIR GUIDE		\$ 53.00	\$ 41.84
54	INTAKE AIR DUCT COVER		\$ 27.00	\$ 21.36
55	WATER DRAINAGE HOSE		\$ 31.00	\$ 24.48
56	AIR FILTER		\$ 259.00	\$ 207.20
57	INTAKE MANIFOLD		\$ 113.00	
58	ENGINE COMPARTMENT COVER		\$ 103.00	
59	A-PILLAR CONNECTING PLATE - RH		\$ 214.00	
60	FRONT CLOSING ELEMENT - RH		\$ 68.00	
	SUB SPARE PARTS		\$ 7,228.00	\$ 15,630.04

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLE 5601 P**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 15,630.04
61	DOOR		\$ 2,279.00	
62	OUTER DOOR SEAL - RH		\$ 146.00	
63	BONDING AGENT		\$ 45.00	
64	CLEANING SOLUTION		\$ 65.00	
65	DOOR ATTACHMENT PARTS		\$ 218.00	
66	DOOR CATCH		\$ 96.00	
67	DOOR CATCH COVER		\$ 13.00	
68	CORNER TRIM - RH		\$ 41.00	
69	TRIM STRIP WINDOW GUIDE - RH		\$ 235.00	
70	FRONT TRIM STRIP WINDOW SLOT SEAL - RH		\$ 282.00	\$ 225.60
71	WATER DEFLECTOR STRIP - RH		\$ 85.00	
72	WINDSCREEN		\$ 988.00	\$ 790.00
73	GEL FOIL RAIN SENSOR		\$ 128.00	\$ 102.40
74	SPRING CLIP		\$ 20.00	
75	ALUMINIUM RIM		\$ 651.00	\$ 520.80
76	RUBBER VALVE	4	\$ 13.00	
77	SIGN ' COUTION '		\$ 13.00	\$ 9.76
78	DATA PLATE TYRE PRESSURE		\$ 26.00	
79	FRONT NO PLATE	S/N	\$ 25.00	
80	FRONT WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
	SUB SPARE PARTS	:	\$ 5,569.00	\$ 17,478.60

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLE 5601 P**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
		<i>c/f</i>	\$ 17,478.60
81	ACRYLIC SEALANT	S/N \$ 180.00	\$ 180.00
82	CAVITY WAX	S/N \$ 140.00	\$ 140.00
83	STONE CHIP	S/N \$ 180.00	\$ 180.00
83a	<i>Added parts - see attached</i>	\$ 2,856.00	\$ 2,282.32
84	SUNDRIES	\$ 1,000.00	\$ 114.64
	TOTAL SPARE PARTS	\$ 29,964.00	\$ 20,375.56
	TOTAL LABOUR CHARGES	\$ 16,792.00	\$ 11,147.00
	GRAND TOTAL	\$ 46,756.00	\$ 31,522.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5601 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER COVER <i>distorted</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00	+
3	FRONT COVER TRIM - LH/RH <i>new</i>	\$ 296.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 148.00	+
5	PULL STRAP - LOWER <i>new</i>	4 \$ 187.00	✓
6	FRONT GUIDE SECTION - LH/RH <i>RH end</i>	\$ 70.00	✓
7	FRONT AIR GUIDE GRILLE - LH/RH <i>RH missing</i>	\$ 198.00	??
8	RADIATOR GRILLE <i>cancel</i>	\$ 637.00	✓
9	RADIATOR GRILLE COVER <i>?</i>	\$ 89.00	?
10	SIDE REINFORCEMENT <i>Bent</i>	\$ 660.00	✓
11	FOAM FILLER PIECE <i>Bent</i>	\$ 125.00	✓
12	FRONT BUMPER REINFORCEMENT COVER <i>cancel</i>	\$ 51.00	✓
13	SIGNAL HORN - HIGH TONE RH <i>?</i>	\$ 182.00	?
14	FRONT NUMBER PLATE <i>Bent</i>	\$ 25.00	✓
15	FRONT BONNET <i>distorted</i>	\$ 2,898.00	✓
16	FRONT BONNET ATTACHMENT PARTS <i>new</i>	\$ 149.00	✓
17	LID HINGE - LH/RH <i>Bent</i>	\$ 112.00	✓
18	GAS FILLED STRUT <i>new</i>	\$ 109.00	+
19	CATCH HOOK <i>Bent</i>	\$ 81.00	✓
20	STRIKER <i>Bent</i>	2 \$ 100.00	✓
	SUB SPARE PARTS	\$ 8,117.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5601 P

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	EDGE PROTECTION - FRONT <i>new</i>	\$	25.00	✓
22	COWL SEAL COVER - RH <i>new</i>	\$	37.00	✓
23	CATCH HOOK <i>Set</i>	\$	58.00	✓
24	LID LOCK MICROSWITCH <i>Dump</i>	2 \$	367.00	✓
(25)	BOWDEN CABLE ? /	\$	53.00	?
26	LID LOCK CABLE ?	\$	67.00	?
27	FRONT FENDER WING - LH/RH <i>RH Deleted</i>	\$	1,550.00	778
28	FRONT FENDER ATTACHMENT PARTS ?	2 \$	130.00	?
29	BRACKET FENDER - RH <i>Set</i>	\$	25.00	✓
30	BRACKET <i>Set</i>	\$	35.00	✓
31	BRACE <i>Set</i>	\$	88.00	✓
32	WING CLOSING ELEMENT - RH ?	\$	30.00	✓
33	ENGINE BONNET SOUND ABS. <i>Comp accepted</i>	\$	201.00	✓
34	WING INSULATION - RH ?	\$	38.00	?
35	SEAL WHEEL HOUSING LINER - RH UPPER ?	\$	31.00	?
36	WHEEL HOUSING LINER - RH <i>Deleted</i>	\$	158.00	?
37	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$	81.00	?
38	GAS DISCHARGE LAMP HEAD LIGHT - LH/RH <i>Deleted</i>	\$	3,650.00	✓
39	GAS DISCHARGE LAMP ?	\$	398.00	?
(40)	POWER MODULE DAY DRIVING LIGHTS ?	\$	522.00	?
	SUB SPARE PARTS <i>Set</i> :	\$	<u>7,550.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5601 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	GAS DISCHARGE LAMP CONTRO UNIT	5	1,051.00 ?
42	LIFT CYLINDER HEADLIGHT WASHER SYSTEM - LH/RH	5	362.00 ?
43	HEADLIGHT WASHER HOSE PIPE	5	170.00 X.
44	COOLANT RADIATOR LOCK CARRIER	5	663.00 -
45	A/C CONDENSER FLUID RECERVOIR	5	516.00 ?
46	A/C CONDENSER REFRIGERANT LINE	5	461.00 ?
47	A/C REFRIGERANT LINE - CUT OFF POINT	5	601.00 ?
48	ADDITIONAL COOLER COOLANT	5	837.00 ?
49	READY-MIX COOLANT	4	84.00
50	AIR GUIDE - LH/RH	5	44.00 L2.
51	AIR GUIDE - UPPER CENTRE	5	88.00 ?
52	RADIATOR FAN RING	5	1,483.00 ?
53	AIR GUIDE	5	53.00 ?
54	INTAKE AIR DUCT COVER	5	27.00 ?
55	WATER DRAINAGE HOSE	5	31.00 ?
56	AIR FILTER	5	259.00 ?
57	INTAKE MANIFOLD	5	113.00 ?
58	ENGINE COMPARTMENT COVER	5	103.00 ?
59	A-PILLAR CONNECTING PLATE - RH	5	214.00 ?
60	FRONT CLOSING ELEMENT - RH	5	68.00 ?
SUB SPARE PARTS		5	7,228.00

+ Intercooler
 + intake manifold.
 + radiator
 + windscreen lower trim
~~X~~ Fender Top support. (Repair)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5601 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	DOOR <i>Repis</i>	\$	2,279.00 +
62	OUTER DOOR SEAL - RH <i>new</i>	\$	146.00 +
63	BONDING AGENT <i>2 new</i>	\$	45.00 +
64	CLEANING SOLUTION <i>new</i>	\$	65.00 +
65	DOOR ATTACHMENT PARTS	\$	218.00 +
66	DOOR CATCH <i>2 new</i>	\$	96.00 +
67	DOOR CATCH COVER <i>new</i>	\$	13.00 +
68	CORNER TRIM - RH <i>new</i>	\$	41.00 +
69	TRIM STRIP WINDOW GUIDE - RH <i>?</i>	\$	235.00 +
70	FRONT TRIM STRIP WINDOW SLOT SEAL - RH <i>new</i>	\$	282.00 ✓
71	WATER DEFLECTOR STRIP - RH <i>new</i>	\$	85.00 +
72	WINDSCREEN <i>Cracked</i>	\$	988.00 ✓
73	GEL FOIL RAIN SENSOR <i>new</i>	\$	128.00 ✓
74	SPRING CLIP <i>new</i>	\$	20.00 ✓
75	ALUMINIUM RIM <i>new</i>	\$	651.00 ✓
76	RUBBER VALVE <i>new</i>	4 \$	13.00 +
77	SIGN ' CAUTION ' <i>new</i>	\$	13.00 ✓
78	DATA PLATE TYRE PRESSURE <i>new</i>	\$	26.00 +
79	FRONT NO PLATE <i>Replaced</i>	S/N \$	25.00 +
80	FRONT WINDSCREEN SEALANT <i>new? APC</i>	S/N \$	200.00 ?
	SUB SPARE PARTS	:	\$ 5,569.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5601 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
81	ACRYLIC SEALANT	S/N \$ 180.00	✓
82	CAVITY WAX	S/N \$ 140.00	✓
83	STONE CHIP	S/N \$ 180.00	✓
84	SUNDRIES	\$ 1,000.00	
	TOTAL SPARE PARTS	: \$ 29,964.00	
	TOTAL LABOUR CHARGES	\$ 16,792.00	
	GRAND TOTAL	\$ 46,756.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLE 5601 P

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0217/2019/NH

26th February 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLE 5601 P, Audi A3 SEDAN 1.4 TFSI.

With reference to the above-mentioned vehicle, no. **SLE 5601 P**, claimant, **Mr. Yeo Tee Khai**, please find the related document per attached.

1. A copy of the Original invoice no. 85014866 – S\$ 28,569.00.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

Norah Khai
Claims Dept

Encl
AIG – SLE 5601 P

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408689
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:00

Company Reg.No.199902271W

GST Reg.No.199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014856 Date : 19/02/2020 Order : SLE5601P Term : 30	Account A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	---

Regn No: SLE5601P (V 30018) Regn Date: 26/07/2016 Mileage: 66518 WIP No : 43102
Model : A3 SEDAN 1.4TFSI (ATTRACTION) Chassis: WAUZZ28V5G1090376 Engine: CZC 540646 DEPT : U
You have been assisted by:- UB-Nora (11)

		Details	Qty	Unit Price	Amount
S	SUBLET	To carry out contractual LIMIT repair basis as agreed	27,000.00	1.00	27,000.00
Q	EXC	Insurance Excess/Liability	-300.00	1.00	-300.00

Parts 0.00
Labour 0.00
Sublet 27,000.00
Menus 0.00
Lubricant 0.00

Sub- Total 26,700.00
7% GST 1,869.00
Grand Total 28,569.00



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLE5601P

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0217/2019/TF
15 March 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages


RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.4 TFSI
Vehicle Chassis No. : WAUZZZ8V5G1090376
Vehicle Regn No. : **SLE5601P**
Vehicle Mileage : 55926 KM
Vehicle Owner : Mr Yeo Tee Khai
Certificate No : 2100476156-02
Own Damage Excess : \$321.00 (Inclusive 7%GST)
Accident Date : 18 Feb 2019
Place : PIE Exit to ECP (City) Cornering Bend
Repair Cost : \$ 28,569.00
WIP No. : 43102
Repairer’s Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte L
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6386 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer’s charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 

Time :

Date : 15/3

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLE5601P

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0217/2019/TF
15 March 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi A3 SEDAN 1.4 TFSI
Vehicle Chassis No. : WAUZZZ8V5G1090376
Vehicle Regn No. : **SLE5601P**
Vehicle Mileage : 55926 KM
Vehicle Owner : Mr Yeo Tee Khai
Certificate No : 2100476156-02
Own Damage Excess : \$321.00 (Inclusive 7%GST)
Accident Date : 18 Feb 2019
Place : PIE Exit to ECP (City) Cornering Bend
Repair Cost : \$ 33408.14
WIP No. : 43102
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : _____
Date : 15/3

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Feb 2019 14:45		21 Feb 2019 12:48 Edit Adj Rpt	S\$27,000.00 Edit Estimates	S\$27,000.00 View Rpt		Pending for Survey Report Cancel Case

















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YEO TEE KHAI , ID: S8115402C, Tel: +6592983853, Email: ERICYE081@GMAIL.COM								
Vehicle Reg. No.:	SLE5601P	Date of Loss:	18/02/2019 08:00 - :59 [30 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 5118973751SG	Policy/Cover Note No.:	2100476156 (Comprehensive)						
		Excess:	S\$300.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 04/03/2019]								
Driver/Custodian:	YEO TEE KHAI (37 / Male), NRIC: S8115402C, Tel: +6592983853 Email: ERICYE081@GMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (17/01/2020): Alert - Adj Mandate Approved (S\$27000.00) - SLE5601P - Claim Handler: Dally Amri... AIG_SG (28/05/2019): Alert - Adj Mandate Maintained - SLE5601P - Claim Handler: Dally Amri, Mimi Zari... AIG_SG (26/02/2019): Alert - Adj Mandate Approved (S\$24139.00) - SLE5601P - Claim Handler: Dally Amri... AIG_SG (22/02/2019): SLE5601P / OD / 18/02/2019 / Coverage & Excess update 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE5601P (5118973751SG)
 OD
 Feb 18 2019 8:00AM
 [YEO TEE KHAI]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View	View in Browser
Video															1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)										Thumbnail	Print			
1	18/02/19 17:42	Video - Accident [Linked Accident Report Documents]											Load MP4			
Assessment Reports															1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	22/02/19 09:51	Adjuster Immediate Advice											Load HTM			
2	26/02/19 13:34	Adjuster Immediate Advice											Load HTM			
Photos/Images															3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
2	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
3	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
4	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
5	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
6	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
7	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
8	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
9	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
10	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
11	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
12	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
13	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
14	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
15	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
16	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
17	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
18	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
19	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
20	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
21	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
22	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
23	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
24	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
25	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
26	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
27	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
28	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
29	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			
30	21/02/19 14:19	General View											Load JPG <input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
31	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
32	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
33	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
34	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
35	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
36	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
37	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
38	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
48	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
49	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
50	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
51	21/02/19 14:19	General View	 Load JPG	<input checked="" type="checkbox"/>
52	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	02/05/19 11:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
81	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
82	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
83	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
84	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
85	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
86	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
87	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
88	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
89	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
90	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
91	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
92	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
93	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
94	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
95	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
96	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
97	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
98	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
99	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
100	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
101	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
102	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
103	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
104	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
105	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
106	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
107	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
108	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
109	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
110	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
111	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
112	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
113	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
114	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
115	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
116	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
117	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
118	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
119	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
120	02/05/19 11:37	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/02/19 14:12	Certificate of Insurance		<input type="checkbox"/>
2	21/02/19 14:12	Driver's Driving License / NIRC		<input type="checkbox"/>
3	21/02/19 14:12	ESTIMATE		<input type="checkbox"/>
4	21/02/19 14:12	Singapore Accident Statement		<input type="checkbox"/>
5	06/05/19 17:08	SUPPLEMENTARY		<input type="checkbox"/>
6	06/05/19 17:08	ESTIMATE		<input type="checkbox"/>
7	28/02/20 16:22	Discharge Voucher		<input type="checkbox"/>
8	28/02/20 16:22	Workshop Invoice		<input type="checkbox"/>

Linked Accident Report Documents

			View	View in Browser
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	18/02/19 17:42	Video - Accident	Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	03/09/19 23:52	Accident Statement	Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	18/02/19 17:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	18/02/19 17:39	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	18/02/19 17:39	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="display: flex; align-items: center;"> ^ v </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19003262/ATD3E2

Date: 28/02/2020

REFERENCE

Insured/Claimant:	YEO TEE KHAI	Policy No:	2100476156	
Date of Loss:	18/02/2019	Nature of Claim:	OD	Claim No: 5118973751SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE5601P		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A)	Engine No:	CZC540646
Reg. Date:	26/07/2016 (Man. Year: 2016)	Chassis No:	WAUZZZ8V5G1090376
Colour:	Black	Odometer:	55927 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,246.32	20,375.56	11,870.76	36.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,322.00	11,147.00	8,175.00	42.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	51,568.32	31,522.56	20,045.76	38.87
Approved Total (Overridden) (S\$)		27,000.00		
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	51,268.32	26,700.00	24,568.32	47.92
+ GST 7.00/7.00% (S\$)	3,588.78	1,869.00	1,719.78	47.92
Nett Amount (S\$)	54,857.10	28,569.00	26,288.10	47.92

INSPECTION

Date of Assignment:	21/02/2019		
Date Inspected:	20/02/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	15.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Distorted	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT COVER TRIM - LH / RH	Not Necessary	296.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	148.00 FS	*- FS
5	4		*PULL STRAP - LOWER	Damaged	187.00 FS	*149.12 FS
6	1		*FRONT GUIDE SECTION - LH / RH	O/S Damaged	70.00 FS	*27.52 FS
7	1		*FRONT AIR GUIDE GRILLE - LH / RH	O/S Missing	198.00 FS	*78.88 FS
8	1		*RADIATOR GRILLE	Cracked	637.00 FS	*509.20 FS
9	1		*RADIATOR GRILLE COVER	Damaged	89.00 FS	*70.88 FS
10	1		*SIDE REINFORCEMENT	Bent	660.00 FS	*527.60 FS
11	1		*FOAM FILLER PIECE	Deformed	125.00 FS	*99.60 FS
12	1		*FRONT BUMPER REINFORCEMENT COVER	Cracked	51.00 FS	*40.40 FS
13	1		*SIGNAL HORN - HIGH TONE RH	Not Necessary	182.00 FS	*- FS
14	1		*FRONT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
15	1		*FRONT BONNET	Distorted	2,898.00 FS	*2,318.40 FS
16	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
17	1		*LID HINGE - LH / RH	Bent	112.00 FS	*88.48 FS
18	1		*GAS FILLED STRUT	Not Necessary	109.00 FS	*- FS
19	1		*CATCH HOOK	Bent	81.00 FS	*64.72 FS
20	2		*STRIKER	Not Necessary	100.00 FS	*- FS
21	1		*EDGE PROTECTION - FRONT	Necessary	25.00 FS	*19.92 FS
22	1		*COWL SEAL COVER - RH	Necessary	37.00 FS	*29.44 FS
23	1		*CATCH HOOK	Bent	58.00 FS	*45.76 FS
24	2		*LID LOCK MICROSWITCH	Damaged	367.00 FS	*293.60 FS
25	1		*BOWDEN CABLE	Damaged	53.00 FS	*41.68 FS
26	1		*LID LOCK CABLE	Not Necessary	67.00 FS	*- FS
27	1		*FRONT FENDER WING - LH / RH	O/S Distorted	1,556.00 FS	*622.00 FS
28	2		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	130.00 FS	*- FS
29	1		*BRACKET FENDER - RH	Bent	25.00 FS	*19.76 FS
30	1		*BRACKET	Bent	35.00 FS	*27.76 FS
31	1		*BRACE	Bent	88.00 FS	*69.84 FS
32	1		*WING CLOSING ELEMENT - RH	Damaged	30.00 FS	*23.76 FS
33	1		*ENGINE BONNET SOUND ABS	Crumpled	201.00 FS	*160.80 FS
34	1		*WING INSULATION - RH	Not Necessary	38.00 FS	*- FS
35	1		*SEAL WHEEL HOUSING LINER - RH UPPER	Not Necessary	31.00 FS	*- FS
36	1		*WHEEL HOUSING LINER - RH	Deformed	158.00 FS	*126.00 FS
37	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	81.00 FS	*- FS
38	1		*GAS DISCHARGE LAMP HEAD LIGHT - LH / RH	Cracked	3,650.00 FS	*2,920.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*GAS DISCHARGE LAMP	Damaged	398.00 FS	*318.40 FS
40	1		*POWER MODULE DAY DRIVING LIGHTS	Damaged	522.00 FS	*417.60 FS
41	1		*GAS DISCHARGE LAMP CONTROL UNIT	Damaged	1,051.00 FS	*840.80 FS
42	1		*LIFT CYLINDER HEADLIGHT WASHER SYSTEM - LH / RH	O/S Damaged	362.00 FS	*144.80 FS
43	1		*HEADLIGHT WASHER HOSE PIPE	Not Necessary	170.00 FS	*- FS
44	1		*COOLANT RADIATOR LOCK CARRIER	Cracked	663.00 FS	*530.40 FS
45	1		*A/C CONDENSER REFRIGERANT LINE	Bent	461.00 FS	*368.80 FS
46	1		*A/C REFRIGERANT LINE - CUT OFF POINT	Bent	601.00 FS	*480.40 FS
47	1		*ADDITIONAL COOLER COOLANT	Bent	837.00 FS	*669.60 FS
48	4		*READY - MIX COOLANT	Necessary	84.00 FS	*67.20 FS
49	1		*AIR GUIDE - LH / RH	O/S Damaged	44.00 FS	*34.24 FS
50	1		*AIR GUIDE - UPPER CENTRE	Not Necessary	88.00 FS	*- FS
51	1		*RADIATOR FAN RING	Cracked	1,483.00 FS	*1,186.40 FS
52	1		*AIR GUIDE	Deformed	53.00 FS	*41.84 FS
53	1		*INTAKE AIR DUCT COVER	Deformed	27.00 FS	*21.36 FS
54	1		*WATER DRAINAGE HOSE	Cut	31.00 FS	*24.48 FS
55	1		*AIR FILTER	Deformed	259.00 FS	*207.20 FS
56	1		*INTAKE MANIFOLD	Not Necessary	113.00 FS	*- FS
57	1		*ENGINE COMPARTMENT COVER	Not Necessary	103.00 FS	*- FS
58	1		*A-PILLAR CONNECTING PLATE - RH	Not Necessary	214.00 FS	*- FS
59	1		*FRONT CLOSING ELEMENT - RH	Not Necessary	68.00 FS	*- FS
60	1		*DOOR	Repair	2,279.00 FS	*- FS
61	1		*OUTER DOOR SEAL - RH	Not Necessary	146.00 FS	*- FS
62	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
63	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
64	1		*DOOR ATTACHMENT PARTS	Not Necessary	218.00 FS	*- FS
65	1		*DOOR CATCH	Not Necessary	96.00 FS	*- FS
66	1		*DOOR CATCH COVER	Not Necessary	13.00 FS	*- FS
67	1		*CORNER TRIM - RH	Not Necessary	41.00 FS	*- FS
68	1		*TRIM STRIP WINDOW GUIDE - RH	Not Necessary	235.00 FS	*- FS
69	1		*FRONT TRIM STRIP WINDOW SLOT SEAL - RH	Cut	282.00 FS	*225.60 FS
70	1		*WATER DEFLECTOR STRIP - RH	Not Necessary	85.00 FS	*- FS
71	1		*WINDSCREEN	Cracked	988.00 FS	*790.00 FS
72	1		*GEL FOIL RAIN SENSOR	Necessary	128.00 FS	*102.40 FS
73	1		*SPRING CLIP	Not Necessary	20.00 FS	*- FS
74	1		*ALUMINIUM RIM	Cut	651.00 FS	*520.80 FS
75	4		*RUBBER VALVE	Not Necessary	13.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*SIGN CAUTION	Necessary	13.00 FS	*9.76 FS
77	1		*DATA PLATE TYRE PRESSURE	Not Necessary	26.00 FS	*- FS
78	1		*FRONT NO PLATE	Repeated	25.00 FS	*- FS
79	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
80	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
81	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
82	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
83	1		*SUNDRIES	Necessary	1,000.00 FS	*114.64 FS
84	1		*A/C PIPE (EXPANSION VALVE -> COMPRESSOR	Bent	368.80 FS	*368.80 FS
85	1		*CHARGE AIR COOLER	Bent	530.40 FS	*530.40 FS
86	1		*SET AIR COOLER BOLT	Necessary	9.60 FS	*9.60 FS
87	2		*AIR COOLER SEAL	Necessary	22.56 FS	*22.56 FS
88	1		*INTAKE MANIFOLD	Bent	429.20 FS	*429.20 FS
89	1		*RADIATOR	Bent	702.40 FS	*702.40 FS
90	2		*RADIATOR BRACKET	Necessary	61.28 FS	*61.28 FS
91	2		*RADIATOR BUSH - LOWER	Necessary	14.24 FS	*14.24 FS
92	1		*COVER FOR PLENUM CHAMBER	Broken	130.80 FS	*130.80 FS
93	1		*OUTER TEMP. SENSOR BRACKET	Necessary	13.04 FS	*13.04 FS
94	1		*A/C CONDENSER FLUID RECERVOIR	Bent	516.00 FS	*412.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 32,246.32 20,375.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,000.00	1,000.00
3	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
4	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEMS AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	280.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET, BOTH HEADLIGHT AND RHS FRONT DOOR. CUT OUT AND REWELD RHS FENDER TOP SUPPORT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	8,400.00	3,000.00
6	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, BONNET, RHS FRONT FENDER TOP SUPPORT, HINGES, RHS FRONT DOOR, RHS UPPER A-PILLAR	New	5,800.00	3,275.00
7	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	TO REPAIR RHS FRONT FENDER SUPPORT AND RHS FRONT DOOR	New	750.00	500.00
10	TO REMOVE AND RENEW INTAKE MANIFOLD WITH INTERCOOLER	New	900.00	900.00
11	TO REMOVE AND RENEW AIR COND PIPES	New	480.00	480.00
12	TO INSTALL SOLAR FILM	New	400.00	400.00
Gross Labour Cost (S\$)			19,322.00	11,147.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >