LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Lionel Tan Date: 22 Feb 2019

Preliminary Advice

Insured Vehicle No : SFR3366J

TP Vehicle No : SHD4130R Accident Date : 20/02/2019 Make : HYUNDAI SONATA Assignment Date : 21/02/2019 Date of Inspection : 21/02/2019 Est. Duration of Repair : 2 days

Inspection At : ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive Singapore 508969

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesrear... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,204.90
Revised Amount	:S\$	900.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	900.00

Lump Sum Repair :S\$

Total Loss Consideration

Other comments: We have not authorized repairs.

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

(X)

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.