

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hwang Shiang Yi

Date: 22 Feb 2019

Preliminary Advice

Vehicle No	: SBM9909C	Accident Date	: 10/02/2019
Make	: SUBARU FORESTER	Policy No.	: D18MTPV01004849
Assignment Date	: 21/02/2019	Excess	: S\$1,500.00
Date of Inspection	: 22/02/2019	Est. Duration of Repair	: 5.00
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD (HQ) 19 LORONG 8 TOA PAYOH SINGAPORE 319255		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,637.30
Revised Amount	:S\$	2,226.90
Check Items (Estimated)	:S\$	3,875.80
Total	:S\$	6,102.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	93,000.00
COE / PARF Rebate	:S\$	55,326.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,674.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :