

Form 1001

ASS. REC. BY:

REF:

08/CTI19003276/Krd3m

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTE

Date/Time:

21/2/19 @ 10.08am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 3978C

Insured:

GX 2175G

at Workshop m/s

Comfort Delgro

Tel:

6383718

of

205 Braddell Road

Policy No:

DMCVSN301660180D

Claim No:

3NM19D2 00843C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

14/02/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

21/2/19 @ 10.12am

Person Contacted:

Andrew

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction
	(✓) Estimate
	SLQ 3978C-x
	GX 2175G-CS3/ET180196SS/Gcd3c2 DUA: 14/10/18
4/4/19	@ 4:14pm Andrew said vehicle pending for parts prices
18/4/19	@ 4:07pm Andrew will email us finalise
6/5/19	@ 11:15am Andrew will email us finalise

ASS. REC. BY:

REF: C721

Henneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 877k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 21 days Res.: Yes or No

Lum Sum: 20+21k 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ 3978C Yr Regn: 07, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Civic cc 1496

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 14P282 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GM4 1105537

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NIP / S/Rim / STD A/Rim or

Tyre Size: Pirelli 185/60R15

Road Plate

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 14/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

7/5/19 11 Pm, Bigcat Carwash (Ref 6928, 407)

RECEIVED 07 MAY 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 7/5 - typist

Report Format:

Lump Sum / L.B.I. (\$)

menmen

10,200/2

Days Of Repair: 21

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Feb 2019		21 Feb 2019 10:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLQ3978C	Date of Loss:	14/02/2019 18:00 - :59
Claim Type:	TP / SNM19D200843C02	Policy/Cover Note No.:	DMCVSN3016601800 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	GX2175G	Policy No. (Claimant):	SLQ3978C
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/03/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Thursday, 21 February 2019 10:05 AM
To: braddell_operation@sparkcarcare.com; 'assignments'
Subject: FW: LCR _ SLQ3978C claim against GX2175G (CLAIM REF: SNM19D200843C02/5)
Attachments: SLQ3978C.pdf

WITHOUT PREJUDICE

Dear Andrew,

We refer to your email of 18.02.19.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please refer to the attachment and proceed to survey the third party vehicle.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: CDGE Braddell Private Cars Crash Repair Operation [mailto:braddell_operation@sparkcarcare.com]
Sent: Monday, 18 February, 2019 10:09 AM
To: Claims Dept of CTI; Angie Foo; joel.goh@sg.cntaiping.com; Irene Tay; Jowyn Tay
Cc: Denis Teo Chin Chye; CDGE Braddell Private Cars Crash Repair Counter; CDGE Braddell Private Cars Crash Repair Operation
Subject: LCR _ SLQ3978C claim against GX2175G _ DOA

Dear Sir / Madam

Please advice on the liability of the accident. Your insured vehicle number GX2175G.

And to arrange to survey the car at CDGE, Braddell.

Car in workshop ready for survey.

Andrew

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

www.SPARKcarcare.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Veron Chen (LKKAUTO)

From: CDGE Braddell Private Cars Crash Repair Operation
<braddell_operation@sparkcarcare.com>
Sent: Tuesday, 7 May 2019 8:33 AM
To: Kenneth Kong (LKKAUTO)
Subject: Re: SLQ3978C - Finalize
Attachments: IMG_3030.JPG; IMG_3031.JPG; IMG_3033.JPG; IMG_3034.JPG; IMG_3035.JPG; IMG_3039.JPG; IMG_3040.JPG; IMG_3045.JPG; IMG_3048.JPG

Kenneth

As per your email request.

Andrew

Best Regards
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767
www.SPARKcarcare.com

From: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Sent: Tuesday, 7 May 2019 8:31:07 AM
To: CDGE Braddell Private Cars Crash Repair Operation
Subject: RE: SLQ3978C - Finalize

Andrew, can I have the after paint photos? Thanks Kenneth

From: CDGE Braddell Private Cars Crash Repair Operation [mailto:braddell_operation@sparkcarcare.com]
Sent: Monday, 6 May, 2019 4:44 PM
To: Veron Chen (LKKAUTO); Kenneth Kong (LKKAUTO)
Cc: Denis Teo Chin Chye; Kristy Tay Siew Hwa
Subject: SLQ3978C - Finalize

Dear Sir / Madam

We forward the documents for finalize.

Please confirm the COR.

Andrew
Best Regards
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)
Fax: 6281 5767
www.SPARKcarcare.com



ANNOUNCING Carway

as sgCarMart Premium Dealer for the 2nd Consecutive Year



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Nov 2016 British Electric Blue Mini Convertible 51



Agent Unit Fully Maintained
Under Warranty Roadcover
New Freedom Only \$123.8k
Kimhung Hegary & Co. [Contact](#)



Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

3 vehicles

Honda Grace

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Grace		Any	Any	2018	Any	Any	Any	Available
	Honda	Grace Hybrid 1.5A LX	\$93,988	\$9,910 /yr	16-May-2018	1,496 cc	78 km	Sedan	Available
Fuel Type: Petrol-Electric Made In Japan! High Horsepower And Very Good Fuel Saver! Buy With Confidence That's Comes With 5 Years Warranty For Peace Of Mind.									
Vincar Pte Ltd									
Posted: 18-Feb-2019 Tags: 2018 Honda Grace, 2018 honda grace, Honda Grace, honda grace, Honda, Grace, grace, Used Honda									
	Honda	Grace Hybrid 1.5A DX	\$79,800	\$7,740 /yr	27-Sep-2018	1,496 cc	50 km	Sedan	Available
Fuel Type: Petrol-Electric Banks/In House Available. Please Call For Financial And Latest Update Price. The Car Regency, Subsidiy Of Thong Lee Trading Is Established Since 1969, And Has Been Awarded As A Premium Dealer Since 201...									
Posted: 29-Jan-2019 Tags: 2018 Honda Grace, 2018 honda grace, Honda Grace, honda grace, Honda, Grace, grace, Used Honda									
	Honda	Grace Hybrid 1.5A DX	\$85,000	\$8,380 /yr	07-Sep-2018	1,496 cc	8 km	Sedan	Available
Fuel Type: Petrol-Electric 5 Years Warranty Or 130,000km Whichever Comes First With Liberty Insurance! Call Our Friendly Salesman For Viewing Now!									
Posted: 24-Jan-2019 Tags: 2018 Honda Grace, 2018 honda grace, Honda Grace, honda grace, Honda, Grace, grace, Used Honda									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & CPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda Grace, Honda Grace Singapore, used Honda Grace Singapore, used Honda Grace, used vehicles Singapore or even buy used Honda Grace Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)
©2004-2019 sgCarMart. All rights reserved.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLQ3978C
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	GRACE 1.5 DX HYBRID CVT ABS D/AIRBAG 2WD
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	LEB5255552
Chassis No.:	GM41105537
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,975.00
Original Registration Date:	07 Jul 2017
First Registration Date:	07 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jul 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,807.00
COE Rebate Amount:	\$44,223.00
Total Rebate Amount:	\$47,973.00

The information contained herein is correct as at 21 Feb 2019.

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/02/2019 13:06
Date Of Accident	14/02/2019 18:15
Exact Location Of Accident	YISHUN AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ3978C
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	INSURANCE@LIONCITYRENTALS.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-88888888

Vehicle Particulars

Manufacturer	HONDA
Model	GRACE HYBRID-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SLQ3978C
Cover Note Number	

Driver

Name of Driver	TAN WEE HOCK SIMON
NRIC No	S0091306E
Date Of Birth	04/03/1954
Occupation	OUTDOOR
Date Of Driving Pass	27/10/1978
Driving Experience	40 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98196696
Fax Number	
Contact Number	
EMail Address	ABUNDANT_GIFTS@YAHOO.COM.SG

Address	BLK 424 HOUGANG AVENUE 6 #10-70
Postcode	530424
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MOHAMMED NOR ABDUL RAHMAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOGANG N.P.C
Police Station Address	ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH TRAFFIC POLICE
Was there any audio recorded?	NO

Details of Witness 1

Name	ABDUL RAHMAN
Phone Number	31381257
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX2175G
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SUKNAN BIN NADIM
NRIC/Passport Number	S1177912C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At About 6.15 pm traffic light at Yishun Ave 1, I jam brake at Traffic Light Junction, then I suddenly there was a loud bang on my car from behind and my car move FORWARD About 100 metre away from the traffic light, the boot of my car was badly damaged and cannot open, a passenger was behind my car and I called the ambulance

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE
ACKNOWLEDGEMENT SLIP

PO 30091306
Tel: 6547 6437

Ref: Report No: 1/2019 0214/0115

I, SAT TUEO 392 REYAN
(Recipient's Name, NRIC or Passport No. / Rank and No.)

of 516/424 18, LIA AVE 3
(Address / Police Station / NPC / NPP)

hereby acknowledge receipt of the below mentioned items of:

- 1 1 X 16GS Micra SP card. (Samsung)
- 2 _____
- 3 _____
- 4 _____
- 5 _____
- 6 _____
- 7 _____
- 8 _____
- 9 _____
- 10 _____

from 30091306 Tan Wei Hee Simon
(Name, NRIC or Passport No. / Rank and No.)

of 51424 Hongkong Ave 6 #10-70 (530424)
(Address / Police Station / NPC / NPP)

on 14/02/2019 at 1900hrs
(Date) (Time)

Witnessed by / Handled over by:

(* Delete if applicable)

Tan 30091306/F
(Signature)

(Name, NRIC or Passport No. / Rank and No.)

Received by:

SAT TUEO 392
(Signature)

(Name, NRIC or Passport No. / Rank and No.)

Other Remarks: _____



**SINGAPORE
POLICE FORCE**



T/20190214/2162

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

1 of 4

Report No. T/20190214/2162

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/02/2019 20:48		Vide Report No.: L/20190214/0115		Station Diary No.: 114	
Informant's Particulars					
Name of Informant: TAN WEE HOCK SIMON			Address: APT BLK 424 HOUGANG AVENUE 6 #10-70 SINGAPORE 530424		
ID Type / ID No.: NRIC NO / S0091306E			Contact No.: Home/Office: Mobile: 98196696		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 64	Date of Birth: 04/03/1954	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Grab Driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 14/02/2019 18:15	Type of Location:
Location: SELETAR EXPRESSWAY turning to Yishun Avenue 1				
Weather:		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GX2175G	Van				Slightly Damaged	0
SLQ3978C	Car				Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE
POLICE FORCE



T/20190214/2162

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 4

Report No. T/20190214/2162

CONTINUATION OF REPORT

Driver			
Name	Suknan Bin Nadim	ID No.	S1177912C
Related Vehicle	GX2175G (Van)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN WEE HOCK SIMON	ID No.	S0091306E
Related Vehicle	SLQ3978C (Car)	Contact No.	98196696
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	Abdul Rahman	ID No.	S9717879H
Related Vehicle	SLQ3978C (Car)	Contact No.	31381257
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On the 14/02/2019 at about 1815hrs, I was driving along Seletar highway turning to yishun ave 1 travelling on the second lane. The traffic light then turned to amber and I started to jam my brakes. I then felt an impact from the back and I saw that a van at knocked my car at the back. There was a passenger inside my car and he complaint of back pain. I then called for the ambulance and the passenger was conveyed to the hospital. I then asked the van driver why did he knocked onto my car and he said that there was a vehicle who stopped at the double yellow line on the left lane and he wanted to dodge the car and that was why he knocked onto my car.

Shortly after the accident, police came down and collected my SD card which was from my in-car camera. The report number was L/20190214/0115.



SINGAPORE
POLICE FORCE



T/20190214/2162

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 4

Report No. T/20190214/2162

CONTINUATION OF REPORT



SINGAPORE
POLICE FORCE



T/20190214/2162

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

4 of 4

Report No. T/20190214/2162

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 GABRIEL LEE BO WENG	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / GIT / Sgt 3 RASHIDAH BINTE AZMAN Contact No.: 65476216	

Signature Of Informant:	
Date/Time: 14/02/2019 20:48	
Classification Of Case:	

Authentication Stamp
NP166



Continental Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TP

Vehicle No. : SLQ3978C

Make & Model : HONDA GRACE HYB 1.5DX

Year of Manufacture : 2016

Chassis No. : GM41105537

Ins Company : AIG / CHINA TAIPING

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 14/02/2019

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor : _____

Repair Estimate

Case Owner : Andrew

Signature : _____

Parts (a) Cost / List Price Items \$ -

Plus/Less 20% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 350.00

Total Parts Cost (Appendix A) \$ 350.00

Labour (Appendix B) \$ 7,410.00

Total Repair Cost \$ 7,760.00

Contact No

Frt Counter Operation

6383 7466 - Patrick Tia

6383 7730 - Brenda Ng

6383 7890 - Rohani

braddell_cri@sparkcarcare.com

Workshop Operation

63837656 - Ngo Toh Wee

63837362 - Andrew Goh

63838115 - William Wang

braddell_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kennerh

Company : LKK

Survey conducted on : 20/2/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 21 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Se Date: 20/2/19

*Not Authorized
Repair by paint*

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLQ3978C Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5D Year Manufacture : 2016

Chassis No : GM41105537 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing <i>BT ✓</i>	1				\$ 40.00	
2	Rear bumper <i>BT ✓</i>	1					
3	Rear bumper reflector LH <i>✓</i>	1					
4	Rear bumper reflector RH <i>CRA ✓</i>	1					
5	Rear bumper side retainer LH <i>CRA ✓</i>	1					
6	Rear bumper side retainer RH <i>CRA ✓</i>	1					
7	Rear bumper clips <i>Re ✓</i>	10					
8	Bootlid <i>BT ✓</i>	1					
9	Bootlid hinge LH <i>BT ✓</i>	1					
10	Bootlid hinge RH <i>BT ✓</i>	1					
11	Bootlid inner trim <i>Return ✓</i>	1					
12	Bootlid inner trim clips <i>Re ✓</i>	10					
13	Bootlid lock <i>BT ✓</i>	1					
14	Bootlid weatherstrip <i>CR ✓</i>	1					
15	Bootlid lamp LH <i>CRA ✓</i>	1					
16	Bootlid lamp RH <i>CRA ✓</i>	1					
17	Bootlid emblem logo H <i>Re ✓</i>	1					
18	Bootlid emblem GRACE <i>Re ✓</i>	1					
19	Bootlid emblem HYBRID <i>Re ✓</i>	1					
20	Bootlid chrome moulding <i>CRA ✓</i>	1					
21	Bootlid chrome moulding clips <i>Re ✓</i>	4					
22	Taillamp LH <i>Bro ✓</i>	1					
23	Taillamp RH <i>Bro ✓</i>	1					
24	Taillamp panel LH <i>BT ✓</i>	1					
25	Taillamp panel RH <i>BT ✓</i>	1					
26	Taillamp clips <i>Re ✓</i>	2					
27	Rear end panel <i>BT ✓</i>	1					
28	Rear end panel top garnish <i>Re ✓</i>	1					
29	LH rear fender <i>Bro ✓</i>	1					
30	RH rear fender <i>Bro ✓</i>	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLQ3978C Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5D Year Manufacture : 2016

Chassis No : GM41105537 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	LH rear fender inner trim <i>Return ✓</i>	1					
32	RH rear fender inner trim <i>✓</i>	1					
33	LH rear fender air vent <i>?</i>	1					
34	RH rear fender air vent <i>?</i>	1					
35	Rear floor panel <i>?</i>	1					
36	Rear floor undercover <i>DIT ✓</i>	1					
37	Rear cargo tools tray <i>?</i>	1					
38	Rear cargo top cover <i>?</i>	1					
39	Rear windscreen glass <i>Sen X</i>	1					
40	Rear windscreen glass moulding upper <i>Acc ✓</i>	1					
41	Rear windscreen glass moulding lower <i>Acc ✓</i>	1					
42	Rear windscreen glass moulding LH <i>Acc ✓</i>	1					
43	Rear windscreen glass moulding RH <i>Acc ✓</i>	1					
44	Sealant <i>Acc</i>	1				S 40.00	✓
45	Inner seal <i>Acc</i>	1				S 30.00	✓
46	Rear end panel buzzer	1					?
47	Reverse sensor <i>Ref</i>	1				S 240.00	<i>2001A</i>
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No. : SLQ3978C Case Owner : Andrew
 Make & Model : ONDA GRACE HYB 1.5DX Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove and replace rear windscreen glass	\$120.00	✓
2	To panel beat, repair, cut and weld to replace rear panels on LH rear fender, RH rear fender, Rear floor panel, Rear end panel and affected areas	\$3,600.00	2880
3	To check wiring functions	\$80.00	30
4	To install reverse sensor	\$80.00	✓
5	To diagnose and reset on electronic systems	\$280.00	200
6	To apply rust proofing on repair and replace panels	\$500.00	150
7	To putty and spray paint Rear floor panel, Rear end panel, Bootlid, LH rear fender, RH rear fender, Rear bumper, LH rear door, RH rear door and affected areas	\$2,500.00	2000
8	To mount vehicle on black hawk floor bench in order to re-align chassis members or body structure. (Photo)	\$250.00	✓
LKK Auto Consultants hereby notify the Repairer of the following: • To reserve before and after spray painting • To display damaged part(s) during survey • Parts prices are subject to confirmation • Third party survey is on a "without prejudice" basis • No illegal modification(s) is allowed • Supplementary work(s) must be surveyed and is subject to final approval from Insurance Company Authorised by Repairer Signature: _____ Date: _____			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ComfortDelgro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Bill To	: <u>CHINA TAIPIING</u>	Vehicle Number	: <u>SLQ3978C</u>
Attn to	: <u>Kenneth</u>	Type Of Claim	: <u>TP</u>

P/P Total	<u>12.790.96</u>
------------------	------------------

Lump Sum Less	20%	\$ 2,558.19
---------------	-----	-------------

Lump Sum Rounding \$ 10,232.77

Total Finalized	\$ 10,200.00
------------------------	---------------------

If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & confirmed.

Andrew / 29.10.2018

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLQ3978C Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5D Year Manufacture : 2016

Chassis No : GM41105537 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing	1				\$ 40.00	
2	Rear bumper	1		\$ 937.60			
3	Rear bumper reflector LH	1					
4	Rear bumper reflector RH	1		\$ 30.80			
5	Rear bumper side retainer LH	1		\$ 14.00			
6	Rear bumper side retainer RH	1		\$ 14.00			
7	Rear bumper clips	10		\$ 39.00			
8	Bootlid	1		\$ 675.20			
9	Bootlid hinge LH	1		\$ 68.40			
10	Bootlid hinge RH	1		\$ 68.40			
11	Bootlid inner trim	1		\$ 99.70			
12	Bootlid inner trim clips	10		\$ 42.00			
13	Bootlid lock	1		\$ 90.30			
14	Bootlid weatherstrip	1		\$ 91.50			
15	Bootlid lamp LH	1		\$ 306.70			
16	Bootlid lamp RH	1		\$ 306.70			
17	Bootlid emblem logo H	1		\$ 27.40			
18	Bootlid emblem GRACE	1		\$ 45.00			
19	Bootlid emblem HYBRID	1		\$ 58.00			
20	Bootlid chrome moulding	1		\$ 165.00			
21	Bootlid chrome moulding clips	4		\$ 16.80			
22	Taillamp LH	1		\$ 381.70			
23	Taillamp RH	1		\$ 381.70			
24	Taillamp panel LH	1		\$ 98.00			
25	Taillamp panel RH	1		\$ 98.00			
26	Taillamp clips	2		\$ 8.60			
27	Rear end panel	1		\$ 395.30			
28	Rear end panel top garnish	1		\$ 86.40			
29	LH rear fender	1		\$ 1,129.40			
30	RH rear fender	1		\$ 1,129.40			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLQ3978C Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5D Year Manufacture : 2016

Chassis No : GM41105537 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	LH rear fender inner trim	1		\$ 265.00			
32	RH rear fender inner trim	1		\$ 265.00			
33	LH rear fender air vent	1					
34	RH rear fender air vent	1					
35	Rear floor panel	1					
36	Rear floor undercover	1		\$ 135.00			
37	Rear cargo tools tray	1		\$ 168.50			
38	Rear cargo top cover	1					
39	Rear windscreen glass	1					
40	Rear windscreen glass moulding upper	1		\$ 38.10			
41	Rear windscreen glass moulding lower	1		\$ 48.80			
42	Rear windscreen glass moulding LH	1		\$ 30.10			
43	Rear windscreen glass moulding RH	1		\$ 38.10			
44	Sealant	1				\$ 40.00	
45	Inner seal	1				\$ 30.00	
46	Rear end panel buzzer	1					
47	Reverse sensor	1				\$ 200.00	
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Vehicle No.	:	<u>SLQ3978C</u>	Case Owner	:	<u>Andrew</u>
Make & Model	:	<u>ONDA GRACE HYB 1.5DX</u>	Year of Manufacture	:	<u>2016</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLQ3978C Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5D Year Manufacture : 2016

Chassis No : GM41105537 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing	1			<i>RM</i>	\$ 40.00	✓
2	Rear bumper	1	<i>RM</i>	\$ 937.60			✓
3	Rear bumper reflector LH	1	<i>Sm</i>	\$ 30.80			X
4	Rear bumper reflector RH	1	<i>CM</i>	\$ 30.80			✓
5	Rear bumper side retainer LH	1	<i>CM</i>	\$ 14.00			✓
6	Rear bumper side retainer RH	1	<i>CM</i>	\$ 14.00			✓
7	Rear bumper clips	10	<i>RM</i>	\$ 39.00			✓
8	Bootlid	1	<i>RM</i>	\$ 675.20			✓
9	Bootlid hinge LH	1	<i>RM</i>	\$ 68.40			✓
10	Bootlid hinge RH	1	<i>RM</i>	\$ 68.40			✓
11	Bootlid inner trim	1	<i>Reform</i>	\$ 99.70			✓
12	Bootlid inner trim clips	10	<i>RM</i>	\$ 42.00			✓
13	Bootlid lock	1	<i>RM</i>	\$ 90.30			✓
14	Bootlid weatherstrip	1	<i>CM</i>	\$ 91.50			✓
15	Bootlid lamp LH	1	<i>CM</i>	\$ 306.70			✓
16	Bootlid lamp RH	1	<i>CM</i>	\$ 306.70			✓
17	Bootlid emblem logo H	1	<i>RM</i>	\$ 27.40			✓
18	Bootlid emblem GRACE	1	<i>RM</i>	\$ 45.00			✓
19	Bootlid emblem HYBRID	1	<i>RM</i>	\$ 58.00			✓
20	Bootlid chrome moulding	1	<i>CM</i>	\$ 165.00			✓
21	Bootlid chrome moulding clips	4	<i>RM</i>	\$ 16.80			✓
22	Taillamp LH	1	<i>RM</i>	\$ 381.70			✓
23	Taillamp RH	1	<i>RM</i>	\$ 381.70			✓
24	Taillamp panel LH	1	<i>RM</i>	\$ 98.00			✓
25	Taillamp panel RH	1	<i>RM</i>	\$ 98.00			✓
26	Taillamp clips	2	<i>RM</i>	\$ 8.60			✓
27	Rear end panel	1	<i>RM</i>	\$ 395.30			✓
28	Rear end panel top garnish	1	<i>RM</i>	\$ 86.40			✓
29	LH rear fender	1	<i>RM</i>	\$ 1,129.40			✓
30	RH rear fender	1	<i>RM</i>	\$ 1,129.40			✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLQ3978C Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5D Year Manufacture : 2016

Chassis No : GM41105537 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	LH rear fender inner trim <i>Return</i>	1		\$ 265.00			✓
32	RH rear fender inner trim <i>h</i>	1		\$ 265.00			✓
33	LH rear fender air vent	1	<i>Sn</i>	\$ 28.80			X ?
34	RH rear fender air vent	1	<i>Sn</i>	\$ 28.80			X ?
35	Rear floor panel <i>R</i>	1		\$ 855.00			X
36	Rear floor undercover <i>Return</i>	1		\$ 135.00			✓
37	Rear cargo tools tray	1	<i>CM</i>	\$ 168.50			✓ ?
38	Rear cargo top cover	1	<i>Sn</i>	\$ 254.30			X ?
39	Rear windscreen glass	1	<i>Sn</i>	\$ 1,650.30			X
40	Rear windscreen glass moulding upper	1	<i>Sn</i>	\$ 38.10			✓
41	Rear windscreen glass moulding lower	1	<i>Sn</i>	\$ 48.80			✓
42	Rear windscreen glass moulding LH	1	<i>Sn</i>	\$ 30.10			✓
43	Rear windscreen glass moulding RH	1	<i>Sn</i>	\$ 38.10			✓
44	Sealant	1			<i>Sn</i> \$ 40.00		✓
45	Inner seal	1			<i>Sn</i> \$ 30.00		✓
46	Rear end panel buzzer <i>Src</i>	1		\$ 85.80			X ?
47	Reverse sensor <i>Ref</i>	1				\$ 240.00	<i>200 Sn</i>
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Labour

Vehicle No. : SLQ3978C Case Owner : Andrew
 Make & Model : ONDA GRACE HYB 1.5DX Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove and replace rear windscreen glass	\$120.00	✓ ✓
2	To panel beat, repair, cut and weld to replace rear panels on LH rear fender, RH rear fender, Rear floor panel, Rear end panel and affected areas	\$3,600.00	2880 ✓
3	To check wiring functions	\$80.00	30 ✓
4	To install reverse sensor	\$80.00	✓ ✓
5	To diagnose and reset on electronic systems	\$280.00	200 ✓
6	To apply rust proofing on repair and replace panels	\$500.00	150 ✓
7	To putty and spray paint Rear floor panel, Rear end panel, Bootlid, LH rear fender, RH rear fender, Rear bumper, LH rear door, RH rear door and affected areas	\$2,500.00	2000 ✓
8	To mount vehicle on black hawk floor bench in order to re-align chassis members or body structure.	\$250.00	✗ ✗
LKK Auto Consultants hence notify the Repairer of the following:- • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer: Signature: _____ Date: _____			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Supplementary 1

Vehicle No : <u>SLQ3978C</u>	Case Owner : <u>Andrew</u>
Make & Model : <u>HONDA GRACE HYB 1.5DX</u>	Year Manufacture : <u>2016</u>
Chassis No : <u>GM41105537</u>	Engine No : <u>0</u>
Sales Order : <u>0</u>	Supplier : <u>0</u>
Order By : _____	Type of Claim : <u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	Bootlid spoiler	1	CM	\$ 364.00			—
2	Rear no plate lamp	1	CM	\$ 28.00			—
3	IPU cooling fan assy	1	CM	\$ 590.60			—
4		0					
5		0					
6		0					
7		0					
8		0					
9		0					
10		0					
11		0					
12		0					
13		0					
14		0					
15		0					
16		0					
17		0					
18		0					
19		0					
20		0					
21		0					
22		0					
23		0					
24		0					
25		0					
26		0					
27		0					
28		0					
29		0					
30		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119003276/KVD3N2

Date: 06/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3016601800	
Claimant Vehicle No :	SLQ3978C	Insured Vehicle No :	GX2175G	
Date of Loss:	14/02/2019	Nature of Claim:	TP	Claim No: SNM19D200843C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ3978C	Engine No:	LEB5255552
Make & Model:	HONDA GRACE HYBRID, 1.5 (A)	Chassis No:	GM41105537
Reg. Date:	07/07/2017 (Man. Year: 2016)	Odometer:	149282 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Roadstone 3 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Roadstone 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,718.00	7,330.96	2,387.04	24.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,410.00	5,460.00	1,950.00	26.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,128.00	12,790.96	4,337.04	25.32
Approved Total (Overridden) (\$\$)		10,200.00		
(\$\$)	17,128.00	10,200.00	6,928.00	40.45
+ GST 7.00/7.00% (\$\$)	1,198.96	714.00	484.96	40.45
Nett Amount (\$\$)	18,326.96	10,914.00	7,412.96	40.45

INSPECTION

Date of Assignment:	21/02/2019	
Date Inspected:	20/02/2019 Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	21.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2019)
Parts:	143	HONDA GRACE HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ3978C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Bent	937.60 FL	*937.60 FL
2	1	*REAR BUMPER REFLECTOR LH	Serviceable	30.80 FL	*- FL
3	1	*REAR BUMPER REFLECTOR RH	Cracked	30.80 FL	*30.80 FL
4	1	*REAR BUMPER SIDE RETAINER LH	Cracked	14.00 FL	*14.00 FL
5	1	*REAR BUMPER SIDE RETAINER RH	Cracked	14.00 FL	*14.00 FL
6	10	*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
7	1	*BOOTLID	Bent	675.20 FL	*675.20 FL
8	1	*BOOTLID HINGE LH	Bent	68.40 FL	*68.40 FL
9	1	*BOOTLID HINGE RH	Bent	68.40 FL	*68.40 FL
10	1	*BOOTLID INNER TRIM	Deformed	99.70 FL	*99.70 FL
11	10	*BOOTLID INNER TRIM CLIPS	Necessary	42.00 FL	*42.00 FL
12	1	*BOOTLID LOCK	Bent	90.30 FL	*90.30 FL
13	1	*BOOTLID WEATHERSTRIP	Cut	91.50 FL	*91.50 FL
14	1	*BOOTLID LAMP LH	Cracked	306.70 FL	*306.70 FL
15	1	*BOOTLID LAMP RH	Cracked	306.70 FL	*306.70 FL
16	1	*BOOTLID EMBLEM LOGO H	Necessary	27.40 FL	*27.40 FL
17	1	*BOOTLID EMBLEM GRACE	Necessary	45.00 FL	*45.00 FL
18	1	*BOOTLID EMBLEM HYBRID	Necessary	58.00 FL	*58.00 FL
19	1	*BOOTLID CHROME MOULDING	Cracked	165.00 FL	*165.00 FL
20	4	*BOOTLID CHROME MOULDING CLIPS	Necessary	16.80 FL	*16.80 FL
21	1	*TAILLAMP LH	Broken	381.70 FL	*381.70 FL
22	1	*TAILLAMP RH	Broken	381.70 FL	*381.70 FL
23	1	*TAILLAMP PANEL LH	Bent	98.00 FL	*98.00 FL
24	1	*TAILLAMP PANEL RH	Bent	98.00 FL	*98.00 FL
25	2	*TAILLAMP CLIPS	Necessary	8.60 FL	*8.60 FL
26	1	*REAR END PANEL	Bent	395.30 FL	*395.30 FL
27	1	*REAR END PANEL TOP GARNISH	Dented	86.40 FL	*86.40 FL
28	1	*LH REAR FENDER	Buckled	1,129.40 FL	*1,129.40 FL
29	1	*RH REAR FENDER	Buckled	1,129.40 FL	*1,129.40 FL
30	1	*LH REAR FENDER INNER TRIM	Deformed	265.00 FL	*265.00 FL
31	1	*RH REAR FENDER INNER TRIM	Deformed	265.00 FL	*265.00 FL
32	1	*LH REAR FENDER AIR VENT	Serviceable	28.80 FL	*- FL
33	1	*RH REAR FENDER AIR VENT	Serviceable	28.80 FL	*- FL
34	1	*REAR FLOOR PANEL	Repair	855.00 FL	*- FL
35	1	*REAR FLOOR UNDERCOVER	Deformed	135.00 FL	*135.00 FL
36	1	*REAR CARGO TOOLS TRAY	Cracked	168.50 FL	*168.50 FL
37	1	*REAR CARGO TOP COVER	Serviceable	254.30 FL	*- FL
38	1	*REAR WINDSCREEN GLASS	Serviceable	1,650.30 FL	*- FL
39	1	*REAR WINDSCREEN GLASS MOULDING UPPER	Necessary	38.10 FL	*38.10 FL
40	1	*REAR WINDSCREEN GLASS MOULDING LOWER	Necessary	48.80 FL	*48.80 FL
41	1	*REAR WINDSCREEN GLASS MOULDING LH	Necessary	30.10 FL	*30.10 FL
42	1	*REAR WINDSCREEN GLASS MOULDING RH	Necessary	38.10 FL	*38.10 FL
43	1	*REAR END PANEL BUZZER	Serviceable	85.80 FL	*- FL
44	1	*BOOTLID SPOILER	Cracked	364.00 FL	*364.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR NO PLATE LAMP	Cracked	28.00 FL	*28.00 FL
46	1		*IPU COOLING FAN ASSY	Cracked	590.60 FL	*590.60 FL
47	1		*REAR NUMBER PLATE WITH CASING	Bent	40.00 FS	*40.00 FS
48	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
49	1		*INNER SEAL	Necessary	30.00 FS	*30.00 FS
50	1		*REVERSE SENSOR	Dented	240.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	12,060.00	9,086.20
- List Item Discount on L Items 20.00/20.00% (S\$)	2,342.00	1,755.24
Total Parts (S\$)	9,718.00	7,330.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS	New	120.00	120.00
2	TO PANEL BEAT,REPAIR,CUT AND WELD TO REPLACE REAR PANELS ON LH REAR FENDER,RH REAR FENDER,REAR FLOOR PANEL,REAR END PANEL AND AFFECTED AREAS	New	3,600.00	2,880.00
3	TO CHECK WIRING FUNCTIONS	New	80.00	30.00
4	TO INSTALL REVERSE SENSOR	New	80.00	80.00
5	TO DIAGNOSE AND RESET ON ELECTRONIC SYSTEMS	New	280.00	200.00
6	TO APPLY RUST PROOFING ON REPAIR AND REPLACE PANELS	New	500.00	150.00
7	TO PUTTY AND SPRAY PAINT REAR FLOOR PANEL,REAR END PANEL,BOOTLID,LH REAR FENDER,RH REAR FENDER,REAR BUMPER,LH REAR DOOR,RH REAR DOOR AND AFFECTED AREAS	New	2,500.00	2,000.00
8	TO MOUNT VEHICLE ON BLACK HAWK FLOOR BENCH IN ORDER TO RE-ALIGN CHASSIS MEMBERS OR BODY STRUCTURE	New	250.00	0.00
Gross Labour Cost (S\$)			7,410.00	5,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >