

Tel: 63837168 / 63837466 Fax:62815767

ComfortDelgro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62815767

Finalization Form

Bill To : CHINA TAIPIING **Vehicle Number** : SLQ3978C
Attn to : Kenneth **Type Of Claim** : TP

A. Spare parts	<u>\$ 7,793.60</u>	F. Total Parts	<u>\$ 7,330.96</u>
B. Supplementary	<u>\$ 982.60</u>	G. Total Labour	<u>\$ 5,460.00</u>
C. Nett Price	<u>\$ -</u>	H. Total Repair	<u>\$ 12,790.96</u>
D. Supp Nett Price	<u>\$ -</u>	I. Excess	<u> </u>
E. S/Nett	<u>\$ 310.00</u>	P/P Total	<u>12,790.96</u>

Total Spare Parts Price		\$ 8,776.20
Cost plus / List Down	20%	1,755.24
Total		7,020.96

Total Nett Price		\$ -
Nett Price Less		\$ -
Total		-

Lump Sum Less 20% \$ 2,558.19

Lump Sum Rounding \$ 10,232.77

Total Finalized \$ 10,200.00

If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm and revert by Fax or Email

Date In : _____ Total Repair Day _____

Date Survey : _____ LOU/ Day _____

Date Out : _____ Total LOU _____

Sat/Sun/Ph. : _____ Rental/Day _____

Authorized Repair Day 10 Total Rental _____

Submitted By / Date : _____ Confirmed By / Date : _____

Andrew / 29.10.2018 _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLQ3978C Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5D Year Manufacture : 2016

Chassis No : GM41105537 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing	1				\$ 40.00	
2	Rear bumper	1		\$ 937.60			
3	Rear bumper reflector LH	1					
4	Rear bumper reflector RH	1		\$ 30.80			
5	Rear bumper side retainer LH	1		\$ 14.00			
6	Rear bumper side retainer RH	1		\$ 14.00			
7	Rear bumper clips	10		\$ 39.00			
8	Bootlid	1		\$ 675.20			
9	Bootlid hinge LH	1		\$ 68.40			
10	Bootlid hinge RH	1		\$ 68.40			
11	Bootlid inner trim	1		\$ 99.70			
12	Bootlid inner trim clips	10		\$ 42.00			
13	Bootlid lock	1		\$ 90.30			
14	Bootlid weatherstrip	1		\$ 91.50			
15	Bootlid lamp LH	1		\$ 306.70			
16	Bootlid lamp RH	1		\$ 306.70			
17	Bootlid emblem logo H	1		\$ 27.40			
18	Bootlid emblem GRACE	1		\$ 45.00			
19	Bootlid emblem HYBRID	1		\$ 58.00			
20	Bootlid chrome moulding	1		\$ 165.00			
21	Bootlid chrome moulding clips	4		\$ 16.80			
22	Taillamp LH	1		\$ 381.70			
23	Taillamp RH	1		\$ 381.70			
24	Taillamp panel LH	1		\$ 98.00			
25	Taillamp panel RH	1		\$ 98.00			
26	Taillamp clips	2		\$ 8.60			
27	Rear end panel	1		\$ 395.30			
28	Rear end panel top garnish	1		\$ 86.40			
29	LH rear fender	1		\$ 1,129.40			
30	RH rear fender	1		\$ 1,129.40			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLQ3978C Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5D Year Manufacture : 2016

Chassis No : GM41105537 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	LH rear fender inner trim	1		\$ 265.00			
32	RH rear fender inner trim	1		\$ 265.00			
33	LH rear fender air vent	1					
34	RH rear fender air vent	1					
35	Rear floor panel	1					
36	Rear floor undercover	1		\$ 135.00			
37	Rear cargo tools tray	1		\$ 168.50			
38	Rear cargo top cover	1					
39	Rear windscreen glass	1					
40	Rear windscreen glass moulding upper	1		\$ 38.10			
41	Rear windscreen glass moulding lower	1		\$ 48.80			
42	Rear windscreen glass moulding LH	1		\$ 30.10			
43	Rear windscreen glass moulding RH	1		\$ 38.10			
44	Sealant	1				\$ 40.00	
45	Inner seal	1				\$ 30.00	
46	Rear end panel buzzer	1					
47	Reverse sensor	1				\$ 200.00	
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62844284,62815767

Supplementary 1

Vehicle No : SLQ3978C Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5DX Year Manufacture : 2016

Chassis No : GM41105537 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	Bootlid spoiler	1		\$ 364.00			
2	Rear no plate lamp	1		\$ 28.00			
3	IPU cooling fan assy	1		\$ 590.60			
4		0					
5		0					
6		0					
7		0					
8		0					
9		0					
10		0					
11		0					
12		0					
13		0					
14		0					
15		0					
16		0					
17		0					
18		0					
19		0					
20		0					
21		0					
22		0					
23		0					
24		0					
25		0					
26		0					
27		0					
28		0					
29		0					
30		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

: 2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.