

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5462G**AAD1902-128***Not Authored
1/ Sep 8*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5462G

VF1ABL15AUC280947

RENAULT

LATITUDE

15.2.2019

EQ

18/12/2014

PART**LIST**

1	1 BUMPER COVER REAR	\$	1,108.46	✓
2	1 BUMPER LOWER REAR	\$	768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	113.47	} X
4	1 BUMPER BRACKET SIDE RH REAR	\$	135.97	
5	1 BUMPER RETAINER RH REAR	\$	44.99	
6	1 BUMPER REFLECTOR RH	\$	43.61	
7	1 BUMPER BRACKET SIDE LH REAR	\$	135.97	
8	1 BUMPER RETAINER LH REAR	\$	44.99	} ?
9	1 BUMPER REFLECTOR LH	\$	43.61	
10	1 BUMPER BEAM REAR	\$	777.52	
11	1 BUMPER BEAM BRACKET LH REAR	\$	225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	225.95	?
13	1 OUTER PANEL REAR (End Panel)	\$	1,471.77	} X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	404.56	
15	1 BOOT REAR	\$	2,872.68	
16	1 TAILLAMP RH	\$	552.55	
17	1 TAILLAMP PANEL RH	\$	986.70	
18	1 TAILLAMP LH	\$	552.55	} X
19	1 TAILLAMP PANEL LH	\$	986.70	

\$ 11,496.85**10% \$ 1,149.69****\$ 10,347.17****Special Nett**

1	1SET PARKING AID	\$	700.00	X
2	1SET REAR BUMPER CLIP	\$	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	33.00	✓

Trans-cab Auto Services Pte Ltd**AAD1902-128**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5462G

4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5 1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
6 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7 1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	nn	17.82	} X
11 2 REAR WINDSCREEN SELANT	\$	nn	80.00	
12 1 WINDSCREEN MOULDING	\$	nn	100.00	
13 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
14 1 REAR BOOT STICKER 'Trans-cab'	\$	nn	80.00	
15 1 REAR BOOT STICKER '6555-3333'	\$	nn	80.00	
TOTAL	\$		605.82	
TOTAL PARTS	\$		10,952.99	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1902-128**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5462G

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 *X*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 *X***TOTAL \$ 7,410.00****Over All Total \$ 28,710.15****(LUMP SUM)****Repair Days**~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: