

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9938U**AAD1902-147**

Not Authorised
11 May @ 5000

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9938U

VF1ABL15AUC277901

RENAULT

LATITUDE

19.2.2019

III

5/6/2014

PART**LIST**

1	1	BUMPER COVER FRT	\$	<i>B</i>	1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>D.I</i>	181.75	✓
3	1	BUMPER ABSORBER FRT	\$	<i>M.I</i>	394.68	✓
4	1	BUMPER RETAINER FRT LH	\$	<i>D.I</i>	151.41	✓
5	1	BUMPER SUPPORT FRT	\$	<i>S</i>	123.88	X
6	1	BUMPER RETAINER FRT RH	\$	<i>CM</i>	150.77	✓
7	1	BUMPER SUPPORT FRT	\$	<i>S</i>	123.88	X
8	1	BUMPER UNDERTRAY FRT	\$	<i>S</i>	472.83	X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>S</i>	266.80	X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>S</i>	207.21	X
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>M.I</i>	207.21	✓
12	1	BUMPER BEAM FRT	\$	<i>B</i>	914.08	✓
13	1	TOW COVER FRT	\$	<i>S</i>	28.61	X
14	1	RADIATOR GRILLE	\$	<i>S</i>	1,707.78	X
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>S</i>	225.36	X
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i>	1,353.75	✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>S</i>	615.90	} X
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i>	89.79	
19	1	FRONT BRACE PANEL	\$	<i>R</i>	177.22	
20	1	HORN	\$	<i>S</i>	314.17	
21	1	HORN BRACKET	\$	<i>R</i>	40.45	
22	1	HEADLAMP LH	\$	<i>S</i>	1,184.43	
23	1	HEADLAMP HARNESS	\$	<i>S</i>	928.29	
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i>	152.15	
25	1	BONNET	\$	<i>R</i>	1,941.63	
26	1	BONNET INSULATOR	\$	<i>S</i>	405.73	
27	1	BONNET STRUT LH	\$	<i>S</i>	88.61	
28	1	BONNET STRUT RH	\$	<i>S</i>	88.61	
29	1	BONNET HINGE LH	\$	<i>R</i>	348.31	

Trans-cab Auto Services Pte Ltd**AAD1902-147**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9938U

30	1	BONNET HINGE RH	\$	R	348.31	}	X
31	1	BONNET LOCK	\$	R	305.48		
32	1	BONNET CABLE	\$	SL	119.19		
33	1	BONNET CABLE COVER	\$	SL	161.03		
34	1	BONNET SEAL OUTER	\$	SL	92.36		
35	1	BONNET SEAL INNER	\$	SL	157.28	}	
36	1	FENDER PANEL FRT RH	\$	Bu	783.83		
37	1	WHEELARCH FRT RH	\$	SL	278.84	}	
38	1	FENDER BRACKET LOWER LH	\$	SL	15.79		
39	1	FENDER INSULATOR LH	\$	SL	130.84	}	X
40	1	FENDER PANEL INNER FRT LH	\$	R	1,693.77		
41	1	FENDER PANEL REINFORCEMENT FRT LH	\$	R	1,096.22		
42	1	WHEEL HOUSING PANEL FRT LH	\$	R	5,173.47		
43	1	TURBO DUCT	\$	SL	1,027.80		
44	1	A/C HEATER VALVE	\$	SL	484.50		
45	1	SUBFRAME OUTER FRT	\$	SL	2,652.45		
46	1	SUBFRAME BRACKET OUTER LH	\$	R	92.36		
47	1	SUBFRAME BRACKET OUTER RH	\$	R	92.36		
48	1	ENGINE UNDERTRAY	\$	SL	564.98		
49	1	A/C CONDENSER	\$	SL	2,020.37		
50	1	A/C CONDENSER GARNISH LH UPPER	\$	SL	39.67		
51	1	A/C CONDENSER GARNISH RH UPPER	\$	SL	39.67		
52	1	A/C CONDENSER GARNISH LH	\$	SL	58.81		
53	1	A/C CONDENSER GARNISH RH	\$	SL	59.60		
54	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	SL	208.39		
55	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	SL	658.72		
74	1	A/C PIPE COMPRESSOR	\$	SL	334.29		
75	1	A/C PIPE	\$	SL	658.72		
76	1	A/C COMRPRESSOR	\$	SL	2,684.61		
77	1	AIR COOLER	\$	SL	792.60		
78	1	AIR INTERCOOLER HOSE (LONG)	\$	SL	1,014.13		
79	1	AIR INTERCOOLER HOSE (Short)	\$	SL	375.14		
80	1	TRANSMISSION COOLER	\$	SL	1,219.30		
81	1	TRANSMISSION COOLER PAD	\$	SL	17.96		
82	1	RADIATOR	\$	SL	1,202.20		
83	2	RADIATOR STUD UPPER	\$	SL	14.41		
84	2	RADIATOR BUSH UPPER	\$	SL	50.12		
85	2	RADIATOR MTG LOWER	\$	SL	55.85		

Trans-cab Auto Services Pte Ltd**AAD1902-147**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9938U

86	1	RADIATOR FAN COWLING	\$	820.54	} X
87	1	RADIATOR FAN MOTOR LH	\$	967.36	
88	1	RADIATOR FAN MOTOR RH	\$	1,479.46	
89	1	RADIATOR TANK	\$	324.62	
90	1	RADIATOR HOSE UPPER	\$	240.56	
91	1	RADIATOR HOSE LOWER	\$	491.18	
92	1	RADIATOR TANK HOSE	\$	61.18	

TOTAL	\$	45,305.01
10%	\$	4,530.50
	\$	40,774.51

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	X
2	1SET	BUMPER CLIP FRT	\$	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00	} X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	
7	1	TOW COVER FRT	\$	14.50	
8	1SET	RADIATOR GRILLE SCREW	\$	16.00	} X
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
13	1	Windscreen moulding	\$	100.00	
14	1	FRONT NUMBER PLATE WITH HOLDER	\$	200.00	255N

TOTAL	\$	682.50
TOTAL PARTS	\$	41,457.01

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 4,000.00 *500/*

Towing Fees.

\$ 120.00 *50/*

Trans-cab Auto Services Pte Ltd**AAD1902-147**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9938U

To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
Putty and spray painting of the affected portion.	\$	4,000.00 440/
To rust-proofing of the affected areas.	\$	170.00 30/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	↷ 220.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	↷ 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	↷ 380.00 X
To lift-up engine with gear box and refit.	\$	↷ 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	↷ 440.00 X
To remove and refit air bag system and reset.	\$	⚡ 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	↷ 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	↷ 380.00 X
To replace, refix and top up coolant for radiator	\$	↷ 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1902-147**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9938U

To vacuum, replace, refix and recharge Air
Intercooler

\$ *nn* 170.00 X

To Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test.

\$ *nn* 170.00 X

To Transfer Of Bonnet Fittings, Attachments And
Perform Water Seepage Test.

\$ *nn* 170.00 X

To Transfer Of Door Fittings, Attachments And
Perform Water Seepage Test.

\$ *nn* 170.00 X**TOTAL \$ 13,000.00****Over All Total \$ 54,457.01****Repair Days (Lump Sum)***20 days**3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: