

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA II	NSURANCE PTE	LTD	Ref : CC4/ASM19003281/Aga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY		Date: 24-04-2020 Code: ASM			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SFL 1109E	Veh. Inspected	SGH 461C	
	Policy No.	VPA/P2080873	Coverage (\$)	0.00	
	Claim No.	S9M01ENL	Excess (\$)	0.00	
	Assign From		Assign Date	21/02/2019	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALTIS	c.c	1598	
I	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	MR053ZEC107117671	Colour	GREY	
	Odometer	144033	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
-	R/H Front Tyre	205/50 R16	BRIDGESTONE	6 mm	
-	L/H Front Tyre	205/50 R16	BRIDGESTONE	6 mm	
-	R/H Rear Tyre	205/50 R16	BRIDGESTONE	6 mm	
Ш	L/H Rear Tyre	205/50 R16	BRIDGESTONE	6 mm	
4.	·				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
4	Accident Date	20/02/2019	Inspection Date	21/02/2019	
	Survey held at	PREMIUM CARZ SERVICES PT	E LTD		
		1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
[STIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				