

Premium Carz

Services Pte Ltd

Co Reg No: 201416720C

1101 Bukit Ave 8 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel: 6636 9110 Fax: 6636 9113

Date : 20/02/2019

TO: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Our Customer : Chung Siew May Juliana

Vehicle No : SGH461C

Model : Toyota Altis

Manufacture Year : 2006

Date of Accident : 20/02/2019

Total Estimate Repair Days : 7

Total Pages : 2

Attn : Motor Claim Department

Email : motor.survey@axa.com.sg

Re: Repair Estimate For Third Party Claim against SFL1109E

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>new</i>	1	\$433.29	\$433.29	✓
2	Rear bumper side retainer RH <i>new</i>	1	\$17.20	\$17.20	✓
3	Rear bumper side retainer LH <i>new</i>	1	\$17.20	\$17.20	x
4	Rear bumper bracket RH <i>new</i>	1	\$48.51	\$48.51	x
5	Tail lamp RH <i>new</i>	1	\$298.40	\$298.40	+
6	Tail lamp lower panel RH <i>new</i>	1	\$89.60	\$89.60	+
7	Rear fender RH	1	repair	repair	+
8	Boot lid	1	\$845.30	\$845.30	x
9	Boot lid reflector RH	1	\$93.10	\$93.10	x
10	Boot lid inner lock	1	\$80.00	\$80.00	x
11	Boot lid lower catch	1	\$25.00	\$25.00	x
12	Boot lid hinges <i>new</i>	2	\$55.20	\$110.40	x
13	Boot "Corolla" emblem	1	\$44.17	\$44.17	x
14	Boot "ALTIS" emblem	1	\$44.17	\$44.17	x
15	Boot "1.6" emblem	1	\$49.40	\$49.40	x
16	Boot "E" emblem	1	\$35.60	\$35.60	x
17	Boot lid "VVTI" emblem	1	\$40.90	\$40.90	x
18	Boot lid weatherstrip	1	\$42.80	\$42.80	x
19	Exhaust silencer	1	\$429.00	\$429.00	x
	Sub Total			\$2,744.04	
	Less 25%			\$686.01	
	Sub Total 1			\$2,058.03	
A.	Spare Parts (S/Nett)				
1	Reverse sensor (set) <i>new</i>	1	\$250.00	\$250.00	200
2	Rear bumper clip <i>new</i>	8	\$4.30	\$34.40	✓ 234
3	Rivet <i>new</i>	4	\$5.00	\$20.00	x 40
	Sub-Total 2			\$304.40	
	Total for Parts			\$2,362.43	
B.	Labour				
1	To check wiring.			\$60.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$800.00	300
3	Spray painting all affected parts & areas.			\$800.00	200 400
4	To spray anti-rust undercoat.			\$90.00	30

780

630

1549.65

-20%

1239.72

rs bpr

end panel

No.	Item Descriptions	Qty	Unit Price	Amount
5	To remove rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$250.00
6	To remove and replace damaged exhaust silencer.			\$180.00
	Total Labour			\$2,180.00
	Total Repair Cost			\$4,542.43

Adrian Lj
21/02/19.
L/s 03 days.

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1373.07

L/s 1.1k ✓

03 days ✓

Premium Carz

Services Pte Ltd

Reg No: 201416720C

Unit 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

Date : 22/02/2019

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Our Customer : Chung Siew May Juliana

Vehicle No : SGH461C

Model : Toyota Altis

Manufacture Year : 2006

Date of Accident : 20/02/2019

Total Estimate Repair Days : 7

Total Pages : 2

Attn : Motor Claim Department

Email : motor.survey@axa.com.sg

Re: Repair Estimate For Third Party Claim against SFL1109E

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear end panel <i>Paper</i>	1	\$580.60	\$580.60	X.
	Sub Total			\$580.60	
			Less 25%	\$145.15	
	Total Supplementary Repair Cost			\$435.45	

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

\$4977.88