

S.S. REC. BY

REF

CS/SMO19003282/Und3et

Special Instruction

Surveyor
merimen

From (Person)

Marlus

chen shuhui agnes

ASSIGNMENT (Office)

of

SMO

Date/Time

2/12/19 @ 11:30am

Estimated Cost

Bill to

OD / TP RES / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

GBE7587C

Insured

FY5232L

at Workshop m/s

Liu's Brother

Tel.

67411730

of

1 Ikaki Bkt Ave 6 #01-01

Policy No.

D18MTMCO1003194

Claim No.

CMTD1901002

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A

29/01/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

12:54pm 2/12/19

Person Contacted

Jufen

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBE7587C--X

FY5232L-X

26/2/19

Send preli revised via merimen

(08/11/13) wef

REF:

5m

ASS. REC. BY Marcus

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

G3E7587C

Yr Regn:

3.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make:

Toyota hiace

c.c

2982

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

5.6592

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT 02PX 00192782

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 2.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/1/19

D.O.I.

21/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 2.5.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/2/19 4/5 & 3850 continue with Susan. (Red 4544.70, 5410)

RECEIVED 26 FEB 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 26/2 - typist

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

250

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

) TOTAL

Report Format:

men men

Lump Sum / I.B.I: (\$ 3850/2)

10

260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Feb 2019		21 Feb 2019 11:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	AMIRUL RUSYDEE BIN MOHAMED AMINUDIN, ID: S9833833		
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	GBE7587C	Date of Loss:	29/01/2019 10:00 - :59
Claim Type:	TP / CMTD1901002	Policy/Cover Note No.:	D18MTMC01003194 (Third Party Only)
Vehicle Reg. No. (Insured):	FY5232L	Policy No. (Claimant):	
		Excess:	
Repairer:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/03/2019]		
Adj Asg. Remarks:	-PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	CHAN SHU HUI AGNES	Date:	26 Feb 2019
<u>Preliminary Advice</u>			

Insured Vehicle No	: FY5232L	Accident Date	: 29/01/2019
TP Vehicle No	: GBE7587C	Assignment Date	: 21/02/2019
Make	: TOYOTA HIACE	Est. Duration of Repair	: 5.00
Date of Inspection	: 21/02/2019	Inspection At : LIU'S BROTHER AUTO ENGINEERING WORKSHOP (KAKI BUKIT) (HQ) BLK 1 KAKI BT AVE 6 #01-01 AUTO BAY @ KAKI BT SINGAPORE 417883, KAKI BUKIT SINGAPORE 417883	

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,394.70
Revised Amount	:S\$	3,850.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,850.00
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :The above survey was conducted on a 'Without Prejudice' basis.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GBE7587C
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2600300
Chassis No.:	JTFHT02PX00192782
Maximum Power Output:	-
Open Market Value:	\$27,741.00
Original Registration Date:	21 Mar 2016
First Registration Date:	21 Mar 2016
Transfer Count:	1
Actual ARF Paid:	\$1,388.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,502.00
COE Rebate Amount:	\$32,884.00
Total Rebate Amount:	\$32,884.00

The information contained herein is correct as at 22 Feb 2019

OK



ANNOUNCING Carway

as sgCarMart Premium Dealer for the 2nd Consecutive Year



CARWAY

Your Satisfaction Is Our Success

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A

2.38%P.A Lowest Interest@GV
Cars Financing \$1500
Downpayment Monthly From
\$468
GV Credit Pte Ltd StarAd



Think One Automobile

**NEW & USED
COMMERCIAL VEHICLES**



Browse by Category

Sort by Date Posted 20 results/page

Hiace








Advanced Search Submit

16 vehicles

Hiace

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hiace		Any	Any	2016	Any	Any	Any	Available
	Toyota	Hiace	\$59,800	\$7,920 /yr	09-Sep-2016	2,982 cc	25,002 km	Van	Available
Fuel Type: Diesel									
Think One Automobile & Trading									
Posted: 21-Feb-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace	\$60,800	\$7,910 /yr	27-Oct-2016	2,982 cc	52,600 km	Van	Available
Fuel Type: Diesel									
Think One Automobile & Trading									
Posted: 20-Feb-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace	\$53,800	\$7,630 /yr	10-Mar-2016	2,982 cc	-	Van	Available
Fuel Type: Diesel									
Special Edition. 1 Owner. View To Believe.									
Car (S) Pte Ltd									
Posted: 20-Feb-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace	\$57,500	\$8,070 /yr	06-Apr-2016	2,982 cc	-	Bus	Available
Fuel Type: Diesel									
In-house Loan Available. Call To View Now. Please Note, This Is Van.not Bus.									
Prime Motor & Leasing									
Posted: 20-Feb-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Fog Light								
Euro 5/6 Toyota Hiace Fog Lamp.									
More info about this product									
	Toyota	Hiace Commuter	\$61,800	\$8,740 /yr	18-Mar-2016	2,982 cc	-	Bus	Available
Fuel Type: Diesel									
(PA) Toyota Hiace Bus 12 Cap! 100% Accident Free. New Condition! 100% Loan Available (In House Loan) Cheaper In Market! Please Call Arrange Viewing! Hot Selling Now!									
ABWIN (1994) Pte Ltd									
Posted: 18-Feb-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace	\$56,800	\$8,170 /yr	02-Feb-2016	2,982 cc	56,620 km	Van	Available
Fuel Type: Diesel									
Well Maintained Since Day 1! Engine And Gearbox In Very Mint Condition And Do Not Require AdBlue. Whole Vehicle Is In Pristine Condition! Serviced Regularly. High Loan And Trade In Welcomed! Call Now ...									
Car (S) Pte Ltd									
Posted: 18-Feb-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									

Compare

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	29/01/2019 21:10
Date Of Accident	29/01/2019 10:40
Exact Location Of Accident	ALONG PUNGGOL ROAD INFRONT 298B COMPASSVALE STREET
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBE7587C
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942888
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	ACT
Fleet Policy	YES
Policy Number	D-18090757MFCV
Cover Note Number	N.A.
Driver	
Name of Driver	HO PENG KHAU
NRIC No	S1426281D
Date Of Birth	02/07/1960
Occupation	OUTDOOR
Date Of Driving Pass	31/12/1979
Driving Experience	39 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88161568
Fax Number	
Contact Number	OFFICE-88161568
Email Address	JASON.TEO@IRCO.COM

Address	BLK 296A COMPASSVALE CRESCENT #09-289
Postcode	541296
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JASON TEO GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was travelling along Punggol road it was a 2 lane traffic and my vehicle GBE7587C was positioned in the left side lane as vehicle ahead me brake I also slow down suddenly vehicle FY5232L collided onto my vehicle GBE7587C rear. No injuries involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FY5232L
Vehicle Make/Model/Colour	KAWASAKI/KR/DAR
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	AMIRUL RUSYDEE BIN MOHAMED AMINUDIN
NRIC/Passport Number	S9833833J
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (i) I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop, and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER


Mohamed Saifullah S/O Syed
Masood

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Common Statement

ACCIDENT STATEMENT (2000 characters)

I was travelling along Punggol road it was a 2 lane traffic and my vehicle GBE7587C was positioned in the left side lane as vehicle ahead me brake I also slow down suddenly vehicle FY5232L collided onto my vehicle GBE7587C rear. No injuries involved.


Taxi Voucher No.

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect.

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SAIFULLAH S/O SYED MASOOD

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

29 January 2019 at 11:27 AM

Date/Time:

29 January 2019 at 11:27 AM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GBE7587C
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2600300
Chassis No.:	JTFHT02PX00192782
Maximum Power Output:	-
Open Market Value:	\$27,741.00
Original Registration Date:	21 Mar 2016
First Registration Date:	21 Mar 2016
Transfer Count:	1
Actual ARF Paid:	\$1,388.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,502.00
COE Rebate Amount:	\$32,951.00
Total Rebate Amount:	\$32,951.00

The information contained herein is correct as at 19 Feb 2019

OK



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-026529
Date of Request: 19/02/2019

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 19/02/2019
Enquiry By Susan Low Siew Yian
TP Vehicle No. FY5232L
Accident Date 29/01/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
FY5232L	Sompo Insurance Singapore Pte. Ltd.	07/06/2018-06/06/2019	6461 6555

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-026529
Date of Request: 19/02/2019
Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 19/02/2019
Enquiry By Susan Low Siew Yian
TP Vehicle No. FY5232L
Accident Date 29/01/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.
This is a computer generated document and requires no signature.

For GIARMC Official use:
Date:
☒ GIRO ☐ Cash ☐ Cheque

LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbro@ymail.com

Invoice/Ref No: GBE7587C190129

Estimate

Customer

Name: Sompo Insurance Singapore Private Limited

Address Motor Claims Department

50 Raffles Place #05-01 / 06

Singapore Land Tower	Singapore 048623
----------------------	------------------

Date: 20-02-19

Vehicle No: GBE7587C

Model/Make: Toyota Hiace

Van Turbo 5 DR Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Tail Lamp <i>CNA</i>	\$ 365.10	
2	Tailgate <i>body</i>	\$ 2,051.60	
3	Bumper <i>7000</i>	\$ 465.00	
4	Bumper Clips 1 set <i>neu</i>	\$ 48.00	
5	Bumper Reverse Sensor <i>shudd</i>	\$ 220.00	SN 2005.0
6	End Panel Inner <i>n</i>	\$ 936.20	X
7	End Panel Outer <i>body</i>	\$ 566.10	
8	End Panel Sealant <i>neu</i>	\$ 50.00	SN 5.0
9	Exhaust Silencer <i>n</i>	\$ 917.60	X
10	Tailgate Windscreen Glass Moulding <i>NS</i>	\$ 219.00	X
11	Tailgate Windscreen Glass Sealant <i>neu</i>	\$ 50.00	SN 405.0
12	Tailgate "8 PAX" Sticker <i>neu</i>	\$ 20.00	SN 105.0
13	Tailgate "70 KM/H" Sticker <i>neu</i>	\$ 20.00	SN 105.0
14	Tailgate "Toyota" Sticker <i>neu</i>	\$ 80.00	
15	Tailgate "Toyota" Motif <i>neu</i>	\$ 68.10	
16	Tailgate "Hiace" Sticker <i>neu</i>	\$ 78.00	
17	Tailgate "Corporate" Advertisement & Artwork <i>neu</i>	\$ 200.00	SN 1805.0
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	- 60
	To check all wiring & electrical component for proper function	\$ 80.00	- 20
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 180.00	- 11X
	Remove and refix rear bumper reverse sensor	\$ 100.00	- 50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	- 700
	To putty & spray painting & including touch up paint on accident affect	\$ 600.00	- 1
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	- 1
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	- 60

Total Parts & Labour of estimate for damaged vehicle	
--	--

\$8,394.70

Total amount in Lump Sum Basis for repaired vehicle	
---	--



M/s Liu's Brother Auto Engrg Wks

SDLS:

Not Authorized

h/h
21/2/19

L/S # 3850
 Wh? Wh. Attemp -
 S by.

P-3627.6

$\frac{257}{27207}$
 S.W 490

641610
4820

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Feb 2019		21 Feb 2019 11:30 Edit Adj Rpt	S\$3,850.00 Edit Estimates	S\$3,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: AMIRUL RUSYDEE BIN MOHAMED AMINUDIN , ID: S9833833J									
Main Claimant: GOLDBELL LEASING PTE LTD , Co. Reg. No.: 199001196N									
Vehicle Reg. No.: GBE7587C		Date of Loss: 29/01/2019 10:00 - :59 [34 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / CMTD1901002		Policy/Cover Note No.: D18MTMC01003194 (Third Party Only)							
Vehicle Reg. No. (Insured): FY5232L		Policy No. (Claimant):							
		Excess:							
Repairer: Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 04/03/2019]									
Adj Asg. Remarks: -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE7587C (CMTD1901002)

[FY5232L]

TP











GOLDBELL LEASING PTE LTD

Jan 29 2019 10:00AM

[AMIRUL RUSYDEE BIN MOHAMED AMINUDIN]

Liu's Brother Auto Engineering Workshop (kaki Bukit)

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 08:55	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
2	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
3	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
4	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
5	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
6	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
7	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
8	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
9	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
10	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
11	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
12	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
13	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
14	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
15	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
16	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
17	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
18	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
19	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
20	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
21	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
22	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
23	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
24	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
25	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
26	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
27	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
28	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
29	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
30	26/02/19 08:48	General View	Load JPG	<input checked="" type="checkbox"/>
31	26/02/19 08:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	26/02/19 08:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	26/02/19 08:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	26/02/19 08:48	Reinspection Photo	Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	26/02/19 08:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	26/02/19 08:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	26/02/19 08:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	26/02/19 08:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	26/02/19 08:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	26/02/19 08:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	26/02/19 08:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	26/02/19 08:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	21/02/19 10:22	Pre-Repair Survey - SAS	 Load PDF	
2	21/02/19 11:30	Pre-Repair Survey - AGREED LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19003282/UVD3E2

Date: 27/02/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTMC01003194

Claimant Vehicle
No : GBE7587C

Insured Vehicle No : FY5232L

Date of Loss: 29/01/2019

Nature of Claim: TP

Claim No: CMTD1901002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE7587C

Make & Model: TOYOTA HIACE, 2.0 (M)

Reg. Date: 21/03/2016 (Man. Year: 2016)

Colour: White

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1KD2600300

Chassis No: JTFHT02PX00192782

Odometer: 56592 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,354.70	3,210.70	3,144.00	49.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,610.00	430.00	21.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,394.70	4,820.70	3,574.00	42.57
Approved Total (Overridden) (S\$)		3,850.00		
Nett Amount (S\$)	8,394.70	3,850.00	4,544.70	54.14

INSPECTION

Date of Assignment: 21/02/2019

Date Inspected: 21/02/2019 Inspected At:

Liu's Brother Auto Engineering Workshop
(kaki Bukit) (HQ)Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @
Kaki Bt Singapore 417883, Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 27 Feb 2019)
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE7587C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH TAIL LAMP	Cracked	365.10 F	*365.10 FL
2	1		*REAR RH TAILGATE	Badly Dented	2,051.60 F	*1,957.30 FL
3	1		*REAR RH BUMPER	Torn	465.00 F	*465.00 FL
4	1		*SET REAR RH BUMPER CLIPS	Necessary	48.00 F	*48.00 FL
5	1		*REAR RH BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
6	1		*REAR RH END PANEL INNER	Repair	936.20 F	*- FL
7	1		*REAR RH END PANEL OUTER	Badly Dented	566.10 F	*566.10 FL
8	1		*REAR RH END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
9	1		*REAR RH EXHAUST SILENCER	Repair	917.60 F	*- FL
10	1		*REAR RH TAILGATE WINDSCREEN GLASS MOULDING	No such part	219.00 F	*- FL
11	1		*REAR RH TAILGATE WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
12	1		*REAR RH TAILGATE 70 KM/H STICKER	Necessary	20.00 FS	*10.00 FS
13	1		*REAR RH TAILGATE TOYOTA STICKER	Necessary	80.00 F	*80.00 FL
14	1		*REAR RH TAILGATE TOYOTA MOTIF	Necessary	68.10 F	*68.10 FL
15	1		*REAR RH TAILGATE HIACE STICKER	Necessary	78.00 F	*78.00 FL
16	1		*REAR RH TAILGATE CORPORATE ADVERTISEMENT & ARTWORK	Necessary	200.00 FS	*180.00 FS
17	1		*REAR RH TAILGATE 8 PAX STICKER	Necessary	20.00 FS	*10.00 FS
				Sub Total (\$\$)	6,354.70	4,117.60
				- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	906.90
				Total Parts (\$\$)	6,354.70	3,210.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	60.00
2	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	20.00
3	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS	New	180.00	0.00
4	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	100.00	50.00
5	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	700.00
6	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECT	New	600.00	600.00
7	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS	New	120.00	120.00
8	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	60.00
Gross Labour Cost (\$\$)			2,040.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >