

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 4859M

DATE 20/2/2019 15:10

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✕			\$ 1,349.50
	Boot Lid Lock Upper ✕			\$ 132.10
	Boot Lid Lock Lower ✕			\$ 30.30
	Boot Lid Sonata Plate ✕			\$ 43.60
	Boot Lid Hyundai Plate ✕			\$ 24.20
	Boot Lid 'H' Emblem ✕			\$ 26.10
	Boot Lid CRDI Plate ✕			\$ 22.70
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Tail Lamp (LH) ✕			\$ 344.00
	Rear Panel ✕			\$ 391.80
	Rear Panel Garnish ✕			\$ 95.80
	SUB TOTAL			\$ 3,867.00
	LESS 20%			\$ 773.40
	DISCOUNTED TOTAL			\$ 3,093.60
	Boot Lid Comfort Logo & Tel No. Sticker ✕			\$ 30.00
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Rubber Mat			\$ 50.00
				\$ 215.70
	Labour Charge			
	Panel Beating			\$ 800.00 ²⁰⁰
	Spray Painting Charge			\$ 900.00 ²⁰⁰
	Wiring Charge			\$ 30.00 ✕
	Tuff Kote			\$ 50.00 ✕
	Remove/Refix Reverse Sensor			\$ 80.00 ²⁰
	TOTAL LABOUR			\$ 1,860.00
	ESTIMATE TOTAL			\$ 5,169.30
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer
Signature: _____
Date: _____

ESTIMATE TOTAL

Kahve LKK

21/2/19 1130h

2 hrs

4/3

Atta Rpr p4

Brookvale