

10/00000

REC. BY

REF

MSGI 9003284 / ESD300

Special Instructions:

WV/101
MUNNEN

Steve
Nor Azian

ASSIGNMENT (Office)

From (Person):

of

MSIA

Date/Time: 20/2/2019 @ 4.06pm

Estimated Cost:

Bill to:

①

TP / WS / TP RES / OD RES / EVA / INV / MVTCS

To Inspect Vehicle No:

3KD 995C

Insured:

at Workshop n/s

Venture Automotive
305 Alexandra Road

Tel:

83833190

of

Policy No:

29100055Mcy

Claim No:

582406

Sum Insured:

Excess:

\$1000.00

Make of Veh:

(Client's Record)

D.O.A.

10/01/2019

CA / (REV) / RRP / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10/11am @ 20/12/19

Person Contacted:

Ming feng

Vehicle

IN

OUT

Date/Time

Action/Instruction

✓

Estimate

Rev with market value

3KD 995C -X

26/02/19

@ 10:41 a.m. Confirmed with Nor Azian Binte Noordin
Cost Plus 20% ~~for~~ after parts prices discount on

26/02/19

@ 16:30 p.m. revised RA to Nor Azian Binte Noordin
via merimer.

26/02/19

@ 16:38 - a ~~new~~ mandate revised authorization to Nor Azian via merimer.

Customer **Steve**

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record) _____
Make of Veh: _____

(Policy Condition) _____
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: **\$220K**
IDAC Accident Rpt: Consistent? : Yes or No _____
GIA / PR Seen: Consistent? : Yes or No _____
Est. Repairs: _____ days Res: Yes or No _____
Lump Sum: _____ % 3 Val: Yes or No _____

CA / REV / REP. / 24 HRS _____
Date: _____ Person Contacted: _____
Vehicle: IN / OUT _____

Veh No: **SKD 995C** Yr Regn: **27 27/12/16**
Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: **BMW X5** C.C. **1995**
Colour: **Black** A/C Insured / Std / NI / NA _____
Sp. Reading: **79126** T/Radio: Insured / Std / NI / NA _____
Eng/No: _____
C/No: **WBAL 5020409416067**
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ Inorder / Jammed / Leaked / Burnt or _____
Brake: ☒ Inorder / Jammed / Leaked / Burnt or _____
Modl: **NII / S/Rim / STD A/Rim or**
Tyre Size: F: **255 / 50 R19**
R: **11**
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **Fitelli**
Front: _____ Rear: _____
R/Bal: **7** mm R/Bal: **7** mm
L/Bal: **7** mm L/Bal: **7** mm
D.O.A: **10/1/19** D.O.I: **21/2/19**
Survey held at: **Vantage Automotive**
Des. of Damages: ☒ Frt / Rear / O/S / N/S / UIC / Rooftop or _____
The UIC / Chassis frame / Body Structure affected due to collision _____

Date / Time Action / Instruction
M/V - 220,000 \$ roll Mchng exp. End 100K 28/2/19 @ 4:50am
P/V - 103,368
N/V - 116,632
RECEIVED 31 MAY 2019

26/02/19 @ 16:30 p.m. - revised IA to Nor Azian Brite Noordin
via merimen
26/02/19 @ 16:33 p.m. mandate requested authorize repair to Nor Azian
Brite Noordin via merimen
26/02/19 @ 17:47 p.m. mandate approved by Jason Sim via merimen

Date/Time: File Page 1 of 7
31/05/19
1) Typist
Date/Time: File Return to
2) _____
Report Format : _____
Lump Sum / I.B.I: (\$) **62,744.45 AP**
Days Of Repair: **12**
Resurvey No. of Trip: **2**
Survey Fee: _____
Transportation: _____
1) Site Insp (\$)
2) Interview (\$)
3) Tech Invs (\$)
4) Weekend (\$)
TOTAL: **311**

27/02/19 @ 11:31 am revert authorize repair to Min Ling (operator)
via email.

13/05/19 Confirmed P/P \$ 62,744.45 @ 12 days with Steve.
(\$ 30,162.66 Red - 33%)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jan 2019		20 Feb 2019 16:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SIME DARBY SERVICES, Co. Reg. No.: 197501065W		
Vehicle Reg. No.:	SKD995C	Date of Loss:	10/01/2019 17:00 - :59 [24 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 582406	Policy/Cover Note No.:	29100055MCY (Comprehensive) Coverage: 01/10/2018 - 30/09/2019
		Excess:	S\$1,000.00
Repairer:	Vantage Automotive Limited (Alexandra) 305 Alexandra Road #02-01, Vantage Automotive Centre, 159942 Alexandra - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Nor Azian Binte Noordin]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/02/2019]		
Driver/Custodian:	LOW ENG SEAH (58 / Male), NRIC: S1428529F, Tel: +6591880439		
Adj Asg. Remarks:	Car in, pls revert with MV		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SKD995C		
Vehicle Type :	R11 - Private Hire (Self-Drive) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	B.M.W.		
Vehicle Model :	X5 XDRIVE25D M SPORT 7 SEAT LED NAV		
Chassis No. :	WBALS020400U16067		
Propellant :	Diesel		
Engine No. :	52759722B47D20B		
Engine Capacity :	1995 cc		
Maximum Power Output :	170.0 kW (227 bhp)		
Maximum Laden Weight :	2980 kg		
Unladen Weight :	2040 kg		
Year Of Manufacture :	2016		
Original Registration Date :	27 Dec 2016		
Lifespan Expiry Date :	-		
COE Category :	E - Open Category		
Quota Premium :	\$50,010.00		
COE Expiry Date :	26 Dec 2026		
Road Tax Expiry Date :	26 Jun 2019		
PARF Eligibility Expiry Date :	26 Dec 2026		
Inspection Due Date :	26 Dec 2019		
Intended Transfer Date :	21 Feb 2019		
CO2 Emission :	151.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SKD995C		
Vehicle Type :	R11 - Private Hire (Self-Drive) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	B.M.W.		
Vehicle Model :	X5 XDRIVE25D M SPORT 7 SEAT LED NAV		
Chassis No. :	WBALS020400U16067		
Propellant :	Diesel		
Engine No. :	52759722B47D20B		
Engine Capacity :	1995 cc		
Maximum Power Output :	170.0 kW (227 bhp)		
Maximum Laden Weight :	2980 kg		
Unladen Weight :	2040 kg		
Year Of Manufacture :	2016		
Original Registration Date :	27 Dec 2016		
Lifespan Expiry Date :	-		
COE Category :	E - Open Category		
Quota Premium :	\$50,010.00		
COE Expiry Date :	26 Dec 2026		
Road Tax Expiry Date :	26 Jun 2019		
PARF Eligibility Expiry Date :	26 Dec 2026		
Inspection Due Date :	26 Dec 2019		
Intended Transfer Date :	23 Jan 2019		
CO2 Emission :	151.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1065W
Vehicle Details	
Vehicle No.:	SKD995C
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	B.M.W.
Vehicle Model:	X5 XDRIVE25D M SPORT 7 SEAT LED NAV
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	52759722B47D20B
Chassis No.:	WBALS020400U16067
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$65,255.00
Original Registration Date:	27 Dec 2016
First Registration Date:	27 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$89,459.00
Intended PARF Rebate Details	44,729.50
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Dec 2026
PARF Rebate Amount:	\$67,094.00
Intended COE Rebate Details	
COE Expiry Date:	26 Dec 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$50,010.00
COE Rebate Amount:	\$36,274.00
Total Rebate Amount:	\$103,368.00

The information contained herein is correct as at 21 Feb 2019

$$23,280 \div 12 = 1940$$

OK

$$\$227,089$$

$$7 \text{ y} - \frac{11.5}{12} \text{ month} = 94$$

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 31 May 2019 4:14 PM
To: 'Melody Teoh Man Lin'
Cc: 'Liu Chun Cheong'; 'Simon Koh Eng Aun'; 'Katherine Chong'; Steve Chen (LKK Auto); SUR
Subject: RE: SKD995C FINALIZATION

Dear Melody,

As spoken, confirmed final fig \$ 62,744.45 @ 12 days of repairs before excess \$ 1,000/- & GST.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Melody Teoh Man Lin [mailto:melody.teoh.manlin@simeдарby.com.sg]
Sent: Friday, 31 May 2019 12:16 PM
To: stevechen@lkkauto.com; SUR <sur@lkkauto.com>
Cc: Liu Chun Cheong <liu.chun.cheong@simeдарby.com.sg>; Simon Koh Eng Aun <simon.koh.engaun@simeдарby.com.sg>; Katherine Chong <katherine.chong@simeдарby.com.sg>
Subject: RE: SKD995C FINALIZATION

Dear Shirley,

Please find the revised finalization report for SKD995C attached above.

We would like to finalize as **Limit Repair (PBP) COR: \$62,744.46** (before GST & before less excess) @ **12 days** repair.

Please kindly check and confirm via reply email.

Thank you.

Best regards,

MELODY TEOH

Customer Service Advisor (Bodyshop)

Vantage Automotive Limited

305 Alexandra Road

Vantage Automotive Centre

Singapore 159942

Regent Motors Limited (FORD)

AutoFrance (PEUGEOT)

DID: +65 6477 7409
HP : +65 9278 2710
Email: melody.teoh.manlin@simedarby.com.sg



From: Melody Teoh Man Lin
Sent: Thursday, May 09, 2019 11:15 AM
To: stevechen@lkkauto.com
Cc: Liu Chun Cheong <liu.chun.cheong@simedarby.com.sg>; Simon Koh Eng Aun <simon.koh.engaun@simedarby.com.sg>; Katherine Chong <katherine.chong@simedarby.com.sg>
Subject: SKD995C FINALIZATION

Dear Steve,

Above attached is **SKD995C** finalized report, together with supporting documents for your reference.

We would like to finalize as **Limit Repair (PBP) COR: \$65,936.59** (before GST & before less excess) @ **12 days** repair.

Please kindly check and confirm via reply email.

Thank you.

Best regards,

MELODY TEOH

Customer Service Advisor (Bodyshop)

Vantage Automotive Limited

305 Alexandra Road

Vantage Automotive Centre

Singapore 159942

Regent Motors Limited (FORD)

AutoFrance (PEUGEOT)

DID: +65 6477 7409

HP : +65 9278 2710

Email: melody.teoh.manlin@simedarby.com.sg



Shirley Hiew (LKK Auto)

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Thursday, 28 February 2019 9:10 AM
To: chong.min.seng@simedarby.com.sg
Cc: Shirley Hiew (LKK Auto)
Subject: SKD995C LIMIT COST OF REPAIR

Dear Mr Chong,

As per our communicate a moment. The above vehicle repair limit is \$100k.

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)
Sent: Thursday, February 28, 2019 8:50 AM
To: Steve Chen (LKK Auto)
Subject: FW: SKD995C LIMIT COST OF REPAIR

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Shir@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Min Seng [<mailto:chong.min.seng@simedarby.com.sg>]
Sent: Wednesday, 27 February 2019 2:38 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: Liu Chun Cheong <liu.chun.cheong@simedarby.com.sg>; Katherine Chong <katherine.chong@simedarby.com.sg>; Simon Koh Eng Aun <simon.koh.engaun@simedarby.com.sg>
Subject: RE: SKD995C LIMIT COST OF REPAIR

Dear Shirley,

As we speak on the phone please let us know the limit cost to repair for SKD995C thanks

Warmest Regards

*Chong Min Seng
Bodywork Customer Service Advisor*

Vantage Automotive Limited
305 Alexandra Road
Vantage Automotive Centre
Singapore 159942
Regent Motors Limited (FORD)
AutoFrance (PEUGEOT)
Email : chong.min.seng@simedarby.com.sg
HPI : 8383 3190

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Wednesday, 27 February, 2019 11:31 AM
To: Chong Min Seng <chong.min.seng@simedarby.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: SKD 995C OD (MSIG) DOA 10/01/2019

Dear Min Seng,

As instructed by our client, please proceed to repair the insured vehicle **SKD 995C (Excess \$ 1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SKD995C (582406)**

OD

Jan 10 2019 5:00PM

[SIME DARBY SERVICES]

Vantage Automotive Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 30/05/2019 17:57 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$62744.45) - SKD995C - Claim Handler: Pang Xiu Shi

Approved:62744.45.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SKD995C (582406)**

OD

Jan 10 2019 5:00PM

[SIME DARBY SERVICES]

Vantage Automotive Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 26/02/2019 17:47 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$68675.10) - SKD995C - Claim Handler: Nor Azian Binte Noordin

Approved:68675.10.

DOCUMENTS SUMMARY

There are no documents.

T OF CASES FINALIZED BY SURVEYOR DURING GROUND PERIOD

veyor Name: Adnan

e: 26/10/15 (2N)

[illegible]

Knowledge Received: _____
Coordinator

Name of Handler : _____

Checked By Mr Lau : _____

Acknowledged Received : _____

When case done

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 16 May 2019

Preliminary Advice

Vehicle No	: SKD995C	Accident Date	: 10/01/2019
Make	: BMW X5	Policy No.	: 29100055MCY
Assignment Date	: 20/02/2019	Excess	: S\$1,000.00
Date of Inspection	: 21/02/2019	Est. Duration of Repair	: 12 Days
Inspection At	: Vantage Automotive Limited (Alexandra) 305 Alexandra Road #02-01, Vantage Automotive Centre Singapore 159942		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	92,913.11 (inclusive supplementary)
Revised Amount	:S\$	62,744.45 (inclusive supplementary)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	62,744.45
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	220,000.00
COE / PARF Rebate	:S\$	103,368.00
Salvage Value	:S\$	
Margin for Repair	:S\$	116,632.00

Remarks

(X) The vehicle is economical for repair. Supplementary amount is \$ 21,318.43.

() The above survey was conducted on a 'without prejudice' basis.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 25 Feb 2019

Preliminary Advice

Vehicle No	: SKD995C	Accident Date	: 10/01/2019
Make	: BMW X5	Policy No.	: 29100055MCY
Assignment Date	: 20/02/2019	Excess	: S\$1,000.00
Date of Inspection	: 21/02/2019	Est. Duration of Repair	: 12 days
Inspection At	: Vantage Automotive Limited (Alexandra) 305 Alexandra Road #02-01, Vantage Automotive Centre Singapore 159942		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	78,558.55
Revised Amount	:S\$	49,743.83
Check Items (Estimated)	:S\$	18,931.27
Total	:S\$	68,675.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	220,000.00
COE / PARF Rebate	:S\$	103,368.00
Salvage Value	:S\$	
Margin for Repair	:S\$	116,632.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Vehicle Registration Number of Driver's Own Vehicle (if applicable)
Insurance Company of Driver's Own Vehicle (if applicable)

General Information of the Accident

Type Of Accident Collision- Head to Rear (TP Hit Insured)
Weather Conditions Clear
Road Surface Dry

Other Information

Was any body injured in the Accident? No
Was any other material or property damaged? Yes

Details of Police Action

Was the accident reported to the police? No
If Yes, Please state which Police Station
Was notice of intended Prosecution given? No
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJW5208X
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver DIANA HENG
NRIC/Passport Number S6940767F
Contact Number 94574899
Address
Postcode
Insurance Company Name Chartis Singapore Insurance Pte Ltd
Nature Of Damage FRONT PORTION
No. Of Passenger (Including Driver)

Details of Witness

Name LEE YING
Phone Number 92324011
Email Address

26/7/19 As per record. *Cefid*

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2019 10:48
Date Of Accident	10/01/2019 17:00
Exact Location Of Accident	JUNCTION OF VICTORIA STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD995C
Insured/Policyholder	
Name Of Registered Owner	SIME DARBY SERVICES
Co Reg No	197501065W
Email Address	CHONG.MIN.SENG@SIMEDARBY.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-83833190

Vehicle Particulars

Manufacturer	BMW
Model	X5-2.0 D XDRIVE25D 7 SEAT LED NAV (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	B29100055
Cover Note Number	

Driver

Name of Driver	LOW ENG SEAH
NRIC No	S1428529F
Date Of Birth	17/06/1960
Occupation	OUTDOOR
Date Of Driving Pass	12/06/1996
Driving Experience	22 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91880439
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	B630 HOUGANG AVE 8 #08-50
Postcode	530630
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - CUSTOMER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : NA GENDER: : MALE
Passenger 2	NAME: : NA GENDER: : MALE
Passenger 3	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	REFER TO POLICE REPORT
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to police report .

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	TRAFFIC POLICE HAVE TAKEN THE SD CARD .
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *Chen Min-wei*
NRIC/FIN No.: *S7587052 B*

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- POLICE REPORT ATTACHED -

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: *Chan Siu - Tang*
NRIC/FIN No.: *S-4616 DT20*



SINGAPORE POLICE FORCE



T/20190110/2149

1 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20190110/2149

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/01/2019 21:31	Vide Report No.: A/20190110/0103	Station Diary No.: 114
Informant's Particulars		
Name of Informant: LOW ENG SEAH	Address: APT BLK 630 HOUGANG AVENUE 8 #08-50 SINGAPORE 530630	
ID Type / ID No.: NRIC NO / S1428529F	Contact No.: Home/Office:	Mobile: 91880439
Nationality: SINGAPORE CITIZEN	Email:	
Sex: Male	Age: 58	Date of Birth: 17/06/1960
Type of Informant: Driver		
Race: Chinese	Language: English	Institution / School Name:
Occupation: Chauffeur	Driving Licence Information: Class: 3,4	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 10/01/2019 17:10	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 VICTORIA STREET ROCHOR ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision:			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SCN3363Z	Car	MERCEDES BENZ		Brown		0
SKD995C	Car	BMW		Black	Slightly Damaged	3
SLU9666S	Car	TOYOTA		White		1



**SINGAPORE
POLICE FORCE**



T/20190110/2149

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 3

Report No. T/20190110/2149

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LOW ENG SEAH	ID No.	S1428529F
Related Vehicle	SKD995C (Car)	Contact No.	91880439
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 10 Jan 2019 at about 1710 hrs, I was travelling along Victoria St towards Hill St on the 2nd lane from the right. When passing through the junction of Victoria St and Rochor Rd, one white car (SLU9666S) came from my left to right. I applied my brakes but was not able to stop in time and collided onto the right side of the vehicle. I alighted from my vehicle to check and noticed a 3rd vehicle, Mercedes (SCN3363Z) involved. According to the driver, his vehicle was hit by the white car.

Passerby called for ambulance and the driver of SLU9666S was conveyed to hospital. Traffic Police was at scene and seized the memory card of my in-vehicle camera.



**SINGAPORE
POLICE FORCE**



T/20190110/2149

3 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20190110/2149

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /
Sgt 2 YAP WEI YANG

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Staff Sgt MOHAMED SUFIAN BIN MOHAMED
JUNID
Contact No.: 65476247

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
10/01/2019 21:31

Classification Of Case:

Vantage Automotive Limited

305 Alexandra Road S'pore 159942

Date : 08.02.2018

RE: VEHICLE REPAIR QUOTATION

Insurance Company	MSIG Insurance Pte Ltd
Vehicle Reg No	SKD995C
Name of Insured	MSIG
Policy Number	B29100055
Date of Accident	10/1/2019
Tyre of Claim	Own Damage Claim
Model	BMW X5-2.0
Chassis No	WBALS020400U16067

We are please to submit our estimate of repairs to the above mention vehicle.

		Labour
1	SUNDRIES	\$ 120.00
2	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING. (NETT)	\$ 120.00
3	SEALANT FOR FRONT LH & RH INNER WHEEL HOUSING. (NETT)	\$ 150.00
4	TUFF KOTE - BODY CAVITY PRESERVATION.(NETT)	\$ 150.00
5	TO REPLACE FRONT BUMPER,BONNET, FRONT LHS & RHS FENDER, SUPPORT PANEL, AND ALL OTHER AFFECTED AREAS	\$ 1,750.00
6	TO SPRAY PAINT FRONT BUMPER,BONNET,FRONT LHS & RHS FENDER SUPPORT PANEL AND ALL OTHER AFEFCTED PARTS AND AREAS	\$ 1,400.00
7	TO MOUNT VEHICLE ON CELETTE BENCH, TO CHECK AND ADJUST CHASSIS ALIGNMENT.(NETT)	\$ 1,680.00
8	HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME HEADLAMP CORRECTOR.(NETT)	\$ 200.00
9	TO REMOVE AND REPLACE FRONT WINDSCREEN, CONDUCT WATER LEAKS TEST .(NETT)	\$ 600.00
10	SEALANT FOR FRONT WINDSCREEN (NETT)	\$ 60.00
11	INNER SEAL FOR FRONT WINDSCREEN (NETT)	\$ 50.00
12	IU BRACKET FOR FRONT WINDSCREEN (NETT)	\$ 26.00
13	TO CONDUCT ECU PROGRAMMING, CHECK AND CLEAR FAULT CODES.(NETT)	\$ 600.00
14	TO REMOVE,RECTIFY AND REPLACE FRONT LEFT PASSENGER SEAT AIRBAG SYSTEM.(NETT)	\$ 300.00
15	TO REMOVE AND REFIX RADIATOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS.(NETT)	\$ 600.00
16	TO REMOVE AND REFIX A/C CONDENSOR,CONDUCT PRESSURE TEST CHECK FOR LEAKS,VACUUM REFILL,RECHARGE AIRCON GAS.(NETT)	\$ 600.00
17	TO SUPPLY AND INSTALL FRONT NUMBER PLATE WITH HOLDER.(NETT)	\$ 70.00

Total (Labour) \$ 8,476.00

	<u>PARTS</u>	<u>LABOUR</u>	
Sub Total :	\$70,082.55	+	\$8,476.00
GST 7%			\$ 78,558.55
			\$ 5,499.10
Grand Total :			<u>\$ 84,057.65</u>

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

CHONG MIN SENG 83833190

Vantage Automotive Limited

305 Alexandra Road S'pore 159942

Date : 08.02.2018

RE: VEHICLE REPAIR QUOTATION

Insurance Company

Vehicle Reg No

Name of Insured

Policy Number

Date of Accident

Tyre of Claim

Model

Chassis No

MSIG Insurance Pte Ltd

SKD955C

MSIG

B29100055

10/1/2019

Own Damage Claim

BMW X5-2.0

WBALS020400U16067

We are please to submit our estimate of repairs to the above mention vehicle.

			Labour
1	SUNDRIES	\$	✓ 120.00 60/
2	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING. (NETT)	\$	✓ 120.00 60/
3	SEALANT FOR FRONT LH & RH INNER WHEEL HOUSING. (NETT)	\$	✓ 150.00 100/
4	TUFF KOTE - BODY CAVITY PRESERVATION.(NETT)	\$	✓ 150.00 170/
5	TO REPLACE FRONT BUMPER,BONNET, FRONT LHS & RHS FENDER, SUPPORT PANEL, AND ALL OTHER AFFECTED AREAS 500 300	\$	✓ 1,750.00 1500/
6	TO SPRAY PAINT FRONT BUMPER,BONNET,FRONT LHS & RHS FENDER, SUPPORT PANEL AND ALL OTHER AFEFCTED PARTS AND AREAS 250	\$	✓ 1,400.00 1000/
7	TO MOUNT VEHICLE ON CELETTE BENCH, TO CHECK AND ADJUST CHASSIS ALIGNMENT.(NETT)	\$	1,680.00 X 1680
8	HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME HEADLAMP CORRECTOR.(NETT)	\$	✓ 200.00 /
9	TO REMOVE AND REPLACE FRONT WINDSCREEN, CONDUCT WATER LEAKS TEST .(NETT)	\$	✓ 600.00 /
10	SEALANT FOR FRONT WINDSCREEN (NETT)	\$	✓ 60.00 /
11	INNER SEAL FOR FRONT WINDSCREEN (NETT)	\$	✓ 50.00 /
12	IU BRACKET FOR FRONT WINDSCREEN (NETT)	\$	✓ 26.00 /
13	TO CONDUCT ECU PROGRAMMING, CHECK AND CLEAR FAULT CODES.(NETT)	\$	✓ 600.00 /
14	TO REMOVE,RECTIFY AND REPLACE FRONT LEFT PASSENGER SEAT AIRBAG SYSTEM.(NETT)	\$	✓ 300.00 /
15	TO REMOVE AND REFIX RADIATOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS.(NETT)	\$	✓ 600.00 300/
16	TO REMOVE AND REFIX A/C CONDENSOR,CONDUCT PRESSURE TEST CHECK FOR LEAKS,VACUUM REFILL,RECHARGE AIRCON GAS.(NETT)	\$	✓ 600.00 300/
17	TO SUPPLY AND INSTALL FRONT NUMBER PLATE WITH HOLDER.(NE	\$	✓ 70.00 /

Total (Labour)

70,082.55

\$ 8,476.00

Sub Total :

83464.31 + 8476.00

\$ 91,940.31

GST 7%

\$ 6,435.82

Grand Total :

\$ 98,376.13

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

CHONG MIN SENG 83833190

stevechen@18kauto.com

Steve (Lkk) 21/2/19 1pm

83228813

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 187611599M GET Reg. No. 90-0020041-e

100, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales)
63190111 (AfterSales)
Fax: 64747710

240, Serangoon Avenue Road
East Coast Centre
Singapore 438140
Tel: 63190888 (AfterSales)
Fax: 63449770

113, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190518 (AfterSales)
63190513 (Motorrad)
Fax: 64736611 (AfterSales)
64736614 (Motorrad)



Express - \$1000

12-18 days

1/3/19

Any remark, before & after spray

Q U O T A T I O N

Account No. :	618056	Quotation No. :	512185
Customer Name :	Vantage Automotive Limited	Quotation Date:	24/01/2019
	305 Alexandra Road	Page No. :	1 of 9
	#02-01 Vantage Automotive Centre	Partsman :	P94MOOS
	Singapore 159942	Del. Doc. :	3660698

S/N	PART NUMBER	DESCRIPTION	ISSUE QTY	SELLING PRICE	DISC. %	NET PRICE
ATTN:TEO KIAT TNG SKD995C 0U16067 F15/X5/25DX						
1	41117377771	FRT LH WHEELHOUSE ?	1	1,819.15	5.00	1,728.19
2	41117377772	FRT RH WHEELHOUSE ?	1	1,819.15	5.00	1,728.19
3	83190301414	BLIND RIVET HEML OCK 813 X	25	2.65	15.00	56.31
4	83190413015	(DG/SL) ADHESIVE GLUE X	1	326.80	15.00	277.78
5	83192211217	(DG) CLEANER R1 (100ML) X	1	26.15	5.00	24.84
6	83422409985	(S/L) SEAM SEAL 300ML X	3	33.80	5.00	96.33
7	41117390609N	SUPPORTING STRUT LEFT ?	1	457.65	5.00	434.77
8	41117377785	SECTION OF LH FRT WHEEL HOUSING ?	1	557.90	5.00	530.01
9	41117390610N	SUPPORTING STRUT RIGHT ?	1	457.65	5.00	434.77
10	41117377786N	SECTION OF RIGHT FRONT W/HOUSING ?	1	557.90	5.00	530.01
11	41117382219N	FRONT LEFT ENGINE SUPPORT ?	1	950.55	5.00	903.02
12	41117382220N	FRONT RIGHT ENGINE SUPPORT ?	1	950.55	5.00	903.02
13	41117174331	SUPPORT WHEELHOUSE LH ?	1	90.25	5.00	85.74
14	41117174332	SUPPORT WHEELHOUSE RH ?	1	90.25	5.00	85.74
15	41117174305	MOUNT CROSS MEMBER LH ?	1	97.20	5.00	92.34
16	41117174306	MOUNT CROSS MEMBER RH ?	1	97.20	5.00	92.34
17	41117442775	WHEELHOUSE SUPPORTING STRUT ?	1	205.55	5.00	195.27
18	41117442776N	WHEELHOUSE SUPPORTING STRUT RH ?	1	205.55	5.00	195.27
19	63127280779	COMPENSATING ELEMENT X	4	8.50	5.00	32.30
20	41117180941	LH ENGINE COMPARTMENT PARTITION ?	1	487.30	5.00	462.94
21	41117180942	RH ENGINE COMPARTMENT PARTITION ?	1	487.30	5.00	462.94
22	41117174329	LH SUPPORTING STRUT REINFORCEMENT ?	1	71.55	5.00	67.97
23	41117174330	RH SUPPORTING STRUT REINFORCEMENT ?	1	71.55	5.00	67.97

Total : 67,829.59
ADD GST @ 7% : 4,748.07
Total Amount : 72,577.66

This is a computer generated Quotation. No signature is required.

- Note :
- (1) The validity of this quotation is 14 days from the above date.
 - (2) Parts are subject to availability.
 - (3) Any prices change is without prior notice.

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559J SST Reg. No. M1-033061-2

109, Alexandra Road
Sime Darby Performance Centre
Singapore 159942
Tel. 63190200 (Sales)
63190211 (AfterSales)
Fax. 64747970

169, Serpong Agung Road
East Coast Centre
Singapore 439100
Tel. 63190800 (AfterSales)
Fax. 63419773

415, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/330 (Motorrad)
Fax. 64794001 (AfterSales)
64794024 (Motorrad)



Q U O T A T I O N

Account No. :	618056	Quotation No. :	512185
Customer Name :	Vantage Automotive Limited	Quotation Date:	24/01/2019
	305 Alexandra Road	Page No. :	2 of 9
	#02-01 Vantage Automotive Centre	Partsman :	P94MOOS
	Singapore 159942	Del. Doc. :	3660698

S/N	PART NUMBER	DESCRIPTION	ISSUE QTY	SELLING PRICE	DISC. %	NET PRICE
24	41117174303	CONNECT. PLATE F LH SIDE ? PANEL FRAM	1	164.50	5.00	156.28
25	41117174304	RH SIDE PANEL FRAME CONNECT PLATE	1	164.50	5.00	156.28
26	41117174301	ENGINE MOUNT SUPPORT RR LH	1	56.15	5.00	53.34
27	41117174302	ENGINE MOUNT SUPPORT RR RH	1	56.15	5.00	53.34
28	51657373541	FRT LH SIDE PANEL / 00	1	1,101.75	10.00	991.58✓
29	51657337093N	FRT LH REINFORCEMENT SIDE PANEL	1	46.40	5.00	44.08
30	51718219511	BLIND RIVET	20	1.40	10.00	25.20
31	51657373542	FRT RH SIDE PANEL / 00	1	1,101.75	10.00	991.58✓
32	51657337094N	FRT RH REINFORCEMENT SIDE PANEL	1	46.40	5.00	44.08
33	51647294543	MODULE CARRIER LH / 07	1	100.65	10.00	90.59✓
34	51647294544	MODULE CARRIER RH / 07	1	100.65	10.00	90.59✓
35	51647294551N	LH SIDE PANEL CENTRE BRACKET	1	34.25	5.00	32.54
36	51647294552	RH SIDE PANEL CENTRE BRACKET	1	34.25	5.00	32.54
37	51657337092N	FRT RH REINFORCEMENT SIDE / 07 PANEL	1	46.40	5.00	44.08✓
38	51657294539N	FRT LH AIR DUCT SIDE PANEL	1	55.95	5.00	53.15
39	51657294540	FRT RH AIR DUCT SIDE PANEL	1	55.95	5.00	53.15
40	07149241763	CLAMP	10	1.60	10.00	14.40
41	51657337094N	FRT RH REINFORCEMENT SIDE PANEL	1	46.40	5.00	44.08
42	51657337095N	FRT LH REINFORCEMENT SIDE PANEL	1	46.40	5.00	44.08
43	51767205141	COVER	2	6.90	10.00	12.42
44	41007381758	BONNET / 00	1	2,493.50	10.00	2,244.15✓
45	41007381781	BONNET LH HINGE / 07	1	138.35	5.00	131.43✓

Total :	67,829.59
ADD GST @ 7% :	4,748.07
Total Amount :	72,577.66

This is a computer generated Quotation. No signature is required.

- Note :
- (1) The validity of this quotation is 14 days from the above date.
 - (2) Parts are subject to availability.
 - (3) Any prices change is without prior notice.

Performance Motors Limited

A member of the Fine Carby Group
Co. Reg. No. 197401559W GST Reg. No. WD-1022081-0

103, Alexandra Road
Fine Carby Performance Centre
Singapore 159942
Tel. 63190100 (Sales)
63190111 (AfterSales)
Fax. 64794770

240, Kembangan Road
East Coast Centre
Singapore 410180
Tel. 63190488 (AfterSales)
Fax. 63449773

315, Alexandra Road
Fine Carby Business Centre
Singapore 159944
Tel. 63190128 (AfterSales)
63190131/330 (Motorrad)
Fax. 64794401 (AfterSales)
64794404 (Motorrad)



QUOTATION

Account No. : 618056
Customer Name : Vantage Automotive Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre
Singapore 159942

Quotation No. : 512185
Quotation Date: 24/01/2019
Page No. : 3 of 9
Partsmen : P94MOOS
Del. Doc. : 3660698

S/N	PART NUMBER	DESCRIPTION	ISSUE QTY	SELLING PRICE	DISC. %	NET PRICE
46	41007381782	BONNET RH HINGE	1	138.35	5.00	131.43
47	51237294524	GAS FILLED STRUT ENGINE COMPARTMENT	2	118.10	10.00	212.58
48	51767183752	ADJUSTER	2	6.30	10.00	11.34
49	51767294489	REAR ENGINE HOOD SEALING	1	38.85	5.00	36.91
50	51767294509	FRT ENGINE HOOD SEALING	1	58.30	5.00	55.39
51	51767294511	LH ENGINE HOOD SEALING	1	33.05	5.00	31.40
52	51767294512	RH ENGINE HOOD SEALING	1	33.05	5.00	31.40
53	51237367536	RR BOWDEN CABLE ENGINE COMP. LID	1	41.40	5.00	39.33
54	51232753419	LOCK F HOOD	1	58.50	10.00	52.65
55	51237308068	LOCK F HOOD RH	1	114.30	10.00	102.87
56	51237294536	CATCH OPERATOR	1	41.40	5.00	39.33
57	51237325992	LOCK UPPER SECTION RH	1	68.60	10.00	61.74
58	51232571186	LOCK UPPER SECTION LH	1	44.30	5.00	42.09
59	51437148524	LEVER FOR ENGINE HOOD MECHANISM	1	34.70	5.00	32.97
60	51437284599	HOLDER BONNET ACTUATOR	1	43.95	5.00	41.75
61	41517386737	FRT LH DOOR	1	2,154.75	10.00	1,939.28
62	41517386738	FRT RH DOOR	1	2,154.75	10.00	1,939.28
63	41007377545N	LH UPPER FRONT DOOR HINGE	1	54.45	5.00	51.73
64	41007377546N	RH UPPER FRONT DOOR HINGE	1	54.45	5.00	51.73
65	41007377547N	LH LOWER FRONT DOOR HINGE	1	54.45	5.00	51.73
66	41007377548N	RH LOWER FRONT DOOR HINGE	1	54.45	5.00	51.73
67	51217290595	FRT DOOR BRAKE	2	97.25	5.00	184.78
68	51717294269	LH CRASH PAD DOOR OUTER	1	35.55	5.00	33.77
69	51717294270N	CRASH PAD DOOR OUTER RH	1	35.55	5.00	33.77
70	13718519138N	INTAKE SILENCER	1	496.30	5.00	471.49
71	13718570043	AIR FILTER ELEMENT	1	78.35	15.00	66.60

Total : 67,829.59
ADD GST @ 7% : 4,748.07
Total Amount : 72,577.66

This is a computer generated Quotation. No signature is required.

Note : (1) The validity of this quotation is 14 days from the above date.
(2) Parts are subject to availability.
(3) Any prices change is without prior notice.

BMW Dealer:

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 137401555M GST Reg. No M2-022061-X

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63194100 (Sales)
63194111 (AfterSales)
Fax. 64747775

286, Kembangan Road
Saver Centre
Singapore 438143
Tel. 63190886 (AfterSales)
Fax. 63449773

317, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190138 (AfterSales)
63190133/310 (Motors)
Fax. 64798431 (AfterSales)
64798434 (Motors)



QUOTATION

Account No. :	618056	Quotation No. :	512185
Customer Name :	Vantage Automotive Limited	Quotation Date:	24/01/2019
	305 Alexandra Road	Page No. :	4 of 9
	#02-01 Vantage Automotive Centre	Partsman :	P94MOOS
	Singapore 159942	Del. Doc. :	3660698

S/N	PART NUMBER	DESCRIPTION	ISSUE QTY	SELLING PRICE	DISC. %	NET PRICE
72	13718519130N	BKT INTAKE SILENCER BOTTOM RIGHT	1	39.30	5.00	37.34
73	13718519131N	BKT INTAKE SILENCER BOTTOM LH	1	39.30	5.00	37.34
74	13718519132N	HOLGER INTAKE SILENCER TOP	1	39.30	5.00	37.34
75	13718570131N	AIR INTAKE DUCT	1	226.70	10.00	204.03
76	13718570289	INTAKE DUCT	1	162.80	10.00	146.52
77	13628570107	HOT FILM AIR MASS METER	1	587.50	10.00	528.75
78	13718471864N	DECOUPLING ELEMENT	2	11.50	10.00	20.70
79	17118654431N	RADIATOR	1	1,092.75	10.00	983.48
80	17118572188	LH MODULE CARRIER	1	77.60	10.00	69.84
81	17118572189	RH MODULE CARRIER	1	77.60	10.00	69.84
82	17117646138	MODULE CARRIER BOTTOM	1	94.85	10.00	85.37
83	17117598791	RUBBER MOUNTING	2	21.70	5.00	41.23
84	17118574000	COVER MODULE CARRIER	1	53.15	10.00	47.84
85	17117553480	RUBBER MOUNTING	2	11.30	10.00	20.34
86	17117553481	SUPPORT RUBBER MOUNTING	2	15.90	5.00	30.21
87	17117533537	BRACKER F RADIATOR	2	35.80	5.00	68.02
88	17517809321	CHARGE-AIR COOLER	1	747.40	5.00	710.03
89	17427634467	FAN HOUSING WITH FAN	1	1,542.40	10.00	1,388.16
90	17428618245	FAN SHROUD	1	308.00	5.00	292.60
91	17138621092	RADIATOR EXPANSION TANK	1	197.60	10.00	177.84
92	17137553919	LEVELLING SWITCH EXPANSION TANK	1	24.40	10.00	21.96
93	17117639020	SCREW CAP FOR EXPANSION TANK	1	26.00	10.00	23.40
94	61132359999	REPAIR KIT SOCKET HOUSING (2 POL)	1	28.70	10.00	25.83
95	61130006665	BUSHING CONTACT (0.75MM2)	1	4.65	10.00	4.19
96	17128514073N	HOSE RADIATOR THERMOSTAT	1	115.10	5.00	109.35

Total :	67,829.59
ADD GST @ 7% :	4,748.07
Total Amount :	72,577.66

This is a computer generated Quotation. No signature is required.

Note : (1) The validity of this quotation is 14 days from the above date.
(2) Parts are subject to availability.
(3) Any price change is without prior notice.

Performance Motors Limited

A member of the Rise Lorry Group
Co. Reg. No. 1974015598 SET Reg. No. 90-000001-9

103, Alexandra Road
Rise Lorry Performance Centre
Singapore 159942
Tel: 43190000 (Sales)
43190111 (AfterSales)
Fax: 44794772

280, Karpang Arang Road
East Coast Centre
Singapore 438140
Tel: 43190888 (AfterSales)
Fax: 43449770

118, Alexandra Road
Rise Lorry Business Centre
Singapore 159944
Tel: 43190518 (AfterSales)
43190533/110 (Motorrad)
Fax: 44794671 (AfterSales)
44794672 (Motorrad)



QUOTATION

Account No. :	618056	Quotation No. :	512185
Customer Name :	Vantage Automotive Limited	Quotation Date:	24/01/2019
	305 Alexandra Road	Page No. :	5 of 9
	#02-01 Vantage Automotive Centre	Partsmen :	P94MOOS
	Singapore 159942	Del. Doc. :	3660698

S/N	PART NUMBER	DESCRIPTION	ISSUE QTY	SELLING PRICE	DISC. %	NET PRICE
97	17128514072N	HOSE CYLINDER HEAD	1	155.15	5.00	147.39
98	17128514433N	HOSE RADIATOR	1	80.10	5.00	76.10
99	17128514076N	HOSE FOR EXPANSION TANK	1	135.10	5.00	128.35
100	17128563936N	BRACKET COOLANT HOSE	1	21.85	5.00	20.76
101	17128514081N	HOSE RADIATOR	1	80.10	5.00	76.10
102	11538514456N	PIPE CYLINDER HEAD	1	44.50	5.00	42.28
103	11538518749N	LINE ONE FILTER MODULE	1	113.25	5.00	107.59
		TRANS OIL				
104	11538573715N	LINE EGR COOLER CHANGEVER	1	147.20	5.00	139.84
		VALVE 2				
105	13627823993	COOLANT TEMPERATURE SENSOR	1	69.85	10.00	62.87
106	11538514066N	HOSE EGR COOLER - COOLANT	1	55.50	10.00	49.95
		PUMP				
107	11538573716N	HOSE CYLINDER HEAD	1	55.50	10.00	49.95
		CHANGOVER VALVE				
108	17228570449	TRANSMISSION OIL COOLER	1	159.85	5.00	151.86
		LINE				
109	17218514515	TRANSMISSION OIL COOLER	1	511.50	10.00	460.35
110	17127799184	LOCK	1	15.80	10.00	14.22
111	11538572508N	CHANGOVER VALVE	1	359.20	5.00	341.24
112	11538514441N	BKT CHANGE OVER VALVE	1	66.35	5.00	63.03
113	11538573717N	BKT CHANGOVER VALVE	1	33.15	5.00	31.49
114	11517643949	AUXILIARY WATER PUMP	1	160.50	15.00	136.43
115	17128526848N	BKT COOLANT HOSE	1	15.90	5.00	15.11
116	11518591016	COOLANT PUMP	1	337.65	15.00	287.00
117	11518623579N	INTERMEDIATE PLATE ASSY	1	55.00	5.00	52.25
118	22116882027N	ENG.SUPPORTING BKT LH	1	195.10	5.00	185.35
119	22116882028N	ENG.SUPPORTING BKT RH	1	170.75	5.00	162.21
120	22116867301N	ENGINE MOUNTING LH	1	228.35	10.00	205.52
121	22116867302N	ENGINE MOUNTING RH	1	198.55	10.00	178.70

Total :	67,829.59
ADD GST @ 7% :	4,748.07
Total Amount :	72,577.66

This is a computer generated Quotation. No signature is required.

- Note :
- (1) The validity of this quotation is 14 days from the above date.
 - (2) Parts are subject to availability.
 - (3) Any prices change is without prior notice.

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197421554M SRT Reg. No. 02-000001-4

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159942
Tel. 64780122 (Sales)
64780111 (AfterSales)
Fax. 64747772

165, Tampung Arang Road
East Coast Centre
Singapore 481885
Tel. 63190884 (AfterSales)
Fax. 63448771

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190128 (AfterSales)
63190127/500 (Motorrad)
Fax. 64794601 (AfterSales)
64794628 (Motorrad)



Q U O T A T I O N

Account No. :	618056	Quotation No. :	512185
Customer Name :	Vantage Automotive Limited	Quotation Date:	24/01/2019
	305 Alexandra Road	Page No. :	6 of 9
	#02-01 Vantage Automotive Centre	Partsman :	P94MOOS
	Singapore 159942	Del. Doc. :	3660698

S/N	PART NUMBER	DESCRIPTION	ISSUE QTY	SELLING PRICE	DISC. %	NET PRICE
122	22326854187	GEARBOX SUPPORT / NN	1	270.80	5.00	257.26
123	22316869723N	GEARBOX MOUNTING / NN	1	198.55	10.00	178.70
124	51317292399	GREEN WINDSCREEN (RLSBS) / BR	1	1,362.15	15.00	1,157.83 ✓
125	83192289285	(DG/SL) W/SCREEN SEALANT / NEC	2	131.55	10.00	236.79 ✓
		(COLD 1 HOUR)				
126	51311925433	W/SCREEN RUBBER BUFFER / NEC	10	1.70	10.00	15.30 ✓
127	51317292394	COVER WINDSHIELD TOP / NEC	1	49.20	10.00	44.28 ✓
128	51118062496	FRT BUMPER PANEL PRIMED (M) / BR	1	1,910.65	10.00	1,719.59 ✓
		PDC/ICAM				
129	51118059937	LH COVER SPRAY NOZZLE / BR	1	57.10	5.00	54.25 ✓
		PRIMED (M)				
130	51118059938N	RH COVER SPRAY NOZZLE / BR	1	57.10	5.00	54.25 ✓
		PRIMED (M)				
131	51118060131	COVER TOWING EYE PRIMED (M)	1	57.10	5.00	54.25
132	51118056305	TRIM AIR DUCT LH (M)	1	100.25	5.00	95.24
133	51118056306	TRIM AIR DUCT RH (M)	1	100.25	0.00	100.25
134	51117294477	FRT BUMPER CARRIER / DO	1	540.10	10.00	486.09 ✓
135	51118054010	FRT SHOCK ABSORBER (M) / RT	1	89.05	10.00	80.15 ✓
136	51647294507N	ADAPTER ELEMENT FRT END LH / BR	1	145.45	10.00	130.91 ✓
137	51647294508	ADAPTER ELEMENT FRT END RH / BR	1	145.45	10.00	130.91 ✓
138	51117308057N	STRUT FRT LH / RT	1	38.90	5.00	36.96 ✓
139	51117308058	STRUT FRT RH / RT	1	38.90	5.00	36.96 ✓
140	51647294491	SUPPORT HEADLIGHT LH / RT	1	74.95	5.00	71.20 ✓
141	51647294492	SUPPORT HEADLIGHT RH / RT	1	74.95	5.00	71.20 ✓
142	51117315959	SUPPORT INSERT LH / RT	1	15.30	10.00	13.77 ✓
143	51117315960	SUPPORT INSERT RH / RT	1	15.30	10.00	13.77 ✓
144	51118054013	GRILLE MIDDLE TOP (M) / BR	1	101.00	10.00	90.90 ✓
145	51118054012	GRILLE MIDDLE BOTTOM (M) / BR	1	113.15	10.00	101.84 ✓
146	51118064633	GRILLE SIDE OPEN LH (M)	1	120.75	10.00	108.68
147	51118064634	GRILLE SIDE OPEN LH (M)	1	149.90	10.00	134.91

Total :	67,829.59
ADD GST @ 7% :	4,748.07
Total Amount :	72,577.66

This is a computer generated Quotation. No signature is required.

- Note : (1) The validity of this quotation is 14 days from the above date.
(2) Parts are subject to availability.
(3) Any prices change is without prior notice.

Performance Motors Limited

A member of the Fine Carby Group
Co. Reg. No. 187411888N GST Reg. No. SG-0020081-0

333, Alexandra Road
Fine Carby Performance Centre
Singapore 159942
Tel: 63190100 (Sales)
63190111 (AfterSales)
Fax: 64767770

245, Serangoon Spring Road
East Coast Centre
Singapore 436180
Tel: 63190686 (AfterSales)
Fax: 63443770

115, Alexandra Road
Fine Carby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64766401 (AfterSales)
64766434 (Motorrad)



Q U O T A T I O N

Account No. :	618056	Quotation No. :	512185
Customer Name :	Vantage Automotive Limited	Quotation Date:	24/01/2019
	305 Alexandra Road	Page No. :	7 of 9
	#02-01 Vantage Automotive Centre	Partsman :	P94MOOS
	Singapore 159942	Del. Doc. :	3660698

S/N	PART NUMBER	DESCRIPTION	ISSUE QTY	SELLING PRICE	DISC. %	NET PRICE
148	51118064635	GRILLE SIDE CLOSED LH (M) <i>RR</i>	1	116.30	10.00 ✓ 100.40	104.67 ✓
149	51118064636	GRILLE SIDE CLOSED RH (M) <i>RR</i>	1	116.20	10.00 ✓ 100.35	104.58 ✓
150	51748055209	AIR DUCT BRAKE LH (M) <i>RR</i>	1	58.75	5.00	55.81 ✓
151	51748055210	AIR DUCT BRAKE RH (M) <i>RR</i>	1	58.75	5.00	55.81 ✓
152	51648055208	COOLING AIR DUCT (M) <i>RR</i>	1	335.45	5.00	318.68 ✓
153	51459298964	INSTRUMENT PANEL (SCHWARZ/SCHWARZ) <i>RR</i>	1	3,433.30	5.00	3,261.64 ✓
154	51489258257	SOUND INSULATION SET <i>X NAI</i>	1	191.05	5.00	181.50
155	51459281640	TRIM CENTRE SPEAKER METAL (SCHWARZ) <i>NAI</i>	1	37.55	5.00	35.67
156	51118174185	BUMPER RIVET <i>X NAI</i>	20	0.50	10.00	9.00
157	51471911992	EXPANDING RIVET D=8MM <i>X NAI</i>	20	1.05	10.00	18.90
158	51717291197N	FRONT LEFT WHEEL ARCH COVER <i>X NAI</i>	1	186.45	5.00	177.13
159	51717291198	FRT RH RR SECTION WHEEL ARCH COVER <i>X NAI</i>	1	186.45	5.00	177.13
160	51717304045	LH WHEEL HOUSING COVER BOTTOM <i>TAI</i>	1	148.95	5.00	141.50 ✓
161	51717304046	RH WHEEL HOUSING COVER BOTTOM <i>TAI</i>	1	148.95	5.00	141.50 ✓
162	51717325401	COVER WHEEL HOUSING FRT LH <i>X NAI</i>	1	124.35	5.00	118.13
163	51717325402N	COVER WHEEL HOUSING FRT RH <i>X NAI</i>	1	124.35	5.00	118.13
164	32308092206	(DG) AIRBAG MODULE DRIVER'S SIDE <i>RR</i>	1	1,393.35	5.00	1,323.68 ✓
165	32307848335	CONNECTING LINE STEERING WHEEL <i>X NAI</i>	1	78.45	5.00	74.53
166	32307847440N	DECORATIVE TRIM STEERING WHEEL <i>X NAI</i>	1	218.75	5.00	207.81
167	63117442650	RH HEADLIGHT LED TECHNOLOGY <i>RR</i>	1	4,909.40	5.00	4,663.93 ✓
168	63117442649	LH HEADLIGHT LED TECHNOLOGY <i>RR</i>	1	4,909.40	5.00	4,663.93 ✓
169	63177317251	LH FOG LIGHT LED <i>RR</i>	1	441.95	15.00	375.66 ✓
170	63177317252	RH FOG LIGHT LED <i>RR</i>	1	441.95	15.00	375.66 ✓

Total :	67,829.59
ADD GST @ 7% :	4,748.07
Total Amount :	72,577.66

This is a computer generated Quotation. No signature is required.

- Note :
- (1) The validity of this quotation is 14 days from the above date.
 - (2) Parts are subject to availability.
 - (3) Any prices change is without prior notice.

Performance Motors Limited

A member of the Singapore Group
 Co. Reg. No. 137421588N GST Reg. No. M2-002081-X

303, Alexandra Road
 Singapore 159942
 Tel. 63190100 (Sales)
 63190111 (AfterSales)
 Fax. 64747777

189, Kembangan Road
 East Coast Centre
 Singapore 438180
 Tel. 63190488 (AfterSales)
 Fax. 63447777

315, Alexandra Road
 Singapore Business Centre
 Singapore 159944
 Tel. 63190128 (AfterSales)
 63190133/333 (Motorcard)
 Fax. 64794001 (AfterSales)
 64794014 (Motorcard)



QUOTATION

Account No. :	618056	Quotation No. :	512185
Customer Name :	Vantage Automotive Limited	Quotation Date:	24/01/2019
	305 Alexandra Road	Page No. :	8 of 9
	#02-01 Vantage Automotive Centre	Partisan :	P94MOOS
	Singapore 159942	Del. Doc. :	3660698

S/N	PART NUMBER	DESCRIPTION	ISSUE QTY	SELLING PRICE	DISC. %	NET PRICE
171	51757290659	ENGINE COMPARTMENT / CRU	1	203.30	5.00	193.14
172	64509239992	SHIELDING FRT	1			
173	64539127927	CONDENSER AIRCON WITH DRIER AD	10	1,028.45	SN 0.00	10,284.50
174	64216955921	DRIER INSERT	1	256.90	5.00	244.06
175	64216955922	WATER HOSE INLET 2.1	1	46.65	5.00	44.32
176	64216955922	WATER HOSE INLET 2.2	1	54.85	5.00	52.11
177	64216945268	WATER HOSE INLET 1	1	38.45	5.00	36.53
178	64116910544	WATER VALVE	1	376.80	5.00	357.96
179	64119197085	ADDITIONAL WATER PUMP	1	309.20	5.00	293.74
179	64539271894	REFRIGERANT LINE, DOUBLE PIPE X NW	1	307.35	10.00	276.62
180	64506842309N	PRESSURE HOSE CONDENSER - EVAPORATO	1	211.55	10.00	190.40
181	64506842312N	PRESSURE HOSE-COMPRESSOR-CONDENSER	1	273.75	10.00	246.38
182	64509337800N	SUCTION PIPE EVAPORATOR-COMPRESSOR	1	323.55	10.00	291.20
183	64509240651N	BRACKET FRAME	2	13.85	5.00	26.32
184	64509139604N	HOLDER DOUBLE PIPE	1	30.50	5.00	28.98
185	72129252310	(DG) AIRBAG FOR FRONT PASSENGER / NR	1	1,333.20	5.00	1,266.54
186	72127284753	(DG) HEAD AIRBAG LH / NEC	1	666.60	5.00	633.27
187	72127284754	(DG) HEAD AIRBAG RH / NAI	1	666.60	5.00	633.27
188	07147265827	BLIND RIVET / NEC	10	1.10	10.00	9.90
189	07149184212N	FILLISTER HEAD SCREW X NAI	20	1.10	10.00	19.80
190	72117343629	(DG) FRT LH UPPER BELT (SCHWARZ) / OM	1	439.65	10.00	395.69
191	72117343630	(DG) FRT RH UPPER BELT (SCHWARZ) / OM	1	439.65	10.00	395.69
192	11148514202N	ENGINE COVER X NAI	1	409.75	5.00	389.26
193	11148514331N	ACOUSTIC COVER FRONT X NAI	1	161.55	5.00	153.47

Total :	67,829.59
ADD GST @ 7% :	4,748.07
Total Amount :	72,577.66

This is a computer generated Quotation. No signature is required.

- Note : (1) The validity of this quotation is 14 days from the above date.
 (2) Parts are subject to availability.
 (3) Any prices change is without prior notice.

Performance Motors Limited

a member of the Fine Carby Group
 Co. Reg. No. 12741122W GST Reg. No. M2-020081-X



373, Alexandra Road
 Fine Carby Performance Centre
 Singapore 159941
 Tel: 63180222 (Malaya)
 63180111 (AfterSales)
 Fax: 64747777

385, Fenggang Arang Road
 East Coast Centre
 Singapore 41160
 Tel: 63180099 (AfterSales)
 Fax: 63449777

315, Alexandra Road
 Fine Carby Business Centre
 Singapore 159944
 Tel: 63180222 (AfterSales)
 63180111 (GST - Motorist)
 Fax: 64749001 (AfterSales)
 64746024 (Motorist)

QUOTATION

Account No. :	618056	Quotation No. :	512185
Customer Name :	Vantage Automotive Limited	Quotation Date:	24/01/2019
	305 Alexandra Road	Page No. :	9 of 9
	#02-01 Vantage Automotive Centre	Partsman :	P94MOOS
	Singapore 159942	Del. Doc. :	3660698

S/N	PART NUMBER	DESCRIPTION	ISSUE QTY	SELLING PRICE	DISC. %	NET PRICE
194	11148513137N	ACOUSTIC FOAM ☒	1	99.30	5.00	94.34
195	11148581112N	HOLDER COVER ☒	1	31.10	5.00	29.55

hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

LKK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

67,829.59
 - 10,284.50
 57,545.09
 X 20%
 11,509.01
 + 57,545.09
 69,054.10
 + 1,028.45(SN)
 70,082.55
 92913.11

Total : 67,829.59
 ADD GST @ 7% : 4,748.07
 Total Amount : **72,577.66**

This is a computer generated Quotation. No signature is required.

Note : (1) The validity of this quotation is 14 days from the above date.
 (2) Parts are subject to availability.
 (3) Any prices change is without prior notice.

Cost Plus 15%
 83,464.31

Vantage Automotive Limited

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Car Reg No: SKD995C

RO Number: B9 47248

Date: 05 APR 2019

NO.	Supplementary / Check Items Parts	Part Number	Qty	Cost Price	Plus	Ext Price
1	HEADLINING (ANTHRAIT) / CRU	51447382321	1	\$1,601.60	10%	\$1,761.77
2	LH SPRING STRUT BRACKET / BT	31126851591	1	\$114.48	10%	\$125.93
3	LH TENSION STRUT W/ RUBBER MTG / BT	31126851691	1	\$429.42	10%	\$472.36
4	LH WISHBONE BTM W/RUBBER MOL / BT	31126864821	1	\$515.31	10%	\$566.84
5	EXCH.STEERING ELECTR / BT	32106889097	1	\$4,380.12	10%	\$4,818.13
6	ALLOY RIM 9JX19 M DOUBLE SPK 467 (14 14) CRU	36117846786	1	\$1,448.60	10%	\$1,593.46
7	LOCK UPPER SECTION LH / BT	51237308076	1	\$61.74	10%	\$67.91
8	FRT GUIDE SUPPORT / BT	31306851880	1	\$191.17	10%	\$210.29
9	FRT LH SPRING STRUT / BT	37106875083	1	\$1,357.74	10%	\$1,493.51
10	FRT LH GRILLE BASIS / BR	51137294485	1	\$144.00	10%	\$158.40
11	FRT RH GRILLE BASIS / BR	51137294486	1	\$144.00	10%	\$158.40
12	SOUND INSULATING ENGINE HOOD / CRU	51487284629	1	\$248.90	10%	\$273.79
13	CLIP / AEC	51489119216	10	\$7.18	10%	\$7.90
14	COVER FOR AIR DUCT / BR	51647326554	1	\$42.18	10%	\$46.40
15	BLIND RIVET / AEC	51717002953	10	\$10.82	10%	\$11.90
16	FRT LH FRT SECTION WHEEL ARCH COV / CRU	51717290853	1	\$177.13	10%	\$194.84
17	FRT RH FRT SECTION WHEEL ARCH COV / CRU	51717325616	1	\$177.13	10%	\$194.84
18	FRT RH TRIM WHEEL ARCH 20 INCH / CRU	51777378582	1	\$246.91	10%	\$271.60
19	BATTERY CABLE (PLUS POLE) SBK3 / AEC	61129322056	1	\$279.25	10%	\$307.18
20	BLIND RIVET / AEC	66316777308	2	\$2.44	10%	\$2.68
21	SENSOR RAIN/LIGHT/SOLAR/CONDENSA / AEC	61356832975	1	\$335.30	10%	\$368.83
22	LH SPRAY NOZZLE / BR	61677292657	1	\$165.42	10%	\$181.96
23	RH SPRAY NOZZLE / BR	61677292658	1	\$165.42	10%	\$181.96
24	HOSE LINE HEADLIGHT CLEANING SYST / CRU	61677327508	1	\$78.30	10%	\$86.13
25	SWITCH CLUSTER STEERING COLUMN / Short	61319368600	1	\$881.27	10%	\$969.40
26	ICM CONTROL UNIT / Short	34529500006	1	\$2,629.55	10%	\$2,892.51
27	FILLER PIPE WASH CONTAINER X NNI	61667325884	1	\$25.11	10%	\$27.62
28	COVER F WINDSHIELD CLEANING CONT X NNI	61667467951	1	\$9.98	10%	\$10.98
29	ANTI-FREEZE 1.5L / AEC	83512355290	2	\$34.16	10%	\$37.58
30	CABLE SET FRONT END / TAI	61129355468	1	\$348.60	10%	\$383.46
31	INSULATION HOUSING, FAN CONNECTOR / AEC	61136825781	1	\$3.20	10%	\$3.52

32	INSULATION HOUSING, FAN CONNECTOR / NEC	61138364551	1	\$3.20	10%	\$3.52
33	CONTROL UNIT AIR BAG / NEC	65776837359	1	\$927.15	10%	\$1,019.87
34	ULTRASONIC SENSOR BLACK / BR	66209274427	2	\$472.53	10%	\$519.78
35	DECOUPING RING PDC TORQUE CONVER / NEC	66209283203	2	\$9.60	10%	\$10.56
36	SURROUND VIEW CAMERA / TN	66539213990	1	\$649.99	10%	\$714.99
37	A/C TEMPERATURE SENSOR / SHRT	65816936953	1	\$69.30	10%	\$76.23
38	LH EXTERIOR MIRROR W/O GLASS HEAT XNN	51167477885	1	\$1,248.66	10%	\$1,373.53
Parts Total:						\$21,600.56

NO.	Supplementary Labour Charges	Price
1	TO REMOVE FRONT & INNER PANEL TO REPLACE SAFETY BELT, SAFETY BELT PRETENSIONER & ALL RELATED COMPONENTS.	\$280.00 /
2	LABOUR TO REMOVE & REPLACE UNDERCARRIAGE RHF KNUCKLE ARM, RHF LOWER ARM, RH WHEEL BEARING, RHF SHOCK ABSORBER, RH STEERING RACK, ANTI ROLL BAR, RH ANTI ROLL BAR LINK & RH DRIVE SHAFT.	\$450.00 ✓
3	TO RESTITCH FRONT LEFT PASSENGER SEAT (NETT)	\$100.00 X
4	TO CONDUCT COMPUTERISED 4-WHEEL ALIGNMENT (NETT)	\$300.00 /
4	TOWING CHARGES (USING KING DOLLY) FROM 325 VICTORIA ST TO 305 ALEXANDRA RD	\$100.00 /
Total Labour:		\$1,230.00

Total Parts & Labour:	\$22,830.56
GST @ 7%:	\$1,598.14
Grand Total:	\$24,428.70

Raised By Technician	Approved By CSA SIMON	Acknowledge By Parts Assistant	BO Parts: Yes / No ETA: _____
-------------------------	---------------------------------	-----------------------------------	--------------------------------------

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after survey settings
- To display damage & parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

4772 65

VANTAGE AUTOMOTIVE LIMITED

(A Sime Darby Motors Company)
Co. Regs. No. 192600045M GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942

Service Booking: 6477 7368
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300



(FINALIZED REPORT) SERVICE TAX INVOICE RE-PRINT

REPAIR ORDER NO. B9 47248		Date IN 19/03/2019 Payment Term 30 Days From Invoice Customer Service Advisor Melody Teoh Man Lin		Invoice Number Invoice Date ?? Invoice By Melody Teoh Man Lin		Page No. 1 of 4
CUSTOMER INFORMATION				INVOICE TO 24748		
Sime Darby Services Private Limited 305 Alexandra Road #02-01 Vantage Automotive Centre Singapore 159942				MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay #24-01 Hong Leong Building Singapore 048581		
REGISTRATION No. SKD995C	CHASSIS No. WBALS020400U16067	STOCK No. 801342	REGISTRATION DATE 27/12/2016	MODEL BMW X5 XDRIV	MILEAGE 14	
CODE	DESCRIPTION	UNITS	NETT			
	TO CONDUCT OD CLAIM - MSIG DOA: 10/01/2019	0	0.00			
	SUNDRIES	1	60.00			
	LABOUR TO REMOVE, REALIGN, REPLACE AND REPAIR FRONT BUMPER, BONNET, FRONT FENDER LH & RH, SUPPORT PANEL, AND ALL AFFECTED AREAS.	1	1,500.00			
	LABOUR TO PUTTY AND RESPRAY FRONT LH & RH DOOR, FRONT LH & RH FENDER, SUPPORT PANEL, FRONT BUMPER, AND ALL AFFECTED AREAS.	1	1,000.00			
	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING.(NETT)	1	60.00			
	TUFF KOTE, ANTI RUST PRESERVATION, BODY CAVITY PRESERVATIONS. (PER PANEL \$60 NETT)	1	120.00			
	TO REMOVE FRONT & REAR INNER PANEL TO REPLACE SAFETY BELT, SAFETY BELT PRETENSIONER AND ALL RELATED COMPONENT.	1	280.00			
	TO REMOVE, RECTIFY AND REPLACE FRONT LEFT PASSENGER SEAT AIR BAG, RH FRONT PASSENGER AIR BAG, RH ROOF AIR BAG, DRIVER STEERING AIR BAG SYSTEM (NETT)	1	300.00			
	TO MOUNT VEHICLE ON CELETTE BENCH, TO CHECK AND ADJUST CHASSIS ALIGNMENT (NETT)	1	1,680.00			
	TO REMOVE AND REFIX RADIATOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS (NETT)	1	300.00			
	TO REMOVE AND REFIX A/C CONDENSOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS, VACUUM REFILL, RECHARGE AIRCON GAS (NETT)	1	300.00			
	LABOUR TO REMOVE & REPLACE UNDERCARRIAGE RHF KNUCKLE ARM, RHF LOWER ARM, RHF WHEEL BEARING, RHF SHOCK ABSORBER, RH STEERING RACK, ANTI ROLL BAR & RH ANTI ROLL BAR LINK & RH DRIVE SHAFT	1	450.00			
	TO RESTITCH FRONT LEFT PASSENGER SEAT (NETT)	1	100.00			
	LABOUR TO REMOVE AND REFIX FRONT WINDSCREEN, CONDUCT WATER LEAKS TEST (NETT)	1	600.00			
	SEALANT FOR FRONT WINDSCREEN (NETT)	1	60.00			
	FRONT WINDSCREEN INNER SEAL (NETT)	1	50.00			
	IU BRACKET FOR FRONT WINDSCREEN (NETT)	1	26.00			
	TO CONDUCT ECU PROGRAMMING CHECK & CLEAR FAULT CODES, RESTORE ALL PROGRAMME MODULE (NETT)	2	600.00			
	HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME HEADLAMP CORRECTOR (NETT)	1	200.00			
	TO SUPPLY AND INSTALL FRONT NUMBER PLATE WITH HOLDER (NETT)	1	70.00			
	COMPUTERISED 4-WHEEL ALIGNMENT (NETT)	1	300.00			
	SEALANT FOR FRONT LH & RH INNER WHEEL HOUSING (NETT)	1	100.00			
	TOWING CHARGES (USING KING DOLLY) FROM 325 VICTORIA ST TO 305 ALEXANDRA ROAD	1	100.00			
			Sub-Total :		8,256.00	

VANTAGE AUTOMOTIVE LIMITED

(A Sime Darby Motors Company)

Co. Regs. No. 192600045M GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942

Service Bookings: 6477 7368
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300



SERVICE TAX INVOICE

RE-PRINT

REPAIR ORDER NO.	Date IN	Invoice Number	Page No.
B9 47248	19/03/2019		2 of 4
	Payment Term	Invoice Date	
	30 Days From Invoice	77	
	Customer Service Advisor	Invoice By	
	Melody Teoh Man Lin	Melody Teoh Man Lin	

CODE	DESCRIPTION	UNITS	NETT
N 51118059938	RH COVER SPRAY NOZZLE PRIMED	1	54.33 ✓ 59.68
N 51118062496	FRT BUMPER PANLE PRIMED	1	1719.59 ✓ 1,891.55
N 51311925433	W/SCREEN RUBBER BUFFER	10	15.30 16.83 ✓ 16.80
N 51317292394	COVER WINDSHIELD TOP	1	44.28 ✓ 48.71
N 51317292399	GREEN WINDSCREEN	1	1157.33 ✓ 1,273.61
N 51757290659	ENGINE COMPARTMENT SHIELDING FRT	1	193.14 ✓ 212.45
N 83192289285	(DG/SL)W/SCREEN SEALANT	2	236.29 240.97 ✓ 260.46
N 51447382321	HEADLINING (ANTHRAX)	1	1,761.77
N 31126851591	LH SPRING STRUT BRACKET	1	114.48 X A 125.93
N 31126851691	LH TENSION STRUT W/RUBBER MTG	1	429.42 X A 472.36
N 31126864821	LH WISHBONE BTM W/RUBBER MOL	1	566.84
N 32106889097	EXCH.STEERING ELECTR	1	515.31 X A 4,818.13
N 36117846786	ALLOY RIM 92X19 M DOUBLE SPK 467	1	4380.12 X A 1,593.46
N 41007381781	BONNET LH HINGE	1	131.43 ✓ 144.57
N 41007381782	BONNET RH HINGE	1	131.43 ✓ 144.57
N 51117294477	FRT BUMPER CARRIER	1	436.09 ✓ 534.70
N 51117308057	STRUT FRT LH	1	36.96 ✓ 40.66
N 51117308058	STRUT FRT RH	1	36.96 ✓ 40.66
N 51117315959	SUPPORT INSERT LH	1	13.99 ✓ 15.15
N 51117315960	SUPPORT INSERT RH	1	13.99 ✓ 15.15
N 51118054010	FRT SHOCK ABSORBER (M)	1	80.15 ✓ 88.17
N 51118054012	GRILLE MIDDLE BOTTOM (M)	1	97.92 ✓ 107.71
N 51118054013	GRILLE MIDDLE TOP (M)	1	27.30 ✓ 96.03
N 51118064635	GRILLE SIDE CLOSED LH (M)	1	100.40 ✓ 110.44
N 51118064636	GRILLE SIDE CLOSED RH (M)	1	100.35 ✓ 110.39
N 51237308076	LOCK UPPER SECTION LH	1	67.91
N 51237294536	CATCH OPERATOR	1	39.53 ✓ 43.26
N 51237325992	LOCK UPPER SECTION RH	1	61.79 ✓ 67.91
N 51647294491	SUPPORT HEADLIGHT LH	1	71.70 ✓ 78.32
N 51647294492	SUPPORT HEADLIGHT RH	1	71.70 ✓ 78.32
N 51647294507	ADAPTER ELEMENT FRT END LH	1	130.91 ✓ 144.00
N 51647294508	ADAPTER ELEMENT FRT END RH	1	130.91 ✓ 144.00
N 51647294544	MODULE CARRIER RH	1	90.59 ✓ 99.65
N 51648055208	COOLING AIR DUCT (M)	1	315.48 ✓ 350.55
N 51657337092	FRT RH SIDE PANEL REINFORCEMENT	1	44.08 ✓ 48.49
N 51657337342	FRT RH SIDE PANEL	1	991.53 ✓ 1,090.74
N 51717304045	LH WHEEL HOUSING COVER BOTTOM	1	141.50 X ✓ 155.65
N 51748055209	AIR DUCT BRAKE LH (M)	1	52.81 ✓ 61.39
N 51748055210	AIR DUCT BRAKE RH (M)	1	52.81 ✓ 61.39
N 51767294509	FRT ENGINE HOOD SEALING	1	55.30 ✓ 60.93
N 63117442649	LH HEADLIGHT LED TECHNOLOGY	1	466.93 ✓ 5,130.32
N 63117442650	RH HEADLIGHT LED TECHNOLOGY	1	466.93 ✓ 5,130.32
N 31306851880	FRT GUIDE SUPPORT	1	210.29
N 37106875083	FRT LH SPRING STRUT	1	1357.74 X A 1,493.51
N 13718519138	INTAKE SILENCER	1	471.49 X ✓ 518.64
N 13718570289	INTAKE DUCT	1	146.52 X ✓ 161.17
N 51137294485	FRT LH GRILLE BASIS	1	158.10
N 51137294486	FRT RH GRILLE BASIS	1	158.40
N 51487284629	SOUND INSULATING ENGINE HOOD	1	273.79
N 51489119216	CLIP	10	7.90
N 51647326554	COVER FOR AIR DUCT	1	46.40
N 51717002953	BLIND RIVET	10	11.90
N 51717290853	FRT LH FRT SECTION WHEEL ARCH COV	1	194.84
N 51717325616	FRT RH FRT SECTION WHEEL ARCH COV	1	194.84
N 51777378582	FRT RH TRIM WHEEL ARCH 20 INCH	1	246.91 X A 271.60
N 61129322056	BATTERY CABLE (PLUS POLE)SBK3	1	307.18
N 64509239992	CONDENSER AIRCON WITH DRIER	1	1,018.17
N 66316777308	BLIND RIVET	2	2.68
N 61356832975	SENSOR RAIN/LIGHT/SOLAR/CONDENSA	1	368.83

VANTAGE AUTOMOTIVE LIMITED

(A Sincere Darby Motors Company)
Co. Regs. No. 192600045M GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942

Service Booking: 6477 7368
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300



SERVICE TAX INVOICE RE-PRINT

REPAIR ORDER NO. B9 47248	Date IN 19/03/2019	Invoice Number	Page No. 3 of 4
	Payment Term 30 Days From Invoice	Invoice Date ??	
	Customer Service Advisor Melody Teoh Man Lin	Invoice By Melody Teoh Man Lin	

CODE	DESCRIPTION	UNITS	NETT
N 61677292657	LH SPRAY NOZZLE	1	165.42 XA 181.96
N 61677292658	RH SPRAY NOZZLE	1	165.42 XA 181.96
N 61677327508	HOSE LINE HEADLIGHT CLEANING SYST	1	78.30 XA 86.13
N 41007381758	BONNET	1	2244.15 XA 2,468.57
N 51118059937	LH COVER SPRAY NOZZLE PRIMED(M)	1	54.75 XA 59.68
N 61319368600	SWITCH CLUSTER STEERING COLUMN	1	969.40
N 34529500006	ICM CONTROL UNIT	1	2624.53 XA 2,892.51
N 51647294543	MODULE CARRIER LH	1	90.59 XA 99.65
N 51717304046	RH WHEEL HOUSING COVER BOTTOM	1	14.50 XA 155.65
N 51657373541	FRT LH SIDE PANEL	1	991.53 XA 1,090.74
N 51767183752	ADJUSTER	2	11.24 XA 12.48
N 61667325884	FILLER PIPE WASH CONTAINER	1	27.62
N 61667467951	COVER F WINDSHIELD CLEANING CONT	1	10.98
N 83512355290	ANTI-FREEZE 1.5L	2	34.16 XA 37.58
N 07147265827	BLIND RIVET	10	9.90 XA 10.90
N 17427634467	FAN HOUSING WITH FAN	1	1338.16 XA 1,526.98
N 32308092206	(DG)AIRBAG MODULE DRIVER'S SIDE	1	1323.62 XA 1,456.05
N 51459298964	INSTRUMENT PANEL (SCHWARZ/SCHWA	1	5261.64 XA 3,587.80
N 63177317251	LH FOG LIGHT LED	1	375.66 XA 413.23
N 63177317252	RH FOG LIGHT LED	1	375.66 XA 413.23
N 72117343629	(DG)FRT LH UPPER BELT(SCHWARZ)	1	345.69 XA 435.25
N 72117343630	(DG)FRT RH UPPER BELT (SCHWARZ)	1	345.69 XA 435.25
N 72127284753	(DG) HEAD AIRBAG LH	1	685.27 XA 696.60
N 72129252310	(DG) AIRBAG FOR FRT PASSENGER	1	1266.54 XA 1,393.19
N 17117553480	RUBBER MOUNTING	2	20.84 XA 22.38
N 17117553481	SUPPORT RUBBER MOUNTING	2	20.21 XA 33.24
N 17117598791	RUBBER MOUNTING	2	41.25 XA 45.36
N 17118572188	LH MODULE CARRIER	1	64.84 XA 76.82
N 17118572189	RH MODULE CARRIER	1	64.84 XA 76.82
N 17118574000	COVER MODULE CARRIER	1	42.84 XA 52.62
N 17118654431	RADIATOR	1	982.43 XA 1,081.83
N 17517809321	CHARGE-AIR COOLER	1	710.03 XA 781.03
N 61129355468	CABLE SET FRONT END	1	343.60 XA 383.46
N 61136825781	INSULATION HOUSING,FAN CONNECTOR	1	3.20 XA 3.52
N 61138364551	INSULATION HOUSING,FAN CONNECTOR	1	3.20 XA 3.52
N 65776837359	CONTROL UNIT AIR BAG	1	1,019.87
N 66209274427	ULTRASONIC SENSOR BLACK	2	519.78
N 66209283203	DECOUPING RING PDC TORQUE CONVER	2	10.56
N 66539213990	SURROUND VIEW CAMERA	1	649.99 XA 714.99
N 65816936953	A/C TEMPERATURE SENSOR	1	69.30 XA 76.23
N 51167477885	LH EXTERIOR MIRROR W/O GLASS HEAT	1	1243.62 XA 1,373.53
Sub-Total :			57,680.59

Attending CSO : Melody Teoh

Should you require further explanation, please reach me at 92782710

1248.66 + 1680

= 2928.66

= 61,899.92

61775.05

VANTAGE AUTOMOTIVE LIMITED

(A Signa Darby Motors Company)

Cc. Regs. No. 192600045M GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942

Service Booking: 6477 7368
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300



SERVICE TAX INVOICE

RE-PRINT

REPAIR ORDER NO. B9 47248	Date IN	Invoice Number	Page No. 4 of 4
	19/03/2019		
	Payment Term	Invoice Date	
	30 Days From Invoice	??	
	Customer Service Advisor	Invoice By	
	Melody Teoh Man Lin	Melody Teoh Man Lin	

4161.54
62744.45
3192.14

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	65,936.59
Labour Charges	8,256.00	Less Insurance Excess	S\$	0.00
Parts Charges	57,680.59	GST @ 7%	S\$	4,615.56
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	70,552.15
		Less Deposit/Voucher	S\$	0.00
Computer generated invoice. No signature is required.		Amount Payable	S\$	70,552.15

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jan 2019		20 Feb 2019 16:06 Edit Adj Rpt	S\$62,744.45 Edit Estimates	S\$62,744.45 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SIME DARBY SERVICES , Co. Reg. No.: 197501065W		
Vehicle Reg. No.:	SKD995C	Date of Loss:	10/01/2019 17:00 - :59 [24 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 582406	Policy/Cover Note No.:	29100055MCY (Comprehensive) Coverage: 01/10/2018 - 30/09/2019
		Excess:	S\$1,000.00
Repairer:	Vantage Automotive Limited (Alexandra) 305 Alexandra Road #02-01, Vantage Automotive Centre, 159942 Alexandra - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pang Xiu Shi - 6594 2586]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 22/03/2019]		
Driver/Custodian:	LOW ENG SEAH (58 / Male) , NRIC: S1428529F, Tel: +6591880439 Email: NOEMAIL		
Adj Asg. Remarks:	Car in, pls revert with MV		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- MSIG_SG (30/05/2019): Alert - Adj Mandate Approved (S\$62744.45) - SKD995C - Claim Handler: Pang Xiu Sh...
- MSIG_SG (26/02/2019): Alert - Adj Mandate Approved (S\$68675.10) - SKD995C - Claim Handler: Nor Azian B...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKD995C (582406)
OD
Jan 10 2019 5:00PM
[SIME DARBY SERVICES]
Vantage Automotive Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
1	14/01/19 13:29	Vantage Automotive Limited (Alexandra) Accident Statement	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 16:30	Adjuster Immediate Advice	 Load HTM	☐
2	23/05/19 14:13	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On		Thumbnail	Print
MSIG Insurance (Singapore) Pte. Ltd. (HQ)				
1	20/02/19 09:55	Photo	 Load JPG	☒
2	20/02/19 09:56	Photo	 Load JPG	☒
3	20/02/19 09:56	Photo	 Load JPG	☒
4	20/02/19 09:56	Photo	 Load JPG	☒
5	20/02/19 09:56	Photo	 Load JPG	☒
6	20/02/19 09:56	Photo	 Load JPG	☒
7	20/02/19 09:56	Photo	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/02/19 08:41	General View	 Load JPG	☒
2	22/02/19 08:41	General View	 Load JPG	☒
3	22/02/19 08:41	General View	 Load JPG	☒
4	22/02/19 08:41	General View	 Load JPG	☒
5	22/02/19 08:41	General View	 Load JPG	☒
6	22/02/19 08:41	General View	 Load JPG	☒
7	22/02/19 08:41	General View	 Load JPG	☒
8	22/02/19 08:41	General View	 Load JPG	☒
9	22/02/19 08:41	General View	 Load JPG	☒
10	22/02/19 08:41	General View	 Load JPG	☒
11	22/02/19 08:41	General View	 Load JPG	☒
12	22/02/19 08:41	General View	 Load JPG	☒
13	22/02/19 08:41	General View	 Load JPG	☒
14	22/02/19 08:41	General View	 Load JPG	☒
15	22/02/19 08:41	General View	 Load JPG	☒
16	22/02/19 08:41	General View	 Load JPG	☒
17	22/02/19 08:41	General View	 Load JPG	☒
18	22/02/19 08:41	General View	 Load JPG	☒
19	22/02/19 08:41	General View	 Load JPG	☒
20	22/02/19 08:41	General View	 Load JPG	☒
21	22/02/19 08:41	General View	 Load JPG	☒
22	22/02/19 08:41	General View	 Load JPG	☒
23	22/02/19 08:41	General View	 Load JPG	☒
24	22/02/19 08:41	General View	 Load JPG	☒
25	22/02/19 08:41	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
26	22/02/19 08:41	General View	 Load JPG	☒
27	22/02/19 08:41	General View	 Load JPG	☒
28	22/02/19 08:41	General View	 Load JPG	☒
29	22/02/19 08:41	General View	 Load JPG	☒
30	22/02/19 08:41	General View	 Load JPG	☒
31	22/02/19 08:41	General View	 Load JPG	☒
32	22/02/19 08:41	General View	 Load JPG	☒
33	22/02/19 08:41	General View	 Load JPG	☒
34	22/02/19 08:41	General View	 Load JPG	☒
35	22/02/19 08:41	General View	 Load JPG	☒
36	22/02/19 08:41	General View	 Load JPG	☒
37	22/02/19 08:41	General View	 Load JPG	☒
38	22/02/19 08:41	General View	 Load JPG	☒
39	22/02/19 08:41	General View	 Load JPG	☒
40	22/02/19 08:41	General View	 Load JPG	☒
41	22/02/19 08:41	General View	 Load JPG	☒
42	22/02/19 08:41	General View	 Load JPG	☒
43	22/02/19 08:41	General View	 Load JPG	☒
44	22/02/19 08:41	General View	 Load JPG	☒
45	22/02/19 08:41	General View	 Load JPG	☒
46	22/02/19 08:41	General View	 Load JPG	☒
47	22/02/19 08:41	General View	 Load JPG	☒
48	22/02/19 08:41	General View	 Load JPG	☒
49	22/02/19 08:41	General View	 Load JPG	☒
50	22/02/19 08:41	Odometer Reading	 Load JPG	☒
51	22/02/19 08:41	General View	 Load JPG	☒
52	22/02/19 08:41	Chassis Number	 Load JPG	☒
53	22/02/19 08:41	General View	 Load JPG	☒
54	22/02/19 08:41	General View	 Load JPG	☒
55	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
56	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
57	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
58	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
59	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
60	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
61	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
62	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
63	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
64	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
65	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
66	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
67	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
68	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
69	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
70	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
71	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
72	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
73	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
74	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
75	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
76	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
77	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
78	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
79	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
80	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
81	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
82	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
83	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
84	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
85	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
86	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
87	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
88	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
89	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
90	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
91	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
92	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
93	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
94	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
95	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
96	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
97	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
98	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
99	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
100	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
101	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
102	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
103	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
104	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
105	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
106	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
107	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
108	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
109	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
110	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
111	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
112	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
113	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
114	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
115	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
116	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
117	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
118	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
119	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
120	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
121	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
122	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
123	15/05/19 18:24	Photographs of Damaged Parts	 Load JPG	☒
124	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
125	15/05/19 18:24	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
126	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
127	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
128	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
129	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
130	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
131	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
132	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
133	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
134	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
135	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
136	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
137	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
138	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
139	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
140	15/05/19 18:24	Reinspection Photo	 Load JPG	☒
141	15/05/19 18:25	Photo After Spray	 Load JPG	☒
142	15/05/19 18:25	Photo After Spray	 Load JPG	☒
143	15/05/19 18:25	Photo After Spray	 Load JPG	☒
144	15/05/19 18:25	Photo After Spray	 Load JPG	☒
145	15/05/19 18:25	Photo After Spray	 Load JPG	☒
146	15/05/19 18:25	Photo After Spray	 Load JPG	☒
147	15/05/19 18:25	Photo After Spray	 Load JPG	☒
148	15/05/19 18:25	Photo After Spray	 Load JPG	☒
149	15/05/19 18:25	Photo After Spray	 Load JPG	☒
150	15/05/19 18:25	Photo After Spray	 Load JPG	☒
151	15/05/19 18:25	Photo After Spray	 Load JPG	☒
152	15/05/19 18:25	Photo After Spray	 Load JPG	☒
153	15/05/19 18:25	Photo After Spray	 Load JPG	☒
154	15/05/19 18:25	Photo After Spray	 Load JPG	☒
155	15/05/19 18:25	Photo After Spray	 Load JPG	☒
156	15/05/19 18:25	Photo After Spray	 Load JPG	☒
157	17/05/19 16:25	Photographs of Damaged Parts	 Load JPG	☒
158	17/05/19 16:25	Photographs of Damaged Parts	 Load JPG	☒
159	17/05/19 16:25	Photographs of Damaged Parts	 Load JPG	☒
160	17/05/19 16:25	Photographs of Damaged Parts	 Load JPG	☒
161	17/05/19 16:25	Photographs of Damaged Parts	 Load JPG	☒
162	17/05/19 16:25	Photographs of Damaged Parts	 Load JPG	☒
163	17/05/19 16:25	Photographs of Damaged Parts	 Load JPG	☒
164	17/05/19 16:25	Photographs of Damaged Parts	 Load JPG	☒
165	17/05/19 16:25	Photographs of Damaged Parts	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/01/19 15:20	COE / PARF Value	 Load PDF	
2	20/02/19 09:51	Email frm Vantage Automotive (to arrange for survey)	 Load PDF	
3	20/02/19 09:52	ESTIMATE	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	20/02/19 14:48	Email - Parts List Issue	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 16:30	ESTIMATE.pdf	 Load PDF	
2	16/05/19 11:23	SKD995C - Supplementary Form.pdf	 Load PDF	
3	23/05/19 14:27	ESTIMATE & SUPP MARKED.pdf	 Load PDF	

Assessment Reports			1 per page	☒
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
4	17/06/19 13:51	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
			1 per page	☒
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
1	14/01/19 13:29	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
1	14/01/19 13:25	Police Report	 Load JPG	☒
2	14/01/19 13:25	Police Report	 Load JPG	☒
3	14/01/19 13:25	Police Report	 Load JPG	☒
4	14/01/19 13:25	Identification Card	 Load JPG	☒
5	14/01/19 13:25	Driving License	 Load JPG	☒
6	14/01/19 13:26	INSURANCE POLICY	 Load JPG	☒
7	14/01/19 13:27	Accident Photo	 Load JPG	☒
8	14/01/19 13:27	Accident Photo	 Load JPG	☒
9	14/01/19 13:27	Accident Photo	 Load JPG	☒
10	14/01/19 13:27	Accident Photo	 Load JPG	☒
11	14/01/19 13:27	Accident Photo	 Load JPG	☒
12	14/01/19 13:27	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
1	14/01/19 13:23	Accident Sketch Plan	 Load JPG	☒
2	14/01/19 13:23	Accident Sketch Plan	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19003284/ESD3E2

Date: 17/06/2019

REFERENCE

Insured/Claimant:	SIME DARBY SERVICES	Policy No:	29100055MCY	
Date of Loss:	10/01/2019	Nature of Claim:	OD	Claim No: 582406

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD995C		
Make & Model:	BMW X5, 2.0 D XDRIVE25D 7 SEAT LED NAV (A)	Engine No:	52759722B47D20B
Reg. Date:	27/12/2016 (Man. Year: 2016)	Chassis No:	WBALS020400U16067
Colour:	Black	Odometer:	79126 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$220,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/50 R19	Rear Tyre Size:	255/50 R19
Front Left Side:	Firelli 7 mm	Rear Left Side:	Firelli 7 mm
Front Right Side:	Firelli 7 mm	Rear Right Side:	Firelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	87,586.45	56,328.45	31,258.00	35.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,586.00	6,416.00	3,170.00	33.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	97,172.45	62,744.45	34,428.00	35.43
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	96,172.45	61,744.45	34,428.00	35.80
+ GST 7.00/7.00% (S\$)	6,732.07	4,322.11	2,409.96	35.80
Nett Amount (S\$)	102,904.52	66,066.56	36,837.96	35.80

INSPECTION

Date of Assignment: 20/02/2019
Date Inspected: 21/02/2019 Inspected At:

Vantage Automotive Limited (Alexandra)
305 Alexandra Road #02-01, Vantage
Automotive Centre
Singapore 159942

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jun 2019)
Parts:	M1-SUV	BMW X5 2.0 D XDRIVE25D 7 SEAT LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD995C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	120.00 FS	*60.00 FS
2	1		*FRT LH WHEELHOUSE (WCP)	Not Necessary	1,728.19 F	*- F
3	1		*FRT RH WHEELHOUSE (WCP)	Not Necessary	1,728.19 F	*- F
4	1		*BLIND RIVET HEMLOCK 813 (25PCS)(WCP)	Not Necessary	56.31 F	*- F
5	1		*(DG/SL) ADHESIVE GLUE (WCP)	Not Necessary	277.78 F	*- F
6	1		*(DG) CLEANER R1 (100ML) (WCP)	Not Necessary	24.84 F	*- F
7	3		*(S/L) SEAM SEAL 300ML (WCP)	Not Necessary	96.33 F	*- F
8	1		*SUPPORTING STRUT LEFT (WCP)	Not Necessary	434.77 F	*- F
9	1		*SECTION OF LH FRT WHEEL HOUSING (WCP)	Not Necessary	530.01 F	*- F
10	1		*SUPPORTING STRUT RIGHT (WCP)	Not Necessary	434.77 F	*- F
11	1		*SECTION OF RIGHT FRONT W/HOUSING (WCP)	Not Necessary	530.01 F	*- F
12	1		*FRONT LEFT ENGINE SUPPORT (WCP)	Not Necessary	903.02 F	*- F
13	1		*FRONT RIGHT ENGINE SUPPORT (WCP)	Not Necessary	903.02 F	*- F
14	1		*SUPPORT WHEELHOUSE LH (WCP)	Not Necessary	85.74 F	*- F
15	1		*SUPPORT WHEELHOUSE RH (WCP)	Not Necessary	85.74 F	*- F
16	1		*MOUNT CROSS MEMBER LH (WCP)	Not Necessary	92.34 F	*- F
17	1		*MOUNT CROSS MEMBER RH (WCP)	Not Necessary	92.34 F	*- F
18	1		*WHEELHOUSE SUPPORTING STRUT (WCP)	Not Necessary	195.27 F	*- F
19	1		*WHEELHOUSE SUPPORTING STRUT RH (WCP)	Not Necessary	195.27 F	*- F
20	4		*COMPENSATING ELEMENT (WCP)	Not Necessary	32.30 F	*- F
21	1		*LH ENGINE COMPARTMENT PARTITION (WCP)	Not Necessary	462.94 F	*- F
22	1		*RH ENGINE COMPARTMENT PARTITION (WCP)	Not Necessary	462.94 F	*- F
23	1		*LH SUPPORTING STRUT REINFORCEMENT (WCP)	Not Necessary	67.97 F	*- F
24	1		*RH SUPPORTING STRUT REINFORCEMENT (WCP)	Not Necessary	67.97 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*CONNECT. PLATE F LH SIDE PANEL FRAM (WCP)	Not Necessary	156.28 F	*- F
26	1		*RH SIDE PANEL FRAME CONNECT PLATE (WCP)	Not Necessary	156.28 F	*- F
27	1		*ENGINE MOUNT SUPPORT RR LH (WCP)	Not Necessary	53.34 F	*- F
28	1		*ENGINE MOUNT SUPPORT RR RH (WCP)	Not Necessary	53.34 F	*- F
29	1		*FRT LH SIDE PANEL (WCP)	Dented	991.58 F	*991.58 F
30	1		*FRT LH REINFORCEMENT SIDE PANEL (WCP)	Not Necessary	44.08 F	*- F
31	20		*BLIND RIVET (WCP)	Not Necessary	25.20 F	*- F
32	1		*FRT RH SIDE PANEL (WCP)	Dented	991.58 F	*991.58 F
33	1		*FRT RH REINFORCEMENT SIDE PANEL (WCP)	Not Necessary	44.08 F	*- F
34	1		*MODULE CARRIER LH (WCP)	Bent	90.59 F	*90.59 F
35	1		*MODULE CARRIER RH (WCP)	Bent	90.59 F	*90.59 F
36	1		*LH SIDE PANEL CENTRE BRACKET (WCP)	Not Necessary	32.54 F	*- F
37	1		*RH SIDE PANEL CENTRE BRACKET (WCP)	Not Necessary	32.54 F	*- F
38	1		*FRT RH REINFORCEMENT SIDE PANEL (WCP)	Bent	44.08 F	*44.08 F
39	1		*FRT LH AIR DUCT SIDE PANEL (WCP)	Not Necessary	53.15 F	*- F
40	1		*FRT RH AIR DUCT SIDE PANEL (WCP)	Not Necessary	53.15 F	*- F
41	10		*CLAMP (WCP)	Not Necessary	14.40 F	*- F
42	1		*FRT RH REINFORCEMENT SIDE PANEL (WCP)	Not Necessary	44.08 F	*- F
43	1		*FRT LH REINFORCEMENT SIDE PANEL (WCP)	Not Necessary	44.08 F	*- F
44	2		*COVER (WCP)	Not Necessary	12.42 F	*- F
45	1		*BONNET (WCP)	Dented	2,244.15 F	*2,244.15 F
46	1		*BONNET LH HINGE (WCP)	Bent	131.43 F	*131.43 F
47	1		*BONNET RH HINGE (WCP)	Bent	131.43 F	*131.43 F
48	2		*GAS FILLED STRUT ENGINE COMPARTMENT (WCP)	Not Necessary	212.58 F	*- F
49	2		*ADJUSTER (WCP)	Bent	11.34 F	*11.34 F
50	1		*REAR ENGINE HOOD SEALING (WCP)	Not Necessary	36.91 F	*- F
51	1		*FRT ENGINE HOOD SEALING (WCP)	Necessary	55.39 F	*55.39 F
52	1		*LH ENGINE HOOD SEALING (WCP)	Not Necessary	31.40 F	*- F
53	1		*RH ENGINE HOOD SEALING (WCP)	Not Necessary	31.40 F	*- F
54	1		*RR BOWDEN CABLE ENGINE COMP. LID (WCP)	Not Necessary	39.33 F	*- F
55	1		*LOCK F HOOD (WCP)	Not Necessary	52.65 F	*- F
56	1		*LOCK F HOOD RH (WCP)	Not Necessary	102.87 F	*- F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
57	1		*CATCH OPERATOR (WCP)	Bent	39.33 F	*39.33 F
58	1		*LOCK UPPER SECTION RH (WCP)	Bent	61.74 F	*61.74 F
59	1		*LOCK UPPER SECTION LH (WCP)	Not Necessary	42.09 F	*- F
60	1		*LEVER FOR ENGINE HOOD MECHANISM (WCP)	Not Necessary	32.97 F	*- F
61	1		*HOLDER BONNET ACTUATOR (WCP)	Not Necessary	41.75 F	*- F
62	1		*FRT LH DOOR (WCP)	Not Necessary	1,939.28 F	*- F
63	1		*FRT RH DOOR (WCP)	Not Necessary	1,939.28 F	*- F
64	1		*LH UPPER FRONT DOOR HINGE (WCP)	Not Necessary	51.73 F	*- F
65	1		*RH UPPER FRONT DOOR HINGE (WCP)	Not Necessary	51.73 F	*- F
66	1		*LH LOWER FRONT DOOR HINGE (WCP)	Not Necessary	51.73 F	*- F
67	1		*RH LOWER FRONT DOOR HINGE (WCP)	Not Necessary	51.73 F	*- F
68	2		*FRT DOOR BRAKE (WCP)	Not Necessary	184.78 F	*- F
69	1		*LH CRASH PAD DOOR OUTER (WCP)	Not Necessary	33.77 F	*- F
70	1		*CRASH PAD DOOR OUTER RH (WCP)	Not Necessary	33.77 F	*- F
71	1		*INTAKE SILENCER (WCP)	Crushed	471.49 F	*471.49 F
72	1		*AIR FILTER ELEMENT (WCP)	Not Necessary	66.60 F	*- F
73	1		*BKT INTAKE SILENCER BOTTOM RIGHT (WCP)	Not Necessary	37.34 F	*- F
74	1		*BKT INTAKE SILENCER BOTTOM LH (WCP)	Not Necessary	37.34 F	*- F
75	1		*HOLGER INTAKE SILENCER TOP (WCP)	Not Necessary	37.34 F	*- F
76	1		*AIR INTAKE DUCT (WCP)	Not Necessary	204.03 F	*- F
77	1		*INTAKE DUCT (WCP)	Crushed	146.52 F	*146.52 F
78	1		*HOT FILM AIR MASS METER (WCP)	Not Necessary	528.75 F	*- F
79	2		*DECOUPLING ELEMENT (WCP)	Not Necessary	20.70 F	*- F
80	1		*RADIATOR (WCP)	Dented	983.48 F	*983.48 F
81	1		*LH MODULE CARRIER (WCP)	Broken	69.84 F	*69.84 F
82	1		*RH MODULE CARRIER (WCP)	Broken	69.84 F	*69.84 F
83	1		*MODULE CARRIER BOTTOM (WCP)	Not Necessary	85.37 F	*- F
84	1		*RUBBER MOUNTING (2PCS)(WCP)	Torn	41.23 F	*41.23 F
85	1		*COVER MODULE CARRIER (WCP)	Broken	47.84 F	*47.84 F
86	2		*RUBBER MOUNTING (WCP)	Torn	20.34 F	*20.34 F
87	1		*SUPPORT RUBBER MOUNTING (2PCS)(WCP)	Torn	30.21 F	*30.21 F
88	2		*BRACKER F RADIATOR (WCP)	Not Necessary	68.02 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
89	1		*CHARGE-AIR COOLER (WCP)	Dented	710.03 F	*710.03 F
90	1		*FAN HOUSING WITH FAN (WCP)	Broken	1,388.16 F	*1,388.16 F
91	1		*FAN SHROUD (WCP)	Not Necessary	292.60 F	*- F
92	1		*RADIATOR EXPANSION TANK (WCP)	Not Necessary	177.84 F	*- F
93	1		*LEVELLING SWITCH EXPANSION TANK (WCP)	Not Necessary	21.96 F	*- F
94	1		*SCREW CAP FOR EXPANSION TANK (WCP)	Not Necessary	23.40 F	*- F
95	1		*REPAIR KIT SOCKET HOUSING (2 POL) (WCP)	Not Necessary	25.83 F	*- F
96	1		*BUSHING CONTACT (0.75MM2) (WCP)	Not Necessary	4.19 F	*- F
97	1		*HOSE RADIATOR THERMOSTAT (WCP)	Not Necessary	109.35 F	*- F
98	1		*HOSE CYLINDER HEAD (WCP)	Not Necessary	147.39 F	*- F
99	1		*HOSE RADIATOR (WCP)	Not Necessary	76.10 F	*- F
100	1		*HOSE FOR EXPANSION TANK (WCP)	Not Necessary	128.35 F	*- F
101	1		*BRACKET COOLANT HOSE (WCP)	Not Necessary	20.76 F	*- F
102	1		*HOSE RADIATOR (WCP)	Not Necessary	76.10 F	*- F
103	1		*PIPE CYLINDER HEAD (WCP)	Not Necessary	42.28 F	*- F
104	1		*LINE ONE FILTER MODULE TRANS OIL (WCP)	Not Necessary	107.59 F	*- F
105	1		*LINE EGR COOLER CHANGE OVER VALVE 2 (WCP)	Not Necessary	139.84 F	*- F
106	1		*COOLANT TEMPERATURE SENSOR (WCP)	Not Necessary	62.87 F	*- F
107	1		*HOSE EGR COOLER - COOLANT PUMP (WCP)	Not Necessary	49.95 F	*- F
108	1		*HOSE CYLINDER HEAD CHANGOVER VALVE (WCP)	Not Necessary	49.95 F	*- F
109	1		*TRANSMISSION OIL COOLER LINE (WCP)	Not Necessary	151.86 F	*- F
110	1		*TRANSMISSION OIL COOLER (WCP)	Not Necessary	460.35 F	*- F
111	1		*LOCK (WCP)	Not Necessary	14.22 F	*- F
112	1		*CHNAGEOVER VALVE (WCP)	Not Necessary	341.24 F	*- F
113	1		*BKT CHANGE OVER VALVE (WCP)	Not Necessary	63.03 F	*- F
114	1		*BKT CHANGE OVER VALVE (WCP)	Not Necessary	31.49 F	*- F
115	1		*AUXILIARY WATER PUMP (WCP)	Not Necessary	136.43 F	*- F
116	1		*BRKT COOLANT HOSE (WCP)	Not Necessary	15.11 F	*- F
117	1		*COOLANT PUMP (WCP)	Not Necessary	287.00 F	*- F
118	1		*INTERMEDIATE PLATE ASSY (WCP)	Not Necessary	52.25 F	*- F
119	1		*ENG. SUPPORTING BKT LH (WCP)	Not Necessary	185.35 F	*- F
120	1		*ENG.SUPPORTING BKT RH (WCP)	Not Necessary	162.21 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
121	1		*ENGINE MOUNTING LH (WCP)	Not Necessary	205.52 F	*- F
122	1		*ENGINE MOUNTING RH (WCP)	Not Necessary	178.70 F	*- F
123	1		*GEARBOX SUPPORT (WCP)	Not Necessary	257.26 F	*- F
124	1		*GEARBOX MOUNTING (WCP)	Not Necessary	178.70 F	*- F
125	1		*GREEN WINDSCREEN (RLSBS) (WCP)	Broken	1,157.83 F	*1,157.83 F
126	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) (2PCS)(WCP)	Necessary	236.79 F	*236.79 F
127	10		*W/SCREEN RUBBER BUFFER (WCP)	Necessary	15.30 F	*15.30 F
128	1		*COVER WINDSHIELD TOP (WCP)	Necessary	44.28 F	*44.28 F
129	1		*FRT BUMPER PANEL PRIMED (M PDC / ICAM (WCP)	Broken	1,719.59 F	*1,719.59 F
130	1		*LH COVER SPRAY NOZZLE PRIMED (M) (WCP)	Broken	54.25 F	*54.25 F
131	1		*RH COVER SPRAY NOZZLE PRIMED (M) (WCP)	Broken	54.25 F	*54.25 F
132	1		*COVER TOWING EYE PRIMED (M) (WCP)	Not Necessary	54.25 F	*- F
133	1		*TRIM AIR DUCT LH (M) (WCP)	Not Necessary	95.24 F	*- F
134	1		*TRIM AIR DUCT RH (M) (WCP)	Not Necessary	100.25 F	*- F
135	1		*FRT BUMPER CARRIER (WCP)	Dented	486.09 F	*486.09 F
136	1		*FRT SHOCK ABSORBER (M) (WCP)	Bent	80.15 F	*80.15 F
137	1		*ADAPTER ELEMENT FRT END LH (WCP)	Broken	130.91 F	*130.91 F
138	1		*ADAPTER ELEMENT FRT END RH (WCP)	Broken	130.91 F	*130.91 F
139	1		*STRUT FRT LH (WCP)	Bent	36.96 F	*36.96 F
140	1		*STRUT FRT RH (WCP)	Bent	36.96 F	*36.96 F
141	1		*SUPPORT HEADLIGHT LH (WCP)	Bent	71.20 F	*71.20 F
142	1		*SUPPORT HEADLIGHT RH (WCP)	Bent	74.95 F	*71.20 F
143	1		*SUPPORT INSERT LH (WCP)	Bent	13.77 F	*13.77 F
144	1		*SUPPORT INSERT RH (WCP)	Bent	13.77 F	*13.77 F
145	1		*GRILLE MIDDLE TOP (M) (WCP)	Broken	90.90 F	*87.30 F
146	1		*GRILLE MIDDLE BOTTOM (M) (WCP)	Broken	101.84 F	*97.92 F
147	1		*GRILLE SIDE OPEN LH (M) (WCP)	Not Necessary	108.68 F	*- F
148	1		*GRILLE SIDE OPEN LH (M) (WCP)	Not Necessary	134.91 F	*- F
149	1		*GRILLE SIDE CLOSED LH (M) (WCP)	Broken	104.67 F	*100.40 F
150	1		*GRILLE SIDE CLOSED RH (M) (WCP)	Broken	104.58 F	*100.35 F
151	1		*AIR DUCT BRAKE LH (M) (WCP)	Broken	55.81 F	*55.81 F
152	1		*AIR DUCT BRAKE RH (M) (WCP)	Broken	55.81 F	*55.81 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
153	1		*COOLING AIR DUCT (M) (WCP)	Broken	318.68 F	*318.68 F
154	1		*INSTRUMENT PANEL (SCHWARZ / SCHWARZ) (WCP)	Broken	3,261.64 F	*3,261.64 F
155	1		*SET SOUND INSULATION (WCP)	Not Necessary	181.50 F	*- F
156	1		*TRIM CENTRE SPEAKER METAL (SCHWARZ) (WCP)	Not Necessary	35.67 F	*- F
157	20		*BUMPER RIVET (WCP)	Not Necessary	9.00 F	*- F
158	20		*EXPANDING RIVET D=8MM (WCP)	Not Necessary	18.90 F	*- F
159	1		*FRONT LEFT WHEEL ARCH COVER (WCP)	Not Necessary	177.13 F	*- F
160	1		*FRT RH RR SECTION WHEEL ARCH COVER (WCP)	Not Necessary	177.13 F	*- F
161	1		*LH WHEEL HOUSING COVER BOTTOM (WCP)	Torn	141.50 F	*141.50 F
162	1		*RH WHEEL HOUSING COVER BOTTOM (WCP)	Torn	141.50 F	*141.50 F
163	1		*COVER WHEEL HOUSING FRT LH (WCP)	Not Necessary	118.13 F	*- F
164	1		*COVER WHEEL HOUSING FRT RH (WCP)	Not Necessary	118.13 F	*- F
165	1		*(DG) AIRBAG MODULE DRIVERS SIDE (WCP)	Broken	1,323.68 F	*1,323.68 F
166	1		*CONENCTING LINE STEERING WHEEL (WCP)	Not Necessary	74.53 F	*- F
167	1		*DECORATIVE TRIM STEERING WHEEL (WCP)	Not Necessary	207.81 F	*- F
168	1		*RH HEADLIGHT LED TECHNOLOGY (WCP)	Broken	4,663.93 F	*4,663.93 F
169	1		*LH HEADLIGHT LED TECHNOLOGY (WCP)	Broken	4,663.93 F	*4,663.93 F
170	1		*LH FOG LIGHT LED (WCP)	Broken	375.66 F	*375.66 F
171	1		*RH FOG LIGHT LED (WCP)	Broken	375.66 F	*375.66 F
172	1		*ENGINE COMPARTMENT SHIELDING FRT (WCP)	Crushed	193.14 F	*193.14 F
173	1		*CONDENSER AIRCON WITH DRIER (10PCS)(WCP)	Dented-1pc only	10,284.50 FS	*1,018.17 FS
174	1		*DRIER INSERT (WCP)	Not Necessary	244.06 F	*- F
175	1		*WATER HOSE INLET 2.1 (WCP)	Not Necessary	44.32 F	*- F
176	1		*WATER HOSE INLET 2.2 (WCP)	Not Necessary	52.11 F	*- F
177	1		*WATER HOSE INLET 1 (WCP)	Not Necessary	36.53 F	*- F
178	1		*WATER VALVE (WCP)	Not Necessary	357.96 F	*- F
179	1		*ADDITIONAL WATER PUMP (WCP)	Not Necessary	293.74 F	*- F
180	1		*REFRIGERANT LINE, DOUBLE PIPE (WCP)	Not Necessary	276.62 F	*- F
181	1		*PRESSURE HOSE CONDENSER - EVAPORATO (WCP)	Not Necessary	190.40 F	*- F
182	1		*PRESSURE HOSE-COMPRESSOR-CONDENSER (WCP)	Not Necessary	246.38 F	*- F
183	1		*SUCTION PIPE EVAPORATOR-COMPRESSOR (WCP)	Not Necessary	291.20 F	*- F
184	1		*BRACKET FRAME (WCP)	Not Necessary	26.32 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
185	1		*HOLDER DOUBLE PIPE (2PCS)(WCP)	Not Necessary	28.98 F	*- F
186	1		*(DG) AIRBAG FOR FRONT PASSENGER (WCP)	Broken	1,266.54 F	*1,266.54 F
187	1		*(DG) HEAD AIRBAG LH (WCP)	Necessary	633.27 F	*633.27 F
188	1		*(DG) HEAD AIRBAG RH (WCP)	Not Necessary	633.27 F	*- F
189	10		*BLIND RIVET (WCP)	Necessary	9.90 F	*9.90 F
190	20		*FILLISTER HEAD SCREW (WCP)	Not Necessary	19.80 F	*- F
191	1		*(DG) FRT LH UPPER BELT (SCHWARZ) (WCP)	Damaged	395.69 F	*395.69 F
192	1		*(DG) FRT RH UPPER BELT (SCHWARZ) (WCP)	Damaged	395.69 F	*395.69 F
193	1		*ENGINE COVER (WCP)	Not Necessary	389.26 F	*- F
194	1		*ACOUSTIC COVER FRONT (WCP)	Not Necessary	153.47 F	*- F
195	1		*ACOUSTIC FOAM (WCP)	Not Necessary	94.34 F	*- F
196	1		*HOLDER COVER (WCP)	Not Necessary	29.55 F	*- F
197	1		*HEADLINING (ANTHRAIT) (WCP)	Crushed	1,601.60 F	*1,601.60 F
198	1		*LH SPRING STRUT BRACKET (WCP)	Bent	114.48 F	*114.48 F
199	1		*LH TENSION STRUT W/RUBBER MTG (WCP)	Bent	429.42 F	*429.42 F
200	1		*LH WISHBONE BTM W/RUBBER MOL (WCP)	Bent	515.31 F	*515.31 F
201	1		*EXCH.STEERING ELECTR (WCP)	Bent	4,380.12 F	*4,380.12 F
202	1		*ALLOY RIM 9JX19 M DOUBLE SPK 467 (FRT LH) (WCP)	Cut	1,448.60 F	*1,448.60 F
203	1		*LOCK UPPER SECTION LH (WCP)	Bent	61.74 F	*61.74 F
204	1		*FRT GUIDE SUPPORT (WCP)	Bent	191.17 F	*191.17 F
205	1		*FRT LH SPRING STRUT (WCP)	Bent	1,357.74 F	*1,357.74 F
206	1		*FRT LH GRILLE BASIS (WCP)	Broken	144.00 F	*144.00 F
207	1		*FRT RH GRILLE BASIS (WCP)	Broken	144.00 F	*144.00 F
208	1		*SOUND INSULATING ENGINE HOOD (WCP)	Crushed	248.90 F	*248.90 F
209	1		*CLIP (10PCS)(WCP)	Necessary	7.18 F	*7.18 F
210	1		*COVER FOR AIR DUCT (WCP)	Broken	42.18 F	*42.18 F
211	1		*BLIND RIVET (10PCS)(WCP)	Necessary	10.82 F	*10.82 F
212	1		*FRT LH FRT SECTION WHEEL ARCH COV (WCP)	Crushed	177.13 F	*177.13 F
213	1		*FRT RH FRT SECTION WHEEL ARCH COV (WCP)	Crushed	177.13 F	*177.13 F
214	1		*FRT RH TRIM WHEEL ARCH 20 INCH (WCP)	Crushed	246.91 F	*246.91 F
215	1		*BATTERY CABLE (PLUS POLE) SBK3 (WCP)	Necessary	279.25 F	*279.25 F
216	2		*BLIND RIVET (WCP)	Necessary	2.44 F	*2.44 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
217	1		*SENSOR RAIN / LIGHT / SOLAR/ CONDENSE (WCP)	Necessary	335.30 F	*335.30 F
218	1		*LH SPRAY NOZZLE (WCP)	Broken	165.42 F	*165.42 F
219	1		*RH SPRAY NOZZLE (WCP)	Broken	165.42 F	*165.42 F
220	1		*HOSE LINE HEADLIGHT CLEANING SYST (WCP)	Crushed	78.30 F	*78.30 F
221	1		*SWITCH CLUSTER STEERING COLUMN (WCP)	Shorted	881.27 F	*881.27 F
222	1		*ICM CONTROL UNIT (WCP)	Shorted	2,629.55 F	*2,629.55 F
223	1		*FILLER PIPE WASH CONTAINER (WCP)	Not Necessary	25.11 F	*- F
224	1		*COVER F WINDSHIELD CLEANING CONT (WCP)	Not Necessary	9.98 F	*- F
225	2		*ANTI-FREEZE 1.5L (WCP)	Necessary	34.16 F	*34.16 F
226	1		*CABLE SET FRONT END (WCP)	Torn	348.60 F	*348.60 F
227	1		*INSULATION HOUSING, FAN CONNECTOR (WCP)	Necessary	3.20 F	*3.20 F
228	1		*INSULATION HOUSING, FAN CONNECTOR (WCP)	Necessary	3.20 F	*3.20 F
229	1		*CONTROL UNIT AIR BAG (WCP)	Necessary	927.15 F	*927.15 F
230	1		*ULTRASONIC SENSOR BLACK (2PCS)(WCP)	Broken	472.53 F	*472.53 F
231	2		*DECOUPING RING PDC TORQUE CONVER (WCP)	Necessary	9.60 F	*9.60 F
232	1		*SURROUND VIEW CAMERA (WCP)	Torn	649.99 F	*649.99 F
233	1		*A/C TEMPERATURE SENSOR (WCP)	Shorted	69.30 F	*69.30 F
234	1		*LH EXTERIOR MIRROR W/O GLASS HEAT (WCP)	Not Necessary	1,248.66 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	87,586.45	51,305.70
+ Margin on L,N Items 0.00/10.00% (\$\$)	0.00	5,022.75
Total Parts (\$\$)	87,586.45	56,328.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING	New	120.00	60.00
2	SEALANT FOR FRONT LH & RH INNER WHEEL HOUSING	New	150.00	100.00
3	TUFF KOTE - BODY CAVITY PRESERVATION	New	150.00	120.00
4	TO REPLACE FRONT BUMPER, BONNET, FRONT LHS & RHS FENDER, SUPPORT PANEL, AND ALL OTHER AFFECTED AREAS	New	1,750.00	1,500.00
5	TO SPRAY PAINT FRONT BUMPER, BONNET, FRONT LHS & RHS FENDER, SUPPORT PANEL AND ALL OTHER AFFECTED PARTS AND AREAS	New	1,400.00	1,000.00
6	TO MOUNT VEHICLE ON CELETTE BENCH, TO CHECK AND ADJUST CHASSIS ALIGNMENT	New	1,680.00	0.00
7	HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME HEADLAMP CORRECTOR	New	200.00	200.00
8	TO REMOVE AND REPLACE FRONT WINDSCREEN, CONDUCT WATER LEAKS TEST	New	600.00	600.00
9	SEALANT FOR FRONT WINDSCREEN	New	60.00	60.00
10	INNER SEAL FOR FRONT WINDSCREEN	New	50.00	50.00
11	IU BRACKET FOR FRONT WINDSCREEN	New	26.00	26.00
12	TO CONDUCT ECU PROGRAMMING, CHECK AND CLEAR FAULT CODES	New	600.00	600.00
13	TO REMOVE, RECTIFY AND REPLACE FRONT LEFT PASSENGER SEAT AIRBAG SYSTEM	New	300.00	300.00
14	TO REMOVE AND REFIX RADIATOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS	New	600.00	300.00
15	TO REMOVE AND REFIX A/C CONDENSOR, CONDUCT PRESSURE TEST CHECK FOR LEAKS, VACUUM REFILL, RECHARGE AIRCON GAS	New	600.00	300.00
16	TO SUPPLY AND INSTALL FRONT NUMBER PLATE WITH HOLDER	New	70.00	70.00
17	TO REMOVE FRONT & INNER PANEL TO REPLACE SAFETY BELT, SAFETY BELT PRETENSIONER & ALL RELATED COMPONENTS	New	280.00	280.00
18	LABOUR TO REMOVE & REPLACE UNDERCARRIAGE RH F KNUCKLE ARM, RH F LOWER ARM, RH WHEEL BEARING, RH F SHOCK ABSORBER, RH STEERING RACK, ANTI ROLL BAR, RH ANTI ROLL BAR LINK & RH DRIVE SHAFT	New	450.00	450.00
19	TO RESTITCH FRONT LEFT PASSENGER SEAT	New	100.00	0.00
20	TO CONDUCT COMPUTERISED 4-WHEEL ALIGNMENT	New	300.00	300.00
21	TOWING CHARGES (USING KING DOLLY) FROM 325 VICTORIA ST TO 305 ALEXANDRA RD	New	100.00	100.00
Gross Labour Cost (\$\$)			9,586.00	6,416.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >