



INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00016750	Date of Loss:	17/02/2019
Vehicle Reg. No.:	SKL8139M	Driveable?	
Driver Age/Info:	52 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PANG CHONG NING	Contact No:	+6581213112
Driver:	PANG CHONG NING		

Make/Model:	AUDI A6, 2.0 TFSI MU (A)	Vehicle Reg. Date:	26/12/2013
Vehicle Colour:	WHITE		
Engine No:	CDN379977	Chassis No:	WAUZZZ4G8EN060155
Odometer:	1 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 8

Description of Accident/Loss: REFER TO THE POLICE REPORT

Remarks: VEHICLE IN ETHOZ BUKIT BATOK

Present Location: ETHOZ PROTECT PTE LTD (BUKIT BATOK)

COST OF CLAIMS

	Amount
Parts	5,798.00
Miscellaneous Items	60.00
Labour	2,470.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	8,328.00
+ GST 7.00% (\$\$)	582.96
Nett Amount (\$\$)	8,910.96

This claim is handled by: KENNETH CORNELIUS / SHAH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference *Shah*

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 20 Feb 2019)

Parts: 143

AUDI A6 2.0 TFSI MU (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: ETHOZ Protect Pte Ltd/SKL8139M/20/02/2019 12:10

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Steve (LKR) 21/2/19 5:30pm
83228813
00 not Antihase
Excise - 609
P/P
5 days
Resy Dismate before b af spray

No.	Qty	Part No.	Particulars	%Disc	%Depr.	Amount
1	1		*FRONT BUMPER / <i>BR</i>	0.00	0.00	*980.00 F
2	1		*FRONT BUMPER RETAINER RH / <i>BR</i>	0.00	0.00	*32.00 F
3	1		*FRONT BUMPER CLIPS / <i>NEC</i>	0.00	0.00	*85.00 F
4	1		*FRONT ENGINE LOWER DUST COVER / <i>BR</i>	0.00	0.00	*310.00 F
5	1		*FRONT GRILLE ASSY / <i>BR</i>	0.00	0.00	*550.00 F
6	1		*FRONT BUMPER SIDE GARNISH RH / <i>MIS</i>	0.00	0.00	*90.00 F
7	1		*FRONT AIRGUIDE RH ?	0.00	0.00	*36.00 F
8	1		*INTERCOOLER ASSY / <i>BT</i>	0.00	0.00	*480.00 F
9	1		*INTERCOOLER HOSE RH ?	0.00	0.00	*245.00 F
10	1		*AIRCON CONDENSER ?	0.00	0.00	*580.00 F
11	1		*RADIATOR ASSY ?	0.00	0.00	*320.00 F
12	1		*SUPPORT PANEL ASSY ?	0.00	0.00	*520.00 F
13	1		*FRONT DOOR RH / <i>DO</i>	0.00	0.00	*1,450.00 F
14	1		*FRONT DOOR WEATHERSTRIP RH / <i>NEC</i>	0.00	0.00	*120.00 F
15	1		*REAR DOOR RH <i>R</i> REPAIR	0.00	0.00	-
16	1		*ROCKER PANEL RH <i>x R</i> REPAIR	0.00	0.00	-

F=Franchise part.

Total Parts (\$\$)

5,798.00

ETHOZ Protect Pte Ltd/SKL8139M/20/02/2019 12:10. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	COOLANT	30.00 ✓
2	1	FRONT NUMBER PLATE NC	30.00 X
Sub Total (S\$)			60.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR TO FACILITATE REPAIR 280	New 660/	1,000.00
2	TO RESPRAY AFFECTED AREAS 290	New 800/	1,200.00
3	TO TOP UP AIRCON GAS	New /	120.00
4	TO REMOVE AND TRANSFER FRONT DOOR COMPONENTS	New 60/	150.00
Gross Labour Cost (S\$)			2,470.00

ETHOZ Protect Pte Ltd/SKL8139M/20/02/2019 12:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

Company Registration No. 199005791M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: