



## Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 21.02.2019

India International Insurance Pte Ltd

64 Cecil Street #04/#05

IOB Building

Singapore 049711

Attn: Motor Claims Dept

### RE: ESTIMATE COST OF REPAIR TO VEHICLE HONDA VEZEL 1.5 SLE583R (2015)

#### To Supply

|                    |                             |    |        |
|--------------------|-----------------------------|----|--------|
| 1 ) 1pc            | Front bumper <i>repair</i>  | \$ | 730.00 |
| 2 ) 1set           | Front bumper clip <i>no</i> | \$ | 30.00  |
| 3 ) 1pc            | Front grille right chrome ? | \$ | 60.00  |
| Sub total Parts    |                             | \$ | 820.00 |
| Less: 20% discount |                             | \$ | 164.00 |
|                    |                             | \$ | 656.00 |

#### L/charges

- |     |                                                                                            |    |                       |
|-----|--------------------------------------------------------------------------------------------|----|-----------------------|
| 1 ) | To remove & replace front bumper & front grille right chrome. Align & adjust front bumper. | \$ | <del>250.00</del> 150 |
| 2 ) | To putty & respray painting front bumper & front grille right chrome. To polish            | \$ | <del>300.00</del> 200 |

*Rahul*  
*Hp 90010568*

|                     |    |                 |
|---------------------|----|-----------------|
| Sub total L/charges | \$ | 550.00          |
| Estimated Total     | \$ | <u>1,206.00</u> |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*2 days*

*L/S*

*21/02/19 @ 1530*

*Resy after repair*