

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III19003308/KGA3Q2

**Date:** 08/10/2020

#### REFERENCE

|   |                             |                          |
|---|-----------------------------|--------------------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No:                  | MCOM0015                 |
| <b>Claimant</b>   |                             |                          |
| <b>Vehicle No :</b> SHD9141B                            | <b>Insured Vehicle No :</b> | SHC3094Z                 |
| Date of Loss: 16/02/2019                                | Nature of Claim:            | TP Claim No: MCT19020861 |

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SHD9141B</b>                   |             |                   |
| Make & Model:               | TOYOTA PRIUS, 1.8 (A)             | Engine No:  | 2ZR2B99590        |
| Reg. Date:                  | 17/01/2019 (Man. Year: 2018)      | Chassis No: | JTDKB3FU003079215 |
| Colour:                     | Metallic Pearl White/Red          | Odometer:   | 6482 km           |
| Engine Capacity:            | 1798 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

#### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/65R15     | Rear Tyre Size:  | 195/65R15     |
| Front Left Side:  | Yokohama 9 mm | Rear Left Side:  | Yokohama 9 mm |
| Front Right Side: | Yokohama 9 mm | Rear Right Side: | Yokohama 9 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b>     | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-----------------------|-------------------|---------------|
| Parts   | 4,642.77          | 906.90                | 3,735.87          | 80.47         |
| Miscellaneous Items                             | 0.00              | 0.00                  | 0.00              |               |
| Labour  | 7,070.00          | 1,060.00              | 6,010.00          | 85.01         |
| Paintwork Labour                                | 0.00              | 0.00                  | 0.00              |               |
| Towing  | 0.00              | 0.00                  | 0.00              |               |
| <b>Gross Total (S\$)</b>                        | <b>11,712.77</b>  | <b>1,966.90</b>       | <b>9,745.87</b>   | <b>83.21</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | <b>819.89</b>     | <b>137.68</b>         | <b>682.21</b>     | <b>83.21</b>  |
| <b>Nett Amount (S\$)</b>                        | <b>12,532.66</b>  | <b>2,104.58</b>       | <b>10,428.08</b>  | <b>83.21</b>  |
| <b>+ Loss of Use (3.5 x S\$40.00/day) (S\$)</b> |                   | 140.00                |                   |               |
| <b>+ Car Rental (3.5 x S\$113.40/day) (S\$)</b> |                   | 396.90                |                   |               |
|   |                   | <b>(S\$) 2,641.48</b> |                   |               |
| <b>Liabile Amount (50.00%) (S\$)</b>            |                   | <b>1,320.74</b>       |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>1,300.00</b>       |                   |               |

#### INSPECTION

|                             |                          |  |
|-----------------------------|--------------------------|--|
| Date of Assignment:         | 20/02/2019               |  |
| Date Inspected:             | 20/02/2019 Inspected At: | Trans Cab Auto Services Pte Ltd -<br>Amk (HQ)<br>No 2 Ang Mo Kio St 63<br>Singapore 569111 |
| Estimated Period of Repair: | 2.5 days                 |  |

---

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                            |  |
|----------------------------|--|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 02 Sep 2020)  |
| <b>Parts:</b> 144          | TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)  |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for SHD9141B)  |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition     | Repairer's  | Amount     |
|-----|-----|----------|----------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *REAR BUMPER SIDE LH             | Serviceable   | 232.00 FL   | *- FL      |
| 2   | 1   |          | *REAR FENDER LH                  | Repair        | 817.50 FL   | *- FL      |
| 3   | 1   |          | *REAR BUMPER                     | Mtg Cracked   | 458.60 FL   | *458.60 FL |
| 4   | 1   |          | *REAR BUMPER RE-INFORCEMENT      | Repair        | 318.80 FL   | *- FL      |
| 5   | 1   |          | *REAR BUMPER TOWING COVER        | Serviceable   | 14.70 FL    | *- FL      |
| 6   | 1   |          | *REAR BUMPER UNDER COVER (BLACK) | Serviceable   | 552.60 FL   | *- FL      |
| 7   | 1   |          | *REAR BUMPER SIDE RETAINER LH    | Distorted     | 112.70 FL   | *112.70 FL |
| 8   | 1   |          | *REAR BUMPER SIDE RETAINER RH    | Serviceable   | 112.70 FL   | *- FL      |
| 9   | 1   |          | *REAR WHEEL RIM                  | Serviceable   | 1,570.55 FS | *- FS      |
| 10  | 1   |          | *REAR WHEEL RIM COVER            | Serviceable   | 175.80 FS   | *- FS      |
| 11  | 1   |          | *CLIP,REAR FENDER LINDER         | Not Necessary | 22.00 FS    | *- FS      |
| 12  | 1   |          | *REAR DOOR STICKER 6555-3333     | Necessary     | 80.00 FS    | *60.00 FS  |
| 13  | 1   |          | *TAILLAMP LOWER RH               | Serviceable   | 548.40 FL   | *- FL      |
| 14  | 1   |          | *TAILLAMP UPPER RH               | Cracked       | 557.90 FL   | *557.90 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>5,574.25</b> | <b>1,189.20</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 931.48          | 282.30          |
| <b>Total Parts (\$\$)</b>                                  | <b>4,642.77</b> | <b>906.90</b>   |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars  | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>             |  |          |                 |                 |
| 1                               | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION   | New      | 3,000.00        | 660.00          |
| 2                               | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME | New      | 3,000.00        | 400.00          |
| 3                               | TO RUST-PROOFING OF THE AFFECTED AREAS   | New      | 170.00          | 0.00            |
| 4                               | TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST  | New      | 170.00          | 0.00            |
| 5                               | TO TRANSFER OF DOOR FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST  | New      | 170.00          | 0.00            |
| 6                               | TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST  | New      | 170.00          | 0.00            |
| 7                               | TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST   | New      | 170.00          | 0.00            |
| 8                               | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT  | New      | 220.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>7,070.00</b> | <b>1,060.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >