

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 19.02.2019

Vehicle No: SLU1473J

Model: BMW 520 SE AUTO

Chassis: WBAJC32030G867973 - 2017

Not Authorized
Presuney B4point

8939.01

88,758.74

6day

Third Party Insurer: AIG

Third Party Veh No: SLE5601P

Date of Accident: 18.02.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER 1844.50 B1	1	\$2,645.00	✓
2	REAR BUMPER REVERSE SENSOR LH 256. Shan	1	\$323.00	✓
3	REAR BUMPER REVERSE SENSOR RING LH (RUBBER SEAL) m	1	\$8.00	✓
4	REAR BUMPER LOWER GARNISH CM	1	\$80.00	✓
5	REAR BUMPER LOWER DIFFUSER CONDR R	1	\$300.00	✓
6	REAR BUMPER REINFORCEMENT 967.25 R	1	\$1,507.75	✓
7	REAR BUMPER INNER UPPER RETAINER GUIDE CM	1	\$111.00	✓
8	REAR BUMPER INNER RETAINER GUIDE CM	1	\$151.70	✓
9	REAR BUMPER INNER SIDE RETAINER GUIDE LH D.1	1	\$110.00	✓
10	REAR BUMPER UPPER SIDE FOIL LH Sn	1	\$30.00	✓
11	REAR BUMPER CLIPS m	12	@\$5.50 - \$66.00	✓
12	REAR KICK SENSOR UPPER nd	1	\$80.00	✓
13	REAR KICK SENSOR LOWER nd	1	\$90.00	✓
14	REAR END PANEL R	1	\$364.50	✓
15	REAR EXHAUST PIPE ASSY R	1	\$2,390.00	✓
16	REAR EXHAUST PIPE TAIL LH (CHROME) nd	1	\$280.00 260	✓
17	REAR EXHAUST PIPE HEAT SHIELD UPPER A9 R	1	\$80.00	✓
18	REAR EXHAUST PIPE HEAT SHIELD LOWER CENTER R	1	\$190.00	✓
19	REAR EXHAUST PIPE HEAT SHIELD LH A6	1	\$292.30	✓
20	REAR EXHAUST PIPE HEAT SHIELD RH A6	1	\$292.30	✓
21	REAR EXHAUST PIPE HANGER RUBBER (MOUNTING) Sn	3	@\$68.00 - \$204.00	✓
22	REAR EXHAUST PIPE TAIL RH (CHROME) Sn	1	\$260.00	✓
23	REAR EXHAUST PIPE HEAT SHIELD NUT (PLASTIC) Sn	8	@\$67.00 - \$536.00	✓
24	REAR BOOT LID	1		REPAIR
25	REAR QUATER PANEL LH	1		REPAIR
			SUB TOTAL	\$10,309.35
			LESS 5%	-\$515.48
			PARTS TOTAL	\$9,793.87

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR END PANEL JOINT SEALANT	1		~ \$80.00
			S/N TOTAL	\$80.00

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 19.02.2019

Third Party Insurer: AIG

Vehicle No: SLU1473J

Third Party Veh No: SLE5601P

Model: BMW 520 SE AUTO

Date of Accident: 18.02.2019

Chassis: WBAJC32030G867973 - 2017

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REFIX/REPLACE REAR ACCIDENT AREAS & ETC. BACK TO ORIGINAL
CONDITION

\$1,000.00 *600*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS

660 \$900.00

TO TUFF KOTE / ANTI-RUST

\$80.00 *30*

TO REMOVE & REFIX/REPLACE REAR BUMPER REVERSE SENSOR, REAR KICK SENSOR & ETC

\$150.00 *80*

TO DISMANTLE & REPLACE REAR EXHAUST PIPE ASSY & ETC

\$220.00 *80*

TO REMOVE & REPLACE REAR EXHAUST PIPE HEAT SHIELD ASSY & ETC

\$120.00 *80*

TO CHECK WIRING & ELETRICAL DIAGNOSTICS

\$150.00 *120*

LABOUR TOTAL

\$2,620.00

ONG

TOTAL

412,494.07

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 19.02.2019

Third Party Insurer: AIG

Vehicle No: SLU1473J

Third Party Veh No: SLE5601P

Model: BMW 520 SE AUTO

Date of Accident: 18.02.2019

Chassis: WBAJC32030G867973 - 2017

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR PARKING SENSOR HOLDER SET	1 SET		140.00
2	REAR BOOTLID SIDE GARNISH LH	1		75.00
3	REAR EXHAUST PIPE HEAT SHIELD LOWER #7	1	345.10	508.75
SUB TOTAL				\$723.75
LESS 5%				-\$36.19
PARTS TOTAL				\$687.56

ONG

TOTAL \$687.56