

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Mar-19

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC6279M

1 pc	Rear upper arm with bush	— <i>Brk</i>	\$	84.00
1 pc	Rear ABS sensor LH	— <i>slt</i>	\$	232.00
1 pc	Rear Bumper Inner Sponge	— <i>br</i>	\$	114.00
1 pc	Rear LH floor side panel	— <i>br</i>	\$	65.00
1 pc	Rear Bumper Stay LH	— <i>Brk</i>	\$	54.00
1 pc	Spare Wheel Clamp	— <i>Brk</i>	\$	10.00
1 pc	Rear bumper reinforcement	— <i>Brk</i>	\$	607.00
			\$	1,166.00
Less 10%			\$	116.60
			\$	1,049.40

To dismantle / replace rear n/s wheel undercarriage

150
\$ ~~250.00~~

Total \$ 1,299.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.**