

INSURANCE

INS. CASE OWNER

CC 4 TP  
AIG 1900

LKK

IDAC

Surveyor:

Kenneth

DOI:

ASSIGNMENT

10/2/19

Date / Time:

10/2/19

Registered in Merimen:

11/2/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

5JW 2715T

Name of Insured:

AN AUTO KENT PLC

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

10/2/19

Is driver the owner?

( YES / NO )

Nature of Accident:

Claim No.:

54930585866

Policy No.:

Make / Model:

Place of Accident:

If NO. Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

5JW 2715T



INSRS:

WSP:

Tel:

Liability:

RMKS:

76T



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

8-3-19 @ 13:00 W/O1 ALVIN THEY FILED REPORT.  
8-3-19 @ 3:03 PM W/DESMOND, PTVC.  
AIG IS NOT INSURING 5JW 2715T (PTVC)

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

UTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No

IN NO or B 28, Ass. Lia

Repair Cost:

\$S

Loss of Rental (LOR):

\$S

( days)

Loss of Use (LOU):

\$S

(5 x days)

Loss of Income (LOI):

\$S

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$S

Medical:

\$S

Disbursement:

\$S

(e.g. Tow/ Independent)

Legal Cost:

\$S

Total:

\$S

Global Sum \$S:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$S

Name 1:

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

VINCENT OF TRT  
WILL BUY OUR  
REPORT.  
IND. REPORT.

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 818k

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SJZ85816 Regn: 24/09, 09Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Lada EX c.c. 1998Colour: White AC: Insured / Std / NI / NASp. Reading: 246863 T/Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C.No: JMY87CY4AMU 000715Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 215/50R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mmR/Bal. 4 mmL/Bal. 5 mmL/Bal. 4 mmD.O.A. 10/2/19D.O.I. 20/2/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / File pass to  
20/2 Est not ready

V/S \$3,700.

F (\$3,447.90/482)

Date/Time, File Pass to?

☐ : Prell. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)Survey Fee: 150Transportation: 50S + RS: 50+50Fees: 27Others: 80

TOTAL

407

# T & T Auto Services Pte Ltd

160 Sin Ming Drive  
#08-14 Sin Ming AutoCity  
Singapore 575722  
Tel: 6266 6876 Fax: 6266 6861

STARS RENTAL & LEASING  
50 SERANGOON NORTH AVE 4  
#02-19 FIRST CENTRE  
SINGAPORE 555856

## ESTIMATE

DATE 20/02/2019  
VEHICLE NO SJZ 8581 G  
MAKE/MODEL Mit. Lancer EX  
ACC DATE 10/02/2019

### PARTICULAR

- NETT ITEMS:
- 1 1 BOOTLID
  - 2 1 BOOTLID TOP LOCK
  - 3 1 BOOTLID LOWER LOCK
  - 4 1 BOOTLID WEATHERSTRIP
  - 5 1 BOOTLID EMBLEM - LANCER EX
  - 6 1 BOOTLID EMBLEM - GT
  - 7 1 BOOTLID AUTO OPEN SENSOR
  - 8 1 REAR BUMPER
  - 9 1 REAR BUMPER REINFORCEMENT
  - 10 2 REAR BUMPER REFLECTOR
  - 11 2 REAR BUMPER RETAINER
  - 12 1 REAR END PANEL
  - 13 1 REAR END PANEL TOP GARNISH

5 days

AMOUNT S\$

Less Discount:

10%

2,637.90

### SPECIAL NETT ITEMS:

- 1 1 REAR NUMBER PLATE
- 2 10 REAR BUMPER CLIP
- 3 1 REAR BOOTLID SPOILER
- 4 2 REAR END PANEL TOP GARNISH
- 5 1 REAR REVERSE CAMERA
- 6 1 REAR REVERSE SENSOR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

### LABOUR CHARGES:

- 1 TO CHECK WIRING
- 2 TO TUFF KOTE
- 3 TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING
- 4 TO REMOVE/REFIX REVERSE SENSOR
- 5 TO REMOVE/REFIX REVERSE CAMERA
- 6 TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS
- 7 TO SPRAY PAINTING ON AFFECTED AREA

GRAND TOTAL:

7,147.90

Singapore Dollars Seven Thousand One Hundred And Forty Seven And Cents Ninety Only.

T & T Auto Services Pte Ltd

# T & T Auto Services Pte Ltd

160 Sin Ming Drive  
#08-14 Sin Ming AutoCity  
Singapore 575722  
Tel: 6266 6876 Fax: 6266 6861

STARS RENTAL & LEASING  
50 SERANGOON NORTH AVE 4  
#02-19 FIRST CENTRE  
SINGAPORE 555856

*Not Notwork*  
*11/2/19*  
*Mevery After Paint*

## ESTIMATE

DATE 20/02/2019  
VEHICLE NO SJZ 8581 G  
MAKE/MODEL Mit. Lancer EX  
ACC DATE 10/02/2019

PARTICULAR *5 days* AMOUNT \$S

NETT ITEMS:			
1	1	BOOTLID	<i>Bu</i> 595.00 <i>✓</i>
2	1	BOOTLID TOP LOCK	<i>nd</i> 85.00 <i>✓</i>
3	1	BOOTLID LOWER LOCK	<i>R</i> 34.00 <i>x</i>
4	1	BOOTLID WEATHERSTRIP	<i>dislun</i> 162.00 <i>502sn</i>
5	1	BOOTLID EMBLEM - LANCER EX	<i>nd</i> 38.00 <i>✓</i>
6	1	BOOTLID EMBLEM - GT	<i>nd</i> 85.00 <i>✓</i>
7	1	BOOTLID AUTO OPEN SENSOR	185.00 <i>?</i>
8	1	REAR BUMPER	<i>Bu</i> 732.00 <i>✓</i>
9	1	REAR BUMPER REINFORCEMENT	<i>R</i> 237.00 <i>?</i>
10	2	REAR BUMPER REFLECTOR	55.00 110.00 <i>?</i>
11	2	REAR BUMPER RETAINER	44.00 <i>sn</i> 88.00 <i>x</i>
12	1	REAR END PANEL	452.00 <i>?</i>
13	1	REAR END PANEL TOP GARNISH	128.00 <i>?</i>
			2,931.00
Less Discount:		10%	293.10
			2,637.90

## SPECIAL NETT ITEMS:

- 1 1 REAR NUMBER PLATE
- 2 10 REAR BUMPER CLIP
- 3 1 REAR BOOTLID SPOILER
- 4 2 REAR END PANEL TOP GARNISH CLIP
- 5 1 REAR REVERSE CAMERA
- 6 1 REAR REVERSE SENSOR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Bu* 50.00 *45sn*  
*nd* 50.00 *✓*  
*msun* 650.00 *✓*  
10.00 *?*  
450.00 *?*  
*nd* 350.00 *200sn*  
1,560.00

## LABOUR CHARGES:

- 1 TO CHECK WIRING
- 2 TO TUFF KOTE
- 3 TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING
- 4 TO REMOVE/REFIX REVERSE SENSOR
- 5 TO REMOVE/REFIX REVERSE CAMERA
- 6 TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS
- 7 TO SPRAY PAINTING ON AFFECTED ARFA

50.00 *2ol*  
250.00 *?*  
150.00 *6ol*  
100.00 *5ol*  
100.00 *4ol*  
1,200.00 *8ool*  
1,100.00 *?*  
2,950.00

GRAND TOTAL: 7,147.90

Singapore Dollars: Seven Thousand One Hundred And Forty Seven And Cents Ninety Only.

T & T Auto Services Pte Ltd

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2317L
Vehicle Details	
Vehicle No.:	SJZ8581G
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER EX 2.0 GT CVT ABS D/AB HID SR
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	4B11DC6247
Chassis No.:	JMYSTCY4AAU000715
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$24,101.00
Original Registration Date:	24 Sep 2009
First Registration Date:	24 Sep 2009
Transfer Count:	6
Actual ARF Paid:	\$24,101.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Sep 2019
PARF Rebate Amount:	\$12,050.00
Intended COE Rebate Details	
COE Expiry Date:	23 Sep 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,289.00
COE Rebate Amount:	\$1,135.00
Total Rebate Amount:	\$13,185.00

The information contained herein is correct as at 21 Feb 2019

OK

- Pre repair inspection request - SJZ8581G VS SJW2715T (OI) DOA: 10/02/2019

From: Abu Kassim, Noor Mariesa  
To: admin-a@kkauto.com, assignments@kkauto.com  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Hor, Yinnul, Kaur, Baljit, Azlan, Syazairdina  
Sent: 20/2/2019 3:36:17 PM

Hi,

Please refer to the enclosed request from **T & T Auto Services Pte Ltd**

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

*Kindly assist to assign Kenneth Kong as Single Joint Expert as requested*

Thank you

Regards,

Mariesa Abu Kassim (Mariesa)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com) | [www.aig.com](http://www.aig.com)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: tntautoservices@gmail.com  
To: NoorMariesa.AbuKassim@aig.com  
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJW2715T AND SJZ8581G ON 10/02/2019  
Date: Wed, 20 Feb 2019 05:43:27 +0000

Dear Sir/Mdm,

Kindly arrange Kenneth Kong from LKK to survey the following vehicle.

Thank you.

Regards,  
Vincent Tan

From: Abu Kassim, Noor Mariesa  
Sent: Wed, 20 Feb 2019 03:51:09 +0000  
To: tntautoservices@gmail.com  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Azlan, Syazairdina, Hor, Yinnul  
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJW2715T AND SJZ8581G ON 10/02/2019

Without Prejudice

Your Reference : SJZ8581G  
Our Reference : SJW2715T

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd

10:14am @ 21/2/19  
Person @ Vincent  
Sur @ Kenneth  
Vehicle In.

Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

**Mariesa Abu Kassim (Mariesa)**

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com) | [www.aig.com](http://www.aig.com)

---

**From:** T & T Auto Services Pte Ltd [mailto:[tntautoservices@gmail.com](mailto:tntautoservices@gmail.com)]

**Sent:** Wednesday, February 20, 2019 10:22 AM

**To:** AIG SGP, Claims-Survey

**Subject:** Accident Involving SJW2715T / SJZ8581G on 10/02/2019

Dear Sir,

We refer to the above matter.

Kindly arrange pre-repair inspection of vehicle no: SJZ8581G at our premises:

T & T Auto Services Pte Ltd  
160 Sin Ming Drive  
#08-14 Sin Ming AutoCity  
S(575722)

Please provide list of surveyors available.

Thank you.

Regards,

Vincent Tan  
T & T Auto Services Pte Ltd  
Tel: 6266 6876 Fax: 6266 6861  
Hp: 9145 9776

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



## View Received Message

This mail is associated with :

**\*SJZ8581G (5493058528SG)  
[SJW2715T]**

TP

STARS RENTAL & LEASING

Feb 10 2019 4:00PM

[AL Autorent Pte Ltd]

T & T Auto Services Pte Ltd (160 Sin Ming)

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 27/02/2019 16:32 PM.  
**To** LKK\_HQ  
**Subject** No OI GIA Report (SJW2715T VS SJZ8581G)

Hi

Pls be advice that no OI GIA report received  
Pls find OI details below for your further actions

OI name : AL Autorent Pte Ltd

Address :  
210 Turf Club Road  
Lot B01 The Grandstand  
Singapore 267995

Mobile No: 63655335

Thank you.

Regards,

Syaza Indina

1725 8442 Demand

### DOCUMENTS SUMMARY

There are no documents.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG19003317/Kjb3

06 March, 2019

**AL Autorent Pte Ltd**  
210 Turf Club Road  
Lot B01 The Grandstand  
Singapore 287995

Dear Sirs,

**ACCIDENT INVOLVING SJW 2715T AND SJZ 8581G ON 10.02.2019 ALONG/  
AT BRADDELL ROAD RIGHT TURN TO LORONG CHUAN**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any mendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Joy Irene  
Claims  
Tel : 6841 2409  
Fax: 6741 4108  
Email : [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com)

c.c. *Claims Manager*  
*AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

# T & T Auto Services Pte Ltd

160 Sin Ming Drive  
#08-14 Sin Ming AutoCity  
Singapore 575722  
Tel: 6266 6876 Fax: 6266 6861  
GST Registration No: 200910712E  
Email: [ttautoservices@gmail.com](mailto:ttautoservices@gmail.com)

Date: 25<sup>th</sup> February 2019  
Our Ref: 0219-1407  
Your Ref:

**Attn: The Motor Claims Department**

**AIG Asia Pacific Insurance Pte Ltd**  
**AIG Building**  
**76 Shenton Way**  
**#08-16**  
**Singapore 079120**

Dear Sir,

**ACCIDENT INVOLVING SJW2715T / SJZ8581G ON 10/02/2019**

Please refer to the above-mentioned accident.

We are writing on behalf of **Stars Rental & Leasing**, the registered owner of motor vehicle no: **SJZ8581G** which was involved in the above accident.

We are instructed that the above accident was caused solely and completely by the negligence of your insured's vehicle no: **SJW2715T**. As a result of which, our client have suffered loss and expenses.

We are instructed by our client to claim for:-


1. Cost of Repair (inclusive of 7% GST)	:S\$3,959.00
2. Loss of Use (5 days @ \$120.00/day)	:S\$ 600.00
3. LTA Search	:S\$ 7.45
<b>TOTAL</b>	<b><u>:S\$4,566.45</u></b>

We enclosed hereby the following documents for your consideration:

- (a) Original Tax Invoice
- (b) GIA Report lodged by our driver
- (c) Owner & Driver I/C/Driving Licence
- (d) Certificate of Insurance
- (e) LTA Search

Kindly acknowledge receipt of the above said documents and your favourable reply is greatly appreciated.

Yours faithfully,

T & T Auto Services Pte Ltd  
  
Vincent Tan

## T & T Auto Services Pte Ltd

160 Sin Ming Drive  
#08-14 Sin Ming AutoCity  
Singapore 575722  
Tel: 6266 6876 Fax: 6266 6861  
GST Registration No: 200910712E

### TAX INVOICE

AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
76 Shenton Way  
#08-16  
Singapore 079120

DATE : 25/02/2019  
VEHICLE NO : SJZ 8581 G  
MAKE/MODEL : Mit. Lancer EX  
ACC DATE : 10/02/2019  
CLAIM NO : 0219-1407  
POLICY NO :

---

### AMOUNT S\$

Lump sum repair inclusive of supplying parts, labour,  
panel beating and spray painting

Repair Amount	3,700.00
Add 7% GST	259.00
Total	<u>3,959.00</u>

Singapore Dollars: Three Thousand Nine Hundred And Fifty Nine Only.

  
T & T Auto Services Pte Ltd

> Back to OneMotoring



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 19 Feb 2019 / 15:28:22

Receipt Date/Time : 19 Feb 2019 / 15:28:22

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-190219-002290

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SJW2715T

As at 10 Feb 2019/16:25:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SJW2715T  
Enquiry Fee  
20190219152725776116

Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

Paid By

20190219152743933 Direct Debit: eNETS Debit  
(Internet Banking) 7.45

Total			7.45
Cash Change			0.00
Tendered Amount			7.45
Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

T&amp;T AUTO SERVICES PTE LTD

Ref : CC4/TP19003317/Kjb3q2

BLK 160 SIN MING DRIVE  
#08-14 SIN MING AUTOCITY  
SINGAPORE 575722

Date : 17-04-2019



ON BEHALF OF STARS RENTAL &amp; LEASING

Code : TP353

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	Veh. Inspected	SJZ 8581G
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	20/02/2019

**2. Vehicle Particulars & Condition**

Make & Model	MITSUBISHI LANCER EX (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JMYSTCY4AAU000715	Colour	WHITE
Odometer	246865	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	215/50 R17	GOODYEAR	5 mm
L/H Front Tyre	215/50 R17	GOODYEAR	5 mm
R/H Rear Tyre	215/50 R17	GOODYEAR	4 mm
L/H Rear Tyre	215/50 R17	GOODYEAR	4 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	10/02/2019	Inspection Date	20/02/2019
Survey held at	T&T AUTO SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY SINGAPORE 575722		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 8581G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOTLID (N)	BUCKLED	595.00	595.00
1	BOOTLID TOP LOCK (N)	DENTED	85.00	85.00
1	BOOTLID LOWER LOCK (N)	TO REPAIR SEE LABOUR	34.00	-
1	BOOTLID EMBLEM -LANCER BX (N)	NECESSARY	38.00	38.00
1	BOOTLID EMBLEM-GT (N)	NECESSARY	85.00	85.00
1	BOOTLID AUTO OPEN SENSOR (N)	DENTED	185.00	185.00
1	REAR BUMPER (N)	BUCKLED	732.00	732.00
1	REAR BUMPER REINFORCEMENT (N)	TO REPAIR SEE LABOUR	237.00	-
2	REAR BUMPER REFLECTOR @\$55.00 (N)	O/S MTG CRACKED	110.00	55.00
2	REAR BUMPER RETAINER @\$44.00 (N)	SERVICEABLE	88.00	-
1	REAR END PANEL (N)	BENT	452.00	452.00
1	REAR END PANEL TOP GARNISH (N)	SERVICEABLE	128.00	-
	LESS 10% DISCOUNT		-276.90	-222.70
			2,492.10	2,004.30
1	BOOTLID WEATHERSTRIP (50%) (SN)	DISTORTED / CUT	162.00	81.00
	LESS 10% DISCOUNT		-16.20	-
			145.80	81.00
<b>SPECIAL NETT ITEMS</b>				
1	REAR NUMBER PLATE (SN)	BENT	50.00	45.00
10	REAR BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	REAR BOOTLID SPOILER (SN)	MTG CRACKED	650.00	650.00
2	REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	10.00	-
1	REAR REVERSE CAMERA (SN)	SERVICEABLE	450.00	-
1	REAR REVERSE SENSOR (SN)	DENTED	350.00	200.00
			1,560.00	945.00
<b>LABOUR</b>				
	TO CHECK WIRING .		50.00	20.00

Report Ref No. CC4/TP19003317/Kjb3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TUFF KOTE.		250.00	60.00
	TO REMOVE /REFIX UPHOLSTERY ,CUSHION SEAT & ROOF LINING.		150.00	60.00
	TO REMOVE/REFIX REVERSE SENSOR .		100.00	50.00
	TO REMOVE/REFIX REVERSE CAMERA .		100.00	40.00
	TO PANEL BEATING ,REMOVING & REPLACING OF NEW PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID LOWER LOCK AND REAR BUMPER REINFORCEMENT .		1,200.00	800.00
	TO SPRAY PAINTING ON AFFECTED AREA.		1,100.00	600.00
			2,950.00	1,630.00
GRAND TOTAL			7,147.90	4,660.30

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00
--	--	--	----------

Report Ref No. CC4/TP19003317/Kjb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.