

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

STARS RENTAL & LEASING
50 SERANGOON NORTH AVE 4
#02-19 FIRST CENTRE
SINGAPORE 555856

ESTIMATE

DATE 20/02/2019
VEHICLE NO SJZ 8581 G
MAKE/MODEL Mit. Lancer EX
ACC DATE 10/02/2019

PARTICULAR *5 days* AMOUNT S\$

NETT ITEMS:			
1	1 BOOTLID		Bu 595.00 ✓
2	1 BOOTLID TOP LOCK		nd 85.00 ✓
3	1 BOOTLID LOWER LOCK		R 34.00 x
4	1 BOOTLID WEATHERSTRIP		dislcn 162.00 508sn
5	1 BOOTLID EMBLEM - LANCER EX		nu 38.00 —
6	1 BOOTLID EMBLEM - GT		nu 85.00 —
7	1 BOOTLID AUTO OPEN SENSOR		185.00 ?
8	1 REAR BUMPER		Bu 732.00 ✓
9	1 REAR BUMPER REINFORCEMENT		P 237.00 ?
10	2 REAR BUMPER REFLECTOR	55.00	110.00 ?
11	2 REAR BUMPER RETAINER	44.00	88.00 x
12	1 REAR END PANEL		452.00 ?
13	1 REAR END PANEL TOP GARNISH		128.00 ?
			2,931.00
Less Discount:		10%	293.10
			2,637.90

SPECIAL NETT ITEMS:	
1	1 REAR NUMBER PLATE
2	10 REAR BUMPER CLIP
3	1 REAR BOOTLID SPOILER
4	2 REAR END PANEL TOP GARNISH CLIP
5	1 REAR REVERSE CAMERA
6	1 REAR REVERSE SENSOR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LABOUR CHARGES:		
1	TO CHECK WIRING	50.00 201
2	TO TUFF KOTE	250.00 ?
3	TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING	150.00 601
4	TO REMOVE/REFIX REVERSE SENSOR	100.00 501
5	TO REMOVE/REFIX REVERSE CAMERA	100.00 401
6	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS	1,200.00 8001
7	TO SPRAY PAINTING ON AFFECTED ARPA	1,100.00 ?
		2,950.00

GRAND TOTAL: 7,147.90

Singapore Dollars Seven Thousand One Hundred And Forty Seven And Cents Ninety Only.

T & T Auto Services Pte Ltd