

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/238/2019/GW
Date : 22-Feb-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Edward Bin Chung Yiu
Address : 29B West Coast Park
: #04-22
Singapore 127724
Telephone : HP +65 97632100
Type of Claim : Third Party Claims
Policy No. : 1800145627
Vehicle No : **SGJ 6328 E**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : 12/12/2018
Engine No : CVK 073207
Chassis No : WAUZZZF57KA009714
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Feb-19
Place of Accident : Capital Tower Car Park Level 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGJ 6328 E

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper assy. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray front bumper.	\$ 900.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
SUB LABOUR CHARGES		: \$ <u>2,622.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGJ 6328 E

S/N	Parts Description	Damaged Parts & Prices S/Nett
1	FRONT BUMPER <i>repld</i>	\$ 2,575.00 ✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 368.00 +
3	FRONT BUMPER GRILLE-CENTER <i>new</i>	\$ 465.00 +
4	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>new</i>	\$ 207.00 +
5	FRONT BUMPER AIR GUIDE GRILLE-RH <i>repld</i>	\$ 630.00 ✓
6	RADIATOR GRILLE <i>new</i>	\$ 2,131.00 +
7	FOAM FILLER PIECE ?	\$ 113.00 ?
8	FRONT BUMPER CARRIER ?	\$ 733.00 ?
9	LED HEADLIGHT-RH <i>repld</i>	\$ 7,204.00 +
10	LED HEADLIGHT BRACKET-RH <i>new</i>	\$ 13.00 +
11	LED HEADLIGHT LIFT CYLINDER-RH <i>new</i>	\$ 181.00 +
12	FRONT SENSOR-OUTER <i>repld</i>	\$ 231.00 ✓
13	FRONT NO .PLATE <i>repld</i>	S/N \$ 25.00 +
14	SUNDRIES ?	\$ 500.00 ?
TOTAL SPARE PARTS CHARGES		\$ 15,376.00
TOTAL LABOUR CHARGES		\$ 2,622.00
GRAND TOTAL		\$ 17,998.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King,
Surveyed Date : 26/02/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : NRP Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant