

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Adress : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacufic Insurance Pte Ltd
Motor Claims Dept

Date : 18 Mar 19

Dear Sirs :

Fax : 64193727

RE : ESTIMATE COST FOR MERCEDES BENZ SPRINTER 2.2 - YP3534B
ACCIDENT INVOLVING YP3534B & GBC4672U ON 23/11/2018

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear sliding door n/s.	1pc	\$ 2,417.18
2	Rear sliding door lower garnish n/s.	1pc	\$ 378.98
3	Rear mudguard n/s.	1pc	\$ 2,169.64
4	Rear mudguard lower garnish n/s	1pc	\$ 238.01
5	Rear lamp n/s.	1pc	\$ 328.30
			\$ 5,532.11
6	Rear lamp meat		\$ 450.00
	Sum Carried Forward		\$ 5,982.11

Sum Carried Forward		\$ 5,982.11
----------------------------	--	--------------------

Labour Charge & Misc

To remove, repair, replace & install damaged parts.	} }	\$ 1,500.00
--	--------	-------------

To R & R wiring.		\$ 80.00
------------------	--	----------

To paster logo (reflector)		\$ 1,800.00
------------------------------	--	-------------

To putty & spray painting.		\$ 1,200.00
----------------------------	--	-------------

Total		<u>\$ 10,562.11</u>
--------------	--	----------------------------

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.