

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

|                   |   |                    |
|-------------------|---|--------------------|
| <b>Estimate</b>   | : | Accident Repairs   |
| <b>Workshop</b>   | : | Ubi Road 1         |
| <b>Contact No</b> | : | 6366 2323          |
| <b>Fax No</b>     | : | 6841 1183          |
| <b>Reference</b>  | : | PA/TP/0232/2019/GW |
| <b>Date</b>       | : | 21-Feb-19          |

Vehicle NOT IN workshop. Kindly arrange for survey.

## AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

**Attn: Motor Claims Dept**

**Tel: 6880 4602 - Fax 6880 4838**

|                          |   |                                   |
|--------------------------|---|-----------------------------------|
| <b>Owner's Name</b>      | : | Premium Leasing Pte Ltd           |
| <b>Address</b>           | : | 9 Leeg Ken Rd<br>Singapore 159090 |
| <b>Telephone</b>         | : | (Office)+65 64712123              |
| <b>Type of Claim</b>     | : | Third Party Claims                |
| <b>Policy No.</b>        | : |                                   |
| <b>Vehicle No</b>        | : | <b>SKS 6594 H</b>                 |
| <b>Model Code</b>        | : | Q5 2.0 TFSI QU                    |
| <b>Model / Year</b>      | : | Apr-15                            |
| <b>Engine No</b>         | : | CNC 065961                        |
| <b>Chassis No</b>        | : | WAUZZZ8R9FA013219                 |
| <b>Mileage</b>           | : |                                   |
| <b>Date In</b>           | : |                                   |
| <b>Liability</b>         | : | -                                 |
| <b>Excess Cost</b>       | : | -                                 |
| <b>Estimated By</b>      | : | Johnny Boo / Allan Wu             |
| <b>Accident Date</b>     | : | 19-Feb-19                         |
| <b>Place of Accident</b> | : | QUEEN SWAY                        |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SKS 6594 H

| S/n                         | Nature of Jobs                                                                                                      | Estimated Charges             |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------|-------------------------------|
| 1                           | To remove and transfer rear parking aid. Check function and renew according to damage.                              | S/N \$ 280.00 ✓               |
| 2                           | To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed. | \$ <del>1,050.00</del> 700 ✓  |
| 3                           | To respray rear bumper and lower spoiler.                                                                           | \$ <del>1,500.00</del> 1200 ✓ |
| 4                           | To remove and renew rhs rear exhaust silencer. To align to position.                                                | S/N \$ 480.00 ?               |
| 5                           | To carry out diagnostic check.                                                                                      | S/N \$ 192.00 ✓               |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                     | <b>: \$ <u>3,502.00</u></b>   |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SKS 6594 H

| S/N                       | Parts Description                        |      | Damaged Parts & Prices<br>S/Nett |
|---------------------------|------------------------------------------|------|----------------------------------|
| 1                         | REAR BUMPER <i>whd</i>                   | \$   | 1,513.00 ✓                       |
| 2                         | REAR BUMPER FIXING PARTS <i>new</i>      | \$   | 150.00 +                         |
| 3                         | TAIL LIGHT-RH <i>lt</i>                  | \$   | 273.00 ✓                         |
| 4                         | REAR BUMPER GUIDE SECTION-LH <i>new</i>  | \$   | 49.00 +                          |
| 5                         | REAR BUMPER GUIDE SECTION-RH             | \$   | 49.00 +                          |
| 6                         | REAR BUMPER SPOILER <i>whd</i>           | \$   | 788.00 ✓                         |
| 7                         | REAR BUMPER CARRIER <i>new</i>           | \$   | 598.00 +                         |
| 8                         | REAR BUMPER HOLDER BRACKET-RH <i>new</i> | \$   | 390.00 +                         |
| 9                         | REAR BUMPER SENSOR <i>new</i>            | \$   | 231.00 +                         |
| 10                        | REAR BUMPER SENSOR- INNER <i>new</i>     | \$   | 210.00 ✓                         |
| 11                        | REAR BUMPER SENSOR SEAL RING <i>new</i>  | 4 \$ | 5.00 ✓                           |
| 12                        | REAR SILENCER-RH ?                       | \$   | 910.00 ?                         |
| 13                        | REAR SILENCER DUAL CLIP ?                | \$   | 49.00 ?                          |
| 14                        | REAR SILENCER BRACKET-LH/RH ?            | 2 \$ | 104.00 ?                         |
| 15                        | SUNDRIES ?                               | \$   | 500.00 ?                         |
| TOTAL SPARE PARTS CHARGES |                                          | :    | \$ 5,819.00                      |
| TOTAL LABOUR CHARGES      |                                          |      | \$ 3,502.00                      |
| GRAND TOTAL               |                                          |      | \$ 9,321.00                      |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian King.  
Surveyed Date : 27/02/19.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 03 Days.

**Please Note** : This estimate is based on visual inspection of the affected  
Should we require further labour charges and spare parts  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant