

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

AXA

25-Feb-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1186 A

1 pc	Rear bumper <i>x 14.72</i>	\$	811.11
1 pc	Rear bumper sponge <i>x 7.20</i>	\$	79.20
1 pc	Rear bumper reinforcement <i>x 5.00</i>	\$	815.64
1 pc	Rear bumper reinforcement centre <i>x 5.00</i>	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 <i>x 2</i>	\$	104.40
		\$	1,889.55
	Less 20%	\$	377.91
		\$	1,511.64

S/NETT

1 set	Rear bumper clips <i>x 2</i>	\$	48.00
	Sundry	\$	50.00 <i>20</i>
	To dismantle and replace reverse sensor and test system	\$	80.00 <i>x 4</i>
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the same, etc	\$	500.00 <i>200</i>
	To putty and spray painting on the rear bumper	\$	200.00 <i>180</i>
	Total	\$	<u>2,389.64</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahillik

25/2/19 1026

2 Pcs

PIR

After Repair

2/3/19

WLS 1440/203

M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification to be carried out
- Supplemental charges must be approved and is subject to approval of the relevant Insurance Company

Acknowledged by Repairer:
Signature:
Date: