

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19003330/ADA3Q2

Date: 24/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100233718

Claimant
Vehicle No : GT388T **Insured Vehicle No :** SJZ646G

Date of Loss: 19/02/2019 Nature of Claim: TP Claim No: 7308126230SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GT388T		
Make & Model:	TOYOTA HIACE, 3.0 D DX (A)	Engine No:	1KD2669585
Reg. Date:	27/03/2017 (Man. Year: 2016)	Chassis No:	KDH2010211615
Colour:	White	Odometer:	74196 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,512.50	2,698.75	813.75	23.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,300.00	1,650.00	55.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,462.50	3,998.75	2,463.75	38.12
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	6,462.50	3,200.00	3,262.50	50.48
+ GST 7.00/7.00% (S\$)	452.38	224.00	228.38	50.48
Nett Amount (S\$)	6,914.88	3,424.00	3,490.88	50.48
+ Car Rental (6.0 x S\$90.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,966.00		
Global Sum Settlement (S\$)		3,960.00		

INSPECTION

Date of Assignment: 20/02/2019

Date Inspected: 19/06/2019 Inspected At:

BLK 3007 UBI ROAD 1 #01-450

SINGAPORE 408700

Repairer: Jack Cars Enterprise Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	2,200.00 FL	*1,765.00 FL
2	1		*REAR BOOT LOCK	Damaged	250.00 FL	*250.00 FL
3	1		*REAR BUMPER	Deformed	550.00 FL	*550.00 FL
4	1		*REAR BUMPER BRACKET -LEFT	Necessary	95.00 FL	*58.00 FL
5	1		*REAR BUMPER BRACKET -RIGHT	Necessary	95.00 FL	*58.00 FL
6	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
7	1		*REAR BOOT WEATHERSTRIP	Cut	300.00 FL	*300.00 FL
8	1		*REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
9	1		*SILICON SEALANT	Not Necessary	100.00 FS	*- FS
10	1		*WINDSCREEN MOULDING	Necessary	250.00 FS	*110.00 FS
11	1		*CLIPS	Necessary	100.00 FS	*30.00 FS
12	1		*TOYOTA EMBLEM	Necessary	95.00 FS	*58.00 FS
13	1		*HIACE , 70KM, 8 PAX & 1250 KG STICKERS	Necessary	150.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,385.00	3,444.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	872.50	745.25
Total Parts (\$\$)	3,512.50	2,698.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,000.00	500.00
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,200.00	600.00
3	TO CHECK WIRING & REWIRE	New	250.00	30.00
4	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	200.00	120.00
5	TO REMOVE & REINSTALL REVERSE SENSOR	New	100.00	50.00
6	ANTI RUST TREATMENT	New	200.00	0.00
Gross Labour Cost (\$\$)			2,950.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >