

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 15.02.2019

Third Party Insurer: AIG

Vehicle No: SLK6740H

Third Party Veh No: SLZ1272X

Model: HONDA VEZEL

Date of Accident: 13.02.2019

Chassis: RU11211124 - 2017

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Ry</i> \$953.30
2	REAR TAILGATE "VEZEL" EMBLEM	1		<i>na</i> \$68.30
3	REAR TAILGATE WINDSCREEN MOULDING	1		<i>na</i> \$180.00
4	REAR BUMPER	1		<i>Ry</i> \$762.70
SUB TOTAL				\$1,964.30
LESS 20%				-\$392.86
PARTS TOTAL				\$1,571.44

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT	1		<i>na</i> \$100.00
2	REAR BUMPER REVERSE SENSOR	1 SET		<i>na</i> \$250.00
3	REAR BUMPER CLIPS	1 SET		<i>na</i> \$50.00
S/N TOTAL				\$400.00

LABOUR CHARGES:

TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC	\$150.00	<i>120</i>
LABOUR CHARGES TO REMOVE & REPLACE REAR ACCIDENT AREAS & ETC	\$500.00	<i>?</i>
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS	\$300.00	<i>?</i>
TO CHECK WIRING & ELECTRICAL SYSTEM	\$80.00	<i>20</i>
LABOUR TOTAL		\$1,030.00

ONG **TOTAL \$3,001.44**

*Not withink
Resurvey B4paim
5days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items should be resurveyed and is subject to final approval of the Insurance Company

Acknowledged by Rep: _____
Signature: _____
Date: _____

Page 1

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143 Tel : +65 6472 1313 Fax : +65 6472 2112
 Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011
 Co. Reg. No. 201212455W

Date: 15.02.2019 Third Party Insurer: AIG
 Vehicle No: SLK6740H Third Party Veh No: SLZ1272X
 Model: HONDA VEZEL Date of Accident: 13.02.2019
 Chassis: RU11211124 – 2017

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR END PANEL	1		<i>RM</i> \$530.90 ✓
2	REAR END PANEL TAILGATE ANTENNA SENSOR BUZZER	1		<i>RM</i> \$85.00 ✓
SUB TOTAL				\$615.90
LESS 20%				-\$123.18
PARTS TOTAL				\$492.72

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR END PANEL JOINT SEALANT	1		<i>RM</i> \$60.00 <i>30sn</i>
S/N TOTAL				\$60.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ON REAR END PANEL	\$200.00 ✓
TO PUTTY & SPRAY PAINTING WITH SEALANT ON REAR END PANEL	\$250.00 <i>200</i>
TO TUFF KOTE / ANTI-RUST	\$60.00 <i>30l</i>
TO DISMANTLE & REINSTALL REAR TAILGATE REVERSE CAMERA / INNER CAMERA RECORDER	\$40.00
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$40.00
LABOUR TOTAL	\$590.00

ONG	TOTAL	\$1,142.72
-----	-------	------------