

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 16 Sep 2019

Preliminary Advice

Vehicle No	: 4758S	Accident Date	: 15/01/2019
Make	: BMW 216I	Policy No.	: 27392999MTR
Assignment Date	: 15/03/2019	Excess	: S\$1,500.00
Date of Inspection	: 22/02/2019	Est. Duration of Repair	: 0.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rooftop and interior and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,849.45
Revised Amount	:S\$	30,107.45
Check Items (Estimated)	:S\$	0.00
Total	:S\$	30,107.45

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

(X) The vehicle is not economical for repair.

() The above survey was conducted on a 'without prejudice' basis.