

47585

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (AfterSales)
Fax. 64796601 (AfterSales)
64796624 (AfterSales)

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



GST REG. NO : M2 - 0020081

E S T I M A T E

Acknowledged by Repairer

Signature:

Date:

Estimate No. : b1 50203
Date Estimated : 20/02/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
	VD11506		216i AT	0

DESCRIPTIONVALUE

To repair roof panel.

850 ✓ 1,275.00

Painting roof panel.

1166 ✓ 1,298.00

To replace all control units.

4250 ✓ 5,100.00

To replace electromechanical power steering including program, initialize steering column adjustment and conduct checks for proper function.

752 ✓ 885.00

To check steering geometry and conduct wheel alignment according to BMW specification (1x)

451 ✓ 531.00

To remove and install front dashboard panel to facilitate repairs.

677 ✓ 797.00

Diagnoss and programming the control units.

1083 ✓ 1,275.00

Sundries.

✓ 150.00

-This vehicle damaged by lighting and estimate prepare based on innitial diagnoss. -Any futher faulty on electric /elctronic component will submit supplementary for approval.

0.00

Total Labour 1: **11,311.00**DESCRIPTIONQTYPRICVALUE

BASIC CONTROL UNIT DME 83T1 (CODED) Battery sick (Short Circuit) 1 2,769.75 2,769.75

CONTROL UNIT DUAL CLUTCH TRANSMISSI 1 1,979.95 1,979.95

EXCH STEERING BOX ELECTR. 1 3,811.95 3,811.95

REPAIR KIT CONTROL UNIT DSC ABS 1 1,912.00 1,912.00

BOOT LID/TAILGATE PUSH BOTTON ICAM Camera 1 48.40 48.40

(DG/SL) BMW AGM BATTERY (70 AH) Battery 1 581.95 581.95

SHIFTBOX GEAR SELECTOR SWITCH gear lever 1 1,146.60 1,146.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 50203**
Date Estimated : **20/02/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
	VD11506		216i AT	0

DESCRIPTION	QTY	PRIC	VALUE
<i>change and test</i> BODY DOMAIN CONTROLLER BDC (CODED) <i>LH Dashed (Shut (Mv))</i>	1	1,348.80	1,348.80
SEAT MODULE	1	501.00	501.00
CONTROL UNIT TAILGATE FUNCTION MODU	1	494.60	494.60
CONTROL UNIT FRT LIGHT ELECTRONICS	2	893.90	1,787.80
CONTROL UNIT AIRBAG	1	1,024.75	1,024.75
CONTROL UNIT PARKING ASSISTANT	1	526.10	526.10
CONTROL UNIT CAM BASED DRIVER SUPP.	1	920.60	920.60
REVERSING CAMERA (VALEO)	1	684.20	684.20

Total Parts : **19,538.45**

Labour 1	:	11,311.00
Parts	:	19,538.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,159.46
Grand Total	:	33,008.91

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **