

05/2014

INS. CASE OWNER:

CL  
T. [unclear] / CC3 / AXA1400 5031 / 17/10/14

LKR:  
IDAC:

ASSIGNMENT

Surveyor:

[unclear]

DOI:

13/03/14

Date/Time:

17/03/14  
13/03/14

Pre-assign / CCU / FTE



Insured Vehicle No.: SKB 6310 A  
Name of Insured: Jay Bee Hua  
Insured Tel No.: HP: 91144753  
Excess Sec II :SS D.O.A: 5/3/14  
Is driver the owner? (YES / NO) Nature of Accident:

Claim No.: 0297701  
Policy No.: P146142  
Make / Model: HONDA Accord  
Place of Accident: Along Amk Ave 6 before Amk Ave

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO Insured Liability :

% Final ? Yes / No

SP788WJ → SKB 6310 A → SHB 7986D → SJU1292J → QX208R



INRS:  
WSP:  
Tel:  
Liability:  
RMKS: 01



INRS:  
WSP: TRANS-COL  
Tel:  
Liability:  
RMKS: TP



INRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/Time	STAGE	DATE / PIC
21/4/14	<b>FOR CSO ONLY:</b>	
	Is driver the owner? (YES / NO)	
	If NO, Driver Name / Age :	
11/06/14	Driver's Own Vehicle Number: SHB 7986D - X; SKB 6310 A - X	Insurance Company:
	POLICE CAR (3RD VEHICLE)	
11/06/14	OFFER TO OI. SAME CONTAMINATED ACCIDENT	
	DETAILS 4 WAS INVOLVED IN A 3 VEH. C.O. 4 WAS THE 4TH VEH. 4 WAS PUSHED FORWARD FROM FRONT. WORKED TP CLAIM 4 NCD HONOR.	
	EMAIL AXA TP BOLA 28 APPLIES.	
15/06/14	EMAIL FROM AXA TO AGREE @ 10-20% ONLY.	
	- TP LOW IN	
	- PROCEEDED.	
21/06/14	EMAIL WARRANTS TO AXA BY EMAIL @ 5% AS PER CDR.	
	- AXA APPROVED WARRANTS.	
	- COULD GET OFFER TO TP.	
19/07/2014	- TP PROS LAWYER TO HANDLE	
	- EMAIL TO AXA TO CLOSE OFF CASE.	
	- NO SETTLEMENT	

FINAL SETTLEMENT	Date:	Confirm with	(to ver. c.c. of 4th 3rd police car)
Repair Cost: (w/ GST)	\$5 21,600.00	Final Liability: 10-20 % (Agreed / Assessed)	BOLA S/N No.: Nil
Loss of Rental:	\$5 2,160.00 (20 days) X 121.98		If NO or B 28, Ass. Lia:
Loss of Use:	\$5 - (5 x days)	1) Claim status: Normal/Reject/Private Settle	
Disbursement: LTA	- 600	2) Report Format: NO SETTLEMENT	
Legal Cost:	\$5 -	3) Survey fee: \$250 (PHB)	
Total:	\$5 -	Global Sum: \$5	

DO APPROVAL  
No Bill

COPY SENT


To scan & close file only.

INS. CASE OWNER: Jacy CL Leong | CC3 AXA1400 5031 / T1ra3 | LKK: 17/3/14  
 IDAC: 13/3/14

Surveyor: TANFIEH | DOI: 13-3-14 | Date / Time: 13/3/14

**Pre-assign / CCU / FTE**

Insured Vehicle No.: SKB 6310 A | Claim No.: C0293701  
 Name of Insured: Toy Bee Hua | Policy No.: VFA/P1462142  
 Insured Tel No.: HP: 91144753 | Make / Model: HONDA ACCORD  
 Excess Sec II :SS | D.O.A: 05-03-14 | Place of Accident: AME AVE 6  
 Is driver the owner? ( YES / NO ) | Nature of Accident: \_\_\_\_\_  
 If NO, Driver Name / Age: \_\_\_\_\_ | OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
 Driver Tel No.: \_\_\_\_\_ | (V/L: YES / NO Insured Liability : % Final ? Yes / No



Date/ Time	FOR CSO ONLY:	STAGE	DATE / PIC
	Is driver the owner? (YES / NO)	Finalisation:	
	If NO, Driver Name / Age :	Email AIG for OI GIA:	
	Driver's Own Vehicle Number: _____ Insurance Company: _____	Apt letter to OI:	
	<u>SHB 7986 D - 05/03/01 11009451 / U/vn. D.O.A: 14/4/11</u>	Call OI:	
	<u>SKB 6310 A - X</u>	After call ltr to OI:	
		Type Report:	
		Prepare Invoice:	
		Others:	
<u>18/06/15 @ 5:10 pm</u>	<u>spoken to OI. OI informed accident details. OI admitted involved 5 veh chain collision. OI 4th veh. Informed OI of TP claim and her NCD will be with held / frozen for the time being.</u>	Documentation Check List:	Handler Typist
	<u>• OI does not want to further discuss on this conversation. OI has hired her lawyer to follow on this file.</u>	OI Apt Ltr:	<input type="checkbox"/>
	<u>• Please do not send any letters to OI for further enquiries contact her Insurance company or her lawyer.</u>	Authorisation To Act:	<input type="checkbox"/>
	<u>• (scribble)</u>	Release Voucher:	<input type="checkbox"/>
		Final Repair Bill:	<input type="checkbox"/>
		Car Rental Invoice:	<input type="checkbox"/>
		LTA / GIA :	<input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		Approval Email:	<input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

FINAL SETTLEMENT	Date :	Confirm with	BOLA S/N No. :
Repair Cost:	SS	Final Liability: <u>10/20</u> % (Agreed / Assessed)	<u>NIL</u>
Loss of Rental:	SS	( days)	If NO or B 28, Ass. Lia :
Loss of Use:	SS	(\$ x days)	1) Claim status: Normal/Reject/Private Settle
Disbursement:			2) Report Format: <u>5 chain collision</u>
Legal Cost:	SS		3) Survey fee: <u>OI: 4th 1st: Police car</u>
Total:	SS	Global Sum: SS	TP: <u>3rd</u>





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933  
 TEL: 6256 3561 FAX: 6256 4315

Reg No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC3/AXA14005031/T1ra3	
8 SHENTON WAY #27-01 SINGAPORE 068811		Date : 17-03-2014	
		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKB 6310A	Veh. Inspected	SHB 7986D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/03/2014
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/03/2014	Inspection Date	13/03/2014
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/03/2014 14:16
Date Of Accident	05/03/2014 18:30
Exact Location Of Accident	Ang Mo Kio Ave 6
Country/State of Loss	Singapore
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHB7986D
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Vehicle Particulars	
Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	Hire and Reward
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Taxi
Insurance Company	
Name of Insurance Company	First Capital Insurance Ltd
Type Of Coverage	Third Party
Fleet Policy	Yes
Policy Number	D-12047359MFSH/486
Cover Note Number	
Driver	
Name of Driver	TEO LAWRENCE
NRIC No	S0584303J
Date Of Birth	22/10/1949
Occupation	Outdoor
Date Of Driving Pass	08/09/1971
Driving Experience	42 Years And 5 Months
Gender	Male
Mobile Number	(Local) +65-97941644
Fax Number	
Contact Number	
E-mail Address	NOEMAIL
Address	BLK 264 BISHAN ST 24 #13-112
Postcode	570264

Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**Details of Witness**

Name  
Phone Number  
Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number SFZ8822J  
Vehicle Make/Model/Colour TOYOTA FORTUNER 2.7  
Details Of Properties  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**Details of Witness**

Name  
Phone Number  
Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 4**

Vehicle Registration Number QX208R  
Vehicle Make/Model/Colour TOYOTA COROLLA ALTIS  
Details Of Properties  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**Details of Witness**

Name  
Phone Number  
Email Address

Police Report Pg.1

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999



T/20140307/4133

1 of 3

Report No. T/20140307/4133

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 07/03/2014 20:40	Vide Report No.:	Station Diary No.: 72
--------------------------------------------	------------------	--------------------------

**Informant's Particulars**

Name of Informant: TEO LAWRENCE			Address: APT BLK 264 BISHAN STREET 24 #13-112 SINGAPORE 570264		
ID Type / ID No.: NRIC NO / S0584303J			Contact No.:		Mobile: 97941644
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 64	Date of Birth: 22/10/1949	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi Driver			Driving Licence Information: Class: 3		Date of Expiry:

**General Information of the Accident**

Type of Accident: Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 05/03/2014 18:30	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 YIO CHU KANG RD ANG MO KIO AVE 3			
Weather: Clear		Road Surface: Dry	Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Color	Condition	No of Passenger	Insurance Company	Insurance No	Effective Date	Expiry Date
SHB7986 D				Seriously Damaged	0				

**Brief Details.**

On 05/03/2014 around 1830hrs, I was driving my taxi (SHB7986D) in the middle lane of Ang Mo Kio Ave 6 from the direction of Yio Chu Kang road towards Ang Mo Kio Ave 3. I had stopped my taxi behind a red Mitsubishi Lancer as the traffic light at the junction was red. After awhile, I feel an impacted from my rear vehicle. As a result my vehicle move forward and my vehicle collided with the red Mitsubishi Lancer. Subsequently, the red Mitsubishi Lancer move forward and collided with the police vehicle which was stopped at the traffic light. At the moment, I fell giddy and I could not managed to take down all the vehicle registration plate as the ambulance

Text size -

**Enquire PARF/COE Rebate for Registered Vehicle**

**Vehicle Owner Particulars**

Owner ID Type: Company  
 Owner ID: 200303878K

**Vehicle Details**

Vehicle No.: SHB7986D  
 Vehicle to be Exported: Yes  
 Intended De-registration Date: 13 Mar 2014  
 Vehicle Make: CHEVROLET  
 Vehicle Model: EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO  
 Primary Colour: Red  
 Manufacturing Year: 2011  
 Engine No.: Z20S1461308K  
 Chassis No.: KL1LA69RJBB122518  
 Maximum Power Output: 110.0 kW (147 bhp)  
 Open Market Value: \$13,971.00  
 Original Registration Date: 29 Jan 2013  
 First Registration Date: 29 Jan 2013  
 Transfer Count: 0  
 Actual ARF Paid: \$13,971.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 28 Jan 2021  
 PARF Rebate Amount: \$10,478.00

**Intended COE Rebate Details**

COE Expiry Date: 28 Jan 2021  
 COE Category: A - Car (1600cc & below)  
 COE Period (Years): 8  
 PQP Paid: \$60,655.00  
 COE Rebate Amount: \$48,524.00  
**Total Rebate Amount: \$59,002.00**

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Mar 2014

OK



Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).  
 Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions  
 Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution  
 Copyright © 2014 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/03/2014 14:17
Date Of Accident	05/03/2014 18:30
Exact Location Of Accident	ALONG ANG MO KIO AVE 6 BEFORE ANG MO KIO AVE 3
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB6310A
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	TAY BEE HUA
NRIC No	S7000206Z

#### Vehicle Particulars

Manufacturer	HONDA
Model	ACCORD-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USED
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
If No, Please state action to be taken	
Vehicle Category	Private Car

#### Insurance Company

Name of Insurance Company	AXA Insurance Singapore Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	VPA/P1462142
Cover Note Number	

#### Driver

Name of Driver	TAY BEE HUA
NRIC No	S7000206Z
Date Of Birth	06/01/1970
Occupation	Indoor
Date Of Driving Pass	19/03/2001
Driving Experience	12 Years And 11 Months
Gender	Female
Mobile Number	(Local) +65-91144753
Fax Number	
Contact Number	
Email Address	SERLINE@HOTMAIL.COM
Address	BLK 714 ANG MO KIO AVENUE 6 #14-4018
Postcode	560714
Was driver an employee of the Insured's Company	No

Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**Details of Witness**

Name  
Phone Number  
Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number UNKNOWN  
Vehicle Make/Model/Colour CHEVROLET  
Details Of Properties FRONT & REAR PORTION DAMAGED  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**Details of Witness**

Name  
Phone Number  
Email Address

**DETAILS OF INJURED PERSON 1**

Name NARELLE SERLINE CHOO  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SKB6310A  
Were seat belts worn?  
Was injured conveyed to hospital by ambulance? Yes  
Address  
Postcode

Sketch Plan #2

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20140306/4039

1 of 3

Report No. T/20140306/4039

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 06/03/2014 11:44		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: TAY BEE HUA			Address: APT BLK 311 ANG MO KIO #11-2114 SINGAPORE 560311		
ID Type / ID No.: NRIC NO / S7000206Z			Contact No.:		Mobile: 91144753
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 44	Date of Birth: 06/01/1970	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: ADMIN			Driving Licence Information: Class: 3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 05/03/2014 18:30	Type of Location: Straight Road
Location: Along Road 1 ANG MO KIO AVE 6				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

<b>Details of Vehicle Involved</b>									
Vehicle No.	Type	Make	Color	Condition	No of Passenger	Insurance Company	Insurance No	Effective Date	Expiry Date
SKB6310 A	Car	HONDA	White	Seriously Damaged	1	AXA INSURANCE SINGAPORE PTE LTD	P1462142	02/01/2014	01/01/2015

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Sketch Plan #4

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20140306/4039

3 of 3

Report No. T/20140306/4039

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / Koh Ping Kwang MOHD FUZAN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / MOHD YAZID BIN MOHD YUSOFF Contact No.: 65472075

Signature Of Informant: 
Date/Time: 06/03/2014 11:44
Classification Of Case:

Authentication Stamp  
SP168

SHB 79860

	Part.	SW	Labour	Total
	1202	1202	24	3000 18066.78
	180	239.94	10	100 984
	356	260	60	120 6350
	102	68.76	35	2400 25400.78 <sup>20%</sup>
	102	68.76	30	30 <sup>1/2</sup> 20300 <sup>20%</sup>
	78	119.74	30	100
	134.37	119.74	15	100
	32.4	973	40	200
	32.4	63.5	192	120
	1222.32	378	18	100
	134.37	623.76	10	80
	816	263.84	200	6350
	816	973	30	
	1250	344.28	30	
	257	466.56	30	
	144.3	39.4	30	
	60	120.62	30	
	618	138.84	30	
	30	119.84	30	
	120	128.4	30	
	367	479.3	80	
	45.02	359	984	
	150	479.3		
	536	359		
	634	298		
	600	418.44		
	652	298		
	10671.18 +	9403.02 -	20074.2	
		10% →	18066.78	

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835  
 TEL NO 6287 6666 FAX NO.6368 8862  
 CO/GST REG NO.201019626G  
 SHB 7986D - AXA

ROEL

DNK

- w/ PHOTOS



63668862

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident:  
 Third Party Insurer :

**SHB 7986D - ROEL**  
**KL1LA69RJBB122518\***  
**CHEVROLET**  
**EPICA 2.0**  
**05.03.2014**  
**AXA**

**PART**

**LIST**

QTY	DESCRIPTION	UNIT	PRICE	TOTAL	REMARKS
1	Front Bumper		\$	1,202.00	de ✓
2	Front Bumper Lower Absorber		\$	180.00	de ✓
3	Front Bumper Reinforcement		\$	356.00	bt ✓
4	Front Bumper Retainer RH		\$	102.00	na ✓
5	Front Bumper Retainer LH		\$	102.00	na ✓
6	Front Bumper Lower Grille		\$	78.00	de ✓
7	Front Bumper Lower Stiffener		\$	134.37	de ✓
8	Front Bumper Fog Lamp Outer Cover RH		\$	32.40	wt ✓
9	Front Bumper Fog Lamp Outer Cover LH		\$	32.40	wt ✓
10	Front tow hook bracket		\$	150.00	x Sw ✓
11	Front Support Panel AssY		\$	1,222.32	bt ✓
12	Front brace panel		\$	134.37	bt ✓
13	Headlamp RH (Lamp A-Head RH)		\$	816.00	act ✓
14	Headlamp RH inner panel		\$	611.16	Rx ✓
15	Headlamp LH (Lamp A-Head LH)		\$	816.00	? x crw ✓
16	Headlamp LH inner panel		\$	611.16	Rx ✓
17	Bonnet (Panel A-Hood)		\$	1,250.00	bt ✓
18	Bonnet Moulding		\$	257.00	de ✓
19	Centre 'CHEVROLET' Logo Badge		\$	144.30	na ✓
20	Bonnet lock		\$	60.00	bt ✓
21	Radiator Assembly		\$	618.00	? photo x ✓
22	Radiator upper hose		\$	30.00	? x de ✓
23	Radiator lower hose		\$	120.00	? x de ✓
24	Radiator Grille		\$	367.00	na ✓
25	Radiator Grille Top Cover		\$	45.02	de ✓
26	Radiator bracket		\$	150.00	na ✓
27	Fan Blade (Small)		\$	536.00	crw ✓
28	Fan Blade (Big)		\$	634.00	? x crw ✓
29	Aircon Condenser		\$	600.00	bt ✓
30	Air Intercooler		\$	652.00	? x crw ✓
31	Front Fender RH		\$	837.60	Rx ✓
32	Front Fender LH		\$	837.60	Rx ✓
33	Front Fender Liner RH		\$	47.00	x Sw ✓

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019828G  
**SHB 7986D - AXA**

ROEL

34	1	Front Fender Liner LH	\$	47.00 x NY
35	1	Rear Bumper	\$	1,202.00 de -
36	1	Rear Bumper Beam	\$	239.94 bf
37	1	Rear Bumper Centre Absorber	\$	260.00 de ✓
38	1	Rear Bumper Side Retainer RH	\$	68.76 ne ✓
39	1	Rear Bumper Side Retainer LH	\$	68.76 ne ✓
40	1	Rear Bumper Reflectors RH	\$	119.74 mis ✓
41	1	Rear Bumper Reflectors LH	\$	119.74 mis ✓
42	1	Rear Bumper Tow Hook Cover	\$	93.00 x NY ✓
43	1	Rear Luggage Floor Panel	\$	973.00 be ✓
44	1	Rear Luggage Floor Panel Insulator	\$	63.50 ne ✓
45	1	Rear Luggage Floor Panel Trim Board	\$	378.00 de ✓
46	1	Rear End Panel Outer	\$	623.76 bf ✓
47	1	Rear End Panel Inner Trim	\$	263.84 de ✓
48	1	Bootlid	\$	973.00 bf ✓
49	1	Bootlid Weatherstrip	\$	344.28 ne ✓
50	1	Bootlid Lock - Top	\$	466.56 bf ✓
51	1	Bootlid lock - bottom	\$	39.40 ne ✓
52	1	Bootlid 'CHEVROLET' Badge	\$	120.62 ne ✓
53	1	Bootlid Logo	\$	138.84 ne ✓
54	1	Bootlid 'EPICA LT' Badge	\$	119.84 ne ✓
55	1	Bootlid Reflector Centre	\$	217.97 x NY ✓
56	1	Bootlid Reflector RH	\$	128.40 x NY ✓
57	1	Bootlid Reflector LH	\$	128.40 ne ✓
58	1	Rear Tail Lamp RH	\$	479.30 ne ✓
59	1	Rear Tail Lamp Panel RH	\$	359.00 bf ✓
60	1	Rear Tail Lamp LH	\$	479.30 ne ✓
61	1	Rear Tail Lamp Panel LH	\$	359.00 ne ✓
62	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	1,110.00 R ✓
63	1	Rear Fender RH	\$	1,145.00 x NY ✓
64	1	Rear Fender Inner Cowling RH	\$	298.00 de ✓
65	1	Rear Fender Inner Trim RH	\$	418.44 de ✓
66	1	Rear Fender LH	\$	1,145.00 R ✓
67	1	Rear Fender Inner Cowling LH	\$	298.00 de ✓
68	1	Rear Fender Inner Trim LH	\$	418.44 de x NY ✓
<b>TOTAL</b>			\$	<b>27,473.53</b>
<b>10%</b>			\$	<b>2,747.35</b>
			\$	<b>24,726.18</b>

**Special Nett**

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.466-488 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
 SHB 7986D - AXA

ROEL

1 Set Front Bumper Fastener Clip	\$	24.00 <sup>na</sup> ✓
1 Set Radiator Grille Top Cover Clip	\$	10.00 <sup>na</sup> ✓
1 Cans Radiator Coolant	\$	60.00 <sup>na</sup> ✓
1 Set Radiator Grille clip	\$	35.00 <sup>na</sup> ✓
1 Set Bonnet under weatherstrip seal clips	\$	30.00 <sup>na</sup> ✓
1 Set Bonnet insulator clip	\$	30.00 <sup>na</sup> ✓
2 Bonnet stopper	\$	15.00 <sup>na</sup> ✓
2Set Front Fender Liner Clip	\$	40.00 <sup>na</sup> ✓
1 Set Front Licence Plate With Holder	\$	192.00 <sup>na</sup> ✓
1 Set Radiator Grille Clip	\$	18.00 <sup>na</sup> ✓
1 Set Radiator Grille Top Cover Clip	\$	10.00 <sup>na</sup> ✓
1 Set Rear Bumper Parking Sensor	\$	300.00 <sup>200na</sup> ✓
1 Set Rear Bumper Fastener Clip	\$	30.00 <sup>na</sup> ✓
1 Rear Boot Sticker 'Trans-cab'	\$	30.00 <sup>na</sup> ✓
1 Rear Boot Sticker '6555-3333'	\$	30.00 <sup>na</sup> ✓
1 Rear Exhaust Mounting	\$	10.00 <sup>X na</sup> ✓
1 Set Rear Fender Inner Trim Clip RH	\$	30.00 <sup>na</sup> ✓
1 Set Rear Fender Inner Trim Clip LH	\$	30.00 <sup>na</sup> ✓
1 Set Rear Fender Inner Cowling LH Clip	\$	30.00 <sup>na</sup> ✓
1 Set Rear Fender Inner Cowling RH Clip	\$	30.00 <sup>na</sup> ✓
1 Set Rear Bumper End Dust Cover Clip	\$	30.00 <sup>na</sup> ✓
1 Rear End Panel Sealant	\$	80.00 <sup>na</sup> ✓
2 Rear Windscreen Sealant	\$	100.00 <sup>X na</sup> ✓
1 Rear Windscreen Inner Sponge Seal	\$	100.00 <sup>X na</sup> ✓

**TOTAL \$ 1,294.00**

**TOTAL PARTS \$ 26,020.18**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3000. 5,600.00
To Check Electrical Lighting Concerned.	\$	100. 170.00
To Rust-Proofing Of The Affected Areas.	\$	120. 170.00
Putty And Spray Painting Of The Affected Portion.	\$	2400. 5,400.00
To reinstall rear bumper parking sensor.	\$	30. 170.00

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
**SHB 7986D - AXA**

**ROEL**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	100. 170.00
To transfer of fender fittings, attachments and perform water seepage test.	\$	100. 170.00
To supply and re-do rear luggage floor panel insulation padding.	\$	200. 380.00
To repair and realign rear exhaust pipe.	\$	120. 170.00
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	x un. 170.00
To transfer of luggage panel fittings and conduct water seepage test.	\$	100. 170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	x un. 170.00
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	x un. 170.00
To check steering geometry and computer wheel alignment	\$	x un. 220.00
Towing Fees.	\$	80. 120.00

Parts - 18066.78

SN - 984

Labour - 6350

25400.78

4/5 @ 20,300 \*

16 days 11/7/14

**TOTAL \$ 13,420.00**

**Over All Total \$ 39,440.18 x**

**Repair Days**

**20 Days**

Tayfith 97495749.

Lumpsum

16 days

Resuming after paint.

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
**SHB 7986D - AXA**

ROEL

date

63668862

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHB 7986D - ROEL**  
**KL1LA69RJBB122518\***  
**CHEVROLET**  
**EPICA 2.0**  
**05.03.2014**  
**AXA**

PART		LIST	
1	1 Front Bumper	\$	1,202.00 de ✓
2	1 Front Bumper Lower Absorber	\$	180.00 de ✓
3	1 Front Bumper Reinforcement	\$	356.00 bt ✓
4	1 Front Bumper Retainer RH	\$	102.00 nd ✓
5	1 Front Bumper Retainer LH	\$	102.00 wa ✓
6	1 Front Bumper Lower Grille	\$	78.00 de ✓
7	1 Front Bumper Lower Stiffener	\$	134.37 de ✓
8	1 Front Bumper Fog Lamp Outer Cover RH	\$	32.40 out ✓
9	1 Front Bumper Fog Lamp Outer Cover LH	\$	32.40 int ✓
10	1 Front tow hook bracket	\$	150.00 x ✓
11	1 Front Support Panel AssY	\$	1,222.32 bt ✓
12	1 Front brace panel	\$	134.37 bt ✓
13	1 Headlamp RH (Lamp A-Head RH)	\$	816.00 act ✓
14	1 Headlamp RH inner panel	\$	611.16 Rx ✓
15	1 Headlamp LH (Lamp A-Head LH)	\$	816.00 ? x ✓
16	1 Headlamp LH inner panel	\$	611.16 Rx ✓
17	1 Bonnet (Panel A-Hood)	\$	1,250.00 bt ✓
18	1 Bonnet Moulding	\$	257.00 de ✓
19	1 Centre 'CHEVROLET' Logo Badge	\$	144.30 wa ✓
20	1 Bonnet lock	\$	60.00 bt ✓
21	1 Radiator Assembly	\$	618.00 ? plus to x ✓
22	1 Radiator upper hose	\$	30.00 ? x ✓
23	1 Radiator lower hose	\$	120.00 ? x ✓
24	1 Radiator Grille	\$	367.00 car ✓
25	1 Radiator Grille Top Cover	\$	45.02 de ✓
26	1 Radiator bracket	\$	150.00 wa ✓
27	1 Fan Blade (Small )	\$	536.00 car ✓
28	1 Fan Blade ( Big )	\$	634.00 ? x ✓
29	1 Aircon Condenser	\$	600.00 bt ✓
30	1 Air Intercooler	\$	652.00 ? x ✓
31	1 Front Fender RH	\$	837.60 Rt ✓
32	1 Front Fender LH	\$	837.60 Lt ✓
33	1 Front Fender Liner RH	\$	47.00 x ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
**SHB 7986D - AXA**

ROEL

34	1	Front Fender Liner LH	\$	47.00 <sup>x</sup>
35	1	Rear Bumper	\$	1,202.00 <sup>de</sup>
36	1	Rear Bumper Beam	\$	239.94 <sup>bt</sup>
37	1	Rear Bumper Centre Absorber	\$	260.00 <sup>ad</sup>
38	1	Rear Bumper Side Retainer RH	\$	68.76 <sup>re</sup>
39	1	Rear Bumper Side Retainer LH	\$	68.76 <sup>re</sup>
40	1	Rear Bumper Reflectors RH	\$	119.74 <sup>mis</sup>
41	1	Rear Bumper Reflectors LH	\$	119.74 <sup>mis</sup>
42	1	Rear Bumper Tow Hook Cover	\$	93.00 <sup>?</sup>
43	1	Rear Luggage Floor Panel	\$	973.00 <sup>bu</sup>
44	1	Rear Luggage Floor Panel Insulator	\$	63.50 <sup>re</sup>
45	1	Rear Luggage Floor Panel Trim Board	\$	378.00 <sup>de</sup>
46	1	Rear End Panel Outer	\$	623.76 <sup>bt</sup>
47	1	Rear End Panel Inner Trim	\$	263.84 <sup>de</sup>
48	1	Bootlid	\$	973.00 <sup>bt</sup>
49	1	Bootlid Weatherstrip	\$	344.28 <sup>bu</sup>
50	1	Bootlid Lock - Top	\$	466.56 <sup>bt</sup>
51	1	Bootlid lock - bottom	\$	39.40 <sup>bt</sup>
52	1	Bootlid 'CHEVROLET' Badge	\$	120.62 <sup>re</sup>
53	1	Bootlid Logo	\$	138.84 <sup>re</sup>
54	1	Bootlid 'EPICA LT' Badge	\$	119.84 <sup>re</sup>
55	1	Bootlid Reflector Centre	\$	217.97 <sup>?</sup>
56	1	Bootlid Reflector RH	\$	128.40 <sup>?</sup>
57	1	Bootlid Reflector LH	\$	128.40 <sup>re</sup>
58	1	Rear Tail Lamp RH	\$	479.30 <sup>re</sup>
59	1	Rear Tail Lamp Panel RH	\$	359.00 <sup>bt</sup>
60	1	Rear Tail Lamp LH	\$	479.30 <sup>re</sup>
61	1	Rear Tail Lamp Panel LH	\$	359.00 <sup>ad</sup>
62	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	1,110.00 <sup>Rx</sup>
63	1	Rear Fender RH	\$	1,145.00 <sup>Rx</sup>
64	1	Rear Fender Inner Cowling RH	\$	298.00 <sup>de</sup>
65	1	Rear Fender Inner Trim RH	\$	418.44 <sup>de</sup>
66	1	Rear Fender LH	\$	1,145.00 <sup>Rx</sup>
67	1	Rear Fender Inner Cowling LH	\$	298.00 <sup>de</sup>
68	1	Rear Fender Inner Trim LH	\$	418.44 <sup>de</sup>

<b>TOTAL</b>	<b>\$</b>	<b>27,473.53</b>
<b>10%</b>	<b>\$</b>	<b>2,747.35</b>
	<b>\$</b>	<b>24,726.18</b>

**Specical Nett**

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHB 7986D - AXA****ROEL**

1 Set Front Bumper Fastener Clip	\$	24.00 <sup>nd</sup> ✓
1 Set Radiator Grille Top Cover Clip	\$	10.00 <sup>nd</sup> ✓
1 Cans Radiator Coolant	\$	60.00 <sup>nd</sup> ✓
1 Set Radiator Grille clip	\$	35.00 <sup>nd</sup> ✓
1 Set Bonnet under weatherstrip seal clips	\$	30.00 <sup>nd</sup> ✓
1 Set Bonnet insulator clip	\$	30.00 <sup>nd</sup> ✓
2 Bonnet stopper	\$	15.00 <sup>nd</sup> ✓
2Set Front Fender Liner Clip	\$	40.00 <sup>nd</sup> ✓
1 Set Front Licence Plate With Holder	\$	192.00 <sup>nd</sup> ✓
1 Set Radiator Grille Clip	\$	18.00 <sup>nd</sup> ✓
1 Set Radiator Grille Top Cover Clip	\$	10.00 <sup>nd</sup> ✓
1 Set Rear Bumper Parking Sensor	\$	300.00 <sup>2.00</sup> ✓
1 Set Rear Bumper Fastener Clip	\$	30.00 <sup>nd</sup> ✓
1 Rear Boot Sticker 'Trans-cab'	\$	30.00 <sup>nd</sup> ✓
1 Rear Boot Sticker '6555-3333'	\$	30.00 <sup>nd</sup> ✓
1 Rear Exhaust Mounting	\$	10.00 <sup>nd</sup> ✓
1 Set Rear Fender Inner Trim Clip RH	\$	30.00 <sup>nd</sup> ✓
1 Set Rear Fender Inner Trim Clip LH	\$	30.00 <sup>nd</sup> ✓
1 Set Rear Fender Inner Cowling LH Clip	\$	30.00 <sup>nd</sup> ✓
1 Set Rear Fender Inner Cowling RH Clip	\$	30.00 <sup>nd</sup> ✓
1 Set Rear Bumper End Dust Cover Clip	\$	30.00 <sup>nd</sup> ✓
1 Rear End Panel Sealant	\$	80.00 <sup>nd</sup> ✓
2 Rear Windscreen Sealant	\$	100.00 <sup>nd</sup> ✓
1 Rear Windscreen Inner Sponge Seal	\$	100.00 <sup>nd</sup> ✓

**TOTAL \$ 1,294.00****TOTAL PARTS \$ 26,020.18**

Panel Beating, Knocking And Straightening  
The Necessary Portion, Remove And  
Renewal Of Parts, Adjust And Realign The  
Same

\$ 5,600.00<sup>3000</sup>

To Check Electrical Lighting Concerned.

\$ 170.00<sup>100</sup>

To Rust-Proofing Of The Affected Areas.

\$ 170.00<sup>120</sup>Putty And Spray Painting Of The Affected  
Portion.\$ 5,400.00<sup>2400</sup>

To reinstall rear bumper parking sensor.

\$ 170.00<sup>50</sup>

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHB 7986D - AXA**

**ROEL**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	100 170.00
To transfer of fender fittings, attachments and perform water seepage test.	\$	100 170.00
To supply and re-do rear luggage floor panel insulation padding.	\$	200 380.00
To repair and realign rear exhaust pipe.	\$	120 170.00
To Remove And Refit Rear W/ Screen Glass To Facilitate Bodywork Repair.	\$	x 170.00
To transfer of luggage panel fittings and conduct water seepage test.	\$	100 170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	x 170.00
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	x 170.00
To check steering geometry and computer wheel alignment	\$	x 220.00
Towing Fees.	\$	80 120.00

Parts - 15483.78  
 SN - 984  
 Labour - 6350  
22817.78  
 1/58 18250\*

<b>TOTAL</b>	<b>\$</b>	<b>13,420.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>39,440.18</b>

**Repair Days**

**20 Days**

Tayth 97495749  
 Lumpsum.

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835  
 TEL NO 6287 6666 FAX NO 6366 8862  
 CO/GST REG NO.201019626G  
**SHB 7986D - AXA**

**ROEL**

*base*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHB 7986D - ROEL**  
 KL1LA69RJBB122518\*  
 CHEVROLET  
 EPICA 2.0  
 05.03.2014  
**AXA**

PART		LIST
1	1 Front Bumper	\$ 1,202.00 <i>de ✓</i>
2	1 Front Bumper Lower Absorber	\$ 180.00 <i>de ✓</i>
3	1 Front Bumper Reinforcement	\$ 356.00 <i>bt ✓</i>
4	1 Front Bumper Retainer RH	\$ 102.00 <i>na ✓</i>
5	1 Front Bumper Retainer LH	\$ 102.00 <i>na ✓</i>
6	1 Front Bumper Lower Grille	\$ 78.00 <i>de ✓</i>
7	1 Front Bumper Lower Stiffener	\$ 134.37 <i>de ✓</i>
8	1 Front Bumper Fog Lamp Outer Cover RH	\$ 32.40 <i>na ✓</i>
9	1 Front Bumper Fog Lamp Outer Cover LH	\$ 32.40 <i>na ✓</i>
10	1 Front tow hook bracket	\$ 150.00 <i>X SVL ✓</i>
11	1 Front Support Panel AssY	\$ 1,222.32 <i>bt ✓</i>
12	1 Front brace panel	\$ 134.37 <i>na ✓</i>
13	1 Headlamp RH (Lamp A-Head RH)	\$ 816.00 <i>na ✓</i>
14	1 Headlamp RH inner panel	\$ 611.16 <i>Ry ✓</i>
15	1 Headlamp LH (Lamp A-Head LH)	\$ 816.00 <i>Ry ✓</i>
16	1 Headlamp LH inner panel	\$ 611.16 <i>Ry ✓</i>
17	1 Bonnet (Panel A-Hood)	\$ 1,250.00 <i>na ✓</i>
18	1 Bonnet Moulding	\$ 257.00 <i>na ✓</i>
19	1 Centre 'CHEVROLET' Logo Badge	\$ 144.30 <i>na ✓</i>
20	1 Bonnet lock	\$ 60.00 <i>bt ✓</i>
21	1 Radiator Assembly	\$ 618.00 <i>na ✓</i>
22	1 Radiator upper hose	\$ 30.00 <i>X SVL ✓</i>
23	1 Radiator lower hose	\$ 120.00 <i>X SVL ✓</i>
24	1 Radiator Grille	\$ 367.00 <i>na ✓</i>
25	1 Radiator Grille Top Cover	\$ 45.02 <i>de ✓</i>
26	1 Radiator bracket	\$ 150.00 <i>na ✓</i>
27	1 Fan Blade (Small )	\$ 536.00 <i>na ✓</i>
28	1 Fan Blade ( Big )	\$ 634.00 <i>X SVL ✓</i>
29	1 Aircon Condenser	\$ 600.00 <i>bt ✓</i>
30	1 Air Intercooler	\$ 652.00 <i>X na ✓</i>
31	1 Front Fender RH	\$ 837.60 <i>Ry ✓</i>
32	1 Front Fender LH	\$ 837.60 <i>Ry ✓</i>
33	1 Front Fender Liner RH	\$ 47.00 <i>X na ✓</i>

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHB 7986D - AXA**

**ROEL**

34	1	Front Fender Liner LH	\$	0 47.00 x 2/2
35	1	Rear Bumper	\$	1,202.00 de ✓
36	1	Rear Bumper Beam	\$	239.94 b/f ✓
37	1	Rear Bumper Centre Absorber	\$	260.00 aa ✓
38	1	Rear Bumper Side Retainer RH	\$	68.76 ne ✓
39	1	Rear Bumper Side Retainer LH	\$	68.76 ne ✓
40	1	Rear Bumper Reflectors RH	\$	119.74 m/s ✓
41	1	Rear Bumper Reflectors LH	\$	119.74 m/s ✓
42	1	Rear Bumper Tow Hook Cover	\$	0 93.00 ? s/c ✓
43	1	Rear Luggage Floor Panel	\$	973.00 bu ✓
44	1	Rear Luggage Floor Panel Insulator	\$	63.50 ne ✓
45	1	Rear Luggage Floor Panel Trim Board	\$	378.00 de ✓
46	1	Rear End Panel Outer	\$	623.76 b/f ✓
47	1	Rear End Panel Inner Trim	\$	263.84 de ✓
48	1	Bootlid	\$	973.00 b/f ✓
49	1	Bootlid Weatherstrip	\$	344.28 bu ✓
50	1	Bootlid Lock - Top	\$	466.56 b/f ✓
51	1	Bootlid lock - bottom	\$	39.40 b/f ✓
52	1	Bootlid 'CHEVROLET' Badge	\$	120.62 ne ✓
53	1	Bootlid Logo	\$	138.84 ne ✓
54	1	Bootlid 'EPICA LT' Badge	\$	119.84 ne ✓
55	1	Bootlid Reflector Centre	\$	0 217.97 ? s/c ✓
56	1	Bootlid Reflector RH	\$	0 128.40 ? s/c ✓
57	1	Bootlid Reflector LH	\$	128.40 bu ✓
58	1	Rear Tail Lamp RH	\$	479.30 bu ✓
59	1	Rear Tail Lamp Panel RH	\$	359.00 b/f ✓
60	1	Rear Tail Lamp LH	\$	479.30 bu ✓
61	1	Rear Tail Lamp Panel LH	\$	359.00 b/f ✓
62	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	1,110.00 R x
63	1	Rear Fender RH	\$	1,145.00 R x
64	1	Rear Fender Inner Cowling RH	\$	298.00 de ✓
65	1	Rear Fender Inner Trim RH	\$	418.44 de ✓
66	1	Rear Fender LH	\$	1,145.00 R x
67	1	Rear Fender Inner Cowling LH	\$	298.00 de ✓
68	1	Rear Fender Inner Trim LH	\$	418.44 de ✓ x

<b>TOTAL</b>	<b>\$</b>	<b>27,473.53</b>
<b>10%</b>	<b>\$</b>	<b>2,747.35</b>
	<b>\$</b>	<b>24,726.18</b>

**Special Nett**

**TRANS-CAB AUTO SERVICES PTE LTD**

NO 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835  
 TEL NO 6287 6666 FAX NO 6366 8862  
 COI/GST REG NO 201019626G  
**SHB 7986D - AXA**

ROEL

1 Set Front Bumper Fastener Clip	\$	24.00 <sup>nd</sup> ✓
1 Set Radiator Grille Top Cover Clip	\$	10.00 <sup>nd</sup> ✓
1 Cans Radiator Coolant	\$	60.00 <sup>nd</sup> ✓
1 Set Radiator Grille clip	\$	35.00 <sup>nd</sup> ✓
1 Set Bonnet under weatherstrip seal clips	\$	30.00 <sup>nd</sup> ✓
1 Set Bonnet insulator clip	\$	30.00 <sup>nd</sup> ✓
2 Bonnet stopper	\$	15.00 <sup>nd</sup> ✓
2Set Front Fender Liner Clip	\$	40.00 <sup>nd</sup> ✓
1 Set Front Licence Plate With Holder	\$	192.00 <sup>nd</sup> ✓
1 Set Radiator Grille Clip	\$	18.00 <sup>nd</sup> ✓
1 Set Radiator Grille Top Cover Clip	\$	10.00 <sup>nd</sup> ✓
1 Set Rear Bumper Parking Sensor	\$	300.00 <sup>nd</sup> ✓
1 Set Rear Bumper Fastener Clip	\$	30.00 <sup>nd</sup> ✓
1 Rear Boot Sticker 'Trans-cab'	\$	30.00 <sup>nd</sup> ✓
1 Rear Boot Sticker '6555-3333'	\$	30.00 <sup>nd</sup> ✓
1 Rear Exhaust Mounting	\$	10.00 <sup>nd</sup> ✓
1 Set Rear Fender Inner Trim Clip RH	\$	30.00 <sup>nd</sup> ✓
1 Set Rear Fender Inner Trim Clip LH	\$	30.00 <sup>nd</sup> ✓
1 Set Rear Fender Inner Cowling LH Clip	\$	30.00 <sup>nd</sup> ✓
1 Set Rear Fender Inner Cowling RH Clip	\$	30.00 <sup>nd</sup> ✓
1 Set Rear Bumper End Dust Cover Clip	\$	30.00 <sup>nd</sup> ✓
1 Rear End Panel Sealant	\$	80.00 <sup>nd</sup> ✓
2 Rear Windscreen Sealant	\$	100.00 <sup>nd</sup> ✓
1 Rear Windscreen Inner Sponge Seal	\$	100.00 <sup>nd</sup> ✓

**TOTAL \$ 1,294.00**

**TOTAL PARTS \$ 26,020.18**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3000. 5,600.00
To Check Electrical Lighting Concerned.	\$	100 170.00
To Rust-Proofing Of The Affected Areas.	\$	120 170.00
Putty And Spray Painting Of The Affected Portion.	\$	2400 5,400.00
To reinstall rear bumper parking sensor.	\$	30 170.00

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835  
 TEL NO. 6287 6666 FAX NO 6366 8862  
 CO/GST REG NO 201019626G  
 SHB 7986D - AXA

ROEL

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	100 170.00
To transfer of fender fittings, attachments and perform water seepage test.	\$	100 170.00
To supply and re-do rear luggage floor panel insulation padding.	\$	200 380.00
To repair and realign rear exhaust pipe.	\$	120 170.00
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	X 170.00
To transfer of luggage panel fittings and conduct water seepage test.	\$	100 170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	X 4.1 170.00
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	X 2.1 170.00
To check steering geometry and computer wheel alignment	\$	X 2.2 220.00
Towing Fees.	\$	30 120.00
<b>TOTAL</b>	<b>\$</b>	<b>13,420.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>39,440.18</b>

**Repair Days** 18278.42. **20 Days**  
 1/5/14600 \* Taylors 97495749.  
 Lumpsum  
 16 days



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607193R

511 BRIDGE LANE #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (65) 62563561 FAX : (65) 62564315

Your ref: To Be Advised  
Our ref: CC3/AXA14005031/T1ra3

Date: 19.03.2014

The Motor Claims Department  
M/s AXA INSURANCE SINGAPORE PTE LTD  
Attn: Sir / Madam

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SHB 7986D**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13.03.2014 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-  
and have the following to report:-

Workshop Estimate Amount	: S\$	<u>39,440.18</u>
Revised Estimate Amount	: S\$	<u>22,817.78</u>
"Check" Items Amount	: S\$	<u>2,978.43</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:  
The vehicle sustained damages at the  
Front & Rear Portion



Comments/Present Status:  
Damages Consistent  
Estimated normal period for repairs: 16 days

Yours faithfully,

**MOHD. TAUFIKH**  
**Licensed Appraiser**

Vic

---

**From:** Vic  
**Sent:** Thursday, 12 June, 2014 9:12 AM  
**To:** Jacqueline Leong Kin Mun  
**Cc:** Winnie Ho Ping Ping; Admin-A (LKK Auto); Vic; Kathy Lai  
**Subject:** RE: WP / TRANS-CAB AUTO / C0297701 / OD- SKB6310A / TP- SHB7986D / DOA: 05.03.2014 / EST: 39,440.18 / NO XS / JL  
**Attachments:** OI GIA REPORT.pdf, TP GIA REPORT.pdf

Yoru Ref: C0297701  
Our Ref: CC3/AXA14005031/T1ra3

Dear Ms Jacqueline,

ACCIDENT INVOLVING VEHICLES SKB 6310A / SHB 7986D / OTHERS ON 05.03.14

We refer to the above matter.

It was reported that this is a 5 vehicle chain collision where insured was the 4<sup>th</sup> vehicle, TP was the 3<sup>rd</sup> vehicle and the first vehicle is a Police Vehicle (government vehicle). Please see attached OI and TP GIA Reports.

We had spoken to the insured where she confirmed that the first vehicle was a police car and she was also informed of the TP claim and the NCD issues where she understands.

Kindly advice if we can settle the matter under BOLA 28 (chain collision) or we can only settle by contribution 10-20% to TP as there is one more vehicle behind insured.

Thank you.

Kind Regards,  
Vic Alpeh Sanghilan  
LKK Auto Consultants Pte Ltd  
51 Ubi Avenue 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933  
DID : 65- 6841 2157  
Fax : 65- 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

---

**From:** Admin-A (LKK Auto)  
**Sent:** Wednesday, 11 June, 2014 3:17 PM  
**To:** Vic  
**Subject:** FW: WP / TRANS-CAB AUTO / C0297701 / OD- SKB6310A / TP- SHB7986D / DOA: 05.03.2014 / EST: 39,440.18 / NO XS / JL

---

**From:** Jacqueline Leong Kin Mun [<mailto:Jacqueline.Leong@axa.com.sg>]  
**Sent:** Tuesday, 8 April, 2014 4:45 PM  
**To:** Admin-B (LKK Auto)  
**Cc:** Kelvyna Ngian; Admin-A (LKK Auto); SUR  
**Subject:** RE: WP / TRANS-CAB AUTO / C0297701 / OD- SKB6310A / TP- SHB7986D / DOA: 05.03.2014 / EST: 39,440.18 / NO XS / JL

Hi Mei Kwan  
OSP cleared. Pls proceed DS. Tks.

**From:** Mei Kwan (Admin-B) [mailto:[admin-b@lkkauto.com](mailto:admin-b@lkkauto.com)]  
**Sent:** Tuesday, April 01, 2014 7:50 PM  
**To:** Winnie Ho Ping Ping; Jacqueline Leong Kin Mun  
**Cc:** Kelyna Ngian; Admin-A (LKK Auto); SUR  
**Subject:** RE: WP / TRANS-CAB AUTO / C0297701 / OD- SKB6310A / TP- SHB7986D / DOA: 05.03.2014 / EST: 39,440.18 / NO XS / JL

**WITHOUT PREJUDICE**

Dear Winnie / Jacqueline,

We refer to our below email.

Kindly advise whether we can proceed direct settlement for this case.

Thank You.

Best Regards,  
*Mei Kwan*  
LKK Auto Consultants Pte Ltd  
DID: 6366 0055  
FAX: 6741 4108  
EMAIL: [admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)

---

**From:** Winnie Ho Ping Ping [mailto:[winnie.ho@axa.com.sg](mailto:winnie.ho@axa.com.sg)]  
**Sent:** Thursday, 20 March, 2014 3:48 PM  
**To:** assignments; 'Team A'; 'Team B'; SUR  
**Cc:** Jacqueline Leong Kin Mun; Kelyna Ngian  
**Subject:** WP / TRANS-CAB AUTO / C0297701 / OD- SKB6310A / TP- SHB7986D / DOA: 05.03.2014 / EST: 39,440.18 / NO XS / JL

Thanks & Regards

---

Winnie Ho  
Claims Assistant – Motor Claims  
AXA Insurance Singapore Pte Ltd  
8 Shenton Way, #27-01 AXA Tower, Singapore 068811  
[winnie.ho@axa.com.sg](mailto:winnie.ho@axa.com.sg)  
DID: (65) 6880 4833 Fax: (65) 6880 4838  
Website: [www.axa.com.sg](http://www.axa.com.sg)



This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

 Please consider the environment before printing this email

---

**From:** Admin-A (LKK Auto) [mailto:[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)]  
**Sent:** Wednesday, March 19, 2014 4:47 PM  
**To:** Winnie Ho Ping Ping; Tan Tiong Beng; Kitty Teo Poh Guek

**Cc:** KKLau; Kathy Lai

**Subject:** Direct Settlement - Accident Involving SKB 6310A (OI : AXA - TBA) & SHB 7986D (TP : LKK REF - CC3/AXA14005031/T1ra3) on 05.03.2014

**WITHOUT PREJUDICE**

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHB 7986D at M/s Trans-cab Auto Services Pte Ltd.

Enclosed herewith a copy of TP's GIA report , estimated cost of repair and preliminary advice for your perusal.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Kathy and she can be contacted at DID: 6841 2928.

Thank You.

Best Regards,

*Mei Kwan*

LKK Auto Consultants Pte Ltd

DID: 6366 0055

FAX: 6741 4108

EMAIL: [admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)