

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

20/02/19

(Wed)

LKK

after 10am

23/01/2019

Owner: MKM CAR LEASING PTE LTD

Not with air

1/1/19 8?

Money After Paint
2 day

ESTIMATE TO REPAIR TOYOTA CAMRY 2.0A - SJQ8264U

1pc	front bumper	\$ 665.55 ?
2pcs	front bumper side retainer @\$132.25	h \$ 264.50 X
1pc	front bumper sponge	\$ 181.60 ?
1pc	front bumper reinforcement	n \$ 289.75 X
1pc	front bumper number garnish	h \$ 85.58 X
1pc	front centre grille	cm \$ 282.10 ✓
1pc	front RH headlamp	\$ 1,200.75 ?
		\$ 2,969.83
		\$ 742.46
		\$ 2,227.37
		\$ 80.00 15h
		un \$ 80.00 X
		\$ 600.00 220l
		\$ 500.00 200l
		\$ 3,487.37

less 25%

1 set & number plate & coding \$45 SN

wiring

tuffkote

spray painting

labour charges

Total



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: