



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685692
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/03/2019

User ID : PehEngHock

Section A - Accident Details

Registration Number	PC8199R
Case Reference Number	BPS/01/19/3002
Registration Date	9/16/2017
Company Type	Bus-Plus Services Pte Ltd
Make	MITSUBISHI
Model	MITSUBISHI ROSA BE641JRMDEB
Driver	Makmon Bin Mohd Abdul Rahman
Type of Accident	Head To Side
Accident Date and Time	1/8/2019 4:30 PM
Accident Reported Date and Time	1/9/2019 11:09 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100420
Special Instruction to ARC, if any	FRONTAL LEFT SIDE BUMPER OF BUS DISLODGED AND DENTED. PLEASE CHECK LEFT SIDE OF BUS FOR ANY OTHER DAMAGE.
Prepared Date and Time	2/22/2019 10:50 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$500.00	\$300.00
Total Spray Cost	\$400.00	\$400.00
Total Spare Part Cost	\$2,225.76	\$405.00
Total Other Cost	\$210.00	\$130.00
TOTAL COST	\$3,335.76	\$1,235.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	4.0
Prepared / Adjusted By	Peh Eng Hock	Resul
ARC / Surveyor Sign Off Date	04/03/2019 2:03 PM	04/03/2019 2:34 PM
Signature	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4
Singapore 757705
Tel: 65 6362 3422
Fax: 65 6368 7420

SMRT Vehicle Repair Estimate

n/w repair
17 months

Group: Buses / Taxis / Private Car

Reg. No.: PC 6199 R

Make / Mo: MITSUBISHI FUSO ROSA

Chassis: BE641JK30367

Name of D: BUS-PLUS SERVICES PTE LTD

Date/Time of Accid: 08-01-2019 / 16:30HRS

Surveyor is Require YES / NO

If Yes, VICOM / LKK / AIS / Others MSIG

Vehicle is Towed EYES / NO

Accident reporting: 09-01-19 16:10

Type of Accident: Skid / Head-Rear / Head-On / Side Swipe / Others

Special Instruction to ARC, if any:

THIRD PARTY CLAIM


Ref. No. BRS/01/19/3002

Reg. Date: 16/9/2017

Mileage:

Rental/Replacement Vehicle: Yes / No

The damages on the vehicle are as indicated in the following diagram:



Accident Repair Job Card No: Date Prepared:

Summary of Repair Estimates

Quotation from ARC

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	\$ 500.00	\$ -
Total Spray Painting Charges	\$ 400.00	\$ -
Total Material Charges	\$ 2,225.77	\$ -
Other Charges	\$ 210.00	\$ -
TOTAL	\$ 3,335.77	\$ -

Lump Sum Repair, if any:

No. of Repair Days: [4] days

Signature: Prepared by: Adjusted by: Rasul - CLK

Q/N No. Invoice No.

Signed:

Date:

Part 1 - Labour Works

Page (2)

Job Scope	Quotation from ARC	
To renew damaged parts, replace and realign hydraulic, and aligned all parts	\$ 500.00	300
Total Labour Cost	\$ 500.00	\$ -

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray affected areas	\$ 400.00	400
Spray Painting	\$ 400.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page ()

Job Scope	Quotation from ARC	
To remove /refit wiring check	\$ 60.00	30
To remove/replace Advertisement sticker	\$ 150.00	100
Total Other Costs	\$ 210.00	

920

Part 4 - Spare Parts / Material Usage

To be completed by Service Advisor, ARC							
Part Number	Parts Description	Qty	Cost Price (\$)	COST LESS 10%	Final Price (\$)	Repair (R) / Replace (/)	Not given (X) / Repair (R) / Replace (/)
1	FRONT BUMPER	1	\$ 1,588.97	10%	\$ 1,430.07	Repair (R)	Not given (X)
2	FRONT BUMPER ADVERTISEMENT STICKER	1	\$ 450.00	10%	\$ 405.00	Repair (R)	Not given (X)
3	FRONT BUMPER SIDE BRACKET LH	1	\$ 113.60	10%	\$ 102.24	X	
4	FRONT SIDE LAMP LH	1	\$ 205.16	10%	\$ 184.64	X?	
5	FRONT SIDE DOOR SIGNAL LAMP LH	1	\$ 115.35	10%	\$ 103.82	X	
TOTAL MATERIALS			\$ 2,473.08	-	\$ 2,225.77		

Surveyor Remark:

Pass - 17p 90010068
 4 days
 P/P
 22/01/19 P 1525

405
 \$30
 1235
 4 days