

INSURANCE

INS. CASE OWNER:

CC 6/CTI1900

3348, KKK 12/12/19 LKK
IDAC

Surveyor:

Kenneth

DOI:

ASSIGNMENT

20/1/19

Date / Time:

20/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMG 23786

Name of Insured:

Fanny SHEE LIM

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

14/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

AMPDSN1832461800

MERCEDES

MOUNT ELIZABETH

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKP 6297E



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hua Song Spray



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SKP 6297E - 4

SMG 23786 - 7

STAGE

DATE / PIC

3/4/19

CALL 01, NO RESPONSE

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI: OK 10/1/19 - 2L

9/4/19 @ 10:55 AM

CALL 01, NO RESPONSE

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

14/8/19 - FILE PAS TO TYPE MANHATTAN

15/1/2020 - FILE PAS TO HUA TO CLOSE

* M80V - X original

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with: Hua Song

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

9

If NO or B 28, Ass. Lia:

Repair Cost:

SS 3005.89

001 FROM MINOR ROBO

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS 320.00

(5 30 x 4 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

SS 2.45

COPY SENT

Medical:

SS

1) Claim Status: Non-Report/Private Settle

Disbursement:

SS

(e.g. Tow/Independent)

2) Report Format: 71

Legal Cost

SS

3) Survey Fee: \$400

Total:

SS 3333.34

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 3333.34

Name 1:

Hua Song Spray Painting Co.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

* ASS. REC. BY:

REF: C721

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

1 / File pass to

PIP - \$3005.89 (Red \$1609.41 / 35%)

Veh No: SKP 67975 Yr Regn: 08, 14

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or AI:

Make: BMW X1 c.c. 1997

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading 55380 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAVL 92010V X 86521

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modf: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225 / 50 R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 16/2/19

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 20/2/19

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Data/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Data/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Parking

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



Auto
Consultants
Pte Ltd

Company Registration No. 189607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62563315

Your ref: To Be Advised
Our ref: CC6/CTI19003348/Khb3

Date: 22.02.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKP6797E

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.02.2019 at the premises of M/s Hwa Seng Spray Painting Co and have the following to report:-

Workshop Estimate Amount	: S\$	4,531.20
Revised Estimate Amount	: S\$	2,651.20
"Check" Items Amount	: S\$	585.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

HWA SENG SPRAY PAINTING CO
 160 Sin Ming Drive
 #05-11 Sin Ming Autocity
 SINGAPORE 575722
 (COMPANY REGISTRATION NO. 09574400B)
 TEL : 64533100
 FAX : 62669932

Date of Accident. 16/02/2019
 Your insured
 Vehicle number: SMG2378G

ESTIMATE REPAIR COSTS TO BMW X1 REG. NO. SKP 6797 E

1pc Left Front Door
 1pc Door Rubber Body
 1pc Door Power Window Regulator
 1pc Power Window Motor
 1pc Emblem '5 Drive'
 1pc Emblem '20i'
 1pc N/S side skirt

	SS	
By	1380.00	✓
Re	180.00	✓
Net	310.00	✓
NN	340.00	✓
Re	50.00	✓
Re	58.00	✓
Re	550.00	X

Sup
 N/S/F DOOR CHECKER \$84.10 / NW
 Less : 10%

2868.00
 286.80

2581.20

LABOUR & MISC CHARGES

Panel Knocking
 Spray Painting
 Tuff Kote
 Labour to transfer door trim & attach part


500.00	400
1000.00	660
250.00	30
200.00	60

TOTAL

4531.20

Not Authorized
 1. B1
 Recovery B4pain
 4 days

HWA SENG SPRAY PAINTING COMPANY



LKK Auto Consultants hence notify the Repainer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repainer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI19003348/Kda3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 20-01-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMG 2378G	Veh. Inspected	SKP 6797E	
Policy No.	DMPCSN1832761800	Coverage (\$)	0.00	
Claim No.	SNM19D200884C02	Excess (\$)	0.00	
Assign From		Assign Date	20/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	BMW X1 (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WBAVL92010VX86521	Colour	METALLIC BLACK	
Odometer	55380	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	PIRELLI	7 mm	
L/H Front Tyre	225/50 R17	PIRELLI	7 mm	
R/H Rear Tyre	225/50 R17	PIRELLI	7 mm	
L/H Rear Tyre	225/50 R17	PIRELLI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/02/2019	Inspection Date	20/02/2019	
Survey held at	HWA SENG SPRAY PAINTING COMPANY 160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 6797E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LEFT FRONT DOOR	BENT	1,380.00	1,380.00
1	DOOR RUBBER BODY	NECESSARY	180.00	180.00
1	DOOR POWER WINDOW REGULATOR	NECESSARY	310.00	310.00
1	POWER WINDOW MOTOR	NOT NECESSARY	340.00	-
1	EMBLEM '5 DRIVE'	NECESSARY	50.00	50.00
1	EMBLEM '20I'	NECESSARY	58.00	58.00
1	N/S SIDE SKIRT	SERVICEABLE	550.00	-
1	N/S/F DOOR CHECKER	NECESSARY	84.10	84.10
	LESS 10% DISCOUNT		-295.21	-206.21
			2,656.89	1,855.89
	LABOUR			
	PANEL KNOCKING.		500.00	400.00
	SPRAY PAINTING.		1,000.00	660.00
	TUFF KOTE.		250.00	30.00
	LABOUR TO TRANSFER DOOR TRIM & ATTACH PART.		200.00	60.00
			1,950.00	1,150.00
	GRAND TOTAL		4,606.89	3,005.89
	RECOMMENDED COST OF REPAIRS			3,005.89

Report Ref No. CC6/CT119003348/Kda3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.