

Kh

HWA SENG SPRAY PAINTING CO
 160 Sin Ming Drive
 #05-11 Sin Ming Autocity
 SINGAPORE 575722
 (COMPANY REGISTRATION NO. 08574400B)
 TEL: 64533100
 FAX: 62669932

Date of Accident: 16/02/2019
 Your Insured
 Vehicle number: SMG 2378G

ESTIMATE REPAIR COSTS TO BMW X1 REG. NO. SKP 6797 E


		SS	
1pc	Left Front Door	1380.00	✓
1pc	Door Rubber Body	180.00	✓
1pc	Door Power Window Regulator	310.00	✓
1pc	Power Window Motor	340.00	X
1pc	Emblem '5 Drive'	50.00	✓
1pc	Emblem '20i'	58.00	✓
1pc	N/S side skirt	550.00	X
		<u>2868.00</u>	
	Less: 10%	286.80	
		<u>2581.20</u>	

LABOUR & MISC CHARGES

Panel Knocking	500.00	✓
Spray Painting	1000.00	✓
Tuff Kote	250.00	✓
Labour to transfer door trim & attach part	200.00	✓
	<u>200.00</u>	✓
TOTAL	<u>4531.20</u>	

NOT Authorized
 1-B.I
 Anthony Bepain
 4 days

HWA SENG SPRAY PAINTING COMPANY



8 3005-89

HWA SENG SPRAY PAINTING CO

1 of 1

160 Sin Ming Drive, #05-11,

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 095744008)

TEL: 64533100

FAX: 62669932

Estimate repair cost to BMW X1 reg no : SKP 6797 E

Supplementary parts

1pc n/s/f door checker

Mr 84.10 ✓

Less 10%

8.41

75.69

HWA SENG SPRAY PAINTING COMPANY

A handwritten signature in black ink, consisting of several overlapping strokes, is written over a horizontal line.