



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 22-02-2019

VEHICLE NO. : SGU9295M
ACCIDENT DATE : 21-02-2019 12:00
THIRD PARTY REF. : GBB4457E

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SGU9295M NISSAN LATIO

QTY PARTS DESCRIPTION

AMOUNT (SG\$)

NETT ITEMS

1	1	FRONT HEADLAMP LH
2	1	FRONT BUMPER
3	1	FRONT BUMPER SIDE RETAINER LH
4	10	FRONT BUMPER CLIP@3.90

11	372.00	α
11	456.30	—
31	23.00	—
11	39.00	—

890.30

LESS 10 %

89.03

TOTAL (B)

801.27

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS
3	1	SPRAYPAINTING CHARGES

30.00 20

450.00 200

480.00 200

TOTAL (D)

960.00

ESTIMATE TOTAL

1,761.27

not Authorized
nor
d/s 2 day.
1/3/19
the photo after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: