

15/02/19

INS. CASE OWNER

CC4 / LPC1900

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SUM485K



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

14.3.19

FILE PASS TO TPST TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS 11,200

(8 days) Reduction:

56 %

Confirm by: Cks

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 15.04.19

Confirm with EOH

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 100%

Repair Cost:

SS 11,200.00

3 VEH CC OLD LAST

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 720.00

(S 80 x 9 days)

Loss of Income (LOI):

SS -

(S x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOU ☐

[Tick only one]

GIA/LTA Search

SS 36.45

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -

Total:

SS 11,956.45

Global Sum SS:

FINAL PAYMENT

Date/Time: 15.04.19

Confirm with: EOH

Email ☒Call ☐

Payee 1:

SS 11,956.45

Name 1:

Zoom AUTOWEBS PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

lpc

22/2/19

Estimated cost

① 117 WS / TP RES / OD RES / EVA / HW / MV

Inspected Vehicle No

SLM 248SK

at Work Shop no

zoom Autowerks

at

15 Kaki Bkt Rd 4 #01-53

Insured

Policy No

Vehicle No

Sum Insured


Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection



Bal. or Market Value

75k

IDAC Accident Rpt

Consistent? Yes or No

GIA / FR Seen

Consistent? Yes or No

Est. Repair

8 days Res.: Yes or No

Lump Sum

0 % 3 Val: Yes or No

CA / REV / REP / 24 HRS

lup

29702

Date

Person Contacted

Vehicle: IN / OUT

Date / Time

Action / Instruction

LRA 46525 Ags. 1 mile deep

4s: 11,200 (RED: 14,375.98 56%)

Date/Time: File Pass to:

☐

Preli. Report

if

☐

Final Report

Date/Time: File Return to:

if

Report Format

Lump Sum / LB 1: 12

Vehicle

SLM 248SK

3 17

Type: Car / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make

Toyota prius Hybrid

1797

Colour

Black

AP: Insured / Std / Nil / NA

Cap Reading

67766

IF Radio: Insured / Std / Nil / NA

Eng/No

Chassis

2VW50 503 4831

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Locked / Jammed / Leaked / Burnt or

Brake: Locked / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

R:

195/65-215

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A.

20/2/19

D.O.I

22/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & R.

The U/C / Chassis frame / Body Structure affected due to collision

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1. 5 + 15 = 20

1. 1000

1. 1000

1. 1000

1. 1000

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

ACCIDENT DATE : 20 February 2019

OWNER : AUTOBAHN RENT A CAR PTE LTD

REG NO. : SLM 2485 K

MAKE/MODEL : TOYOTA PRIUS

27 February 2019

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding	\$ All 55.00 ✓
1	Rear tailgate	\$ Bert 929.00 ✓
2	Rear tailgate dampers	\$ 11 470.00 X
1	Rear tailgate inner board	\$ 11 252.00 X
1	Rear tailgate lock	\$ 2w1 452.00 ✓
1	Rear tailgate logo	\$ All 48.00 ✓
1	Rear tailgate rubber	\$ 2w1 360.00 ✓
1	Rear tailgate "PRIUS" emblem	\$ All 53.00 ✓
1	Rear tailgate "X" emblem	\$ NZ 50.00 X
1	Rear tailgate outer garnish	\$ Bert/CR 892.00 ✓
2	Rear taillamps -top	\$ NLS/CR 866.00 1PC
2	Rear taillamps -lower	\$ NLS/CR 972.00 1PC
1	Rear end panel	\$ 11 630.00 ✓
1	Rear end panel inner garnish	\$ 11 180.00 X
1	Rear bumper	\$ Bert 423.00 ✓
2	Rear bumper top brackets	\$ 11 220.00 X
1	Rear bumper inner sponge	\$ NZ 110.50 X
1	Rear bumper lower diffuser	\$ Dis 552.00 ✓
1	Rear bumper reinforcement	\$ Bert 318.00 ✓
2	Rear bumper side retainers	\$ Bert 224.00 ✓
1	Rear floor board	\$ 11 543.60 X
1	Rear floor panel	\$ 2 629.00 X
1	Rear exhaust silencer	\$ 11 1,173.00 X
2	Rear exhaust mountings	\$ 11 90.00 X
1	Rear fender	\$ 2 824.00 X
2	Rear fender inner trims	\$ 11 900.00 X
1	Front bonnet	\$ 11 938.00 X
1	Front bonnet lock	\$ 11 133.00 X
1	Front bonnet rubber	\$ 11 61.20 X
2	Front headlamps	\$ CR 5,116.00 ✓
1	Front grille	\$ 3/20 356.00 ✓
1	Front bumper	\$ Dis 495.00 ✓
1	Front bumper clip (1 set)	\$ 2w1 60.00 ✓
		\$ 19,375.30

c/f:

\$

19,375.30

LIST ITEMS

2	Front bumper fog lamps	745x22-1490	\$	C10	1,820.00	/
1	Front bumper inner sponge		\$	70-1	72.00	/
1	Front bumper lower grille		\$	70-1	165.00	/
1	Front bumper reinforcement		\$	3-1	692.00	/
2	Front bumper side retainers		\$	3-1	154.00	/
1	Front bumper logo		\$	1-1	88.00	/
2	Front fenders		\$	1-1	1,866.00	X
1	Front support panel -top		\$	1-1	365.00	X
1	Air con condenser		\$	1-1	1,303.00	X
1	Radiator		\$	1-1	1,841.00	X
			\$		27,741.30	
			\$		6,935.33	
			\$		20,805.98	

Less 25%

14482.00
10861.50SPECIAL NETT ITEMS

1	Rear windscreen sealant		\$	2-1	80.00	40
1	Rear bumper clip (1 set)		\$	2-1	50.00	✓
1	Rear number plate with holder		\$	1-1	50.00	X
1	Front number plate with holder		\$	3-1	50.00	40
			\$		230.00	

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focussing.		\$		80.00	30
2	To remove, replaced damaged lamps and check up rear wiring.		\$		80.00	✓
3	To remove and refit inner garnishes.		\$		150.00	80
4	To transfer boot lid mechanism and wiring assembly.		\$		120.00	60
5	To remove, replace air-con condenser and conduct leakage test.		\$	1-1	180.00	X
6	To remove and refit rear windscreen glass.		\$		180.00	120
7	To remove, refit and replace exhaust silencer and mountings.		\$	1-1	150.00	X
8	To apply undercoating.		\$		200.00	60
9	Panel beating.		\$		1,800.00	1200
10	To re-spray painting on the affected areas.		\$		1,600.00	1500
			\$		4,540.00	

GRAND TOTAL :

\$ 25,575.98

LKKAuto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PAGE 2 OF 2

14041.5
11233.

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 21 February 2019 3:44 PM
To: Zoom Autowerks; MT_Claim_SG; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: MT_Claim_SG
Subject: RE: Our Ref: 18/19/19/VC05/021444 Pre-Repair Inspection for SLM 2485 K // Accident on 20/02/2019 @ 17:55HR at along PIE(Changi), before KJE Exit involving SLM 2485 K & GV 8755 D [External General]
Attachments: SLM 2485 K.PDF

4.40pm @ 21/2/19
Elin
vehicle
agreed survey on 22/2/19

Lonpac External - General

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Zoom Autowerks [mailto:zoomautowerks@gmail.com]

Sent: Thursday, 21 February, 2019 2:51 PM

To: MT_Claim_SG

Subject: Pre-Repair Inspection for SLM 2485 K // Accident on 20/02/2019 @ 17:55HR at along PIE(Changi), before KJE Exit involving SLM 2485 K & GV 8755 D

Dear Sir/Madam,

We are instructed by Autobahn Rent A Car Pte Ltd to notify you of a road traffic accident on 20 /02/2019

at about 17:55HR at along PIE(Changi), before KJE Exit involving our client's vehicle registration number SLM 2485 K and vehicle registration number GV 8755 D driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178 08.

Warmest Regards,
Elin Cai

Zoom Autowerks Pte Ltd
130 Bedok Reservoir Road
#08-1339 Singapore 470130
☎9450 7920
✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19003365/Ueb3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 02-05-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GV 8755D	Veh. Inspected	SLM 2485K
Policy No.	Z18VC05001216	Coverage (\$)	0.00
Claim No.	18/19/19/VC05/021444	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	21/02/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS HYBRID (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZVW508034831	Colour	BLACK
Odometer	67766	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	TOYO	6 mm
L/H Front Tyre	195/65R15	TOYO	6 mm
R/H Rear Tyre	195/65R15	TOYO	6 mm
L/H Rear Tyre	195/65R15	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/02/2019	Inspection Date	22/02/2019
Survey held at	15 KAKI BUKIT ROAD 4 #01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 2485K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOLDING	NECESSARY	55.00	55.00
1	REAR TAILGATE	DENTED / BENT	929.00	929.00
2	REAR TAILGATE DAMPERS	NOT NECESSARY	470.00	-
1	REAR TAILGATE INNER BOARD	NOT NECESSARY	252.00	-
1	REAR TAILGATE LOCK	TWISTED	452.00	452.00
1	REAR TAILGATE LOGO	NECESSARY	48.00	48.00
1	REAR TAILGATE RUBBER	TWISTED	360.00	299.00
1	REAR TAILGATE "PRIUS" EMBLEM	NECESSARY	53.00	53.00
1	REAR TAILGATE "X" EMBLEM	NOT FITTED	50.00	-
1	REAR TAILGATE OUTER GARNISH	DEFORMED / CRACKED	892.00	892.00
2	REAR TAILLAMPS - TOP	N/S CRACKED	866.00	433.00
2	REAR TAILLAMPS - LOWER	N/S CRACKED	972.00	486.00
1	REAR END PANEL	DENTED	630.00	630.00
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	180.00	-
1	REAR BUMPER	BENT	423.00	423.00
2	REAR BUMPER TOP BRACKETS	NOT NECESSARY	220.00	-
1	REAR BUMPER INNER SPONGE	NOT FITTED	110.50	-
1	REAR BUMPER LOWER DIFFUSER	DISTORTED	552.00	552.00
1	REAR BUMPER REINFORCEMENT	BENT	318.00	318.00
2	REAR BUMPER SIDE RETAINERS	BENT	224.00	224.00
1	REAR FLOOR BOARD	NOT NECESSARY	543.60	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	629.00	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	1,173.00	-
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	90.00	-
1	REAR FENDER	TO REPAIR SEE LABOUR	824.00	-
2	REAR FENDER INNER TRIMS	NOT NECESSARY	900.00	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	938.00	-
1	FRONT BONNET LOCK	NOT NECESSARY	133.00	-

Report Ref No. CC4/LPC19003365/Ueb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BONNET RUBBER	NOT NECESSARY	61.20	-
2	FRONT HEADLAMPS	CRACKED	5,116.00	5,116.00
1	FRONT GRILLE	BROKEN	356.00	356.00
1	FRONT BUMPER	DISTORTED	495.00	495.00
1	SET FRONT BUMPER CLIP	NECESSARY	60.00	60.00
2	FRONT BUMPER FOG LAMPS	CRACKED	1,820.00	1,490.00
1	FRONT BUMPER INNER SPONGE	TORN	72.00	72.00
1	FRONT BUMPER LOWER GRILLE	TORN	165.00	165.00
1	FRONT BUMPER REINFORCEMENT	BENT	692.00	692.00
2	FRONT BUMPER SIDE RETAINERS	BENT	154.00	154.00
1	FRONT BUMPER LOGO	NECESSARY	88.00	88.00
2	FRONT FENDERS	TO REPAIR SEE LABOUR	1,866.00	-
1	FRONT SUPPORT PANEL - TOP	NOT NECESSARY	365.00	-
1	AIR CON CONDENSER	NOT NECESSARY	1,303.00	-
1	RADIATOR	NOT NECESSARY	1,841.00	-
	LESS 25% DISCOUNT		-6,935.32	-3,620.50
			20,805.98	10,861.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	REAR NUMBER PLATE WITH HOLDER (SN)	NOT NECESSARY	50.00	-
1	FRONT NUMBER PLATE WITH HOLDER (SN)	BENT	50.00	40.00
			230.00	130.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING. }		80.00	30.00
	TO REMOVE, REPLACE DAMAGED LAMPS AND CHECK UP REAR WIRING. }		80.00	-
	TO REMOVE AND REFIT INNER GARNISHES.		150.00	80.00
	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY.		120.00	60.00
	TO REMOVE, REPLACE AIR-CON CONDENSER AND CONDUCT LEAKAGE TEST.	NOT NECESSARY	180.00	-

Report Ref No. CC4/LPC19003365/Ueb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	120.00
	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.		150.00	-
	TO APPLY UNDERCOATING.		200.00	60.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL, REAR FENDER, FRONT BONNET AND FRONT FENDERS.		1,800.00	1,200.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,600.00	1,500.00
			4,540.00	3,050.00
GRAND TOTAL			25,575.98	14,041.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,200.00

Report Ref No. CC4/LPC19003365/Ueb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.