


Vic

Finalized-H3

Section A - Accident Details

|                                    |                    |
|------------------------------------|--------------------|
| Registration Number                | SHB296H            |
| Case Reference Number              | TAX/02/19/2100     |
| Registration Date                  | 9/7/2014           |
| Company Type                       | SMRT Taxis Pte Ltd |
| Make                               | TOYOTA             |
| Model                              | PRIUS              |
| Name of Driver                     | YAP TEK YEK        |
| Type of Accident                   | Side Swipe         |
| Accident Date and Time             | 20/2/2019 1:00 PM  |
| Accident Reported Date and Time    | 20/2/2019 2:56 PM  |
| Is Surveyor Required?              | Yes                |
| Survey by                          |                    |
| Vehicle is Towed Back?             | No                 |
| Towed Back Date and Time           |                    |
| Replacement Vehicle issued?        | No                 |
| Job Card Number                    | 24100209           |
| Special Instruction to ARC, if any | TSS/ AXA           |
| Prepared Date and Time             | 21/2/2019 3:47 PM  |
| Chassis Number                     |                    |
| Mileage                            |                    |
| Work Shop                          |                    |
| Repair Completion Date and Time    |                    |



Left Side

Section B - Summary of Repair Estimates

Summary of Repair Estimates

|                              | Quotation from ARC             | Adjusted by Surveyor, if applicable |
|------------------------------|--------------------------------|-------------------------------------|
| Total Labour Cost            | \$1,014.00                     | \$600.00                            |
| Total Spray Cost             | \$1,674.00                     | \$650.00                            |
| Total Spare Part Cost        | \$5,816.84                     | \$2,261.95                          |
| Total Other Cost             | \$1,145.00                     | \$80.00                             |
| <b>TOTAL COST</b>            | <b>\$9,649.84</b>              | <b>\$3,591.95</b>                   |
| Lump Sum Total               | \$9,650.00                     | \$3,600.00 (L/S)                    |
| Number of Repair Days        | 7.0                            | 4.0                                 |
| Prepared / Adjusted By       | Tuck Foo Kok                   | Hwee Jie (LKK) / AXA                |
| ARC / Surveyor Sign Off Date | 25/02/2019 9:56 AM             | 22/02/2019 4:24 PM                  |
| Signature                    |                                |                                     |
| Remarks                      | L/S REPAIR, PHOTO AFTER PAINT. |                                     |



# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757105  
FAX Number: 63655592  
Estimator Telephone Number: 68642623  
Accident Reporting Number: 68652672

Date Generated: 28/03/2019  
User ID: Peh Guan

## Section C - Quotation and Accident Invoice Details

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-1903-0002 | Invoice Number |  |
| Quotation Date   | 01.03.2019   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

| Job Scope                  | Quotation from AR | Adjusted by Surveyor, if applicable |
|----------------------------|-------------------|-------------------------------------|
| TO REPAIR FRONT LH PORTION | \$1,014.00        | \$600.00                            |
| <b>Total Labour</b>        | <b>\$1,014.00</b> | <b>\$600.00</b>                     |

### Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO REPSRAY FRONT BUMPER                         | \$378.00           | \$200.00                            |
| TO REPSRAY FRONT HOOD                           | \$378.00           | \$200.00                            |
| TO RESPRAY FRONT SUPPORT PANEL                  | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT FENDER LH                      | \$378.00           | \$200.00                            |
| TO RESPRAY APRON PANEL LH                       | \$180.00           | \$0.00                              |
| TO RESPRAY RIM                                  | \$180.00           | \$50.00                             |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>\$1,674.00</b>  | <b>\$650.00</b>                     |

### Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                                         | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---------------------------------------------------|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION               | \$80.00            | \$20.00                             |
| TO APPLY RUST-PROOFING ON AFFECTED AREA           | \$100.00           | \$30.00                             |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING            | \$120.00           | \$0.00                              |
| TO TOP UP A/C GAS                                 | \$120.00           | \$0.00                              |
| TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET) | \$125.00           | \$0.00                              |
| TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS      | \$120.00           | \$0.00                              |
| TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)   | \$120.00           | \$30.00                             |
| TO REMOVE AND REFIT WIRE HARDESS                  | \$200.00           | \$0.00                              |
| TO REPLACE SUNDRY PARTS                           | \$100.00           | \$0.00                              |
| TO WASH AND VACUUM                                | \$60.00            | \$0.00                              |
| <b>Total Other Costs</b>                          | <b>\$1,145.00</b>  | <b>\$80.00</b>                      |

### Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name                  | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|----------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 52119-47930  | BUMPER FRT                 | 1.00     | \$482.00        | 25.00        | \$361.50         | Replace            | Replace           |
|             |         | 52161-16010  | BUMPER CLIPS               | 10.00    | \$1.61          | 25.00        | \$12.08          | Replace            | Replace           |
|             |         | 52611-47080  | BUMPER ENERGY ABSORBER FRT | 0.00     | \$78.80         | 0.00         | \$0.00           | Replace            | Check X           |
|             |         | 52021-47023  | BUMPER REINFORCEMENT FRT   | 0.00     | \$498.40        | 0.00         | \$0.00           | Replace            | Check X           |
|             |         | 57014-47030  | ARM SUB-ASSY, FR BUMPER LH | 0.00     | \$250.40        | 0.00         | \$0.00           | Replace            | Check X           |
|             |         | 52116-47040  | BUMPER SUPPORT F/LH        | 0.00     | \$76.40         | 0.00         | \$0.00           | Replace            | Check X           |

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park S4, Singapore 757105  
FAX Number : 93685562  
Estimator Telephone Number : 68662623  
Accident Reporting Number : 68662672

Date Generated : 28/03/2019  
User ID : Poh Guan

|         |                   |                               |      |            |        |            |         |           |   |
|---------|-------------------|-------------------------------|------|------------|--------|------------|---------|-----------|---|
|         | 81529-47060       | BRACKET, FR TURN CENTER LH    | 0.00 | \$58.20    | 0.00   | \$0.00     | Replace | Check     | Y |
|         | 81529-47050       | BRACKET, FR TURN LOWER LH     | 0.00 | \$26.00    | 0.00   | \$0.00     | Replace | Check     | X |
|         | 81529-47040       | BRACKET, FR TURN UPPER LH     | 0.00 | \$24.40    | 0.00   | \$0.00     | Replace | Check     | X |
|         | 81521-47050       | LENS & BODY, FR TURN LH       | 1.00 | \$511.80   | 10.00  | \$460.62   | Replace | Replace   | / |
|         | 52618-47050       | BUMPER FRT ABSORBER LOWER     | 0.00 | \$127.70   | 0.00   | \$0.00     | Replace | Check     | X |
|         | 82113-47180       | WIRE, ENGINE ROOM, NO.3       | 0.00 | \$242.00   | 0.00   | \$0.00     | Replace | Check     | X |
|         | 53301-47060       | HOOD PANEL                    | 1.00 | \$748.10   | 25.00  | \$561.08   | Replace | Replace   | / |
|         | 53420-47070       | HOOD HINGE LH                 | 0.00 | \$55.90    | 0.00   | \$0.00     | Replace | Check     | X |
|         | 53410-47070       | HOOD HINGE RH                 | 0.00 | \$55.90    | 0.00   | \$0.00     | Replace | Not Given | X |
|         | 53510-47102       | HOOD LOCK                     | 0.00 | \$128.90   | 0.00   | \$0.00     | Replace | Not Given | X |
|         | 53201-47902       | SUPPORT SUB-ASSY              | 0.00 | \$1,460.40 | 0.00   | \$0.00     | Replace | Check     | X |
|         | 81170-47500       | HEAD LAMP LH                  | 1.00 | \$945.20   | 10.00  | \$850.68   | Replace | Replace   | / |
|         | 53802-47050       | FENDER FRT/LH                 | 1.00 | \$723.40   | 25.00  | \$542.55   | Replace | Replace   | / |
|         | 75374-47051       | NAME PLATE (HYBRID)           | 1.00 | \$51.90    | 25.00  | \$38.93    | Replace | Replace   | / |
|         | 53876-47030       | FENDER LINER FRT/LH           | 0.00 | \$171.70   | 0.00   | \$0.00     | Replace | Check     | X |
|         | 53826-47010       | FENDER PROTECTOR FRT/LH UPPER | 0.00 | \$46.10    | 0.00   | \$0.00     | Replace | Check     | X |
|         | 53702-47050       | FENDER APRON SUB FRT/LH       | 0.00 | \$637.80   | 0.00   | \$0.00     | Replace | Not Given | X |
| 6503707 |                   | TYRE                          | 0.00 | \$126.74   | 0.00   | \$0.00     | Replace | Not Given | X |
|         | 42611-47140 (Frt) | WHEEL DISC. FRONT             | 1.00 | \$1,484.20 | 100.00 | \$0.00     | Replace | Repair    | / |
|         | 62120-47021       | QUARTER GLASS FRT/LH          | 0.00 | \$234.90   | 0.00   | \$0.00     | Replace | Not Given | X |
|         |                   | SEALANT W/SCREEN              | 0.00 | \$37.00    | 0.00   | \$0.00     | Replace | Not Given | X |
| Total   |                   |                               |      | \$9,285.85 |        | \$2,827.44 |         |           |   |

## Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| Total       |         |              |           |          |               |              |                  |           |                |

2827.44  
- 202  
2261.95  
+ 600.00  
+ 730.00  


---

3591.95  
45 \$3600/-