


Vic

Finalized-H3

Section A - Accident Details

Registration Number	SHB296H
Case Reference Number	TAX/02/19/2100
Registration Date	9/7/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YAP TEK YEK
Type of Accident	Side Swipe
Accident Date and Time	20/2/2019 1:00 PM
Accident Reported Date and Time	20/2/2019 2:56 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100209
Special Instruction to ARC, if any	TSS/ AXA
Prepared Date and Time	21/2/2019 3:47 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Left Side

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$600.00
Total Spray Cost	\$1,674.00	\$650.00
Total Spare Part Cost	\$5,816.84	\$2,261.95
Total Other Cost	\$1,145.00	\$80.00
TOTAL COST	\$9,649.84	\$3,591.95
Lump Sum Total	\$9,650.00	\$3,600.00 (L/S)
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AXA
ARC / Surveyor Sign Off Date	25/02/2019 9:56 AM	22/02/2019 4:24 PM
Signature		
Remarks	L/S REPAIR, PHOTO AFTER PAINT.	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757105
 FAX Number: 63655592
 Estimator Telephone Number: 68642623
 Accident Reporting Number: 68652672

Date Generated: 28/03/2019
 User ID: PehGuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1903-0002	Invoice Number	
Quotation Date	01.03.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$1,014.00	\$600.00
Total Labour	\$1,014.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$1,674.00	\$650.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,145.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Check
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Check

Buc
 Nec
 SVC
 SVC
 SVC
 SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park S4, Singapore 757105
FAX Number : 93685562
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/03/2019
User ID : PohSuan

	81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	✓	SVC
	81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check	✓	SVC
	81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	✓	SVC
	81521-47050	LENS & BODY, FR TURN LH	1.00	\$511.80	10.00	\$460.62	Replace	Replace	✓	SCR
	52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check	✓	SVC
	82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Check	✓	SVC
	53301-47060	HOOD PANEL	1.00	\$748.10	25.00	\$561.08	Replace	Replace	✓	Buc
	53420-47070	HOOD HINGE LH	0.00	\$55.90	0.00	\$0.00	Replace	Check	✓	SVC
	53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	✓	SVC
	53510-47102	HOOD LOCK	0.00	\$128.90	0.00	\$0.00	Replace	Not Given	✓	SVC
	53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Check	✓	SVC
	81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	✓	Cra
	53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	✓	Buc
	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓	Nec
	53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Check	✓	SVC
	53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Check	✓	SVC
	53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Not Given	✓	SVC
6503707		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	✓	SVC
	42611-47140 (Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	✓	SVC
	62120-47021	QUARTER GLASS FRT/LH	0.00	\$234.90	0.00	\$0.00	Replace	Not Given	✓	SVC
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	✓	SVC
Total				\$9,285.85		\$2,827.44				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2827.44
- 202
2261.95
+ 600.00
+ 730.00

3591.95
45 \$3600/-