

BAN HONG GEOK KEE CO.
BLK 5038 ANG MO KIO IND PARK 2 #01-419
Singapore 569541
Tel: 64812156, 64815790
Fax: 64845121

ASSESSMENT FOR REPAIR FBM7954J HONDA CB150R

Chassis No. : MLHKC2886J5003153
Engine No. : KC32E0003153

QTY	DESCRIPTION	ESTIMATE	
2 pcs	Front Fork <i>local repair</i> BENT	750.00	650.00 (SN)
1 pc	Front Wheel <i>X NN</i>	485.00	X
1 pc	Handle Bar <i>OT</i>	175.00	/
1 pc	Lever <i>CA</i>	38.00	/
1 pc	Lever Holder <i>CA</i>	68.00	/
1 pc	Signal Lamp <i>Dis</i>	110.00	/
1 pc	Mirror <i>scr</i>	98.00	/
1 pc	Number Plate <i>CA</i>	12.00	/
1 pc	Handle End <i>CA</i>	30.00	/
1 pc	Gear Lever <i>BT</i>	90.00	/
1 pc	Front Footrest <i>BR</i>	75.00	/
1 pc	Rear Footrest <i>CA</i>	65.00	/
1 pc	Tank Cover <i>CA</i>	220.00	/
1 pc	Left Cover <i>CA</i>	150.00	/
		2366.00	1131
	Less 10 %	236.60	
		2129.40	1017.9

Add Special Nett From Above

Towing Fees	50.00	<i>CA</i>
IU <i>CA</i>	155.80	
Labour Charges	380.00	<i>150</i>
Body Repair	350.00	<i>X NN</i>
	3065.20	

LKK Auto Consultants hence notify the Repairer of the following:

(BAN HONG GEOK KEE CO)

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

2 Days. 22/2/19. 20%: 115.
Lumpsum repair.
After repair photos
Gue Group - 8288 0282