

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0228/2019/GW
Date	:	21-Feb-19

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Seow Tuan Choo
Address	:	23 Thomson Hill Singapore 574796
Telephone	:	HP +65 96262682
Type of Claim	:	Own Damage Claims
Policy No.	:	1700026327-01
Vehicle No	:	SLQ 7758 U
Model Code	:	Audi Q2 1.0 TFSI S
Model / Year	:	Jul-17
Engine No	:	CHZ 384814
Chassis No	:	WAUZZZGA5HA058432
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	12-Oct-18
Place of Accident	:	Serangoon North Ave 4

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLQ 7758 U

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid.check function.	S/N \$ 280.00 ✓ ✓
2	To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed . \$90.0	\$ 1,050.00 500 ✓ ✓
3	To respray rear bumper, lower spoiler, both rear wheel arch covers, rhs rear fender and rhs rear door. ✓ 512 X	\$ 3,400.00 1100 ✓ ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓ ✓
TOTAL LABOUR CHARGES		: \$ 4,922.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

S/N are Special Nett.

Steve Chen @ KKauth.com

83228813

Steve 11.35am 21/2/19
with ~~for~~ 4 days

[Signature]
25/2/19

Re: bef. - climate parts - Af1 spy
p/p
or not Authorise
Excess - ?

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 7758 U

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER / CUT	\$ 1,016.00	810.80
2	REAR BUMPER FIXING PARTS / NEC X NN	\$ 66.00	
3	REAR BUMPER SPOILER / CUT	\$ 247.00	197.00
4	REAR BUMPER TOWING COVER X NN	\$ 20.00	
5	REAR LIGHT RELECTOR-LH/RH X NN	2 \$ 52.00	
6	REAR BUMPER GUDIE SECTIO-RH ? X NN	\$ 46.00	
7	REAR SENSOR NN	\$ 211.00	
8	REAR SENSOR SEAL RING / NEC X NN	4 \$ 14.00	
9	REAR WHEEL COVER-LH/RH LH / NEC RH / CUT	2 \$ 298.00	238.40
10	REAR BUMPER CLIP / NEC X NN	14 \$ 30.00	
11	TAIL LIGHT-RH / CUT	\$ 1,149.00	919.00
12	TAIL LIGHT TRIM-RH ? X NN	\$ 26.00	
13	SUNDRIES ? X NN	\$ 300.00	
TOTAL SPARE PARTS		\$ 3,475.00	
TOTAL LABOUR CHARGES		\$ 4,922.00	
GRAND TOTAL		\$ 8,397.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0228/2019/GW
Date	:	21-Feb-19

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Steve,
4 days ok - Carline 10/10/2019

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Seow Tuan Choo
Address	:	23 Thomson Hill Singapore 574796
Telephone	:	HP +65 96262682
Type of Claim	:	Own Damage Claims
Policy No.	:	1700026327-01
Vehicle No	:	SLQ 7758 U
Model Code	:	Audi Q2 1.0 TFSI S
Model / Year	:	Jul-17
Engine No	:	CHZ 384814
Chassis No	:	WAUZZZGA5HA058432
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	12-Oct-18
Place of Accident	:	Serangoon North Ave 4

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLQ 7758 U

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer rear parking aid.check function.	S/N \$ 280.00	\$ 280.00
2	To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed .	\$ 1,050.00	\$ 500.00
3	To respray rear bumper, lower spoiler, both rear wheel arch covers, rhs rear fender and rhs rear door.	\$ 3,400.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,922.00	\$ 2,072.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

S/N are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 7758 U

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,016.00	812.8
2	REAR BUMPER FIXING PARTS	\$ 66.00	
3	REAR BUMPER SPOILER	\$ 247.00	197.2
4	REAR BUMPER TOWING COVER	\$ 20.00	
5	REAR LIGHT RELECTOR-LH/RH	2 \$ 52.00	
6	REAR BUMPER GUDIE SECTIO-RH	\$ 46.00	
7	REAR SENSOR	\$ 211.00	
8	REAR SENSOR SEAL RING	4 \$ 14.00	
9	REAR WHEEL COVER-LH/RH	2 \$ 298.00	238.4
10	REAR BUMPER CLIP	14 \$ 30.00	
11	TAIL LIGHT-RH	\$ 1,149.00	919.2
12	TAIL LIGHT TRIM-RH	\$ 26.00	
13	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		: \$ 3,475.00	\$ 2,167.60
TOTAL LABOUR CHARGES		: \$ 4,922.00	\$ 2,072.00
GRAND TOTAL		: \$ 8,397.00	\$ 4,239.60

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 11 October 2019 8:49 AM
To: Carrine Leong; SUR; Steve Chen (LKK Auto)
Cc: 'Boo seng yak'; 'Chang Chee Sing'; jiajee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SLQ7758U - OD AIG - SURVEYED 21 FEB 19

Dear Carrine,

Confirm repair cost of \$4239.60 before excess \$1300 and GST @ 4 days.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Thursday, 10 October 2019 5:47 PM
To: SUR <sur@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Chang Chee Sing' <claims@premiumauto.com.sg>; jiajee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SLQ7758U - OD AIG - SURVEYED 21 FEB 19

Hi Steve,

Revised estimate is attached.

Please confirm repair cost of \$4239.60 @ 4 days.

Your early closure is well appreciated.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLQ 7758 U

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0228/2019/NH

16 October 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLQ 7758 U, Audi Q2 1.0 TFSI S TRONIC.

With reference to the above-mentioned vehicle, no. **SLQ 7758 U**, claimant, **Ms. Seow Tuan Choo** please find the related document per attached.

1. A copy of the Original invoice no. 85014346 – S\$ 3,145.37.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLQ 7758 U

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9826 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:00

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014346 Date : 14/10/2019 Order : SLQ7758U Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120	
Regn No: SLQ7758U (V 34496)	Regn Date: 21/07/2017	Mileage: 32453	WIP No.: 28542
Model: Q2 1.0 TFSI S tronic GABANG	Chassis: WAUZZZGA5HA058432	Engine: CHZ 384814	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1300.00	1.00	-1,300.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	280.00	1.00	280.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER ASSY. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER AND RHS REAR FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A81A945092A	TAILLIGHT	1.00	1149.00	919.20
X	A81A853818 4W3	COVER	1.00	149.00	119.20
X	A81A853817 4W3	COVER	1.00	149.00	119.20
X	A81A807067A GRU	COVER	1.00	1016.00	812.80
X	A81A807521B 4W3	SPOILER	1.00	246.50	197.20

Parts 2,167.60
Labour 0.00
Sublet 2,072.00
Menus 0.00
Lubricant 0.00



Sub-Total	2,939.60
7% GST	205.77
Grand Total	3,145.37

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLQ 7758 U

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0228/2019/GW
25 February 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q2 Sport 1.0 TFSI
Vehicle Chassis No. : WAUZZZGA5HA058432
Vehicle Regn No. : SLQ 7758 U
Vehicle Mileage : 32453 km
Vehicle Owner : Ms. Seow Tuan Choo
Certificate No : 1700026327-01
Own Damage Excess : S\$ 1,319 (Inclusive of 7% GST)
Accident Date : 12/10/2018
Place : Serangoon North Ave 4
Repair Cost : \$ 3,145.37
WIP No. : 28542
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :



10 am

1/3/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2018		22 Feb 2019 15:32 Edit Adj Rpt	S\$4,239.60 Edit Estimates	S\$4,239.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS	[Created by insurer]
Insured: SEOW TUAN CHOO , ID: S0018290G, Tel: +6596262682	
Vehicle Reg. No.: SLQ7758U	Date of Loss: 12/10/2018 13:00 - :59 [14 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type: OD / 4067941163SG	Policy/Cover Note No.: 1700026327 (Comprehensive)
	Excess: S\$1,300.00
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911	
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 05/03/2019]	
Driver/Custodian: NG SAN SAN (43 / Female) , NRIC: S7502258A, Tel: +6596262682 Email: Michellwright33@gmail.com	

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
AIG_SG (04/03/2019): SLQ7758U / OD / 12/10/2018 / Coverage & Excess update	

ALL ASSOCIATED TASKS	View All Search Tasks Create New Task Complete																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10" style="text-align: center;">No results.</td> </tr> </tbody> </table>	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?												
No results.																					

Claim Documents

***SLQ7758U (4067941163SG)**
OD
Oct 12 2018 1:00PM
[SEOW TUAN CHOO]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 08:47	General View	Load JPG	☒
2	25/02/19 08:47	General View	Load JPG	☒
3	25/02/19 08:47	General View	Load JPG	☒
4	25/02/19 08:47	General View	Load JPG	☒
5	25/02/19 08:47	General View	Load JPG	☒
6	25/02/19 08:47	General View	Load JPG	☒
7	25/02/19 08:47	General View	Load JPG	☒
8	25/02/19 08:47	General View	Load JPG	☒
9	25/02/19 08:47	General View	Load JPG	☒
10	25/02/19 08:47	General View	Load JPG	☒
11	25/02/19 08:47	General View	Load JPG	☒
12	25/02/19 08:47	General View	Load JPG	☒
13	25/02/19 08:47	General View	Load JPG	☒
14	25/02/19 08:47	General View	Load JPG	☒
15	25/02/19 08:47	General View	Load JPG	☒
16	25/02/19 08:47	General View	Load JPG	☒
17	25/02/19 08:47	General View	Load JPG	☒
18	25/02/19 08:47	General View	Load JPG	☒
19	25/02/19 08:47	General View	Load JPG	☒
20	25/02/19 08:47	General View	Load JPG	☒
21	25/02/19 08:47	General View	Load JPG	☒
22	25/02/19 08:47	General View	Load JPG	☒
23	25/02/19 08:47	General View	Load JPG	☒
24	25/02/19 08:47	General View	Load JPG	☒
25	25/02/19 08:47	General View	Load JPG	☒
26	25/02/19 08:47	General View	Load JPG	☒
27	25/02/19 08:47	General View	Load JPG	☒
28	11/10/19 08:47	Reinspection Photo	Load JPG	☒
29	11/10/19 08:47	Reinspection Photo	Load JPG	☒
30	11/10/19 08:47	Reinspection Photo	Load JPG	☒
31	11/10/19 08:47	Reinspection Photo	Load JPG	☒
32	11/10/19 08:47	Reinspection Photo	Load JPG	☒
33	11/10/19 08:47	Reinspection Photo	Load JPG	☒
34	11/10/19 08:47	Reinspection Photo	Load JPG	☒
35	11/10/19 08:47	Reinspection Photo	Load JPG	☒
36	11/10/19 08:47	Reinspection Photo	Load JPG	☒
37	11/10/19 08:47	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 08:48	Singapore Accident Statement	Load PDF	
2	25/02/19 08:48	MARK ESTIMATE	Load PDF	
3	01/03/19 10:39	Certificate of Insurance	Load PDF	

Linked Accident Report Documents

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&objid=752663&extid=296003&corole... 2/2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19003372/EVD3S2
Date: 18/10/2019

REFERENCE

Insured/Claimant: SEOW TUAN CHOO Policy No: 1700026327
Date of Loss: 12/10/2018 Nature of Claim: OD Claim No: 4067941163SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ7758U Engine No: CHZ384814
Make & Model: AUDI Q2, 999cc TFSI S-TRONIC (A) Chassis No: WAUZZZGA5HA058432
Reg. Date: 21/07/2017 (Man. Year: 2017) Odometer: 24103 km
Colour: Silver
Engine Capacity: 1000 cc
Market Value/New Car Price: S\$84,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,475.00	2,167.60	1,307.40	37.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,922.00	2,072.00	2,850.00	57.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,397.00	4,239.60	4,157.40	49.51
- Excess (S\$)	1,300.00	1,300.00	0.00	0.00
(S\$)	7,097.00	2,939.60	4,157.40	58.58
+ GST 7.00/7.00% (S\$)	496.79	205.77	291.02	58.58
Nett Amount (S\$)	7,593.79	3,145.37	4,448.42	58.58

INSPECTION

Date of Assignment: 22/02/2019

Date Inspected: 21/02/2019 Inspected At:

281 Alexandra Road
Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	1,016.00 FS	*812.80 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	66.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	247.00 FS	*197.20 FS
4	1		*REAR BUMPER TOWING COVER	Not Necessary	20.00 FS	*- FS
5	2		*REAR LIGHT REFLECTOR-LH/RH	Not Necessary	52.00 FS	*- FS
6	1		*REAR BUMPER GUIDE SECTIO-RH	Not Necessary	46.00 FS	*- FS
7	1		*REAR SENSOR	Not Necessary	211.00 FS	*- FS
8	4		*REAR SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
9	2		*REAR WHEEL COVER-LH/RH	O/s Cut/N/s Necessary	298.00 FS	*238.40 FS
10	14		*REAR BUMPER CLIP	Not Necessary	30.00 FS	*- FS
11	1		*TAIL LIGHT-RH	Cut	1,149.00 FS	*919.20 FS
12	1		*TAIL LIGHT TRIM-RH	Not Necessary	26.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.					Total Parts (\$\$)	3,475.00 2,167.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER ASSY.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER,LOWER SPOILER,BOTH REAR WHEEL ARCH COVERS,RHS REAR FENDER AND RHS REAR DOOR	New	3,400.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,922.00	2,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >