

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0228/2019/GW
Date : 21-Feb-19

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Seow Tuan Choo
Address : 23 Thomson Hill
Singapore 574796
Telephone : HP +65 96262682
Type of Claim : Own Damage Claims
Policy No. : 1700026327-01
Vehicle No : **SLQ 7758 U**
Model Code : Audi Q2 1.0 TFSI S
Model / Year : Jul-17
Engine No : CHZ 384814
Chassis No : WAUZZZGA5HA058432
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Oct-18
Place of Accident : Serangoon North Ave 4

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLQ 7758 U

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid.check function.	S/N \$ 280.00 ✓
2	To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed . \$90	\$ 1,050.00 500 ✓
3	To respray rear bumper, lower spoiler, both rear wheel arch covers, rhs rear fender and rhs rear door. ✓ 550 X	\$ 3,400.00 1190 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 4,922.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

S/N are Special Nett.

sterechen@1kkath.com

83228813

Steve 11.35am 21/2/19

~~with~~ ~~for~~

4 days

Res. bef. , dismate parts. Aft spray
P/P

OD not Authorise

Excess - ?

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 7758 U

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	REAR BUMPER / CUT	\$	1,016.00
2	REAR BUMPER FIXING PARTS / NEC	\$	66.00
3	REAR BUMPER SPOILER / CUT	\$	247.00
4	REAR BUMPER TOWING COVER X	\$	20.00
5	REAR LIGHT RELECTOR-LH/RH X	2 \$	52.00
6	REAR BUMPER GUDIE SECTIO-RH ?	\$	46.00
7	REAR SENSOR BX	\$	211.00
8	REAR SENSOR SEAL RING / NEC	4 \$	14.00
9	REAR WHEEL COVER-LH/RH LH / NEC RH / CUT	2 \$	298.00
10	REAR BUMPER CLIP / NEC	14 \$	30.00
11	TAIL LIGHT-RH / CUT	\$	1,149.00
12	TAIL LIGHT TRIM-RH ?	\$	26.00
13	SUNDRIES ?	\$	300.00
TOTAL SPARE PARTS		\$	3,475.00
TOTAL LABOUR CHARGES		\$	4,922.00
GRAND TOTAL		\$	8,397.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant