

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0228/2019/GW  
**Date** : 21-Feb-19

**Vehicle not IN workshop. Kindly arrange for survey.**

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Hi Steve,  
4 days ok - Carrine 10/10/2019

**Attn: Mr. Adrian Ling - Motor Claims Dept**  
**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Ms. Seow Tuan Choo  
**Address** : 23 Thomson Hill  
Singapore 574796  
**Telephone** : HP + 65 96262682  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 1700026327-01  
**Vehicle No** : **SLQ 7758 U**  
**Model Code** : Audi Q2 1.0 TFSI S  
**Model / Year** : Jul-17  
**Engine No** : CHZ 384814  
**Chassis No** : WAUZZZGA5HA058432  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 12-Oct-18  
**Place of Accident** : Serangoon North Ave 4

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SLQ 7758 U

| S/N                         | Nature of Jobs                                                                                                       | Estimated Charges    |                    |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------|----------------------|--------------------|
| 1                           | To remove and transfer rear parking aid.check function.                                                              | S/N \$ 280.00        | \$ 280.00          |
| 2                           | To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed . | \$ 1,050.00          | \$ 500.00          |
| 3                           | To respray rear bumper, lower spoiler, both rear wheel arch covers, rhs rear fender and rhs rear door.               | \$ 3,400.00          | \$ 1,100.00        |
| 4                           | To carry out diagnostic check.                                                                                       | S/N \$ 192.00        | \$ 192.00          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                      | <b>: \$ 4,922.00</b> | <b>\$ 2,072.00</b> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

S/N are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLQ 7758 U

|                             |                             | <u>Damage Parts &amp; Prices</u> |                    |
|-----------------------------|-----------------------------|----------------------------------|--------------------|
| <u>S/N</u>                  | <u>Parts Description</u>    | <u>S/NETT</u>                    | <u>REMARKS</u>     |
| 1                           | REAR BUMPER                 | \$ 1,016.00                      | 812.8              |
| 2                           | REAR BUMPER FIXING PARTS    | \$ 66.00                         |                    |
| 3                           | REAR BUMPER SPOILER         | \$ 247.00                        | 197.2              |
| 4                           | REAR BUMPER TOWING COVER    | \$ 20.00                         |                    |
| 5                           | REAR LIGHT RELECTOR-LH/RH   | 2 \$ 52.00                       |                    |
| 6                           | REAR BUMPER GUDIE SECTIO-RH | \$ 46.00                         |                    |
| 7                           | REAR SENSOR                 | \$ 211.00                        |                    |
| 8                           | REAR SENSOR SEAL RING       | 4 \$ 14.00                       |                    |
| 9                           | REAR WHEEL COVER-LH/RH      | 2 \$ 298.00                      | 238.4              |
| 10                          | REAR BUMPER CLIP            | 14 \$ 30.00                      |                    |
| 11                          | TAIL LIGHT-RH               | \$ 1,149.00                      | 919.2              |
| 12                          | TAIL LIGHT TRIM-RH          | \$ 26.00                         |                    |
| 13                          | SUNDRIES                    | \$ 300.00                        |                    |
| <b>TOTAL SPARE PARTS</b>    |                             | <b>\$ 3,475.00</b>               | <b>\$ 2,167.60</b> |
| <b>TOTAL LABOUR CHARGES</b> |                             | <b>\$ 4,922.00</b>               | <b>\$ 2,072.00</b> |
| <b>GRAND TOTAL</b>          |                             | <b>\$ 8,397.00</b>               | <b>\$ 4,239.60</b> |

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.