

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 25 Feb 2019

Preliminary Advice

Vehicle No	: GBD3434S	Accident Date	: 01/02/2019
Make	: NISSAN CABSTAR	Policy No.	: DMCVSN1432731804
Assignment Date	: 21/02/2019	Excess	: S\$500.00
Date of Inspection	: 22/02/2019	Est. Duration of Repair	: 14 days
Inspection At	: Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate Singapore 677981		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,215.00
Revised Amount	:S\$	27,895.00
Check Items (Estimated)	:S\$	14,230.00
Total	:S\$	42,125.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	41,000.00
COE / PARF Rebate	:S\$	8,865.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,135.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : WE ARE PENDING REPAIR COST FROM REPAIRER