

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0205/2019/GW
Date : 16-Feb-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SHC 8794 D

India International Insurance Pte Ltd

64 Cecil Street

#04-00/05-00 IOB Building

Singapore 049711

Attn: Motor Claims Dept

Tel: 6347 6100 Fax: 6224 4174

Owner's Name : Mr. Hughes Nicholas William Morris
Address : 8 Pasir Ris Ave
Singapore 519675
Telephone : HP +65 91866348
Type of Claim : Third Party Claims
Policy No. : 2100384335-04
Vehicle No : **SKL 6100 L**
Model Code : Q5 3.0 TFSI QU
Model / Year : Nov-13
Engine No : CTV 002929
Chassis No : WAUZZZ8R2DA070696
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Feb-19
Place of Accident : Simei Street 1 & Simei Rise Insection

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKL 6100 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,050.00 700	
3	To respray rear bumper.	\$ 900.00 700	
4	To remove and renew lhs rear exhaust silencer. To align to position.	S/N \$ 480.00 ✗	
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,902.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKL 6100 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Relnd</i>	\$ 1,888.00	✓
2	REAR BUMPER FIXING PARTS <i>re n</i>	\$ 150.00	+
3	REAR WHEEL COVER-LH/RH <i>no + re n</i>	2 \$ 146.00	+
4	TAIL LIGHT-LH <i>Net re n</i>	\$ 273.00	+
5	REAR BUMPER GUIDE SECTION-LH/RH <i>re n</i>	2 \$ 98.00	+
6	REAR BUMPER SPOILER <i>lit</i>	\$ 714.00	✓
7	REAR BUMPER COVER <i>re n</i>	\$ 672.00	+
8	REAR BUMPER TRIM <i>lit</i>	\$ 254.00	✓
9	REAR BUMPER CARRIER <i>re n</i>	\$ 598.00	+
10	REAR BUMER HOLDER BRACKET-LH/RH <i>re n</i>	2 \$ 390.00	+
11	REAR SENSOR <i>re n</i>	3 \$ 629.00	+
12	REAR SILENCER-LH	\$ 2,153.00	+
13	REAR SILENCER DUAL CLIP-LH	\$ 49.00	+
14	REAR BRACKET-LH/RH	2 \$ 104.00	+
15	SUNDRIES	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		\$ 8,618.00	
TOTAL LABOUR CHARGES		\$ 2,902.00	
GRAND TOTAL		\$ 11,520.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 22/02/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant