

83228813

7/7/2003

A.S.S. REC. BY:

REF:

CS/GAI19003380/ETD302

Special Instruction:

Surveyor:

Steve

ASSIGNMENT (Office)

From (Person):

Kelvyna Ngien

of

GAI

Date/Time:

21/2/19 @ 3:55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBE5117P

Insured:

at Workshop n/s

Leong Beng Motor

Tel:

62737469

of

Blk 1006, Blk Menh Lane 2 # 01-08

Policy No:

Claim No:

CLMOM VM 000000447

Sum Insured:

Excess:

\$750.00

Make of Veh:

D.O.A.

15/02/19

(Client's Record)

CA

REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:00am 22/2/19

Person Contacted:

Mr. Teo

Vehicle

IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

FBE5117P-NBA/GAI19003381/Y

DOA: 15/2/19

confirm finalise \$5800, 4 days 15/3/19

(Red: 350th, 37%)

1/3/2019 - Revert via email to kelvyna.

7/march - insurance sent to workshop authorise repair limit bk

REF:

ASSIGNMENT

15/05/10
23/02/19

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	N/S	O/S
<input checked="" type="checkbox"/>		

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lump Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

V. Regn: _____

Type: M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Honda CB400SF

c.c.

400

Colour: _____

White

A/C

Insured / Std / NI / NA

Sp. Reading: _____

144556

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

NC42100214

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: _____

F:

120/60R17

R:

160/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

METZELER

Front

Rear

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

D.O.I. _____

22/2/19

Survey held at _____

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☒ N/S / ☐ UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

MV - 5000

PV - 153

NV - 4847



25/2/19

RECEIVED 1 2 2019

Date/Time: File Pass to?

1) 18/3 Typist

Date/Time: File Return to?

2)

Report Format: _____

Lump Sum / I.B.E. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____

☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Survey Fee: _____

Transportation

) \$ + RS \$

) Photos

) Other

) _____

TOTAL

250

250



Nivitha (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Thursday, 21 February 2019 3:55 PM
To: Admin-D (LKKAuto); 'Admin A'
Subject: OD survey - FBE5169P (CLMOMVM000000446) & FBE5117P (CLMOMVM000000447) O/D claim - request for survey
Attachments: FBE5117P_15022019.PDF; FBE5169P_15022019.PDF; IMG_20190220_0008.pdf

Hi team

Please conduct OD survey for these 2 vehicles and authorize if consistent. Excess \$750.00 applicable.

Thanks
Kelvyna

From: leongseng <leongsen@singnet.com.sg>
Sent: 20 February 2019 18:19
To: General Claims <GeneralClaims@sg.gaig.com>
Subject: [External] FBE5169 & FBE5117 O/D claim - request for survey

Dear Sir/Mdm

Pls be informed that owner of FBE5169P and FBE5117P (Certis Cisco) had appointed us to submit an O/D claim for these 2 bikes.

Kindly find enclosed accident report and our repair estimate for both bikes.

Kindly arrange your appointed surveyor to conduct damage survey on these 2 bikes, at our workshop.

Thanks

c s teo

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 1 March 2019 5:59 PM
To: Ngian, Kelvyna; Veron Chen (LKKAUTO); SUR
Subject: RE: OD survey - FBE5117P & FBE5169P (CLMOMVM000000446)
Attachments: MARK EST_0001.pdf; PRELI REVISED.pdf; PRELI ADVISED FBE 5117P.pdf; FBE5117 EST.pdf

Dear Kelvyna

Enclosed preliminary revised of vehicle **SKU 3291R and FBE 5117P**

We have offer at lump sum \$4500/- and did not authorise repair for FBE 5117P.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Friday, 1 March 2019 5:34 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: OD survey - FBE5117P & FBE5169P (CLMOMVM000000446)

Hi Denise

As spoken, please let us know the latest on the OD developments for this 2 vehicles, in particular FBE5117P and if repairs had been authorized?

Thanks
Kelvyna

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Wednesday, February 27, 2019 11:42 AM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: [External] RE: OD survey - FBE5117P & FBE5169P (CLMOMVM000000446)

Dear Kelvyna,

Will check with our surveyor and get back to you



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CLMOMVM000000447

Date: 25/2/2019

Our Ref: CS/GAI19003380/Etd3

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sirs/Mdm,


PRELIMINARY ADVICE OF VEHICLE NO. FBE 5117P .

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 22/2/2019 at the premises of M/s Leong Seng Motor and have the following to report: -

Workshop Estimate Amount	: S\$ 9,305.00
Revised Estimate Amount	: S\$ 7,392.50
Check" Items Amount	: S\$ 1,080.00
Market Value	: S\$ 5,000.00
LTA Reimbursement Value	: S\$ 153.00
Nett Value	: S\$ 4847.00

Description of Damage:

The vehicle sustained at the rear and N/S portion.



Comments/ Present Status:

Damage consistent

Yours faithfully
Steve
Motor Surveyor

Steve Chen (LKK Auto)

From: leongseng <leongsen@singnet.com.sg>
Sent: Friday, March 15, 2019 10:54 AM
To: Steve Chen (LKK Auto)
Subject: Re: FBE5117P Finalize

Dear Steve

Pls refer to your offer,

Pls be informed that as to save cost and time for all parties, we are agreeable to your offer of Lump sum \$5800.

We will submit our final repair bill accordingly.

Thanks

c s teo

From: Steve Chen (LKK Auto)
Sent: Friday, March 15, 2019 10:03 AM
To: leongsen@singnet.com.sg
Subject: FBE5117P Finalize

Dear Mr Teo,

I have come out with the finalize \$5,800 lump sum. 4 days.

Kindly check and confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAUTO)

From: leongseng <leongsen@singnet.com.sg>
Sent: Friday, 8 March 2019 7:06 PM
To: SUR
Subject: FBE5117 marked estimate
Attachments: IMG_20190308_0002.pdf

Dear Steve

Pls find enclosed FBE5117 marked estimate and email printout from GAI officer.

Pls check and advice us on your recommended COR

Pls find below are our working on COR

parts	\$4020.00
less 10%	(\$ 402.00)
	\$3618.00
net items & labour	\$3760.00
sub total	\$7378.00
less 20%	(\$ 1475.60)
total	\$5902.40

Based on our above working, we will like to request for Lump Sum repair of \$5900.00.

Kindly consider and update us with your recommendation.

Thanks

c s teo

leongseng

From: "Ngian, Kelvyna" <Kelvyna.Ngian@sg.gaig.com>
Date: Thursday, 7 March 2019 1:40 PM
To: "leongseng" <leongsen@singnet.com.sg>
Subject: RE: Re: CLMOMVM000000447 FBE5117 O/D claim, market value

Hi Teo,

As we spoke earlier, may proceed with repair limit of \$6000.00. Noted that repairs likely not more than \$5800.00.

Thank you
Kelvyna

From: Ngian, Kelvyna
Sent: Wednesday, March 06, 2019 7:13 PM
To: 'leongseng' <leongsen@singnet.com.sg>
Subject: RE: [External] Re: CLMOMVM000000447 FBE5117 O/D claim, market value

Hi Teo,

Yes, no worries understand your concern.
Thanks for your feedback. Is with feedback that there is improvement.

We have reviewed the market value and done the adjustment, I will call you tomorrow morning prior to authorization.

Thank you
Kelvyna
68046059

From: leongseng <leongsen@singnet.com.sg>
Sent: Friday, March 01, 2019 7:18 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] Re: CLMOMVM000000447 FBE5117 O/D claim, market value

Owner ID type:	Company
Owner ID:	0822K
Vehicle Details	
Vehicle No.:	FBES117P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	CB400SF
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	NC42E1113538
Chassis No.:	NC421200214
Maximum Power Output:	-
Open Market Value:	\$8,366.00
Original Registration Date:	15 May 2010
First Registration Date:	15 May 2010
Transfer Count:	1
Actual ARF Paid:	\$1,255.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 May 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,253.00
COE Rebate Amount:	\$153.00
Total Rebate Amount:	\$153.00

The information contained herein is correct as at 23 Feb 2019

Home (/) > Motorbikes (/categories/motorbikes-108) > Motorbikes for Sale (/categories/motorbikes-108/motorbikes-for-sale-1392)
 > Class 2A (/categories/motorbikes-108/motorbikes-for-sale-1392/class-2a-1594)



Share This Listing



(https://www.facebook.com/sharer.php?u=https://sg.carousell.com/p/cb400-spec-1-revised-210607775/) (https://sg.carousell.com/p/cb400-spec-1-revised-210607775/)

Public Comments

Be the first to write a public comment. Ask a question or mention a friend to check this out!

Post a New Comment

Cb400 spec 1 revised

34 Chat Make Offer

- 1 month ago by boredon (/boredon)
- \$54,700
- 34 Likes
- Used
- In Class 2A (/categories/class-2a-1594)
- Spec 1 with blueflame exhaust in immaculate condition.
 Coe August 2019
 Road tax end of may 2019
 Inspection done on November 2018
 Next oil change should be in March
 No leaks and easy to start even after two days of not using. Able to ride with peace of mind until expiry in August without any repairs, just regular maintenance will do. Full tank around 300 km

Nea rebate 3.5k
 Blueflame 500
 Upon scrapping, other parts like tank, tyres, box, meter, showa suspension, seat, tailboard, mirror, rack etc etc can also fetch a few hundreds. Therefore, new owner is paying close to nothing for this bike

Non-urgent sale, will just ride until scrap and sell the parts individually if no buyers

Tags: Honda super four super 4
 cb400 CB 400 spec 1 spec1 vtec1
 vtec1 nea rebate

Make
 Honda
 Type
 Road Bike

Insurance
 Insure this vehicle with AXA.
 Premiums start from \$322.66

BUY AXA
 INSURANCE
 NOW

Getting This

Mailing & Delivery

Meet The Seller

boredon (/boredon/)
 Joined 4 years ago
 Verified

Reviews 5.0 ★★★★★ (13)

fatboyimg (/fatboyimg/) Great seller to deal with! Prompt delivery! Item d...read more
 1 month ago

ghufan222 (/ghufan222) Great seller to deal with! Punctual! Pleasant tran...read more
 8 months ago

mymobileshop (/mymobileshop) Great seller to deal and friendly fast transaction...read more
 9 months ago

Read All Reviews

YOU MAY ALSO LIKE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	19/02/2019 18:50
Date Of Accident	15/02/2019 16:00
Exact Location Of Accident	EXIT OF KPE TOWARDS PIE (CHANGI)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBE5117P
Insured/Policyholder	
Name Of Registered Owner	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
Co Reg No	200900882K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84823697
Alternative Phone No	OFFICE-84823697
Vehicle Particulars	
Manufacturer	HONDA
Model	CB400SF-399CC
Exact Purpose for which vehicle was being used at time of accident	GOING BACK TO BASE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT20171744
Cover Note Number	
Driver	
Name of Driver	DRALRAFFIAN BIN DAREN SETRIA
NRIC No	S9025345Z
Date Of Birth	23/07/1990
Occupation	OUTDOOR
Date Of Driving Pass	12/10/2016
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84823697
Fax Number	
Contact Number	OTHERS-84823697
Email Address	NOEMAIL

Address	BLK 179 BOON LAY DRIVE #03-470
Postcode	640179
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBE5169P
Vehicle Make/Model/Colour	HONDA CBR 400
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2



Vehicle Registration Number	SMF7392B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG YING YUAN (HUANG YING YUAN)
NRIC/Passport Number	S7627033C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

ATTACHMENT



INCIDENT REPORT FOR DUTY POST

Location of Duty Post	Type of Business (Bank/KINs/Embassy/ Residence/Factory)	Date of Incident	Time of Incident	Weather Condition
TUHS WEST AVENUE (NEAR SMOKEY OPS)		15/02/2019	1600 hrs.	clear
Person(s) Involved	Particulars of Witness(es)			
CPL MARILL 87765				
Details of Incident (Who, What, Where, When, Why, How and Other Essential Details)				
WHILST TRAVELLING BACK TO PAYA LEBAR DIVISION AFTER END OF OP OPERATION, I WAS INVOLVED IN A ROAD TRAFFIC ACCIDENT. A WHITE BMW MODEL SUV, SMH 7392B SUDDENLY JAMMED BRAKE AND CHANGE DIRECTION ACROSS THE CHEVRON MARKING, CAUSING BY MY COLLEAGUE CORPORAL MARILL 87765 WHO WAS RIDING MOTORCYCLE FBE 517P TO JAMMED HIS BRAKE, THUS I APPLIED MY BRAKE TO AVOID THE CRASH. MY MOTORCYCLE WAS SLIGHTLY DAMAGED AND NO ONE WAS INJURED AND FOOTAGE WAS RECORDED IN THE MOTORCYCLE CAMERA. PARTICULARS OF BMW DRIVER IS NG YIN YUAN (HUANG YIN YUAN), 97629033. MY MOTORCYCLE IS FBE 517P.				
Reported by : (Rank/Svc No/Name) CPL 92746 DEARAFAN		Signature 	Date 15/02/2019	Time 1655 hrs.

19/02/2019
ROSLI WATKINS

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Steve Supp b AFL 8/3/19
2.00pm

Veh No : FBE5117P
Model : CB400 Revo

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Headlamp assy / BR		\$ 450.00	/	
2	Front signal lamp / RH CUT	21	\$ 150.00	/ 75	
3	Horn / BT	2	\$ 90.00	/	
4	Front fender / CUT		\$ 220.00	/	
5	Front brake disc plate / BT		\$ 445.00	/	
6	Front fork assy / RH / LH BT	2	\$ 1,780.00	/	
7	Fork under bracket / BT		\$ 320.00	/	
8	Front wheel axle X NN		\$ 125.00	X	
9	Coolant tank ? X NN		\$ 755.00	X	
10	Handle bar / BT		\$ 235.00	/	
11	Handle grip (LH) TN		\$ 25.00	/ 3945	
12	Clutch lever / CUT		\$ 30.00	/ -10%	
13	Mirror (LH) CUT		\$ 85.00	/ 3550.50	
14	Side cover / LH BK		\$ 190.00	/	
15	Coolant X NN			\$ 50.00	X
16	Front wind shield / BR			\$ 380.00	/
17	ERP IU X X NN			\$ 165.00	X
18	IU bracket / BT			\$ 25.00	/
19	Front blinker lamp X LH X NN			\$ 250.00	X
20	Siren assy / DD			\$ 850.00	/
21	Front crash bar / CUT			\$ 450.00	/
22	Rear crash bar / CUT			\$ 350.00	/
23	Side box X NN			\$ 440.00	X
24	Side box bracket X BT			\$ 350.00	/
25	Front no plate / MEC			\$ 15.00	/
26	Co logo sticker / MEC			\$ 200.00	/
27	Respray windshield, fender, side box, side cover		400	\$ 450.00	
28	Towing 2 way		90	\$ 120.00	
29	Repair alignment		200	\$ 300.00	
30	Labour		400	\$ 500.00	
31	LKS Auto Consultants hence notify the Repairer of the following: • To resurvey before repair spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
32					3710
33					
34					
35					
36	Acknowledged by Repairer				
37	Signature:				
38	Date:				
39					

Steve b DD Authn
22/3/19
1.10pm
EXCEPT - 750
L/S
RA AF spay
Less 10%
4 days
83228813

\$ 4,900.00 \$ 4,895.00
\$ 490.00
\$ 4,410.00
7260.50
L/S - 5808.40
= 5800
9305

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBE5117P

Model : CB400 Revo

S/No	Parts Description	QTY	List Price	Nett Price	Remark
1	Headlamp assy / BR		\$ 450.00		
2	Front signal lamp / RH CUT	2	\$ 150.00		
3	Horn / BT	2	\$ 90.00		
4	Front fender / CUT		\$ 220.00		
5	Front brake disc plate BR ?		\$ 445.00		
6	Front fork assy BT / RH / LH BT	2	\$ 1,780.00		
7	Fork under bracket BT / BT		\$ 320.00		
8	Front wheel axle X NN		\$ 125.00	X	
9	Coolant tank ?		\$ 755.00		
10	Handle bar / BT		\$ 235.00		
11	Handle grip / LH TN		\$ 25.00		
12	Clutch lever / BT		\$ 30.00		
13	Mirror / CUT		\$ 85.00		
14	Side cover / LH BR		\$ 190.00		
15	Coolant / NEC			\$ 50.00	
16	Front wind shield / BR			\$ 380.00	
17	ERP IU / CUT			\$ 165.00	
18	IU bracket / BT			\$ 25.00	
19	Front blinker lamp / LH BT CUT BT			\$ 250.00	
20	Siren assy / BT BT			\$ 850.00	
21	Front crash bar / BT BT			\$ 450.00	
22	Rear crash bar / BT BT			\$ 350.00	
23	Side box X NN			\$ 440.00	X
24	Side box bracket BT / BT BT			\$ 350.00	
25	Front no plate / BT			\$ 15.00	
26	Co logo sticker / NEC BT			\$ 200.00	
27	Respray windshield, fender, side box, side cover		400	\$ 450.00	
28	Towing 2 way		90	\$ 120.00	
29	Repair alignment		200	\$ 300.00	
30	Labour		400	\$ 500.00	
31					
32				1250	
33					
34					
35					
36					
37					
38					
39					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 4,900.00 \$ 4,895.00
490.00

\$ 4,410.00

Arrowsay - 1450

Steve to OO Author
22/2/19 EXCESS - 750 Less 10%
1.10pm L/S 4 days
Rex AF spray

85228813




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI19003380/Etd3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date : 20-03-2019	
			Code : GAI	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.			Veh. Inspected	FBE 5117P
Policy No.	MT20171744		Coverage (\$)	0.00
Claim No.	CLMOMVM000000447		Excess (\$)	750.00
Assign From	KELVYNA NGIAN		Assign Date	21/02/2019
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400SF	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	NC421200214	Colour	WHITE	
Odometer	144556	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/60 R17	METZELER	7 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R17	METZELER	7 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/02/2019	Inspection Date	22/02/2019	
Survey held at	LEONG SENG MOTOR PTE LTD BLK 1006, BUKIT MERAH LANE 2 #01-08 ALEXANDRA VILLAGE SINGAPORE 159762.			
5a. Remarks				
A)THE MARKET VALUE IS S\$5,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 5117P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEADLAMP ASSY	BROKEN	450.00	450.00
2	FRONT SIGNAL LAMP	O/S CUT	150.00	75.00
2	HORN	BENT	90.00	90.00
1	FRONT FENDER	CUT	220.00	220.00
1	FRONT BRAKE DISC PLATE	BENT	445.00	445.00
2	FRONT FORK ASSY	BENT	1,780.00	1,780.00
1	FORK UNDER BRACKET	BENT	320.00	320.00
1	FRONT WHEEL AXLE	NOT NECESSARY	125.00	-
1	COOLANT TANK	NOT NECESSARY	755.00	-
1	HANDLE BAR	BENT	235.00	235.00
1	HANDLE GRIP (LH)	TORN	25.00	25.00
1	CLUTCH LEVER	CUT	30.00	30.00
1	MIRROR (LH)	CUT	85.00	85.00
1	SIDE COVER (LH)	BROKEN	190.00	190.00
	LESS 10% DISCOUNT		-490.00	-394.50
			4,410.00	3,550.50
<u>SPECIAL NETT ITEMS</u>				
1	COOLANT (SN)	NOT NECESSARY	50.00	-
1	FRONT WIND SHIELD (SN)	BROKEN	380.00	380.00
1	ERP IU (SN)	NOT NECESSARY	165.00	-
1	IU BRACKET (SN)	BENT	25.00	25.00
1	FRONT BLINKER LAMP LH (SN)	NOT NECESSARY	250.00	-
1	SIREN ASSY (SN)	DENTED	850.00	850.00
1	FRONT CRASH BAR (SN)	CUT	450.00	450.00
1	REAR CRASH BAR (SN)	CUT	350.00	350.00
1	SIDE BOX (SN)	NOT NECESSARY	440.00	-
1	SIDE BOX BRACKET (SN)	BENT	350.00	350.00
1	FRONT NO PLATE (SN)	NECESSARY	15.00	15.00
1	CO LOGO STICKER (SN)	NECESSARY	200.00	200.00
			3,525.00	2,620.00

Report Ref No. CS/GAI19003380/Etd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	RESPRAY WINDSHIELD, FENDER, SIDE BOX, SIDE COVER.		450.00	400.00
	TOWING 2 WAY.		120.00	90.00
	REPAIR ALIGNMENT.		300.00	200.00
	LABOUR.		500.00	400.00
			1,370.00	1,090.00
GRAND TOTAL			9,305.00	7,260.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,800.00
LESS EXCESS			-750.00
NETT LIABILITY			5,050.00

Report Ref No. CS/GAI19003380/Etd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.