

PLEASE ARRANGE TO SURVEY  
VEHICLE AT 30 BUKIT BATOK  
CRESCENT (S 658075)

Selamatshahh  
CLAIM DEPARTMENT  
DID : 66547519  
FAX :

Date : 19/02/2019  
To : ERGO INSURANCE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd  
: SOMPO INSURANCE SINGAPORE PTE. LTD.  
Certificate No : D18MTHCVE000160 Accident Date : 07/11/2018  
Vehicle No : GBG-8577-P Make & Model : TOYOTA DYNA 150 (EURO 6) 3.0 DIESEL G (M

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY                      | DESCRIPTION                            | REPAIRER AMT (\$)                  | SURVEYOR APP. |
|--------------------------|----------------------------------------|------------------------------------|---------------|
| <b>Nett Item</b>         |                                        |                                    |               |
| 1                        | REAR TAILGATE DOOR PANEL <i>PA ✓</i>   | 1,200.00                           |               |
| 1                        | REAR END PANEL                         | RESTORE                            |               |
|                          | <b>Sub Total</b>                       | <b>1200.00</b>                     |               |
| <b>Special Nett Item</b> |                                        |                                    |               |
| 1                        | REAR ADVERTISEMENT STICKER <i>ne ✓</i> | <del>300.00</del> <i>200</i>       |               |
| 1                        | 70 KM/H STICKER <i>ne ✓</i>            | 15.00                              |               |
| 1                        | TAILGATE ALUMINUM PANEL                | 400.00 <i>X 800 <sup>SVC</sup></i> |               |

Date : 19/02/2019  
To : ERGO INSURANCE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd  
: SOMPO INSURANCE SINGAPORE PTE. LTD.  
Certificate No : D18MTHCVE000160 Accident Date : 07/11/2018  
Vehicle No : GBG-8577-P Make & Model : TOYOTA DYNA 150 (EURO 6) 3.0 DIESEL G (M

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|-------------|-------------------|---------------|
|-----|-------------|-------------------|---------------|

|           |  |        |  |
|-----------|--|--------|--|
| Sub Total |  | 715.00 |  |
|-----------|--|--------|--|

#### Labour & Misc

LABOUR TO FACILITATE REPAIR  
TO RESPRAY AFFECTED AREAS

Sub Total

|                |     |
|----------------|-----|
| 500.00         | 300 |
| 500.00         | 250 |
| <b>1000.00</b> |     |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remarks:

3 days - repair

SUB TOTAL 3,035.00

GST 7.0 % 212.45

TOTAL 3,247.45

Surveyor's name: Rasu - HP 50010068

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 22/02/19 @ 1600

Resu after repair

PAGE : 2