

**The One Holdings Pte Ltd**

Office: 8 Woodlands Industrial Park E3 (S757786)

Reg :201704052Z

Phone: 67558810 Fax: 67558809

Our Ref: TP/PC7464T/0003

Date: 16/02/2019

**QUOTATION**

Dear Sir,

DOA : 12/02/2019

Cost of Repair to Vehicle PC7464T

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	Rear Engine Cover Assy SVC X	1	2,800.00	2,800.00
2.	Rhs Rear Cap Panel Assy SVC X	1	1600.00	1600.00
3.	Rear Bumper Assy DEF /	1	1800.00	1800.00 1500/
4.	60 KM Sticker NEC /	1	5.00	5.00 /
5.	RHS Rear Tail lamp CRA /	1	280.00	280.00 /
6.	HIGER Air Con Assy SVC X	1	2500.00	2500.00
7.	Aircon Fanbelt CUT /	1	225.00	225.00 180/
8.	Spray Painting on the whole rear cap, rear engine cover, rear bumper with Artwork	1	3000.00	1500 3000.00 -10%
9.	Labour & Misc. Charges: To remove the affected parts & all relevant attachment & fittings to commence repairs; cut & weld the necessary parts as listed above; panel beat & reshapes the affected areas; replace the damaged components, reinstall & realign all necessary parts (16Mandays)	16	400.00	6400.00 1400
10.	Loss of use	8	250.00	2000.00 } x GST
SUB-TOTAL				SS\$20,610.00

Thanks you.  
Yours faithfully,Vincent Yeo  
Claims Department

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

+ 0% GST

Hwee Jie-LKK

20/2/19

L/s S. S. S.

as