

ASS. REC. BY

REF

8/INC1900399/R1vd302

Special Instruction

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person) Annie Koh

of

INC

Date/Time

22/2/19 @ 9:23am

Estimated Cost

Bill to

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No:

PC 5799R

Insured:

SJV 6975M

at Workshop n/s

SMRT

Tel:

8858 3566

of

1 Hospital Drive # Singapore General Hospital

Policy No:

Claim No:

MT/1005132-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/02/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:40am 22/2/19

Person Contacted

Mr. Peh

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

PC5799R-NA/INC18014165/Y

DOA: 4/8/2018

SJV 6975M-NA/INC18014165/Y

DOA: 4/8/2018

PehEnghtock@smrt.com.sg

8/3/19

@ 257pm Mr Peh said vehicle has not send in for repair

10/4/19

@ 1130am Mr Peh said vehicle has not send in for repair

Page

REF: INC

35248

ASSIGNMENT

Form Date 22/2/2019

Estimated Cost

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: PC 5799R

at Workshop n/s: SMRT

at 1 Hospital Drive, Singapore General Hospital (SGH multi storey car park H)

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh: 3pm (owner waiting)

Mr. Peh @ 88583566

(Policy Condition) call him before go

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: PC 5799R

Regn: 2012 MY

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or: Mini-Bus

Make: Mitsubishi Rosa

CC: 2998

Colour: White

A/C: Insured / Std / NI / NA

Sp/Reading: 75185

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: BE 641 JK 30780

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 7-00 R16 LT

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or: WHT LK

Front: R/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 08/02/19

Survey held at: 1, Hospital Dr

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/5/19 Final fig \$1450 confirmed by email (Ref 4121-20, 7419)

RECEIVED 23 MAY 2019

Date/Time: File Pass to? ☐ : Preli. Report

Days Of Repair: 4

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time: File Return to?

Survey Fee:

Transportation

23/5 - typist

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Weekend (\$

Y. C. R. S.

Y. Photos

Y. Other

Y. Total

Report Format: TP

Lump Sum / LB L / S

TP

1450/-

TOTAL

250

250

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Friday, 22 February 2019 9:43 AM
To: 'assignments@lkkauto.com'
Subject: RE: TP CASES FARMED OUT TO LKK ON 22/02/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Friday, 22 February 2019 9:23 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>, Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 22/02/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
----	-----	-----------	---------	---------------	------------------	------------------	-------------	--------	-----	--------------------

1	ALICE LOW	MT/1005132- 001	PC5799R	SMART AUTOMOTIVE SERVICES PTE LTD	1 HOSPITAL DRIVE # SINGAPORE GENERAL HOSPITAL SINGAPORE 169608	88583566 / Peh Eng Ho	14:00- 14:00	SJV6975M	8/2/19	SGH Multi Storey Car Part H
2	JEFF LIN	MT/1025062- 002	YP8350G	WOON MENG MOTOR PTE LTD	50 BUKIT BATOK STREET 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578	MS HENG / 63161131		SJQ6334P	23/12/18	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	12/02/2018 09:00
Date Of Accident	08/02/2018 14:00
Exact Location Of Accident	SGH BLOCK 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	PC5799R
Insured/Policyholder	
Name Of Registered Owner	BUS-PLUS SERVICES PTE LTD
Co Reg No	199403524H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	BUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-II027593MFBP
Cover Note Number	
Driver	
Name of Driver	KHAIROL NIZA BIN MUSA
NRIC No	G6627419K
Date Of Birth	08/10/1982
Occupation	OUTDOOR
Date Of Driving Pass	12/02/2010
Driving Experience	7 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 60 WOODALNDS IND PARK E4

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 5

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

MY BUS WAS STATIONARY AT SGH BLOCK 3 WAITING TO ALIGHT PASSENGERS. WHEN SUDDENLY, ONE PRIVATE VEHICLE, SJV6975M FROM BEHIND TRIED TO OVERTAKE MY BUS AND IN THE PROCESS, THE LEFT PORTION OF THE SAID VEHICLE GRAZED AGAINST THE REAR RIGHT PORTION OF MY BUS. THERE WERE 4 PASSENGERS IN MY BUS AND NO INJURY WAS REPORTED AT THE MATERIAL TIME. THIRD PARTY PROPOSED FOR PRIVATE SETTLEMENT & I INFORMED MY COMPANY TO CALL HIM FOR NECESSARY FOLLOW UP

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV6975M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver JEFFEREY WONG

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

— As Attached —

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Please refer to GIA report.


DECLARATION

I/We declare the foregoing particulars are true in every respect.




Policyholder's Signature
Date & Time:

 9 FEB 2018
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SGH BLOCK 3

MAIN ENTRANCE




SMRT Vehicle Repair Estimate

Group :	<u>Buses / Taxis / Private Car</u>	Ref. No. :	_____
Reg. No. :	<u>PC 5799 R</u>	Reg. Date :	<u>5/11/2017</u>
Make / Model :	<u>Mitsubishi Fuso</u>	Mileage :	_____
Chassis No. :	<u>BE641JK30260</u>	Rental/Replacement Vehicle :	<u>Yes / No</u>
Name of Driver :	<u>BUS PLUS SERVICES PTE LTD</u>		
Date/Time of Accident :	<u>08/02/2018 14:00:00 PM</u>		
Surveyor is Required ?	<u>YES / NO</u>		
If Yes, VICOM / LKK / AIS / Others MSIG :	_____		
Vehicle is Towed Back ?	<u>YES / NO</u> Date / Time : _____		
Accident reporting date :	<u>12/2/2018 09:00:00AM</u>		
Type of Accident : Skid / Head-Rear / <u>Head-On</u> / Side Swipe / Others			
Special Instruction to ARC, if any :	<u>LUMP SAM TP</u>		

Signed :		Date :	

The damages on the vehicle are as indicated in the following diagram :



Accident Repair Job Card No. :	_____	Date Prepared :	_____
Summary of Repair Estimates		Repair Completed :	_____
	Quotation from ARC		Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ _____ 500.00		\$ _____ -
Total Spray Painting Charges :	\$ _____ 800.00		\$ _____ -
Total Material Charges :	\$ _____ 3,504.08		\$ _____ -
Other Charges :	\$ _____ 600.00		\$ _____ -
TOTAL :	\$ _____ 5,404.08		\$ _____ -
	Lump Sum Repair, if any :		_____
No. of Repair Days :	[<u>4</u>] days		[_____] days
Signature :	Prepared by: _____		Adjusted by: _____

QN No. _____	Invoice No. _____
Signed :	Date : _____

Part 1 - Labour Works

Job Scope	Quotation from ARC	
To renew damaged parts, replace and realign hydraulic, and aligned all parts	\$ 500.00	
Total Labour Cost	\$ 500.00	\$ -

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray affected areas	\$ 800.00	
Spray Painting	\$ 800.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page ()

Job Scope	Quotation from ARC	
Towing		
Windscreen sealant		
To tuffcoat affect areas		
To remove & refix front windscreen		
To renew engine mountings		
To remove /refit aircon condensor, pipings, vacuum and recharge aircon gas		
To remove/refit replace dashboard		
To remove and refit interior upholstery & cushion seat		
To remove and replace steering column		
To remover /refit wiring check		
To remove/refit adjust brake 4 wheel		
To remove/replace exhaust silencer box and straighten centre pipe		
To remove & refix side glass RH		
To remove & replace advertisement sticker		
To remove & renew Fuel Tank		
To remove and replace advertisement sticker	\$ 600.00	
Total Other Costs	\$ 600.00	

Part 4 - Spare Parts / Material Usage

To be completed by Service Advisor, ARC							
Part Number	Parts Description	Qty	Cost Price (\$)	less 10%	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
	REAR BUMPER	1	\$ 1,588.59	10%	\$ 1,429.73		
	REAR BUMPER SIDE BRACKET RH	1	\$ 82.61	10%	\$ 74.35		
Special Nett Items	Parts Description	Qty	Cost Price (\$)	Discount	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
	FRONT SIDE PANEL ADVERTISEMENT STICKER LH	1	\$ 800.00		\$ 800.00		
	REAR SIDE PANEL ADVERTISEMENT RH	1	\$ 1,200.00	-	\$ 1,200.00		
TOTAL MATERIALS			\$ 3,671.20	-	\$ 3,504.08		

Surveryor Remark:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number	: 63685592
Estimator Telephone Number	: 68662623
Accident Reporting Number	: 68662672

Date Generated : 09/11/2018

User ID : PehEngHock

Section A - Accident Details	
Registration Number	PC5799R
Case Reference Number	BPS/02/18/3001
Registration Date	1/1/1900
Company Type	Bus-Plus Services Pte Ltd
Make	MITSUBISHI
Model	MITSUBISHI ROSA BE637
Name of Driver	Khairul Niza Bin Musa
Type of Accident	SIDE SWIPE
Accident Date and Time	2/8/2018 2:02 PM
Accident Reported Date and Time	2/9/2018 12:00 AM
Is Surveyor Required?	Yes
Survey by	IDAC
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	rear right portion scratched TP: SJV6975M(NTUC)
Prepared Date and Time	09/02/2018 3:40 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$500.00	\$0.00
Total Spray Cost	\$800.00	\$0.00
Total Spare Part Cost	\$3,504.08	\$0.00
Total Other Cost	\$600.00	\$0.00
TOTAL COST	\$5,404.08	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	09/11/2018 1:56 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/11/2018

User ID : PehEngHock

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & REFIT ALL AFFECTED AREA		\$500.00				300 300 /			
Total Labour		\$500.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PUTTY AFFECTED AREAS		\$800.00				400 /			
Total Spray Painting & Panel Beating		\$800.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
ADVERTISEMENT STICKER		\$600.00				300 / nil			
Total Other Costs		\$600.00							
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			REAR BUMPER	1.00	\$1,588.59	10.00	\$1,429.73	Replace	repair
			REAR BUMPER SIDE BRACKET RH	1.00	\$82.61	10.00	\$74.35	Replace	X nn
			FRONT SIDE PANEL ADVERTISEMENT STICKER LH	1.00	\$800.00	0.00	\$800.00	Replace	na X nn
			REAR SIDE PANEL ADVERTISEMENT RH	1.00	\$1,200.00	0.00	\$1,200.00	Replace	na 450 / price?
Total					\$3,671.20		\$3,504.08		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5591.20

Faruk

Hp 90010068

4 days

P/P

22/02/19 P1530

Resy after repair

25/2/19



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
00 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 68662033
Accident Reporting Number : 68662672

Date Generated : 09/11/2018

User ID : PehEngHock

Section A - Accident Details

Registration Number	PC5789R
Case Reference Number	BPS/02/18/0001
Registration Date	1/1/1900
Company Type	Bus-Plus Services Pte Ltd
Make	MITSUBISHI
Model	MITSUBISHI ROSA BE637
Name of Driver	Khalid Niza Bin Musa
Accident	SIDE SWIPE
Accident Date and Time	2/8/2018 2:02 PM
Accident Reported Date and Time	2/9/2018 12:00 AM
Is Surveyor Required?	Yes
Survey by	IDAC
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	2A00A52
Special Instruction to ARC, if any	rear right portion scratched TP: SJV8975M(NTUC)
Prepared Date and Time	09/02/2018 3:40 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$500.00	\$0.00
Total Spray Cost	\$800.00	\$0.00
Total Spare Part Cost	\$3,504.08	\$0.00
Total Other Cost	\$600.00	\$0.00
TOTAL COST	\$5,404.08	\$0.00
Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	09/11/2018 1:56 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/11/2018

User ID : PehEngHock

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & REFIT ALL AFFECTED AREA	\$500.00	300
Total Labour	\$500.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PUTTY AFFECTED AREAS	\$800.00	400
Spray Painting & Panel Beating	\$800.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
ADVERTISEMENT STICKER	\$500.00	300
Total Other Costs	\$500.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			REAR BUMPER	1.00	\$1,588.59	10.00	\$1,429.73	Replace	replace
			REAR BUMPER SIDE BRACKET RH	1.00	\$82.61	10.00	\$74.35	Replace	X
			FRONT SIDE PANEL ADVERTISEMENT STICKER LH	1.00	\$800.00	0.00	\$800.00	Replace	new X
			REAR SIDE PANEL ADVERTISEMENT RH	1.00	\$1,200.00	0.00	\$1,200.00	Replace	new X
Total					\$3,671.20		\$3,504.08		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Farul
Hp 90010068
4 days
P/P
22/02/19 P1530
Ready after repair
25/2/19

1000
450
1200
2200
1450

Veron Chen (LKKAUTO)

From: Peh Eng Hock (Auto Svcs/ARC/AR & SC/Taxis) <PehEngHock@smrt.com.sg>
Sent: Wednesday, 22 May 2019 1:09 PM
To: Rasul (LKKAUTO)
Subject: RE: PC5799R After Repair Photos

Hi Rasul,

We have confirmed the finalise amount at COR \$1,450.00 and 4 repair days

Thank you

Regards
Peh Eng Hock
SMRT Automotive Services Pte Ltd (ARC) Direct : +65 68662673 Mobile : +65 88583566 E-mail :
PehEngHock@smrt.com.sg

Peh Eng Hock

Hi Mr Peh,

As spoken, finalise amount is \$ 1450 / 4 days of repair Kindly confirm

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |
S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Peh Eng Hock (Auto Svcs/ARC/AR & SC/Taxis) [mailto:PehEngHock@smrt.com.sg]
Sent: Wednesday, 22 May, 2019 9:11 AM
To: Rasul (LKKAUTO)
Subject: Re: PC5799R After Repair Photos

Hi Rasul,

Please find file attached after repair photos for PC5799R.

Hope we can finalize ASAP.

Thank you

Regards
Peh Eng Hock
SMRT Automotive Services Pte Ltd (ARC) Direct : +65 68662673 Mobile : +65 88583566 E-mail :
PehEngHock@smrt.com.sg

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19003399/R1vd3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556

Date: 23-05-2019



ATTN : ALICE LOW

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJV 6975M	Veh. Inspected	PC 5799R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1005132-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	22/02/2019

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI ROSA	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	BE641JK30280	Colour	WHITE
Odometer	65185 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	7.00 R16LT	WEST LAKE	7 mm
L/H Front Tyre	7.00 R16LT	WEST LAKE	7 mm
R/H Rear Tyre	7.00 R16LT (D)	WEST LAKE	7/7 mm
L/H Rear Tyre	7.00 R16LT (D)	WEST LAKE	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/02/2019	Inspect Date / Time	22/02/2019 (03:26 PM)
Survey held at	1 HOSPITAL DRIVE# SINGAPORE GENERAL HOSPITAL		
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 5799R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,588.59	-
1	REAR BUMPER SIDE BRACKET RH	NOT NECESSARY	82.61	-
			1,671.20	-
SPECIAL NETT ITEMS				
1	ADVERTISEMENT STICKER (SN)	NECESSARY	600.00	300.00
1	FRONT SIDE PANEL ADVERTISEMENT STICKER LH (SN)	NOT NECESSARY	800.00	-
1	REAR SIDE PANEL ADVERTISEMENT RH (SN)	NECESSARY	1,200.00	450.00
			2,600.00	750.00
LABOUR				
	TO REMOVE & REFIT ALL AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		500.00	300.00
	PUTTY AFFECTED AREAS.		800.00	400.00
			1,300.00	700.00
GRAND TOTAL			5,571.20	1,450.00

RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,450.00
--	--	--	-----------------

Report Ref No. CS/INC19003399/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.