

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

*Authorise.
@13.00pm*

22 FEB 2019

Survey LKk-Auto

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLH7209K

Chassis No : JHMRU1810GX201295

Model : HRV DX-SIN CVT YM 2016

Owner's Name : ANG ZIQIANG

Ins Policy No. :

Date of Accident : 4/2/2019

Document No. : SQT19000733 Page 1

Date : 14. Feb 2019

Customer No. : WZI007

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15B4531296

Date | Time : 14. Feb 2019 5:33:25 PM

Surveyor Name :

Survey Date : DID : +65 6846 5673

Authorisation Date : HP : +65 8100 6306

Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72177)						
	OWNER: ANG ZIQIANG						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 04-02-2019@19.30PM						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD						
	TP VEH: SH8872E - TOYATA/PRIUS/BLUE/TAXI						
33150-T7S-E11	HEAD LIGHT ASSY,L.	<i>scr</i> 1	1509.30	25	1131.97	79.24	1211.21
04711-T7A-N00ZZ	FACE,FR.BUMPER	<i>Deep cut</i> 1	475.60	25	356.70	24.97	381.67
91505-TM8-003	CLIP,BUMPER	<i>ru</i> 10	2.30	25	17.25	1.21	18.46
71106-T7A-000	GARNISHL,FR.FOG LIGHT	<i>in</i> 1	21.50	25	16.12	1.13	17.25
71130-T7A-010ZZ	BEAM COMP,FR.BUMPER	<i>in</i> 1	222.90	25	167.17	11.70	178.87
71198-T7A-J00	SPACER,L,FR.BUMPER SIDE	<i>all</i> 1	11.00	25	8.25	0.58	8.83
71193-T7A-J00	SPACER,R,FR.BUMPER SIDE	<i>in</i> 1	11.00	25	8.25	0.58	8.83
74107-T7B-003	PROTECTOR,R,FR.WHEEL ARCH	<i>cut</i> 1	153.60	25	115.20	8.06	123.26
	Sum Item				1820.91	127.47	1,948.38
BOSUN	SUNDRIES	<i>her</i> 1	40.00	20	40.00	2.80	42.80
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	140.00	100	140.00	9.80	149.80
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1400.00	560	1400.00	98.00	1498.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1400.00	900	1400.00	98.00	1498.00
	Sum Labor				2980.00	208.60	3,188.60

Survey By

Date & Time

Excess

nicolus HLL

22/2/19

Not Authorised

3 day.

Take photo before survey.

LKk Auto Consultants hence notify

the Repairer of the following

• Total Amount 4,800.91 336.07

• To resurvey before/after spray painting

Total (Inclusive of GST) 5,136.98

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: