

22/02/2019

ASS. REC. BY

REF

CS/MSG/19003426/USD3M2

Special Instruction

Surveyor

Narany

ASSIGNMENT (Office)

From (Person)

Mund Ashik

of

MS/G

Date/Time

22/2/19 @ 4:41pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLZ 6093M

Insured

GBC 7799T

at Workshop m/s

Ace Autolution

Tel

6844 1184

of

B/113 Kalki Bkt Rd 4 #03-29

Policy No.

28634653

Claim No.

585307

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A. 16/02/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

10:19am @ 28/2/19

Person Contacted

Anna

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLZ 6093M-X
	GBC 7799T
28/02/19	@ 09:32 a.m. revert pending estimate from repairer to Ashik via narany.

(08/11/13) wef

REF:

ASS. REC. BY: *Marcus***ASSIGNMENT**

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SL 26093M*
 at Workshop m/s *Acc Action*
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *27k*
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: *7* days Res.: Yes or No
 Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

19/7/2020

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SL 26093M* Yr Regn: *7.10*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA*
 Make: *Honda Stream* c.c. *1799*
 Colour: *white* A/C: Insured / Std / NI / NA
 Sp. Reading: *129872* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *JHMRN68609C200093*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: *215/50R17*
 R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. *6* mm R/Bal. *6* mm
 L/Bal. *6* mm L/Bal. *6* mm
 D.O.A. *16/2/19* D.O.I. *25/2/19*
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
u/s fl.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rep 10c.

anomaly Estimate. LTA 19415 1454ale.
re H 7589

28/5/19 L/S \$5900 confirmed with Anna.
(\$ 5,834.72 red - 50%)

[Signature]
28/5/2019

RECEIVED 28 MAY 2019

Date/Time, File Pass to?

28/05/19☐ : Preli. ReportDays Of Repair: *7*1) *Typ. 54*☒ : Final ReportResurvey No. of Trip: *2*

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$Transportation: *200*☐ : Interview (\$) *10* S + RS, SI☐ : Tech. Invs (\$

) Photos

☐ : Weekend (\$

) Others

Report Format :

Lump Sum / I.B.I. (\$ *5,900/- 45*)

TOTAL

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Identified	Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Feb 2019		22 Feb 2019 16:41 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	NAM LEONG PTE. LTD., Co. Reg. No.: 195800019C		
Main Claimant:	Lim Mui Kim		
Vehicle Reg. No.:	SLZ6093M	Date of Loss:	16/02/2019 15:00 - :59 [8 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 585307	Policy/Cover Note No.:	28634653 (Comprehensive) Coverage: 05/11/2018 - 04/11/2019
Vehicle Reg. No. (Insured):	GBC7799T	Policy No. (Claimant):	
		Excess:	
Repairer:	Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre, 417807 Kaki Bukit - Tel: 68441184		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/02/2019]		
Driver/Custodian (Insured):	RAMASAMY VELMURUGAN (), NRIC: G6833801N, Tel: +6581208689 Email:		
Adj Asg. Remarks:	Liability unclear, SJE agree - Marcus Chua from LKK Auto. Contact : Ms Anna at 6844 1184		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due	Prior	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.								

View Sent Message

This mail is associated with :

***SLZ6093M (585307)**
[GBC7799T]

TP
Lim Mui Kim
Feb 16 2019 3:00PM
[NAM LEONG PTE. LTD.]
Ace Autolution Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 28/02/2019 09:32 AM.
To ashik_madi@sg.msg-asia.com
CC sur@lkkauto.com
Subject SLZ6093M (585307) [GBC7799T] TP

Dear Ashik,

Please be informed that we have inspected the vehicle SLZ 6093M on 25/02/2019.
We are pending estimate from repairer.



Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.



stream Price Range Depreciation 2010 Vehicle Type Submit Advanced Search

Home » Used Cars » MS Carz » Honda Stream 1.8A X

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres

Honda Stream 1.8A X

Overview Financial Insurance Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details	
Price	\$30,800
Depreciation	\$12,330 /yr View models with similar depreciation
Reg Date	12-Oct-2010 (1yr 7mths 16days COE left)
Manufactured	2009
Mileage	96,000 km (11.5k /yr)
Transmission	Auto
Engine Cap	1,799 cc
Road Tax	\$978 /yr
Power	103.0 kW (138 bhp) View specs of the Honda Stream (2007-2014)
Curb Weight	1,360 kg
Features	Powerful 1.8L I-VTEC Engine, 16 Valves, Smooth 5 Speed Automatic Transmission, Airbags, Digital Climatic Control Aircon, Retractable Side Mirrors.
Accessories	Front Camera, Reverse Camera, Sports Rims, Retractable Wing Mirrors, Reverse Sensors, Solar Film, Leather Seats, Knockdown Rear Seat.
Description	Low Drepre, Very Well Maintained, Interior And Exterior In Good Condition! Engine Still Roaring Strong, Gearbox Transition Very Smooth. The One Unit You Can Buy Without Worries! Bank Loan Available, Call Our Sale For More Informations.
COE	\$42,801
OMV	\$21,476
ARF	\$21,476
Dereg Value	\$18,777 as of today (change)
No. of Owners	2
Type of Veh	MPV
Category	PARF Car
Availability	Available

Add to Shortlist Add to Compare Add a Note

Posted on: 24-Feb-2019 | Last Updated on: 24-Feb-2019
Tags: Honda Stream, honda stream, 2010 Honda Stream, 2010 honda stream, Honda, Stream, stream, Used Honda



Seller Information

Company	MS Carz » dealer's pricelist » 18 vehs sold 10 vehs available
Address	210 Turf Club Road Lot B31 Search cars nearby this location
Location	Car Mall @ The Grandstand
Contact Person(s)	Ck 96920330 William 83186606 Jack 98506880

Useful Services

STA
VEHICLE INSPECTION

Afraid of lemons? Request to have this car evaluated professionally.
Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.
Free Valuation

RENEW
YOUR COE



1.99%*P.A ONLY

MONEYMAX
LEASING
MEMBER OF MONEYMAX FINANCIAL SERVICES LTD.

stream

Price Range

Depreciation

2010

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Swee Watt Motor Trading » Honda Stream 1.8A X

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres



Honda Stream 1.8A X

Overview Financial Insurance Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$24,900	
Depreciation	\$13,060 /yr	
Reg Date	25-Mar-2010	
Manufactured	2009	
Mileage	112,339 km (12.6k /yr)	
Transmission	Auto	
Engine Cap	1,799 cc	
Road Tax	\$978 /yr	
Power	103.0 kW (138 bhp)	
Curb Weight	1,350 kg	
Features	16 Valves I-VTEC Engine, 5 Speed Auto Transmission, Dual Airbags, Auto Retractable Side Mirrors, Climatic Control Aircon.	
Accessories	Leather Seats, Arm Rest, Reverse Sensor, Reverse Camera, Sport Rims, Fog Lamps.	
Description	(We Assure 100% Genuine Mileage,) Original Condition,	
COE	\$24,229	
OMV	\$21,680	
ARF	\$21,680	
Dereg Value	\$14,533 as of today (change)	
No. of Owners	2	
Type of Veh	MPV	
Category	PARF Car	
Availability	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 09-Feb-2019 | Last Updated on: 24-Feb-2019
Tags: Honda Stream, honda stream, 2010 Honda Stream, 2010 honda stream, Honda, Stream, stream, Used Honda



Seller Information

Company	Swee Watt Motor Trading
Address	61 Ubi Avenue 2 #02-10
Location	Automobile Megamart
Office No	63441932
Contact Person(s)	Ms Ivy 97370832 Mr Ang 98320832

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

Free Valuation



Upfront Payment

more Financial info

Transfer Fee	\$25	
Down Payment	\$7,470 (change)	Maximum 70% Loan

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	3424G

Vehicle Details

Vehicle No.:	SLZ6093M
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L AT SUNROOF
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	R18A13850092
Chassis No.:	JHMRN68609C200093
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$25,131.00
Original Registration Date:	20 Jul 2010
First Registration Date:	20 Jul 2010
Transfer Count:	1
Actual ARF Paid:	\$25,131.00 12868

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jul 2020
PARF Rebate Amount:	\$13,822.00

Intended COE Rebate Details

COE Expiry Date:	19 Jul 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$43,003.00
COE Rebate Amount:	\$5,593.00
Total Rebate Amount:	\$19,415.00

The information contained herein is correct as at 25 Feb 2019

OK



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

Page No. 1

Vehicle No. SLZ6093M HONDA STREAM

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	FRONT BONNET	Dis	1011.00	✓
2	FRONT BONNET HINGE RH & LH @105.00	38 90x2" Berl	77.80	✓
1	FRONT BONNET CABLE	Dis	68.50	✓
1	FRONT BONNET LOCK	Dis	85.10	✓
1	FRONT HEADLAMP RH	Dis	680.40	✓
1	FRONT HEADLAMP BRACKET RH	Dis	52.50	✓
1	FRONT HEADLAMP WIRE RH	Dis	69.00	✓
1	FRONT GRILLE BASE	Dis	315.00	✓
1	FRONT BUMPER	Dis	635.20	✓
1	FRONT BUMPER SIDE RETAINER RH	Dis	35.20	✓
1	FRONT Bonnet insulator	Dis	205.00	✓
1	FRONT BUMPER REINFORCEMENT	Dis	465.00	✓
1	FRONT BUMPER FOGLAMP COVER RH	Dis	65.00	✓
1	FRONT SUPPORT PANEL	Dis	466.20	✓
1	FRONT SUPPORT PANEL TOP COVER	Dis	165.30	✓
2	FRONT FENDER RH & LH @530.00	Dis	519.30	✓
1	FRONT FENDER INNER SHIELD RH	Dis	85.70	✓
1	FRONT FENDER SIGNAL LAMP RH	Dis	192.00	✓
1	FRONT FENDER SIGNAL LAMP WIRE RH	Dis	69.00	✓
1	FRONT FENDER INNER COVER RH	Dis	36.50	✓
1	FRONT WINDSCREEN MOULDING o/s	Dis	195.00	✓
1	FRONT WIPER COVER	Dis	194.20	✓
1	FRONT WIPER HOLE	Dis	85.00	✓
1	FRONT WIPER SPARE TANK	Dis	350.00	✓
1	FRONT fender inner panel o/s	Dis	680.70	✓
			9805.90	
less 20%			1961.18	20%
			7844.72	
SPECIAL NETT ITEMS				
1 SET	FRONT BUMPER CLIPS	Dis	80.00	35
1 SET	FRONT SUPPORT PANEL TOP COVER CLIPS	Dis	100.00	30
1 SET	FRONT BONNET STICKER	Dis	150.00	100
1 SET	FRONT DOOR RH STICKER	Dis	120.00	✓
Total Parts			8294.72	

285

not Authorized
H/5 5900
1.1.1
the photo attached

5205.50
27.
4164.4



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SLZ6093M HONDA STREAM

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00 —	1400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00 —	1180
3	To remove and refix wiring at damaged areas	200.00 —	50
4	To perform anti rust treatment on affected areas	240.00 —	120
5	To refill air con gas	100.00 ✓	100
6	To conduct wheel alignment	100.00 —	80
Labour Total :			
TOTAL (PARTS & LABOUR):			

3440

11734.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To survey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Subsequent repairs must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-4164.40
S.N-285.00
Labour-2930.00
7379.40
202
5903.52

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19003426/USD3N2

Date: 29/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28634653		
Claimant Vehicle No :	SLZ6093M	Insured Vehicle No :	GBC7799T		
Date of Loss:	16/02/2019	Nature of Claim:	TP	Claim No:	585307

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ6093M	Engine No:	R18A13850092
Make & Model:	HONDA STREAM, 1.8 Sunroof (A)	Chassis No:	JHMRN68609C200093
Reg. Date:	20/07/2010 (Man. Year: 2009)	Odometer:	129872 km
Colour:	White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50R17	Rear Tyre Size:	215/50R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,294.72	4,449.40	3,845.32	46.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	2,930.00	510.00	14.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,734.72	7,379.40	4,355.32	37.11
Approved Total (Overridden) (S\$)		5,900.00		
Nett Amount (S\$)	11,734.72	5,900.00	5,834.72	49.72

INSPECTION

Date of Assignment:	22/02/2019		
Date Inspected:	25/02/2019	Inspected At:	Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 May 2019)
Parts:	M1-MPV	HONDA STREAM 1.8 Sunroof (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ6093M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Distorted	1,011.00 FL	*638.90 FL
2	2		*FRONT BONNET HINGE RH & LH	Bent	210.00 FL	*77.80 FL
3	1		*FRONT BONNET CABLE	Torn	98.00 FL	*68.50 FL
4	1		*FRONT BONNET LOCK	Twisted	155.00 FL	*85.10 FL
5	1		*FRONT HEADLAMP RH	Broken	1,795.00 FL	*680.40 FL
6	1		*FRONT HEADLAMP BRACKET RH	Cracked	80.90 FL	*52.50 FL
7	1		*FRONT HEADLAMP WIRE RH	No such part	69.00 FL	*- FL
8	1		*FRONT GRILLE BASE	Cracked	315.00 FL	*315.00 FL
9	1		*FRONT BUMPER	Distorted	1,055.00 FL	*635.20 FL
10	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	140.00 FL	*35.20 FL
11	1		*FRONT BONNET INSULATOR	Distorted	205.00 FL	*205.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	465.00 FL	*- FL
13	1		*FRONT BUMPER FOGLAMP COVER RH	Not Necessary	65.00 FL	*- FL
14	1		*FRONT SUPPORT PANEL	Bent/Distorted	510.00 FL	*466.20 FL
15	1		*FRONT SUPPORT PANEL TOP COVER	Torn	190.00 FL	*165.30 FL
16	1		*FRONT FENDER RH & LH	O/s Distorted/N/s Repair	1,060.00 FL	*519.30 FL
17	1		*FRONT FENDER INNER SHIELD RH	Torn	171.00 FL	*85.70 FL
18	1		*FRONT FENDER SIGNAL LAMP RH	Not Necessary	192.00 FL	*- FL
19	1		*FRONT FENDER SIGNAL LAMP WIRE RH	Torn	69.00 FL	*69.00 FL
20	1		*FRONT FENDER INNER COVER RH	Distorted	210.00 FL	*36.50 FL
21	1		*FRONT WIPER COVER	Distorted	220.00 FL	*194.20 FL
22	1		*FRONT WIPER HOLE	Not Necessary	85.00 FL	*- FL
23	1		*FRONT WIPER SPARE TANK	Serviceable	350.00 FL	*- FL
24	1		*FRONT FENDER INNER PANEL O/S	Distorted	890.00 FL	*680.70 FL
25	1		*FRONT WINDSCREEN MOULDING O/S	Cut	195.00 FL	*195.00 FL
26	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*35.00 FS
27	1		*SET FRONT SUPPORT PANEL TOP COVER CLIPS	Necessary	100.00 FS	*30.00 FS
28	1		*SET FRONT BONNET STICKER	Necessary	150.00 FS	*100.00 FS
29	1		*SET FRONT DOOR RH STICKER	Necessary	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,255.90	5,490.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,961.18	1,041.10
Total Parts (\$\$)	8,294.72	4,449.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	1,400.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	1,180.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	200.00	50.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	240.00	120.00
5	TO REFILL AIR CON GAS	New	100.00	100.00
6	TO CONDUCT WHEEL ALIGNMENT	New	100.00	80.00
Gross Labour Cost (\$\$)			3,440.00	2,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >