



# KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

# SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE  
 Chassis No: JHMRU1810GX201693  
 License No: **SLK5080K**  
 Mileage: 37503  
 Engine No: L15B4531693

Document No: SVO19015994  
 Printed By: ARYCHUA  
 Order Date: 13. March 2019  
 Order Time: 12:53:45 PM  
 Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72200) OWNER: TONG WAI PING OWNER INSURER: AVIVA LTD ACC DATE: 18/02/2019@18.00PM ACC: CTE SLIP RD LOR CHUAN (L/P81) ~ BRADDELL RD <b>SURVEYED BY: GUO QIANG(LKK) 26-02-2019@15.15PM</b> REF NO: CC4/ASM19003429/Gfa3 TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: GBE5043T - TOYOTA/VAN/WHITE						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
34155-T7A-J01	LIGHT ASSYLID	1	269.90	25	202.42	14.17	216.59
33552-T7A-J01	LAMP UNITL.	1	441.50	25	331.12	23.18	354.30
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
74890-T7A-J122D	GARNISH ASSYRR.LICENSE	1	193.60	25	145.20	10.16	155.36
75722-T7W-A01	EMBLEMRR.	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
71593-T7A-J00	SPACER R,RR.BPR S	1	16.90	25	12.67	0.89	13.56
71598-T7A-000	SPACERL,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
74800-T7A-J02	LOCK ASSYTAILGATE	1	78.90	25	59.17	4.14	63.31
68100-T8P-U10ZZ	TAILGATE COMP	1	855.70	25	641.77	44.92	686.69
90676-SA7-003	GROMMET.SCREW.5	2	2.30	25	3.45	0.24	3.69
66100-T7A-300ZZ	PANEL COMPRR.	1	373.10	25	279.82	19.59	299.41
74940-TZ5-A01	BUZZER ASSYSMART	1	60.40	25	45.30	3.17	48.47
04718-T7A-000ZZ	FACEL,RR.BUMPER CORNER	1	94.10	25	70.57	4.94	75.51
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.90	25	32.92	2.30	35.22
	<b>SUM PARTS:</b>				<b>2,355.07</b>	<b>164.84</b>	<b>2,519.91</b>
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML02I	0760 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	100.00		100.00	7.00	107.00
BA02R	0760 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00		140.00	9.80	149.80
BG02D	0760 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00		300.00	21.00	321.00
BOMISC1	0760 RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM(N)	1	300.00		300.00	21.00	321.00

*WD = 6+2*  
*WD = 8*  
*Emo Amp.*  
*15/4/19.*  
*8 days. Close.*



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer:** WZA006 / AXA INSURANCE  
**Chassis No:** JHMRU1810GX201693  
**License No:** SLK5080K  
**Mileage:** 37503  
**Engine No:** L15B4531693

**Document No:** SVO19015994  
**Printed By:** ARYCHUA  
**Order Date:** 13. March 2019  
**Order Time:** 12:53:45 PM  
**Service Advisor:** ARY CHUA WAI NGEE

BOMISC1	0760 REMOVE & INSTALL REVERSE CAMERA & CALIBRATION(N)	1	300.00	300.00	21.00	321.00
BMI03D	0760 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	350.00	350.00	24.50	374.50
BKTG02R	0760 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00	450.00	31.50	481.50
BP04R	0760 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(4P)	1	1,800.00	1,800.00	126.00	1,926.00
BKRP22M	0760 CUT OFF & RENEW RR PANEL & RENEW DAMAGE PARTS STRAIGHTEN RR CHASSIS & RENEW DAMAGE PARTS.	1	2,240.00	2,240.00	156.80	2,396.80
<b>SUM LABOUR:</b>				<b>6,000.00</b>	<b>420.00</b>	<b>6,420.00</b>
<b>TOTAL SGD</b>				<b>8,355.07</b>	<b>584.84</b>	<b>8,939.91</b>
<b>Total Payable (SGD)</b>						<b>8,939.91</b>

GST Amount is calculated from individual line(s).



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer:** \*\*\*\*4320J / TONG WAI PING  
**Chassis No:** JHMUR1810GX201693  
**License No:** SLK5080K  
**Mileage:** 37503  
**Engine No:** L15B4531693

**Document No:** SVO19015994  
**Printed By:** ARYCHUA  
**Order Date:** 13. March 2019  
**Order Time:** 12:53:45 PM  
**Service Advisor:** ARY CHUA WAI NGENE

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST	
<b>SUPPLEMENTARY ITEM PARTS &amp; LABOR</b>								
90676-SA7-003	GROMMET.SCREW.5	2	2.30	25	3.45	0.24	3.69	
66100-T7A-300ZZ	PANEL COMPRR.	1	373.10	25	279.82	19.59	299.41	
74940-TZ5-A01	BUZZER ASSYSMART	1	60.40	25	45.30	3.17	48.47	
04718-T7A-000ZZ	FACELRR.BUMPER CORNER	1	94.10	25	70.57	4.94	75.51	
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.90	25	32.92	2.30	35.22	
	<b>SUM PARTS:</b>				<b>432.06</b>	<b>30.24</b>	<b>462.30</b>	
BKRP22M	0760 CUT OFF & RENEW RR PANEL RR R FENDER. STRAIGHTEN ALIGN RR CHASSIS & RENEW DAMAGE PARTS.	1	1,120.00		1,120.00	78.40	1,198.40	
	<b>SUM LABOUR:</b>				<b>1,120.00</b>	<b>78.40</b>	<b>1,198.40</b>	
					<b>TOTAL SGD</b>	<b>1,552.06</b>	<b>108.64</b>	<b>1,660.70</b>
<b>Total Payable (SGD)</b>							<b>1,660.70</b>	

GST Amount is calculated from individual line(s)